

## Quote Details

### General Information

**Quote Number:** Q1900011852  
**Service Request Number:** SR1900183567  
**Product:** COMPETITOR-PRODUCT  
**Dealer Contact:** 908 561-2100  
**Model:** H180T-02(LINDE)  
**Problem Reported:** cylinders are leaking, and need to go to the  
**Call Type:** MNTB-Maintenance (B)  
**PO Number:** --  
**Serial Number:** 50J07332518  
**Asset Number:** --  
**Date Received:** 10/3/19 2:57 PM  
**Dealer Name:** BARCLAY BRAND CORP-074612000  
**Dealer Phone Number:** 908 561-2100  
**Work Order Number:** 991968-YFLI  
**Status:** Approved and Transfer  
**Quote Threshold:** \$ 1300.00  
**Applicable Contract:** 230005730  
**CustomerBill To:** 431500  
**Customer Name:** LINDE NORTH AMERICA INC.  
**Customer Contact:** alex  
**Customer Location Name:** TLG Dayton NJ  
**Customer Phone:** (732) 343-4306  
**Primary Error Code:** --  
**Potential Problem Description:** cylinders are leaking, and need to go to the  
**Fleet Recommendation:** --  
**Recommendation Comments:** --  
**Meter Reading:** 6037

### Equipment Details

Serial Number:	Model:	Unit Type	Hours On Truck	Fuel Type	Warranty End Date	Unit Age	Lease End Date	Status
50J07332518	H180T-02(LINDE)		6037		--	--	01/01/1900	--

### Failure Information

**Causal Part Number:** -- **Fault Code:** --  
**Causal Part Description:** -- **Fault Found:** LEAKING  
**Component Code:** Hydraulics - All Cylinders (Tilt, Lift) **Caused by:** DAILY USE  
**Condition Found:** Located unit and trouble shoot for multiple leaks. Found second stage cylinder leaking from top and tube also leaking. Steer cylinder leaking. Main free lift cylinder leaking from bottom. Truck to go to shop for repairs. Rental info supplied to Alex by FSS Levi  
 10/3 REQUESTED ADDITIONAL REPAIRS BE ADDED TO QUOTE: Replace stretched free lift chains, cracked/chaffed side shift hoses, tune up including plugs/wires/air filter/oil, drive belt. Replacement of steer tires  
**Work to be Performed:** In shop inspection (3 hr). Reseal steer cylinder (4 hr). Reseal right side 2nd stage cylinder (4 hr). Replace main lift tube assembly (2 hr). Reseal free lift cylinder (6 hr).  
 ...ADDITIONAL REPAIRS RECOMMENDED TO BE ADDED TO QUOTE:  
 Remove and replace free lift chains (4.5 hr). Remove, fabricate and install side shift hoses (3.5 hr). Tune up including plugs/wires/air filter/oil (3 hr). Remove and replace drive belt (.5 hr). Adjust timing cover to prevent rubbing drive belt (1 hr). Remove steer tires, press off and press on new. Install (2 hrs)  
 \* Quote will be revised once in shop inspection has been performed \*  
 \* Quote valid for 14 days from revision submission \*

### Labor Details

Labor Job Code	Standard Hours	Job Description	Additional Labor Hours	Cost Per Hour	Extended Labor Price	Reason for Additional Labor
CMF-RR	0.00	-REMOVE AND REPLACE	33.50	\$ 116.16	\$ 3891.36	REPLACE

Standard Service(s)	Description	Standard Hours	Flat Fee	Additional Labor Hours	Extended Labor Price	Reason for Additional Labor
---------------------	-------------	----------------	----------	------------------------	----------------------	-----------------------------

Overtime Labor Multiplier	Overtime Labor Hours	Overtime Labor Reason
Night & Saturday Labor Hours	0.0	--
Sunday Labor Hours	0.0	--
Holiday Labor Hours	0.0	--

Parts/Components Details

OEM-Parts/Components to be Installed/Purchased

Part Serial Number	Part Number	Description	Quantity	Unit Price	Extended Price
--	150018129	TEL S2 V 46 - 5 GPL	1	\$ 96.81	\$ 96.81
--	513498801	ELEMENT	1	\$ 8.58	\$ 8.58
--	524315934	18X7 8 4.33 SOLID SOLV	2	\$ 154.02	\$ 308.04
--	524306991	FORMULASHELL SAE 10W30	1	\$ 18.99	\$ 18.99

OEM-Parts/Components to be Replaced

Part Serial Number	Part Number	Description	Quantity
--------------------	-------------	-------------	----------

Non-OEM Parts/Services

Part Number	Description	Quantity	Unit Price	Extended Price
PY4620	CLEANER	3	\$ 6.50	\$ 19.50
L0009520208	FITTING	2	\$ 2.98	\$ 5.96
3014509001	STEER CYLINDER KIT	1	\$ 234.06	\$ 234.06
L0009520133	UNION SOCKET	1	\$ 8.34	\$ 8.34
L0009520108	UNION NUT	1	\$ 4.78	\$ 4.78
L0009608132	NAUB KUFT SEAK	1	\$ 20.49	\$ 20.49
L0009608009	MAIN LIFT SEAL	1	\$ 17.92	\$ 17.92
L1624481826	HYDRAULIC TUBE	1	\$ 206.98	\$ 206.98
L0009608012	FREE LIFT SEAL	1	\$ 34.49	\$ 34.49
L9495076061	CHAIN	2	\$ 171.11	\$ 342.22
800128982	SPARK PLUG	4	\$ 2.08	\$ 8.32
LI1604465500	ANCHOR CHAIN	4	\$ 49.23	\$ 196.92
L1604462505	CHAIN SUPPORT	4	\$ 95.74	\$ 382.96
LI151380K	WIRES PLUG	1	\$ 118.46	\$ 118.46
800056096	FAN BELT	1	\$ 3.85	\$ 3.85
800124193	AIR FILETER	1	\$ 25.38	\$ 25.38
L9495076095	CHAIN	2	\$ 244.71	\$ 489.42
SIDE SHIFT HOSES	SIDE SHIFT HOSES	2	\$ 250.00	\$ 500.00
800125492	INNER LUBE	1	\$ 5.23	\$ 5.23

Travel Details

<b>Travel Location:</b>		<b>Number of Trips:</b>	0
<b>Travel Hours:</b>	0.65	<b>Travel Distance:</b>	25.94

Miscellaneous Details

Miscellaneous

Misc Description	Price	Quantity	Extended Price
FREIGHT	\$ 400.00	1	\$ 400.00

<b>Drayage :</b>	\$ 500.00
------------------	-----------

Customer Invoice Information

Category	Part Number	Quantity	Price	Current Amount
Labor			\$ 116.16	\$ 3891.36
OEM Parts	150018129	1	\$ 96.81	\$ 432.42
	513498801	1	\$ 8.58	
	524315934	2	\$ 154.02	
	524306991	1	\$ 18.99	
Non OEM Parts	PY4620	3	\$ 6.50	\$ 2625.28
	L0009520208	2	\$ 2.98	
	3014509001	1	\$ 234.06	
	L0009520133	1	\$ 8.34	
	L0009520108	1	\$ 4.78	
	L0009608132	1	\$ 20.49	
	L0009608009	1	\$ 17.92	
	L1624481826	1	\$ 206.98	
	L0009608012	1	\$ 34.49	
	L9495076061	2	\$ 171.11	
	800128982	4	\$ 2.08	
	L11604465500	4	\$ 49.23	
	L1604462505	4	\$ 95.74	
	L1151380K	1	\$ 118.46	
	800056096	1	\$ 3.85	
	800124193	1	\$ 25.38	
	L9495076095	2	\$ 244.71	
	SIDE SHIFT HOSES	2	\$ 250.00	
800125492	1	\$ 5.23		
Travel			\$ 0.00	\$ 0.00
Drayage			\$ 500.00	\$ 500.00
Miscellaneous	FREIGHT	1	\$ 400.00	\$ 400.00
Total Amount				\$ 7849.06