

## Asset/Equipment Work Order History Brief

Asset ID: PRSS 038		Asset: PRESS 300 TON STRAIGHT SIDE SHUT HIGHT 20.75"				
Work Order ID	Description	Scheduled Date	Completed Date	Days Past Due	Total Cost	
279	MONTHLY PM FOR AUTOMATIC PRE	4/3/2000	4/11/2000 10:09:25 AM	8	\$0.00	
1248	MONTHLY PM FOR AUTOMATIC PRE	5/11/2000	5/11/2000 7:32:01 AM	0	\$29.13	
1760	RESET COMPUTER		5/22/2000 1:10:36 PM	36668	\$23.24	
1942	REPLACE LIGHT BULBS IN LFT TRU		5/26/2000	36672	\$38.84	
1976	REPAIR LIFT TRUCK LIGHTS		5/31/2000	36677	\$10.02	
2221	REPAIR LIFT TRUCK LIGHTS		6/2/2000	36679	\$39.02	
2372	MONTHLY PM FOR AUTOMATIC PRE	6/12/2000	6/27/2000 9:28:53 AM	15	\$29.81	
2461	SAFETY INSPECTION PERFORMED	5/15/2000	6/13/2000 2:19:19 PM	29	\$5.08	
2687	SAFETY INSPECTION PERFORMED	6/20/2000	8/1/2000 1:10:00 PM	42	\$5.08	
2951	REPLACE BROKEN BOLTS IN RAM B		6/24/2000	36701	\$109.04	
2957	REPLACE BROKEN BOLTS FROM RA		6/26/2000 10:48:24 AM	36703	\$478.80	
2969	REPLACE BARRELS AND LEVEL RA		6/26/2000	36703	\$239.46	
3054	REPAIR RAM ADJUSTMENT		6/29/2000	36706	\$159.64	
3057	REPAIR RAM		6/29/2000	36706	\$352.48	
3130	PULL BOLSTE FOR RE DRILLING		6/30/2000	36707	\$120.11	
3133	REPLACE BOLTS IN SCREW BARRE		6/30/2000	36707	\$159.64	
3156	INSTASLL ROD BARREL CUP AND B		7/3/2000	36710	\$221.06	
3191	INSTALL SIDE PLATES		7/5/2000	36712	\$119.73	
3194	REPAIR HOLDING CONTACTS		7/5/2000	36712	\$39.91	
3205	REPLACE BOLSOM PLATE		7/6/2000	36713	\$117.48	
3364	READJUST COUNTER BALANCE AIR		7/10/2000	36717	\$9.79	
3381	ADJUST BRAKE		7/11/2000 11:38:04 AM	36718	\$23.74	

## Asset/Equipment Work Order History Brief

3407	CHECK AIR PRESSURE ON COUNT		7/12/2000 1:27:19 PM	36719	\$23.74
3440	READJUSTED BRAKE		7/14/2000 9:09:12 AM	36721	\$23.74
3628	RESET COUNTER BALANVER AIR P		7/14/2000	36721	\$59.87
3630	ADJUST RAM		7/14/2000	36721	\$79.82
3788	MONTHLY PM FOR AUTOMATIC PRE	7/27/2000	8/4/2000 6:14:18 AM	8	\$29.81
4106	REPAIR PARTS COUNTER		7/28/2000	36735	\$88.12
4142	REPAIR RAM		7/31/2000	36738	\$23.74
4146	ADJUST BRAKE		8/1/2000 1:30:25 PM	36739	\$23.74
4276	SAFETY INSPECTION PERFORMED	8/8/2000	8/28/2000	20	\$7.67
4347	REPAIR RAM BRAKE		8/8/2000	36746	\$30.50
4774	REPAIR RAM		8/22/2000	36760	\$0.00
4807	REPAIR TONNAGE MONITORS		8/24/2000 7:58:58 AM	36762	\$0.00
4820	RESET TONNAGE MONITOR		8/25/2000 5:36:20 AM	36763	\$0.00
5090	MONTHLY PM FOR AUTOMATIC PRE	9/5/2000	9/13/2000 6:23:33 AM	8	\$30.30
5161	SAFETY INSPECTION PERFORMED	9/5/2000	9/15/2000	10	\$5.17
5221	REPAIR TONNAGE MONITORS		9/6/2000	36775	\$29.87
5236	LEVEL RAM		9/7/2000 9:59:32 AM	36776	\$0.00
5251	LEVEL RAM AND CHECK TONNAGE		9/7/2000	36776	\$40.58
5446	LEVEL RAM AND ADJUSTED COUN		9/12/2000	36781	\$20.67
5568	LEVEL RAM AND REPLACE AIR REG		9/15/2000	36784	\$29.87
5584	LEVEL RAM		9/15/2000	36784	\$56.64
5691	SAFETY INSPECTION PERFORMED	9/22/2000	11/8/2000	47	\$5.17
6000	START UP PRESS		10/2/2000 7:32:28 AM	36801	\$0.00

## Asset/Equipment Work Order History Brief

6034	REPAIR		10/3/2000 8:15:06 AM	36802	\$10.10
6050	LEVEL RAM		10/3/2000	36802	\$44.78
6072	REPAIR HOLDING CONTACTS		10/3/2000	36802	\$101.45
6172	MONTHLY PM FOR AUTOMATIC PRE	10/13/2000	10/30/2000 1:30:10 PM	17	\$30.30
6243	CHECK LEVEL OF RAM		10/7/2000	36806	\$28.32
6257	LEVEL RAM		10/9/2000 10:50:43 AM	36808	\$60.60
6279	LEVEL RAM		10/10/2000 10:06:26 AM	36809	\$60.60
6322	REPAIR RAM LIMET SWITCHES		10/11/2000	36810	\$202.90
6516	REPAIR		10/17/2000 10:15:46 AM	36816	\$0.00
7177	SAFETY INSPECTION PERFORMED	11/15/2000	11/20/2000 2:38:17 PM	5	\$5.17
7542	MONTHLY PM FOR AUTOMATIC PRE	11/29/2000	12/12/2000 8:55:52 AM	13	\$30.30
7636	SAFETY INSPECTION PERFORMED	11/27/2000	11/27/2000	0	\$5.17
7800	SAFETY INSPECTION PERFORMED	12/4/2000	12/13/2000 11:05:42 AM	9	\$5.17
8392	SAFETY INSPECTION PERFORMED	12/20/2000	1/9/2001 2:22:37 PM	20	\$5.17
8735	MONTHLY PM FOR AUTOMATIC PRE	1/11/2001	1/10/2001 8:07:50 AM	0	\$30.30
9068	SAFETY INSPECTION PERFORMED	1/16/2001	1/17/2001	1	\$5.17
9264	SAFETY INSPECTION PERFORMED	1/24/2001	1/30/2001	6	\$5.17
9667	MONTHLY PM FOR AUTOMATIC PRE	2/9/2001	3/27/2001 6:17:14 AM	46	\$30.30
9729	SAFETY INSPECTION PERFORMED	2/6/2001	2/12/2001	6	\$5.17
10254	SAFETY INSPECTION PERFORMED	2/19/2001	3/21/2001 2:14:57 PM	30	\$5.17
11384	SAFETY INSPECTION PERFORMED	3/28/2001	4/25/2001	28	\$5.17
12151	MONTHLY PM FOR AUTOMATIC PRE	4/26/2001	5/4/2001 8:06:46 AM	8	\$30.30
12229	INSTALL CONTROLER		4/20/2001	37001	\$23.97

## Asset/Equipment Work Order History Brief

12481	SAFETY INSPECTION PERFORMED	5/2/2001	6/2/2001	31	\$6.82
13534	MONTHLY PM FOR AUTOMATIC PRE	6/4/2001	6/7/2001 9:52:24 AM	3	\$30.30
13853	SAFETY INSPECTION PERFORMED	6/11/2001	6/14/2001 1:47:10 PM	3	\$5.17
14160	SAFETY INSPECTION PERFORMED	6/21/2001	6/20/2001 11:28:25 AM	0	\$5.17
14448	SAFETY INSPECTION PERFORMED	6/27/2001	6/29/2001 1:21:44 PM	2	\$7.67
14774	MONTHLY PM FOR AUTOMATIC PRE	7/9/2001	8/2/2001 6:06:39 AM	24	\$0.00
14839	SAFETY INSPECTION PERFORMED	7/9/2001	7/13/2001	4	\$7.67
15056	SAFETY INSPECTION PERFORMED	7/20/2001	7/17/2001 3:18:00 PM	0	\$7.67
15286	SAFETY INSPECTION PERFORMED	7/24/2001	7/23/2001	0	\$7.67
15526	SAFETY INSPECTION PERFORMED	7/30/2001	7/30/2001	0	\$7.67
15734	SAFETY INSPECTION PERFORMED	8/6/2001	8/9/2001 1:04:29 PM	3	\$7.67
15995	SAFETY INSPECTION PERFORMED	8/16/2001	8/13/2001	0	\$7.67
16261	SAFETY INSPECTION PERFORMED	8/20/2001	8/29/2001	9	\$7.67
16667	MONTHLY PM FOR AUTOMATIC PRE	9/4/2001	9/18/2001 6:25:38 AM	14	\$30.30
16703	SAFETY INSPECTION PERFORMED	9/5/2001	9/5/2001	0	\$7.67
16843	SAFETY INSPECTION PERFORMED	9/12/2001	9/13/2001 2:45:17 PM	1	\$5.17
17030	SAFETY INSPECTION PERFORMED	9/20/2001	10/1/2001	11	\$5.17
17074	REPAIR		9/14/2001	37148	\$134.34
17580	SAFETY INSPECTION PERFORMED	10/8/2001	10/12/2001	4	\$5.17
17778	MONTHLY PM FOR AUTOMATIC PRE	10/18/2001	12/13/2001 7:09:55 AM	56	\$30.30
17803	SAFETY INSPECTION PERFORMED	10/19/2001	10/25/2001	6	\$5.17
18197	SAFETY INSPECTION PERFORMED	11/1/2001	11/2/2001	1	\$5.17
18478	SAFETY INSPECTION PERFORMED	11/9/2001	11/6/2001	0	\$5.17

## Asset/Equipment Work Order History Brief

18606	SAFETY INSPECTION PERFORMED	11/13/2001	11/17/2001	4	\$7.08
18871	SAFETY INSPECTION PERFORMED	11/26/2001	12/27/2001	31	\$5.79
19684	SAFETY INSPECTION PERFORMED	1/3/2002	1/7/2002	4	\$7.67
20023	MONTHLY PM FOR AUTOMATIC PRE	1/14/2002	1/25/2002 2:10:47 PM	11	\$0.00
20061	SAFETY INSPECTION PERFORMED	1/14/2002	1/14/2002	0	\$7.67
20261	SAFETY INSPECTION PERFORMED	1/22/2002	1/23/2002 2:54:35 PM	1	\$5.17
20440	SAFETY INSPECTION PERFORMED	1/30/2002	1/28/2002 3:07:17 PM	0	\$7.67
20755	SAFETY INSPECTION PERFORMED	2/4/2002	2/4/2002	0	\$7.67
20972	SAFETY INSPECTION PERFORMED	2/11/2002	2/15/2002	4	\$5.17
21280	REPAIR ELECTRICAL WIRING		2/20/2002	37307	\$20.67
21292	REPAIR WIRING (LOOSE CONNECTIO		2/20/2002	37307	\$0.00
21354	MONTHLY PM FOR AUTOMATIC PRE	2/25/2002	2/26/2002 10:58:28 AM	1	\$30.30
21407	SAFETY INSPECTION PERFORMED	2/22/2002	3/7/2002	13	\$7.67
21735	UNJAM PRESS (REVERSE MOTOR/R		3/6/2002	37321	\$40.58
21839	SAFETY INSPECTION PERFORMED	3/14/2002	3/14/2002	0	\$7.67
22090	SAFETY INSPECTION PERFORMED	3/21/2002	3/28/2002 1:47:05 PM	7	\$7.67
22306	MONTHLY PM FOR AUTOMATIC PRE	3/28/2002	3/27/2002	0	\$30.30
22317	MONTHLY PM FOR AUTOMATIC PRES	3/28/2002	3/25/2002 10:48:45 AM	0	\$0.00
22626	SAFETY INSPECTION PERFORMED	4/4/2002	4/9/2002	5	\$5.17
23115	SAFETY INSPECTION PERFORMED	4/16/2002	4/18/2002 2:54:40 PM	2	\$5.17
23274	REPAIR E-STOP BUTTON		4/18/2002	37364	\$20.67
23295	MONTHLY PM FOR AUTOMATIC PRE	4/26/2002	4/30/2002 6:51:34 AM	4	\$0.00
23362	SAFETY INSPECTION PERFORMED	4/25/2002	4/30/2002	5	\$5.17

## Asset/Equipment Work Order History Brief

23725	SAFETY INSPECTION PERFORMED	5/7/2002	5/7/2002	0	\$5.17
23991	SAFETY INSPECTION PERFORMED	5/14/2002	5/13/2002 3:41:52 PM	0	\$7.67
24218	SAFETY INSPECTION PERFORMED	5/20/2002	5/21/2002 3:24:39 PM	1	\$7.67
24412	MONTHLY PM FOR AUTOMATIC PRE	5/30/2002	5/28/2002 10:55:29 AM	0	\$0.00
24455	SAFETY INSPECTION PERFORMED	5/28/2002	5/29/2002	1	\$7.67
24658	SAFETY INSPECTION PERFORMED	6/5/2002	6/4/2002	0	\$5.17
24989	SAFETY INSPECTION PERFORMED	6/11/2002	6/13/2002 3:05:53 PM	2	\$3.55
25274	SAFETY INSPECTION PERFORMED	6/20/2002	6/21/2002	1	\$3.55
25423	MONTHLY PM FOR AUTOMATIC PRE	6/27/2002	6/26/2002 9:06:04 AM	0	\$32.55
25707	ANNUAL PM FOR PRESS	7/5/2002	7/31/2002	26	\$43.40
25708	SAFETY INSPECTION PERFORMED	7/1/2002	7/10/2002	9	\$5.54
26135	SAFETY INSPECTION PERFORMED	7/17/2002	7/23/2002	6	\$5.54
26324	MONTHLY PM FOR AUTOMATIC PRE	7/26/2002	7/31/2002	5	\$32.55
26641	SAFETY INSPECTION PERFORMED	7/30/2002	8/3/2002	4	\$7.60
26973	SAFETY INSPECTION PERFORMED	8/12/2002	8/8/2002	0	\$5.58
27176	SAFETY INSPECTION PERFORMED	8/15/2002	8/22/2002	7	\$5.54
27564	REPAIR FAN AT PRESS 38		8/22/2002 10:05:20 AM	37490	\$43.40
27657	MONTHLY PM FOR AUTOMATIC PRE	8/30/2002	9/26/2002 10:34:35 AM	27	\$0.00
27720	SAFETY INSPECTION PERFORMED	8/29/2002	8/27/2002	0	\$3.55
27952	SAFETY INSPECTION PERFORMED	9/3/2002	9/4/2002 12:47:29 PM	1	\$3.55
28121	SAFETY INSPECTION PERFORMED	9/11/2002	9/12/2002	1	\$5.58
28369	SAFETY INSPECTION PERFORMED	9/19/2002	9/19/2002	0	\$3.55
28635	SAFETY INSPECTION PERFORMED	9/26/2002	9/23/2002 11:18:23 AM	0	\$5.54

## Asset/Equipment Work Order History Brief

28888	SAFETY INSPECTION PERFORMED	9/30/2002	10/8/2002	8	\$5.54
29352	SAFETY INSPECTION PERFORMED	10/15/2002	10/15/2002 1:39:26 PM	0	\$3.55
29588	SAFETY INSPECTION PERFORMED	10/22/2002	11/6/2002	15	\$3.55
29800	MONTHLY PM FOR AUTOMATIC PRE	10/28/2002	11/5/2002 2:00:21 PM	8	\$32.55
30290	SAFETY INSPECTION PERFORMED	11/13/2002	11/14/2002	1	\$5.54
30485	SAFETY INSPECTION PERFORMED	11/21/2002	11/22/2002 10:11:45 AM	1	\$3.55
30617	REPLACE ELECT VALVE (AIR BLOW		11/21/2002	37581	\$95.90
30701	MONTHLY PM FOR AUTOMATIC PRE	12/5/2002	12/13/2002 6:40:18 AM	8	\$32.55
30832	SAFETY INSPECTION PERFORMED	12/2/2002	12/6/2002 2:51:21 PM	4	\$5.54
30889	REPLACE START STOP BUTTON		11/22/2002	37582	\$47.95
30991	UNJAM PRESS		12/3/2002 3:05:28 PM	37593	\$42.82
31151	SAFETY INSPECTION PERFORMED	12/13/2002	12/12/2002	0	\$5.58
31372	SAFETY INSPECTION PERFORMED	12/19/2002	12/18/2002	0	\$5.35
31629	SAFETY INSPECTION PERFORMED	1/2/2003	1/6/2003	4	\$5.54
31957	MONTHLY PM FOR AUTOMATIC PRE	1/13/2003	2/18/2003 6:37:43 AM	36	\$32.55
32042	SAFETY INSPECTION PERFORMED	1/13/2003	1/31/2003 1:17:43 PM	18	\$5.35
32619	SAFETY INSPECTION PERFORMED	2/7/2003	2/4/2003	0	\$5.58
32813	SAFETY INSPECTION PERFORMED	2/11/2003	2/13/2003 12:49:00 PM	2	\$3.55
33038	SAFETY INSPECTION PERFORMED	2/20/2003	2/20/2003	0	\$5.54
33265	SAFETY INSPECTION PERFORMED	2/27/2003	2/25/2003	0	\$5.54
33488	SAFETY INSPECTION PERFORMED	3/4/2003	3/5/2003	1	\$5.54
33694	SAFETY INSPECTION PERFORMED	3/12/2003	3/13/2003	1	\$5.54
33919	MONTHLY PM FOR AUTOMATIC PRE	3/20/2003	3/18/2003 7:10:36 AM	0	\$32.55

## Asset/Equipment Work Order History Brief

33920	SAFETY INSPECTION PERFORMED	3/20/2003	3/19/2003	0	\$3.55
34140	SAFETY INSPECTION PERFORMED	3/26/2003	3/26/2003	0	\$3.57
34405	SAFETY INSPECTION PERFORMED	4/2/2003	3/31/2003	0	\$5.58
34683	SAFETY INSPECTION PERFORMED	4/7/2003	4/9/2003	2	\$5.54
34917	MONTHLY PM FOR AUTOMATIC PRE	4/17/2003	4/15/2003 10:21:43 AM	0	\$32.55
34918	SAFETY INSPECTION PERFORMED	4/16/2003	4/15/2003 1:56:05 PM	0	\$3.55
35112	SAFETY INSPECTION PERFORMED	4/22/2003	4/23/2003	1	\$3.57
35363	SAFETY INSPECTION PERFORMED	4/30/2003	5/2/2003	2	\$0.00
	Comments: DOWN FOR DIE MAINTENANCE				
35665	SAFETY INSPECTION PERFORMED	5/9/2003	5/8/2003	0	\$3.57
35847	MONTHLY PM FOR AUTOMATIC PRE	5/15/2003	5/14/2003 8:59:14 AM	0	\$0.00
35848	SAFETY INSPECTION PERFORMED	5/15/2003	5/13/2003 3:09:16 PM	0	\$5.54
36072	SAFETY INSPECTION PERFORMED	5/20/2003	5/20/2003 1:58:38 PM	0	\$3.55
36301	SAFETY INSPECTION PERFORMED	5/27/2003	5/29/2003	2	\$3.55
36408	REPAIR		5/28/2003	37769	\$22.31
36546	SAFETY INSPECTION PERFORMED	6/5/2003	6/3/2003	0	\$7.36
36708	MONTHLY PM FOR AUTOMATIC PRE	6/13/2003	7/1/2003 6:12:47 AM	18	\$32.55
36709	SAFETY INSPECTION PERFORMED	6/10/2003	6/10/2003 2:12:05 PM	0	\$3.55
36741	REVERSE MOTOR FOR DIE REMOVA		6/2/2003	37774	\$22.31
36977	SAFETY INSPECTION PERFORMED	6/17/2003	6/19/2003 12:51:51 PM	2	\$3.55
37173	SAFETY INSPECTION PERFORMED	6/26/2003	6/23/2003	0	\$3.55
37408	SAFETY INSPECTION PERFORMED	6/30/2003	7/14/2003	14	\$3.55
37973	SAFETY INSPECTION PERFORMED	7/21/2003	7/23/2003	2	\$3.55
38236	ANNUAL PM FOR PRESS	7/31/2003	10/7/2003 10:39:00 AM	68	\$43.40

## Asset/Equipment Work Order History Brief

38237	MONTHLY PM FOR AUTOMATIC PRE	7/31/2003	8/11/2003 2:21:15 PM	11	\$32.55
38238	SAFETY INSPECTION PERFORMED	7/30/2003	7/29/2003	0	\$5.54
38404	SAFETY INSPECTION PERFORMED	8/5/2003	8/5/2003 3:10:58 PM	0	\$5.54
38536	SAFETY INSPECTION PERFORMED	8/12/2003	8/25/2003	13	\$3.55
38663	UNJAM		8/14/2003	37847	\$22.31
39126	SAFETY INSPECTION PERFORMED	9/2/2003	9/11/2003 2:14:24 PM	9	\$5.54
39297	MONTHLY PM FOR AUTOMATIC PRE	9/10/2003	9/23/2003 11:02:49 AM	13	\$32.55
39504	SAFETY INSPECTION PERFORMED	9/18/2003	9/17/2003	0	\$4.10
39731	SAFETY INSPECTION PERFORMED	9/24/2003	9/22/2003	0	\$3.55
39883	SAFETY INSPECTION PERFORMED	9/29/2003	9/30/2003	1	\$3.55
40105	SAFETY INSPECTION PERFORMED	10/7/2003	10/6/2003	0	\$3.55
40290	SAFETY INSPECTION PERFORMED	10/13/2003	10/14/2003 2:41:42 PM	1	\$3.57
40538	MONTHLY PM FOR AUTOMATIC PRE	10/23/2003	10/28/2003	5	\$32.55
40539	SAFETY INSPECTION PERFORMED	10/21/2003	10/22/2003 4:45:01 PM	1	\$3.55
40753	SAFETY INSPECTION PERFORMED	10/29/2003	10/27/2003	0	\$3.55
40963	SAFETY INSPECTION PERFORMED	11/3/2003	11/4/2003	1	\$3.55
41146	SAFETY INSPECTION PERFORMED	11/11/2003	11/12/2003	1	\$3.55
41328	SAFETY INSPECTION PERFORMED	11/19/2003	11/18/2003 2:06:59 PM	0	\$5.58
41589	SAFETY INSPECTION PERFORMED	11/25/2003	11/24/2003 2:12:19 PM	0	\$3.55
41775	MONTHLY PM FOR AUTOMATIC PRE	12/1/2003	12/9/2003 1:32:19 PM	8	\$32.55
41776	SAFETY INSPECTION PERFORMED	12/1/2003	12/3/2003 1:18:36 PM	2	\$3.55
41860	REPLACE BLOWN FUSE		11/26/2003	37951	\$10.85
42063	SAFETY INSPECTION PERFORMED	12/10/2003	12/8/2003 2:12:29 PM	0	\$3.55

## Asset/Equipment Work Order History Brief

42258	SAFETY INSPECTION PERFORMED	12/15/2003	12/18/2003 3:09:22 PM	3	\$3.57
42642	MONTHLY PM FOR AUTOMATIC PRE	1/8/2004	1/15/2004 1:40:13 PM	7	\$32.55
42643	SAFETY INSPECTION PERFORMED	1/5/2004	1/7/2004	2	\$5.54
42761	REPAIR BROKEN AIR LINE		12/23/2003	37978	\$43.40
42918	SAFETY INSPECTION PERFORMED	1/14/2004	1/14/2004 3:26:01 PM	0	\$3.55
43099	SAFETY INSPECTION PERFORMED	1/21/2004	1/21/2004	0	\$3.55
43231	SAFETY INSPECTION PERFORMED	1/28/2004	1/29/2004 3:07:07 PM	1	\$3.55
43507	SAFETY INSPECTION PERFORMED	2/5/2004	1/30/2004	0	\$3.55
43765	SAFETY INSPECTION PERFORMED	2/6/2004	2/12/2004 2:39:22 PM	6	\$3.55
43994	MONTHLY PM FOR AUTOMATIC PRE	2/16/2004	2/24/2004	8	\$32.55
43995	SAFETY INSPECTION PERFORMED	2/19/2004	2/22/2004	3	\$7.15
44085	GRIND DIE BLOCK		2/18/2004 7:22:55 AM	38035	\$10.85
44140	UNJAM PRESS		2/17/2004	38034	\$22.31
44392	SAFETY INSPECTION PERFORMED	3/1/2004	3/2/2004 4:17:11 PM	1	\$3.55
44643	SAFETY INSPECTION PERFORMED	3/9/2004	3/10/2004	1	\$3.55
44813	SAFETY INSPECTION PERFORMED	3/17/2004	3/15/2004	0	\$5.54
44996	MONTHLY PM FOR AUTOMATIC PRE	3/25/2004	4/2/2004 7:06:14 AM	8	\$32.55
44997	SAFETY INSPECTION PERFORMED	3/22/2004	3/25/2004 1:55:18 PM	3	\$3.55
45285	SAFETY INSPECTION PERFORMED	4/1/2004	3/31/2004 4:31:38 PM	0	\$3.55
45471	SAFETY INSPECTION PERFORMED	4/7/2004	4/5/2004	0	\$5.54
45504	REPAIR		4/5/2004 7:15:11 AM	38082	\$43.40
45671	SAFETY INSPECTION PERFORMED	4/12/2004	4/19/2004 3:50:01 PM	7	\$3.55
46068	SAFETY INSPECTION PERFORMED	4/26/2004	5/4/2004	8	\$5.54

## Asset/Equipment Work Order History Brief

46309	MONTHLY PM FOR AUTOMATIC PRE	5/3/2004	5/6/2004 8:58:44 AM	3	\$32.55
46549	SAFETY INSPECTION PERFORMED	5/11/2004	5/10/2004	0	\$4.10
46700	REPAIR ELECTYRICAL TO SAFETY B		5/13/2004	38120	\$44.62
46749	SAFETY INSPECTION PERFORMED	5/17/2004	5/18/2004 1:05:20 PM	1	\$12.42
46965	SAFETY INSPECTION PERFORMED	5/25/2004	5/25/2004	0	\$3.55
47160	SAFETY INSPECTION PERFORMED	6/1/2004	6/2/2004	1	\$3.43
47427	MONTHLY PM FOR AUTOMATIC PRE	6/7/2004	6/14/2004 10:42:24 AM	7	\$0.00
47428	SAFETY INSPECTION PERFORMED	6/9/2004	6/10/2004	1	\$3.55
47658	SAFETY INSPECTION PERFORMED	6/17/2004	6/22/2004	5	\$4.10
47955	REPAIR		6/21/2004	38159	\$88.68
47973	REPAIR INSTALL NEW CLM MODULE		6/22/2004	38160	\$177.36
48100	SAFETY INSPECTION PERFORMED	6/29/2004	6/29/2004	0	\$4.10
48179	REPAIR ELECTRICAL (SHORTED WI		6/28/2004	38166	\$88.68
48234	SAFETY INSPECTION PERFORMED	7/6/2004	7/6/2004	0	\$4.10
48463	MONTHLY PM FOR AUTOMATIC PRE	7/14/2004	7/20/2004 1:30:47 PM	6	\$32.55
48464	SAFETY INSPECTION PERFORMED	7/13/2004	7/15/2004 11:34:56 AM	2	\$3.57
48724	SAFETY INSPECTION PERFORMED	7/22/2004	7/20/2004	0	\$4.10
48962	SAFETY INSPECTION PERFORMED	7/27/2004	7/27/2004 2:58:45 PM	0	\$3.57
49198	SAFETY INSPECTION PERFORMED	8/3/2004	8/2/2004	0	\$4.10
49266	REPAIR COUNTER BALANCERS		7/29/2004	38197	\$369.92
49334	SAFETY INSPECTION PERFORMED	8/9/2004	8/11/2004	2	\$5.58
49614	MONTHLY PM FOR AUTOMATIC PRE	8/19/2004	9/1/2004 9:47:13 AM	13	\$32.55
49615	SAFETY INSPECTION PERFORMED	8/18/2004	8/16/2004	0	\$4.10

## Asset/Equipment Work Order History Brief

49722	UNJAM PRESS		8/16/2004		38215	\$22.17
49826	SAFETY INSPECTION PERFORMED	8/23/2004	8/23/2004		0	\$5.58
50057	SAFETY INSPECTION PERFORMED	8/30/2004	8/27/2004		0	\$4.10
50295	SAFETY INSPECTION PERFORMED	9/3/2004	9/7/2004		4	\$3.55
50340	REPAIR AIR REGULATOR (COUNTER		9/7/2004 10:35:24 AM		38237	\$49.66
50468	SAFETY INSPECTION PERFORMED	9/14/2004	9/14/2004 1:41:49 PM		0	\$11.16
50648	SAFETY INSPECTION PERFORMED	9/21/2004	9/22/2004		1	\$3.55
50863	MONTHLY PM FOR AUTOMATIC PRE	10/1/2004	10/4/2004 8:34:17 AM		3	\$0.00
50864	SAFETY INSPECTION PERFORMED	9/29/2004	9/27/2004		0	\$4.10
51063	ANNUAL PM FOR PRESS	10/6/2004	10/8/2004 4:59:42 PM		2	\$43.40
51064	SAFETY INSPECTION PERFORMED	10/4/2004	10/4/2004 3:42:32 PM		0	\$4.46
51340	SAFETY INSPECTION PERFORMED	10/11/2004	10/11/2004		0	\$3.55
51567	SAFETY INSPECTION PERFORMED	10/18/2004	10/20/2004		2	\$4.46
51774	SAFETY INSPECTION PERFORMED	10/27/2004	10/28/2004		1	\$3.55
51937	MONTHLY PM FOR AUTOMATIC PRE	11/3/2004	11/13/2004		10	\$46.85
51938	SAFETY INSPECTION PERFORMED	11/4/2004	11/1/2004		0	\$4.10
52179	SAFETY INSPECTION PERFORMED	11/8/2004	11/9/2004		1	\$4.20
52435	SAFETY INSPECTION PERFORMED	11/16/2004	11/15/2004		0	\$3.63
52647	SAFETY INSPECTION PERFORMED	11/22/2004	11/23/2004		1	\$3.63
52755	SAFETY INSPECTION PERFORMED	11/30/2004	12/1/2004 3:14:08 PM		1	\$6.80
53031	SAFETY INSPECTION PERFORMED	12/8/2004	12/6/2004		0	\$4.20
53267	MONTHLY PM FOR AUTOMATIC PRE	12/13/2004	12/22/2004 3:55:23 PM		9	\$34.07
53268	SAFETY INSPECTION PERFORMED	12/13/2004	12/14/2004		1	\$4.20

## Asset/Equipment Work Order History Brief

53504	SAFETY INSPECTION PERFORMED	12/21/2004	12/20/2004	0	\$6.80
53617	REPAIR OIL LINE		12/22/2004 4:02:41 PM	38343	\$21.92
53628	REPAIR		12/22/2004	38343	\$431.16
53726	SAFETY INSPECTION PERFORMED	12/31/2004	1/3/2005	3	\$4.54
53939	SAFETY INSPECTION PERFORMED	1/10/2005	1/10/2005 2:56:30 PM	0	\$4.54
54211	MONTHLY PM FOR AUTOMATIC PRE	1/21/2005	1/21/2005 8:36:04 AM	0	\$34.07
54212	SAFETY INSPECTION PERFORMED	1/18/2005	1/14/2005	0	\$4.20
54385	SAFETY INSPECTION PERFORMED	1/21/2005	1/26/2005	5	\$3.63
54587	SAFETY INSPECTION PERFORMED	2/2/2005	1/31/2005	0	\$3.65
54797	SAFETY INSPECTION PERFORMED	2/7/2005	2/7/2005	0	\$3.63
55059	SAFETY INSPECTION PERFORMED	2/14/2005	2/15/2005	1	\$4.20
55287	MONTHLY PM FOR AUTOMATIC PRE	2/21/2005	3/4/2005 8:36:01 AM	11	\$34.07
55288	SAFETY INSPECTION PERFORMED	2/22/2005	2/22/2005	0	\$4.20
55474	SAFETY INSPECTION PERFORMED	3/1/2005	3/4/2005 10:58:17 AM	3	\$3.63
55689	SAFETY INSPECTION PERFORMED	3/11/2005	3/10/2005 2:46:09 PM	0	\$3.63
55925	SAFETY INSPECTION PERFORMED	3/17/2005	3/15/2005	0	\$4.20
56147	SAFETY INSPECTION PERFORMED	3/22/2005	3/23/2005 3:16:33 PM	1	\$3.63
56315	SAFETY INSPECTION PERFORMED	3/30/2005	4/1/2005 10:56:53 AM	2	\$3.63
56506	MONTHLY PM FOR AUTOMATIC PRE	4/4/2005	4/22/2005 1:01:38 PM	18	\$34.07
56507	SAFETY INSPECTION PERFORMED	4/8/2005	4/8/2005 9:34:15 AM	0	\$3.63
56623	CHECK TOTATION OF DRIVE MOTO		4/7/2005	38449	\$22.82
56734	SAFETY INSPECTION PERFORMED	4/15/2005	4/18/2005	3	\$3.63
57208	SAFETY INSPECTION PERFORMED	4/25/2005	4/27/2005 1:44:36 PM	2	\$3.63

## Asset/Equipment Work Order History Brief

57397	SAFETY INSPECTION PERFORMED	5/4/2005	5/3/2005 4:32:21 PM	0	\$3.63
57591	SAFETY INSPECTION PERFORMED	5/10/2005	5/12/2005 1:16:52 PM	2	\$3.63
57751	SAFETY INSPECTION PERFORMED	5/19/2005	5/18/2005	0	\$3.65
58041	MONTHLY PM FOR AUTOMATIC PRE	5/23/2005	5/26/2005 1:37:18 PM	3	\$0.00
58042	SAFETY INSPECTION PERFORMED	5/25/2005	5/25/2005	0	\$3.63
58186	REPAIR OF EQUIPMENT		5/25/2005	38497	\$0.00
	Comments: BRAKE NOT WORKING PROPERLY. ADJUSTED BRAKE				
58280	SAFETY INSPECTION PERFORMED	6/1/2005	5/31/2005	0	\$3.63
58478	SAFETY INSPECTION PERFORMED	6/7/2005	6/8/2005	1	\$4.20
58693	SAFETY INSPECTION PERFORMED	6/15/2005	6/14/2005	0	\$3.63
58758	REPAIR OF EQUIPMENT		6/9/2005	38512	\$22.82
	Comments: OPERATOR SAID PRESS STARTED STROKING ON ITS OWN. CHECKED SYMAK CONTROLLER RELAYS AND ALL TERMINATION. STARTED PRESS. CHECKED ALL SOFTY FUNCTIONS. OK. ASSISTED BY KEN RILEY AND BEATTY MOORE.				
58960	WEEKLY SAFETY INSPECTION PERF	6/21/2005	6/21/2005	0	\$3.65
59115	MONTHLY PM FOR AUTOMATIC PRE	6/27/2005	6/30/2005 8:20:21 AM	3	\$68.13
59254	WEEKLY SAFETY INSPECTION PERF	6/28/2005	6/29/2005	1	\$3.63
59445	WEEKLY SAFETY INSPECTION PERF	7/6/2005	7/6/2005	0	\$3.63
59547	REPAIR OF EQUIPMENT		7/1/2005	38534	\$398.02
	Comments: REPLACED FLEX & WIRES BURNT/MELTED/SHORTED TOGETHER FROM BUSS PLUG TO FEEDER TO STRAGJENER TO DECOILER				
59613	REPAIR OF EQUIPMENT		7/6/2005	38539	\$45.36
	Comments: HOSE FOR CLUTCH WAS OFF MACHINE. REPLACED AIR HOSE.				
59616	REPAIR OF EQUIPMENT		7/7/2005	38540	\$43.84
	Comments: REPLACED FUSE. CHECKED FOR SHORT.				
59702	WEEKLY SAFETY INSPECTION PERF	7/13/2005	7/13/2005	0	\$3.63
59764	REPAIR OF EQUIPMENT		7/11/2005	38544	\$94.66
	Comments: #32 EAST END COUNTER BALANCE WAS MAKING NOISE. ADJUSTED, INSPECTED, AND LUBED COUNTER BALANCE SEALS. OPS CHECK OK.				
59912	WEEKLY SAFETY INSPECTION PERF	7/20/2005	7/22/2005 11:08:39 AM	2	\$3.63
60168	WEEKLY SAFETY INSPECTION PERF	7/29/2005	8/2/2005	4	\$3.63
60271	REPAIR OF EQUIPMENT		7/25/2005	38558	\$22.68
	Comments: CHECKED AIR LEAK. ADJUSTED VALVE.				

## Asset/Equipment Work Order History Brief

60272	REPAIR OF EQUIPMENT		7/25/2005	38558	\$22.68
	Comments: PRESS HAS VALVE LEAKING. BACKED VALVE OFF TO RELIEVE C/B PRESSURE.				
60393	MONTHLY PM FOR AUTOMATIC PRE	8/1/2005	8/6/2005 9:28:41 AM	5	\$0.00
60478	REPLACE		8/1/2005	38565	\$96.28
	Comments: REPLACE AIR REGULATOR ON PRESS				
60601	WEEKLY SAFETY INSPECTION PERF	8/9/2005	8/9/2005	0	\$3.63
60709	REPLACE		8/9/2005	38573	\$96.28
	Comments: CHANGE AIR REGULATOR AND COUNTER.				
60862	WEEKLY SAFETY INSPECTION PERF	8/16/2005	8/18/2005	2	\$3.63
61106	WEEKLY SAFETY INSPECTION PERF	8/25/2005	8/25/2005	0	\$3.63
61183	REPAIR OF EQUIPMENT		8/22/2005	38586	\$78.66
	Comments: MOUNT FAN ON POST AT 38 PRESS. WEILDED MOUNT TO POST. MOVED FAN.				
61221	REPAIR OF EQUIPMENT		8/25/2005 7:34:01 AM	38589	\$188.70
	Comments: LOUVERED RAN TO SLOW. ROD CAME OUT OF RAM. PUT BACK AND RELEVELED RAM.				
61339	WEEKLY SAFETY INSPECTION PERF	9/1/2005	9/2/2005 2:06:11 PM	1	\$3.63
61444	REPAIR OF EQUIPMENT		8/30/2005	38594	\$43.84
	Comments: WORKED ON 38 PRESS LINE BROKE LUBRICATING LINE.				
61480	REPAIR OF EQUIPMENT		8/31/2005	38595	\$22.82
	Comments: VANISHING OIL WILL NOT STOP SPRAYING. CHECK UNIT. DISSAMBLE VALVE AND CLEAN TRASH OUT OF BELLOW. REASSEMBLE.				
61553	MONTHLY PM FOR AUTOMATIC PRE	9/6/2005	9/8/2005 7:53:19 AM	2	\$34.07
61554	WEEKLY SAFETY INSPECTION PERF	9/9/2005	9/8/2005	0	\$0.00
61740	WEEKLY SAFETY INSPECTION PERF	9/15/2005	9/14/2005	0	\$3.63
61843	REPAIR OF EQUIPMENT		9/10/2005	38605	\$129.72
	Comments: GOT A MINOR LEAK. VANISHING OIL LINE ABOVE PRESS. CHECKED LEAK 6:30 ON 9/10/05. WILL HAVE TO MOVE COIL RACK AND SHUT DOWN PRESS. INFORMED KEN RILEY 7:30 9/10/05. HE SAID HE WOULD LOOK AT SITUATION AND ADVISE.				
61844	REPAIR OF EQUIPMENT		9/10/2005	38605	\$60.08
	Comments: MOUNT BRACKET FOR SAFETY LIGHTS NEED MODIFYING. DID MODIFY LIGHT BRACKETS.				
61847	REPAIR OF EQUIPMENT		9/10/2005	38605	\$156.45
	Comments: MODIFY BRACKETS FOR SAFETY LIGHT, INSTALL BRACKETS AND LIGHTS, MAKE BRACKET FOR REM BAR. WIRE UP SAFETY LIGHTS. SET DIP SWITCHES AND ADJUST.				
61872	REPAIR OF EQUIPMENT		9/12/2005 8:42:51 AM	38607	\$118.33
	Comments: UNJAMMED PRESS. PRESS WAS JAMMED SATURDAY OR SATURDAY NIGHT. PRESS HAS NOT ENOUGH POWER TO FLY WHEEL FOR THIS JOB.				
61914	REPAIR OF EQUIPMENT		9/12/2005	38607	\$26.22
	Comments: REPLACE BLOWN FUSE IN CONTROL PANEL.				

## Asset/Equipment Work Order History Brief

61941	REPAIR OF EQUIPMENT		9/14/2005		38609	\$26.22
	Comments: FUSE DOWN IN CONTROL PANEL.					
62038	WEEKLY SAFETY INSPECTION PERF	9/21/2005	9/22/2005		1	\$3.63
62206	WEEKLY SAFETY INSPECTION PERF	9/29/2005	9/29/2005		0	\$3.63
62433	WEEKLY SAFETY INSPECTION PERF	10/6/2005	10/6/2005		0	\$3.63
62693	ANNUAL PM FOR PRESS	10/10/2005	10/14/2005 6:43:05 AM		4	\$45.42
62694	MONTHLY PM FOR AUTOMATIC PRE	10/10/2005	10/14/2005 6:42:36 AM		4	\$34.07
62695	WEEKLY SAFETY INSPECTION PERF	10/13/2005	10/14/2005 6:59:42 AM		1	\$3.63
62765	REPAIR OF EQUIPMENT		10/8/2005		38633	\$356.73
	Comments: INSTALL NEW RAM. ADJUSTMENT STOPS. PUT NEW STOPS AND WEDLED TABS FOR RAM STOP ON SCREW. WILL HAVE TO GET PPS CLEARED FOR FINAL ADJUSTMENTS. FAB WILL LET US KNOW.					
62799	REPAIR OF EQUIPMENT		10/11/2005 7:30:48 AM		38636	\$0.00
	Comments: ADJUST LIMIT SWITCH. CAN'T GET DIE IN PRESS.					
62814	INSTALL EQUIPMENT OR OTHER ITE		10/11/2005		38636	\$22.82
	Comments: INSTALL PALM BUTTON AND CONTACT BLOCK FOR E STOP.					
62948	WEEKLY SAFETY INSPECTION PERF	10/21/2005	10/19/2005		0	\$3.63
63112	REPAIR OF EQUIPMENT		10/17/2005		38642	\$45.36
	Comments: FEEDER WIL NOT FEED. SAME LENGTH EVERY STROKE. FOUND AND REPLACED BROKEN SPRING ON DIE.					
63175	WEEKLY SAFETY INSPECTION PERF	10/26/2005	10/28/2005 8:00:22 AM		2	\$3.63
63247	REPAIR OF EQUIPMENT		10/24/2005		38649	\$143.72
	Comments: RAM WILL NOT RAISE. MOTOR MAKING NOISE. CHECK UNIT, FOUND BROKE WIRE ON CABLE FROM J BOX TO RAM LIMIT SWITCH, REPAIRED. NEED TO REPLACE CABLE. CHECK MOTOR, CLUTCH MAKING NOISE. CHECK EDDY CURRENT DRIVE. DC OUT PUT. OK.					
63253	REPAIR OF EQUIPMENT		10/25/2005		38650	\$136.26
	Comments: PULL GUARD AND MOTOR. MOTOR BAD.					
63413	WEEKLY SAFETY INSPECTION PERF	11/4/2005	11/3/2005		0	\$3.63
63465	REPAIR OF EQUIPMENT		10/29/2005		38654	\$197.97
	Comments: MOUNT MOTOR BACK ON PRESS.					
63468	REPAIR OF EQUIPMENT		10/29/2005		38654	\$62.16
	Comments: START PUTTING MOTOR BACK ON PRESS.					
63485	REPAIR OF EQUIPMENT		10/31/2005		38656	\$147.12
	Comments: REMOVE CLUTCH ASSEMBLY FROM PUMP FOR REFUELS.					
63486	REPAIR OF EQUIPMENT		10/31/2005		38656	\$26.22
	Comments: PUT LIGHT FLUSH UP AT PRESS.					
63495	INSTALL EQUIPMENT OR OTHER ITE		10/31/2005		38656	\$136.08
	Comments: INSTALL REBUILD EDDY CURRENT MOTOR. WORKED ON PUTTING BACK TOGETHER. CHECK AMPS 35 AMPS ON MOTOR.					

## Asset/Equipment Work Order History Brief

63502	REPAIR OF EQUIPMENT		11/1/2005	38657	\$0.00
	Comments:	TRUN PRESS ON AND RAISE RAM TO GET DIE OUT TO USE IN PRESS 30.			
63520	CLEAN EQUIPMENT		11/4/2005 7:14:06 AM	38660	\$45.42
	Comments:	CLEAN UP CLUTCH ASSEMBLY			
63521	REPAIR OF EQUIPMENT		11/3/2005	38659	\$43.84
	Comments:	PUT NEW CLUTCH HOUSING ON PRESS			
63614	WEEKLY SAFETY INSPECTION PERF	11/10/2005	11/10/2005	0	\$3.63
63705	REPAIR OF EQUIPMENT		11/4/2005	38660	\$192.56
	Comments:	START PUTTING PRESS 38 BACK TOGETHER.			
63707	REPAIR OF EQUIPMENT		11/7/2005 6:26:49 AM	38663	\$181.68
	Comments:	FINISH PUTTING CLUTCH ON 38 PRESS AND GUARD.			
63709	REPAIR OF EQUIPMENT		11/4/2005	38660	\$43.84
	Comments:	WORK ON KEY WAY AND SHAFT.			
63715	REPAIR OF EQUIPMENT		11/7/2005	38663	\$22.82
	Comments:	REMOVE CLUTCH ASSEMBLY.			
63717	REPAIR OF EQUIPMENT		11/8/2005 6:10:04 AM	38664	\$181.68
	Comments:	REPLACE SPRING AND CLEAN PRESSURE PLATES. PUT SWITCH BACK TOGETHER.			
63727	REPAIR OF EQUIPMENT		11/7/2005	38663	\$21.92
	Comments:	CHECK ON MOTOR DRIVE. TOOL COVER OFF TO LOOK AT CLUTCH.			
63764	REPAIR OF EQUIPMENT		11/8/2005	38664	\$65.76
	Comments:	CHECK RUNNING ADJUSTED BREAK. WATCH RUN FOR ABOUT AN HOUR. TOOK CLUTCH BACK APART.			
63870	MONTHLY PM FOR AUTOMATIC PRE	11/14/2005	11/22/2005 6:38:29 AM	8	\$0.00
63871	WEEKLY SAFETY INSPECTION PERF	11/17/2005	11/18/2005 8:20:20 AM	1	\$3.63
63932	REPAIR OF EQUIPMENT		11/9/2005	38665	\$141.99
	Comments:	PUT CLUTCH ASSEMBLY BACK TOGETHER.			
63941	REPAIR OF EQUIPMENT		11/12/2005	38668	\$34.82
	Comments:	MOTOR WON'T RUN. LOOKED AT MOTOR.			
63962	REPAIR OF EQUIPMENT		11/14/2005	38670	\$114.10
	Comments:	WIRE UP DRIVE MOTOR, START UP AND CHECK ROTATION. COULD NOT GET DC VOLTAGE ON CONTROL CARD. CHANGE OUT CONTROLLER. STILL HAVE SAME PROBLEM.			
63975	REPAIR OF EQUIPMENT		11/15/2005	38671	\$181.44
	Comments:	WON'T RUN. REPLACED MOTOR/DRIVE.			
63992	REPAIR OF EQUIPMENT		11/15/2005	38671	\$45.36
	Comments:	WON'T RUN. REPLACED DRIVE AMP AND ADJUSTED			
64284	WEEKLY SAFETY INSPECTION PERF	11/28/2005	12/1/2005	3	\$3.63
64360	REPAIR OF EQUIPMENT		11/22/2005	38678	\$26.22
	Comments:	FILLED OILER			
64545	WEEKLY SAFETY INSPECTION PERF	12/8/2005	12/5/2005	0	\$3.63
64601	REPAIR OF EQUIPMENT		12/2/2005	38688	\$22.82
	Comments:	INSTALLED NEW COUNTER			

## Asset/Equipment Work Order History Brief

64629	REPAIR OF EQUIPMENT		12/6/2005		38692	\$22.82
	Comments: LIGHT OUT OVER PRESS. REHANG LIGHT AND REPAIR WIRING.					
64785	WEEKLY SAFETY INSPECTION PERF		12/12/2005	12/16/2005 8:15:32 AM	4	\$0.00
65018	MONTHLY PM FOR AUTOMATIC PRE		12/22/2005	12/23/2005 8:01:32 AM	1	\$34.07
65019	WEEKLY SAFETY INSPECTION PERF		12/23/2005	12/21/2005 1:07:26 PM	0	\$3.63
65236	WEEKLY SAFETY INSPECTION PERF		12/28/2005	1/5/2006	8	\$3.63
65543	WEEKLY SAFETY INSPECTION PERF		1/12/2006	1/12/2006	0	\$3.63
65698	REPAIR OF EQUIPMENT			1/11/2006	38728	\$0.00
	Comments: METAL LOADER GOT KNOCKED TRACK BY LIFT. BUT BACK ON AND REPLACED 10 AMP FUSE.					
65816	WEEKLY SAFETY INSPECTION PERF		1/19/2006	1/19/2006	0	\$3.63
66000	MONTHLY PM FOR AUTOMATIC PRE		1/23/2006	1/26/2006 7:45:57 AM	3	\$0.00
66001	WEEKLY SAFETY INSPECTION PERF		1/26/2006	1/26/2006	0	\$3.63
66140	REPAIR OF EQUIPMENT			1/26/2006	38743	\$0.00
	Comments: FUSE BLOWN ON LOADER. REPLACED FUSE. LOADER WAS HUNG UP. GOT LOADER UNHUNG.					
66141	REPAIR OF EQUIPMENT			1/26/2006	38743	\$0.00
	Comments: OVERLOAD TRIPED ON LOADER. RESET AND WATCH TO SEE WHY.					
66219	WEEKLY SAFETY INSPECTION PERF		2/2/2006	2/3/2006 9:59:40 AM	1	\$3.63
66457	WEEKLY SAFETY INSPECTION PERF		2/10/2006	2/9/2006	0	\$3.63
66539	REPAIR OF EQUIPMENT			2/6/2006	38754	\$47.33
	Comments: CHANGED FORKS ON LIFT TRUCK SO THEY WOULD REACH MOTOR ON # 38 PRESS. SECURED FORKS AND HOIST TO MAINT. LIFT. DID SO (AS INSTRUCTED) HAD TO GO DOWN TO BUILDING ON HILL AND GET BOOM.					
66540	REPAIR OF EQUIPMENT			2/6/2006	38754	\$240.70
	Comments: REPLACE DRIVE MOTOR REPLACED EDDIE CURRENT DRIVE MOTOR. THE INSULATION ON THE MOTOR WAS BURNT UP SHORTING THE WINDINGS.					
66552	REPAIR OF EQUIPMENT			2/6/2006	38754	\$91.28
	Comments: CHANGE OUT DRIVE MOTOR					
66594	REPAIR OF EQUIPMENT			2/7/2006	38755	\$335.64
	Comments: PRSS MOTOR (DRIVE MOTOR) WAS REPORTED SMOKE CAME FROM IT. 3RD SHIFT REPLACED FUSE BUT IT ALSO BLEW. CHECK MOTOR AND PULL, GET NEW MOTOR AND BOLD READY.					
	#38 PRESS- AMPS W/O DIE- 26-28 AMPS AMPS WITH DIE- 27-29 AMPS					
66719	WEEKLY SAFETY INSPECTION PERF		2/16/2006	2/17/2006	1	\$3.63

## Asset/Equipment Work Order History Brief

66809	REPAIR OF EQUIPMENT		2/10/2006		38758	\$0.00
	Comments: LOOKED AT MOTOR AND SWITCH. DID NOT KNOW HOW WIRE RAM FROM SWITCH TO MOTOR. HAD TO OHM OUT AND MADE A MAP WHEN I WAS OHMING OUT. WIRE ONE DID NOT READ. CHECK WIRE TI HAD A BAD PLACED IN IT. I REPAIRED WIRE AND AFTER I WAS THRU OHMING OUT WIRES, I FOUND MOTOR WAS WIRED WRONG. MOVED WIRES # 5 TO 5 AND WIRE # 1 AND # 3 TO WIRE # 29 IT IS NOW WORKING.					
67058	WEEKLY SAFETY INSPECTION PERF		2/24/2006	2/24/2006 11:40:22 AM	0	\$3.63
67290	MONTHLY PM FOR AUTOMATIC PRE		2/27/2006	3/15/2006 5:57:46 AM	16	\$34.07
67291	WEEKLY SAFETY INSPECTION PERF		3/3/2006	3/3/2006 11:57:24 AM	0	\$3.63
67535	WEEKLY SAFETY INSPECTION PERF		3/10/2006	3/6/2006	0	\$3.63
67783	WEEKLY SAFETY INSPECTION PERF		3/13/2006	3/13/2006	0	\$0.00
68073	WEEKLY SAFETY INSPECTION PERF		3/20/2006	3/22/2006	2	\$3.63
68132	REPAIR OF EQUIPMENT			3/18/2006	38794	\$0.00
	Comments: PRESS 38 WILL NOT RUN IN AUTO. DIS WAS SET TO FAR TO FRONT "PART WAS IN SAFETY LIGHT"					
68133	REPAIR OF EQUIPMENT			3/18/2006	38794	\$31.08
	Comments: CHECK FUSE ON FEEDER. CHANGE BLOWN FUSE. REPLACED SHORTED WIRE.					
68134	REPAIR OF EQUIPMENT			3/18/2006	38794	\$31.29
	Comments: WILL NOT RUN IN AUTO. CHECK UNIT, FOUND PARTS GOING THROUGH SAFETY LIGHTS. MAKE OPERATOR RELOCATE DIE.					
68138	REPAIR OF EQUIPMENT			3/18/2006	38794	\$34.82
	Comments: MACHINE WON'T RUN ON AUTO. ADJUSTED EMERGENCY STOP SYSTEM, LIGHT, BUTTONS, ETC.					
68143	REPAIR OF EQUIPMENT			3/18/2006	38794	\$0.00
	Comments: REPLACED FUSE IN FEEDER.					
68333	WEEKLY SAFETY INSPECTION PERF		3/29/2006	3/31/2006	2	\$3.63
68580	WEEKLY SAFETY INSPECTION PERF		4/7/2006	4/7/2006 10:49:43 AM	0	\$3.63
68878	MONTHLY PM FOR AUTOMATIC PRE		4/14/2006	4/26/2006	12	\$34.07
68879	WEEKLY SAFETY INSPECTION PERF		4/14/2006	4/10/2006 7:42:13 AM	0	\$3.63
68982	REPAIR OF EQUIPMENT			4/11/2006	38818	\$0.00
	Comments: REPLACED AIR GUAGES AND CHECKED AIR PRESSURE.					
69148	WEEKLY SAFETY INSPECTION PERF		4/17/2006	4/21/2006 11:20:59 AM	4	\$3.63
69291	REPAIR OF EQUIPMENT			4/17/2006	38824	\$11.34
	Comments: REPLACE FUSE IN FEEDER.					
69429	WEEKLY SAFETY INSPECTION PERF		4/28/2006	4/28/2006 8:36:31 AM	0	\$3.63
69678	WEEKLY SAFETY INSPECTION PERF		5/5/2006	5/1/2006	0	\$3.63

## Asset/Equipment Work Order History Brief

69995	WEEKLY SAFETY INSPECTION PERF	5/8/2006	5/9/2006	1	\$3.63
70291	WEEKLY SAFETY INSPECTION PERF	5/16/2006	5/16/2006	0	\$3.63
70613	MONTHLY PM FOR AUTOMATIC PRE	5/26/2006	5/23/2006	0	\$34.07
70614	WEEKLY SAFETY INSPECTION PERF	5/23/2006	5/23/2006	0	\$3.63
70914	WEEKLY SAFETY INSPECTION PERF	5/30/2006	6/1/2006	2	\$3.63
71179	WEEKLY SAFETY INSPECTION PERF	6/8/2006	6/6/2006	0	\$3.63
71433	WEEKLY SAFETY INSPECTION PERF	6/13/2006	6/14/2006	1	\$3.63
71517	REPAIR OF EQUIPMENT		6/12/2006	38880	\$22.68
	Comments: FEEDER QUIT. BLOWS CONTROL VOLTAGE FUSE REPEATEDLY. FOUND FLEX GOING TOWARD STRAIGHTENER IN BAD SHAPE. ALSO OTHERS IN BAD SHAPE. ISOLATED CONT TRANX, WIRE #4 READS SHORTED TO GROUND. CANNOT LOCATE CORRECT WIRING DIAGRAM. ALMOST QUTTING TIME ANYWAY				
71547	REPAIR OF EQUIPMENT		6/13/2006	38881	\$34.23
	Comments: BLOWING CONTROL FUSE ON FEEDER. CHECKED UNIT FOUND PUSH BUTTONS HAD BEEN REVERSED ON DRUM SWITCH. CHANGED BUTTON AROUND. ORDERED CORRECT PENDANT.				
71681	MONTHLY PM FOR AUTOMATIC PRE	6/22/2006	6/23/2006 7:45:04 AM	1	\$34.07
71682	WEEKLY SAFETY INSPECTION PERF	6/21/2006	6/23/2006 9:58:55 AM	2	\$3.63
71825	REPAIR OF EQUIPMENT		6/21/2006	38889	\$0.00
	Comments: FEEDER WILL NOT RUN. E-STOP FAULT. WENT AND CHECKED WIRE AND PRINT CONTROLLER WAS OVER TEMP AFTRE TALKING TO BO, HE SAID IT DID THE SAME THING LAST SUMMER.				
71881	REPAIR OF EQUIPMENT		6/22/2006	38890	\$68.46
	Comments: FEEDER GOING INTO E-STOP. CHECKED UNIT. TRACED ALL E-STOP CIRCUITS TO E-STOP CONTACTOR. CHECKED CONTACTOR, FOUND BAD SET OF CONTACTS. REMOVED, REPLACED ALL CONTACTS. UNIT OK				
71994	WEEKLY SAFETY INSPECTION PERF	6/30/2006	6/28/2006	0	\$3.63
72043	REPAIR OF EQUIPMENT		6/23/2006	38891	\$22.68
	Comments: E-STOP FAULT. AFTER FAN INSTALLED, FAULT IS CLEAR. V'D @ 1600 - CLEAR V'D @ 1800 - CLEAR V'D @ 2000 - CLEAR STARTED RUNNING PRESS @ 2100, STILL RUNNING GOOD @ 2330				
72335	WEEKLY SAFETY INSPECTION PERF	7/5/2006	7/11/2006	6	\$1.81
72641	REPAIR OF EQUIPMENT		7/10/2006	38908	\$22.68
	Comments: PRESS QUIT RUNNING. IDENTIFIED CORRECT PRESS TO WORK ON. (38 NOT 30), REDUCED COUNTERBALANCE AND PRESSURE.				
72825	WEEKLY SAFETY INSPECTION PERF	7/18/2006	7/20/2006 11:07:53 AM	2	\$0.00
72982	PRESS OPERATOR PM		9/29/2006 7:44:23 AM	38989	\$0.00

## Asset/Equipment Work Order History Brief

73023	PRESS OPERATOR PM	7/21/2006		0	\$0.00
73167	MONTHLY PM FOR AUTOMATIC PRE	7/24/2006	7/25/2006 6:08:06 AM	1	\$0.00
73168	WEEKLY SAFETY INSPECTION PERF	7/27/2006	7/28/2006 9:31:57 AM	1	\$18.14
73227	PRESS OPERATOR PM	7/28/2006	7/21/2006 8:42:57 AM	0	\$0.00
73546	WEEKLY SAFETY INSPECTION PERF	8/4/2006	8/10/2006 11:36:04 AM	6	\$1.81
73621	PRESS OPERATOR PM	8/4/2006	8/10/2006 8:42:47 AM	6	\$0.00
73820	PRESS OPERATOR PM	8/11/2006	8/18/2006 1:18:17 PM	7	\$0.00
74023	REPAIR OF EQUIPMENT		8/8/2006	38937	\$76.23
	Comments: POPULAR BROKEN BOLTS RAM SCREW ADJUSTMENT BARREL. REMOVED BROKEN BOLTS, WENT BOUTHERT NEW BOLTS COVERED WITH LOCK TITE AND INSTALLED BOLTS. OPERATES OK. PEGUES RUN PRESS AND I CHECKED TIGHTNESS AGAIN. TORQUED CHEATER BAR FT # UNLOCKED PRESS AND RECORDED IN LOCK OUT TAG OUT BOOK				
74131	WEEKLY SAFETY INSPECTION PERF	8/17/2006	8/18/2006 11:40:42 AM	1	\$3.63
74177	PRESS OPERATOR PM	8/18/2006	8/18/2006 12:58:02 PM	0	\$0.00
74231	REPAIR OF EQUIPMENT		8/8/2006	38937	\$68.25
	Comments: BOLT BROKE OFF IN LEFT JUG ASSEMBLY.				
74430	MONTHLY PM FOR AUTOMATIC PRE	8/24/2006	8/23/2006 6:36:42 AM	0	\$34.07
74431	WEEKLY SAFETY INSPECTION PERF	8/25/2006	8/22/2006	0	\$3.63
74478	PRESS OPERATOR PM	8/25/2006	8/28/2006 2:41:21 PM	3	\$0.00
74878	WEEKLY SAFETY INSPECTION PERF	8/29/2006	8/30/2006	1	\$3.63
74943	PRESS OPERATOR PM	9/1/2006	9/15/2006 9:29:43 AM	14	\$0.00
75236	WEEKLY SAFETY INSPECTION PERF	9/6/2006	9/6/2006	0	\$1.81
75301	PRESS OPERATOR PM	9/8/2006	9/15/2006 9:43:11 AM	7	\$0.00
75539	WEEKLY SAFETY INSPECTION PERF	9/13/2006	9/14/2006	1	\$0.00
75605	PRESS OPERATOR PM	9/15/2006	9/15/2006 8:45:31 AM	0	\$0.00
75882	MONTHLY PM FOR AUTOMATIC PRE	9/22/2006	9/20/2006 8:12:00 AM	0	\$34.07
75883	WEEKLY SAFETY INSPECTION PERF	9/21/2006	9/20/2006	0	\$3.63

## Asset/Equipment Work Order History Brief

75939	PRESS OPERATOR PM	9/22/2006	9/29/2006 7:52:56 AM	7	\$0.00
76244	WEEKLY SAFETY INSPECTION PERF	9/27/2006	9/29/2006 6:42:38 AM	2	\$3.63
76296	PRESS OPERATOR PM	9/29/2006	9/29/2006 7:33:59 AM	0	\$0.00
76578	WEEKLY SAFETY INSPECTION PERF	10/6/2006	10/2/2006	0	\$1.83
76635	PRESS OPERATOR PM	10/6/2006	10/6/2006 8:40:31 AM	0	\$0.00
76730	REPAIR OF EQUIPMENT		9/30/2006	38990	\$155.40
	Comments:	WIRE EXPOSED, INSULATION MISSING, CABLES TANGLED IN FLOOR. REPAIRED BROKEN FLEX, CLEANED UP CABLES, HEAT SHRINK ON EXPOSED WIRES.			
76731	REPAIR OF EQUIPMENT		9/30/2006	38990	\$31.08
	Comments:	WON'T STROKE. REPLACED SQD PLC CONTROLLER.			
76733	REPAIR OF EQUIPMENT		9/29/2006	38989	\$45.36
	Comments:	GATHER MATERIAL FOR SATURDAY WORK.			
76737	REPAIR OF EQUIPMENT		9/30/2006	38990	\$65.90
	Comments:	PLACE SET PARAMETERS ON RAM ADJUSTMENT. GOT READY TO SET RAM UP AND DOWN STOPS AND COULD NOT USE POWER. POWER TO PRESS CUT OFF. ELECT. ETCH HAS WIRE CUT AND TRYING TO REPAIR. WILL DO RAM PARAMETERS LATER.			
76738	REPAIR OF EQUIPMENT		9/30/2006	38990	\$259.86
	Comments:	RAM ADJUST WON'T STOP UP OR DOWN. BUILT RAM ADJUST BRACKET AND INSTALLED. OPERATES OK.			
76997	WEEKLY SAFETY INSPECTION PERF	10/9/2006	10/12/2006	3	\$3.63
77074	PRESS OPERATOR PM	10/13/2006	10/13/2006 7:46:34 AM	0	\$0.00
77436	ANNUAL PM FOR PRESS	10/16/2006	11/2/2006 7:48:15 AM	17	\$45.42
77437	MONTHLY PM FOR AUTOMATIC PRE	10/20/2006	10/24/2006 7:04:28 AM	4	\$34.07
77438	WEEKLY SAFETY INSPECTION PERF	10/19/2006	10/18/2006	0	\$3.63
77495	PRESS OPERATOR PM	10/20/2006	10/20/2006 7:45:20 AM	0	\$0.00
77784	WEEKLY SAFETY INSPECTION PERF	10/25/2006	10/23/2006	0	\$3.63
77830	PRESS OPERATOR PM	10/27/2006	10/27/2006 7:24:46 AM	0	\$0.00
78085	WEEKLY SAFETY INSPECTION PERF	10/30/2006	11/3/2006 10:05:49 AM	4	\$3.65
78141	PRESS OPERATOR PM	11/3/2006	11/3/2006 9:36:09 AM	0	\$0.00
78198	REPAIR OF EQUIPMENT		10/30/2006	39020	\$43.84
	Comments:	WENT AND BROKE THE LUBE AND WATER LINE OVER PRESS # 38, HAD TO GO TO TOWN TO GET PARTS AND GLUE FOR REPAIR.			

## Asset/Equipment Work Order History Brief

78213	REPAIR OF EQUIPMENT		10/30/2006		39020	\$272.93
	Comments: STRIP OUT ALL OLD CONTROLS FOR FEEDER. CLEAN UP AND START INSTALLATION OF NEW CONTROLS					
78214	REPAIR OF EQUIPMENT		10/30/2006		39020	\$0.00
	Comments: RAN 480 V POWER OVER TO FEEDER CONTROL BOARD.					
78399	WEEKLY SAFETY INSPECTION PERF	11/10/2006		11/6/2006	0	\$3.63
78454	PRESS OPERATOR PM	11/10/2006	11/10/2006 10:31:10 AM		0	\$0.00
78517	REPAIR OF EQUIPMENT			11/6/2006	39027	\$0.00
	Comments: LEARNED HOW TO ADJUST FEED SETTING FROM .010 TO .001. TOOK LONGER THAN EXPECTED.					
78704	WEEKLY SAFETY INSPECTION PERF	11/13/2006		11/13/2006	0	\$0.00
78775	PRESS OPERATOR PM	11/17/2006	11/17/2006 8:54:22 AM		0	\$0.00
79012	MONTHLY PM FOR AUTOMATIC PRE	11/23/2006	12/7/2006 8:26:32 AM		14	\$34.07
79013	WEEKLY SAFETY INSPECTION PERF	11/20/2006		11/20/2006	0	\$3.63
79070	PRESS OPERATOR PM	11/24/2006	11/22/2006 10:43:30 AM		0	\$0.00
79297	WEEKLY SAFETY INSPECTION PERF	11/27/2006		11/29/2006	2	\$0.00
79343	PRESS OPERATOR PM	12/1/2006	12/1/2006 7:22:43 AM		0	\$0.00
79622	WEEKLY SAFETY INSPECTION PERF	12/6/2006		12/4/2006	0	\$3.63
79953	WEEKLY SAFETY INSPECTION PERF	12/11/2006	12/15/2006 7:05:44 AM		4	\$3.63
80009	PRESS OPERATOR PM	12/8/2006	12/8/2006 12:49:43 PM		0	\$0.00
80010	PRESS OPERATOR PM	12/15/2006	12/15/2006 7:50:51 AM		0	\$0.00
80139	REPAIR OF EQUIPMENT			12/12/2006	39063	\$0.00
	Comments: SWITCH NOT TURN ON ALL THE WAY.					
80295	WEEKLY SAFETY INSPECTION PERF	12/22/2006	12/22/2006 9:11:46 AM		0	\$3.63
80365	PRESS OPERATOR PM	12/22/2006	12/22/2006 9:14:54 AM		0	\$0.00
80720	WEEKLY SAFETY INSPECTION PERF	12/29/2006	1/5/2007 9:52:07 AM		7	\$0.00
80790	PRESS OPERATOR PM	12/29/2006	1/5/2007 10:03:38 AM		7	\$0.00
80791	PRESS OPERATOR PM	1/5/2007		1/8/2007	3	\$0.00
81030	MONTHLY PM FOR AUTOMATIC PRE	1/8/2007	1/12/2007 7:58:54 AM		4	\$34.07

## Asset/Equipment Work Order History Brief

81031	WEEKLY SAFETY INSPECTION PERF	1/12/2007	1/12/2007 8:24:46 AM	0	\$0.00
81081	PRESS OPERATOR PM	1/12/2007	1/10/2007	0	\$0.00
81390	WEEKLY SAFETY INSPECTION PERF	1/19/2007	1/17/2007	0	\$3.63
81474	PRESS OPERATOR PM	1/19/2007	1/19/2007	0	\$0.00
81570	REPAIR OF EQUIPMENT		1/12/2007	39094	\$36.47
	Comments: SPRAYER NOT WORKING. CLEAN TRASH OUT OF SPRAYER TIP.				
81734	WEEKLY SAFETY INSPECTION PERF	1/24/2007	1/26/2007 7:12:35 AM	2	\$0.00
81768	PRESS OPERATOR PM	1/26/2007	1/26/2007 10:00:23 AM	0	\$0.00
82034	WEEKLY SAFETY INSPECTION PERF	2/2/2007	1/29/2007	0	\$3.63
82065	PRESS OPERATOR PM	2/2/2007	2/1/2007	0	\$0.00
82164	REPAIR OF EQUIPMENT		1/26/2007	39108	\$18.24
	Comments: PRESS WON'T FUNCTION ON INCH MODE. CHECKED OUT UNIT. OK.				
82195	REPAIR OF EQUIPMENT		1/29/2007	39111	\$36.47
	Comments: TAKE CARE OF EXPOSED WIRES ON PRESS.REPAIRED WIRE WAY COVER.				
82325	WEEKLY SAFETY INSPECTION PERF	2/5/2007	2/6/2007	1	\$3.63
82399	PRESS OPERATOR PM	2/9/2007	2/8/2007	0	\$0.00
82436	REPAIR OF EQUIPMENT		2/1/2007 6:59:48 AM	39114	\$26.80
	Comments: PUT NEW VALVE ON LUBE LINE.				
82437	REPAIR OF EQUIPMENT		2/1/2007 7:01:08 AM	39114	\$0.00
	Comments: VALVE LEAKING HEAVLY FOR SPRAYER. REPLACE VALVE.				
82616	REPAIR OF EQUIPMENT		2/6/2007 7:47:01 AM	39119	\$26.80
	Comments: LOOSE WIRE ON THE TONER.				
82650	REPAIR OF EQUIPMENT		2/6/2007	39119	\$0.00
	Comments: PLEASE TAKE CARE OF EXPOSED WIRES ON PRESS.				
	PUT WIRE COVER BACK AGAIN.				
82778	MONTHLY PM FOR AUTOMATIC PRE	2/12/2007	2/13/2007 8:23:44 AM	1	\$40.20
82779	WEEKLY SAFETY INSPECTION PERF	2/13/2007	2/16/2007 8:48:45 AM	3	\$3.63
82825	PRESS OPERATOR PM	2/16/2007	2/16/2007 9:45:29 AM	0	\$0.00
83127	WEEKLY SAFETY INSPECTION PERF	2/23/2007	2/21/2007	0	\$3.63
83185	PRESS OPERATOR PM	2/23/2007	2/23/2007 9:45:11 AM	0	\$0.00
83322	REPAIR OF EQUIPMENT		2/20/2007	39133	\$0.00
	Comments: REPAIRED RAKE.				

## Asset/Equipment Work Order History Brief

83457	WEEKLY SAFETY INSPECTION PERF	2/28/2007	3/2/2007 9:40:19 AM	2	\$0.00
	Comments: NT				
83511	PRESS OPERATOR PM	3/2/2007	3/2/2007 6:42:17 AM	0	\$0.00
83844	WEEKLY SAFETY INSPECTION PERF	3/9/2007	3/6/2007	0	\$5.84
83908	PRESS OPERATOR PM	3/9/2007	3/7/2007	0	\$0.00
84213	MONTHLY PM FOR AUTOMATIC PRE	3/15/2007	3/16/2007 8:57:54 AM	1	\$40.20
84214	WEEKLY SAFETY INSPECTION PERF	3/13/2007	3/13/2007	0	\$1.81
84267	PRESS OPERATOR PM	3/16/2007	3/16/2007 9:24:16 AM	0	\$0.00
84552	WEEKLY SAFETY INSPECTION PERF	3/20/2007	3/20/2007	0	\$0.00
84603	PRESS OPERATOR PM	3/23/2007	3/23/2007 8:50:18 AM	0	\$0.00
84786	REPAIR OF EQUIPMENT		3/21/2007	39162	\$36.13
	Comments: CHECK AIR REGULATOR FOR BLOW OFF.				
84891	WEEKLY SAFETY INSPECTION PERF	3/27/2007	3/26/2007	0	\$1.81
84941	PRESS OPERATOR PM	3/30/2007	3/30/2007 10:03:59 AM	0	\$0.00
85098	REPAIR OF EQUIPMENT		3/28/2007 8:17:58 AM	39169	\$53.60
	Comments: ROD ON OILER BROKE.				
85125	REPAIR OF EQUIPMENT		3/26/2007	39167	\$22.68
	Comments: BLOW OFF QUIT WORKING. HAVE TO ADJUST PRESS AFTER 1ST SHIFT LEAVES.				
85172	REPAIR OF EQUIPMENT		3/28/2007	39169	\$22.68
	Comments: CHECK BLOW OFFS. ADJUSTED ACCUATOR				
85284	WEEKLY SAFETY INSPECTION PERF	4/2/2007	4/2/2007	0	\$5.84
85343	PRESS OPERATOR PM	4/6/2007	4/9/2007	3	\$0.00
85569	WEEKLY SAFETY INSPECTION PERF	4/9/2007	4/13/2007 9:53:14 AM	4	\$0.00
85611	PRESS OPERATOR PM	4/13/2007	4/13/2007 8:48:19 AM	0	\$0.00
85692	REPAIR OF EQUIPMENT		4/9/2007	39181	\$70.15
	Comments: SPARKS/SMOKE COMING OFF OF SHAFT. FOUND INTERMEDIATE SHAFT WELD BROKEN. REMOVED DIE, LOCKED OUT DISCONNECT.				
85723	REPAIR OF EQUIPMENT		4/10/2007	39182	\$481.70
	Comments: EMEDIADTE SHAFT FLANGE BROKE AND CRACKED. TOOK FIRE RETARDANT BLANKETS AND WRAPPED PRESS SO NO SPARKS COULD GET INTO OIL FLOW OR SUPPLY. CHIPPED OUT BROKE FLANGE AND REWELDED FLANGE TO SHAFT. CHECKED ROTATION AFTER WELD. GOT A LITTLE WOBBLE (NO MORE THAN EXPECTED) OPERATES OK.				
85896	MONTHLY PM FOR AUTOMATIC PRE	4/16/2007	4/24/2007	8	\$40.20

## Asset/Equipment Work Order History Brief

85897	WEEKLY SAFETY INSPECTION PERF	4/20/2007	4/18/2007 9:46:18 AM	0	\$5.84
85968	PRESS OPERATOR PM	4/20/2007	4/20/2007 11:03:55 AM	0	\$0.00
86164	WEEKLY SAFETY INSPECTION PERF	4/25/2007	4/23/2007	0	\$5.84
86215	PRESS OPERATOR PM	4/27/2007	4/26/2007	0	\$0.00
86622	WEEKLY SAFETY INSPECTION PERF	4/30/2007	4/30/2007	0	\$1.81
86656	PRESS OPERATOR PM	5/4/2007	5/4/2007 8:42:41 AM	0	\$0.00
86942	WEEKLY SAFETY INSPECTION PERF	5/7/2007	5/7/2007	0	\$3.63
86994	PRESS OPERATOR PM	5/11/2007	5/10/2007	0	\$0.00
87281	WEEKLY SAFETY INSPECTION PERF	5/14/2007	5/14/2007	0	\$5.84
87351	PRESS OPERATOR PM	5/18/2007	5/18/2007 8:38:16 AM	0	\$0.00
87666	MONTHLY PM FOR AUTOMATIC PRE	5/24/2007	5/22/2007 10:23:51 AM	0	\$57.23
87667	WEEKLY SAFETY INSPECTION PERF	5/21/2007	5/21/2007	0	\$5.84
87699	PRESS OPERATOR PM	5/25/2007	5/23/2007	0	\$0.00
87842	REPAIR OF EQUIPMENT		5/23/2007	39225	\$132.12
	Comments: RAM ADJUSTMENTS NOT WORKING. REPLACED TWO CURLY CORDS INSIDE RAM.				
87988	WEEKLY SAFETY INSPECTION PERF	5/28/2007	5/29/2007	1	\$5.84
88020	PRESS OPERATOR PM	6/1/2007	6/1/2007	0	\$0.00
88113	REPAIR OF EQUIPMENT		5/29/2007	39231	\$0.00
	Comments: WIRE FOR STOP BLOCK PULLED OUT OF PRESS. REPAIRED WIRING AND STOP BLOCK CONNECTOR.				
88260	WEEKLY SAFETY INSPECTION PERF	6/5/2007	6/4/2007	0	\$5.84
88290	PRESS OPERATOR PM	6/8/2007	6/7/2007	0	\$0.00
88607	WEEKLY SAFETY INSPECTION PERF	6/11/2007	6/11/2007	0	\$5.84
88679	PRESS OPERATOR PM	6/15/2007	6/15/2007 11:53:59 AM	0	\$0.00
88899	INSTALL EQUIPMENT OR OTHER ITE		6/13/2007	39246	\$12.50
	Comments: INSTALL AND ATTACH KEY LOCK BOX.				
89011	MONTHLY PM FOR AUTOMATIC PRE	6/21/2007	6/20/2007 9:40:16 AM	0	\$40.20

## Asset/Equipment Work Order History Brief

89012	WEEKLY SAFETY INSPECTION PERF	6/18/2007	6/18/2007	0	\$5.84
89080	PRESS OPERATOR PM	6/22/2007	6/22/2007	0	\$0.00
89408	WEEKLY SAFETY INSPECTION PERF	6/25/2007	6/29/2007 10:36:43 AM	4	\$0.00
89649	REPAIR OF EQUIPMENT		6/28/2007	39261	\$0.00
	Comments: AIR LINE BROKE. REPLACED COPPER AIR LINE TO BLOW OUT PARTS FROM DIE				
89744	WEEKLY SAFETY INSPECTION PERF	7/6/2007	7/6/2007 8:10:44 AM	0	\$3.63
89971	WEEKLY SAFETY INSPECTION PERF	7/13/2007	7/10/2007	0	\$5.84
90273	MONTHLY PM FOR AUTOMATIC PRE	7/20/2007	7/20/2007	0	\$40.20
90274	WEEKLY SAFETY INSPECTION PERF	7/17/2007	7/17/2007 9:47:29 AM	0	\$5.84
90602	WEEKLY SAFETY INSPECTION PERF	7/24/2007	7/27/2007 11:04:18 AM	3	\$3.63
90982	WEEKLY SAFETY INSPECTION PERF	8/3/2007	7/30/2007 2:23:11 PM	0	\$5.84
91121	REPAIR OF EQUIPMENT		7/30/2007	39293	\$54.71
	Comments: REPLACE FLUORESCENT BULB BEHIND PRESS. (HAD TO GO GET)				
91249	WEEKLY SAFETY INSPECTION PERF	8/6/2007	8/6/2007	0	\$5.84
91486	WEEKLY SAFETY INSPECTION PERF	8/13/2007	8/13/2007	0	\$5.84
91911	MONTHLY PM FOR AUTOMATIC PRE	8/20/2007	8/23/2007 10:25:39 AM	3	\$40.20
91912	WEEKLY SAFETY INSPECTION PERF	8/20/2007	8/20/2007	0	\$5.84
92224	WEEKLY SAFETY INSPECTION PERF	8/27/2007	8/29/2007 10:12:47 AM	2	\$5.84
92506	WEEKLY SAFETY INSPECTION PERF	9/5/2007	9/7/2007 12:57:02 PM	2	\$0.00
92832	WEEKLY SAFETY INSPECTION PERF	9/14/2007	9/10/2007	0	\$5.84
93112	WEEKLY SAFETY INSPECTION PERF	9/17/2007	9/18/2007 9:59:30 AM	1	\$5.84
93429	REPAIR OF EQUIPMENT		9/20/2007	39345	\$0.00
	Comments: CUT AND WELD SOME PARTS ON METAL APPARATUS FOR STRAIGHTENER.				
93523	MONTHLY PM FOR AUTOMATIC PRE	9/24/2007	9/26/2007 10:25:15 AM	2	\$40.20
93524	WEEKLY SAFETY INSPECTION PERF	9/25/2007	9/24/2007	0	\$5.84
93621	REPAIR OF EQUIPMENT		9/21/2007	39346	\$150.01
	Comments: WORK ON METAL BENDER. ROLLER TENSIONER. READY TO INSTALL.				

## Asset/Equipment Work Order History Brief

93720	REPAIR OF EQUIPMENT		9/26/2007	39351	\$11.34
	Comments: STRAIGHTENER WILL NOT RUN. RESET FAULT ON DRIVE.				
93880	WEEKLY SAFETY INSPECTION PERF	10/1/2007	10/4/2007 1:12:38 PM	3	\$5.84
94186	WEEKLY SAFETY INSPECTION PERF	10/11/2007	10/8/2007	0	\$2.92
94515	WEEKLY SAFETY INSPECTION PERF	10/15/2007	10/17/2007	2	\$0.00
94935	MONTHLY PM FOR AUTOMATIC PRE	10/26/2007	10/25/2007 10:46:34 AM	0	\$40.20
94936	WEEKLY SAFETY INSPECTION PERF	10/24/2007	10/26/2007 6:34:49 AM	2	\$5.84
95288	ANNUAL PM FOR PRESS	11/2/2007	11/30/2007 11:15:51 AM	28	\$0.00
95289	WEEKLY SAFETY INSPECTION PERF	11/2/2007	10/31/2007	0	\$5.84
95492	REPAIR OF EQUIPMENT		11/1/2007 8:40:09 AM	39387	\$448.65
	Comments: CLUTCH/BRAKE HANGING UP.				
95509	REPAIR OF EQUIPMENT		10/31/2007	39386	\$196.79
	Comments: MOTOR SMOKING AND PRESS RUNS BY ITSELF. TIGHTEN BELTS, RUN PRESS. THING THERE ARE SOME BAD CLUTCH DISC AND BAD BEARINGS. AND MIGHT BE A BAD MOTOR.				
95529	REPAIR OF EQUIPMENT		11/1/2007	39387	\$0.00
	Comments: MEG OUT MOTOR AT STARTER.				
95537	REPAIR OF EQUIPMENT		11/1/2007	39387	\$340.20
	Comments: TEAR DOWN PRESS. REBUILD PRESS. CHECKED MOTOR AND DRIVE. REMOVED CLUTCH ASSY. AND GUARDS. INSTALLED BEARINGS, CLEANED UP, INSTALLED OUTER SHAFT, AND INSTALLED NEW KEY IN MOTOR PULLEY.				
95542	REPAIR OF EQUIPMENT		11/2/2007 7:58:30 AM	39388	\$448.65
	Comments: PRESS REASSEMBLY.				
95649	WEEKLY SAFETY INSPECTION PERF	11/7/2007	11/6/2007	0	\$5.84
95706	REPAIR OF EQUIPMENT		11/5/2007 6:54:39 AM	39391	\$269.19
	Comments: REASSEMBLE PRESS.				
95718	REPAIR OF EQUIPMENT		11/2/2007	39388	\$72.94
	Comments: HELP GET SHAFT READY. PUT BEARING RACE ON AND TOOK TO HANCOCK TO HAVE IT WELDED AND TURN DOWN WHERE BEARINGS WOULD FIT.				
95723	REPAIR OF EQUIPMENT		11/3/2007	39389	\$93.90
	Comments: REPLACE MOTOR FOR MAIN DRIVE. TOOK BAD MOTOR DOWN AND PUT NEW ONE UP.				
95726	REPAIR OF EQUIPMENT		11/3/2007	39389	\$284.34
	Comments: ASSEMBLE PRESS DRIVE. INSTALLED BEARINGS, CAP, INSTALLED FLYWHEEL. WIRED MOTOR, INSTALLED BELTS, BELIEVE CLUTCH IS INSTALLED BACKWARDS.				
95736	REPAIR OF EQUIPMENT		11/3/2007	39389	\$881.25
	Comments: PRESS WORK.				

## Asset/Equipment Work Order History Brief

95766	REPAIR OF EQUIPMENT		11/5/2007		39391	\$416.29
	Comments:	FINISH ASSEMBLE OF # 38 PRESS COVERS, CLUTCHES, AND BRAKE ASSEMBLY. SHIMMED CLUTCH .125 WAS DRAGGING.				
95771	REPAIR OF EQUIPMENT		11/5/2007		39391	\$132.80
	Comments:	HANG 4 LITES AT 38 PRESS.				
95772	REPAIR OF EQUIPMENT		11/5/2007		39391	\$304.13
	Comments:	FLYWHEEL PROBLEMS. STARTED WORK ON FLYWHEEL REMOVAL.  WORK DONE ON 10/31/07 RECEIVED 11/6/07.				
95773	REPAIR OF EQUIPMENT		11/5/2007		39391	\$304.13
	Comments:	FLYWHEEL BEARINGS BAD. STARTED REMOVED AND REPLACEMENT.  WORK DONE ON 11/1/07 RECEIVED ON 11/6/07.				
95774	REPAIR OF EQUIPMENT		11/5/2007		39391	\$840.85
	Comments:	TAKE SHAFT TO ELECT. AND MACHINE SERVICE AND CLEAN UP PRESS FOR INSTALLATION WHEN SHAFT COMES BACK. START INSTALLATION UNTIL MACHINE RUNS OR ANOTHER SHIFT TAKES OVER. DID TAKE SHAFT TO SHOP. DID GET BACK IN TIME TO INSTALL OR START INSTALLING.				
95804	REPAIR OF EQUIPMENT		11/5/2007		39391	\$109.41
	Comments:	HELP GET 38 PRESS RUNNING. HELP RESET BELTS AND PRESSURE PLATE FOR THE CLUTCH.				
95812	REPAIR OF EQUIPMENT		11/6/2007		39392	\$79.13
	Comments:	WENT UP TOP, WENT TO THE EAST, WENT TO THE WEST. ONLY RACKET WE HEARD IS A LITTLE COUNTER BALANCE. LEAKES, NOT ENOUGH TO BE EXCITED ABOUT.				
95959	WEEKLY SAFETY INSPECTION PERF		11/13/2007	11/15/2007 8:21:20 AM	2	\$5.84
96309	WEEKLY SAFETY INSPECTION PERF		11/22/2007	11/21/2007 8:34:15 AM	0	\$0.00
96591	MONTHLY PM FOR AUTOMATIC PRE		11/26/2007	12/1/2007	5	\$40.20
96592	WEEKLY SAFETY INSPECTION PERF		11/28/2007	11/30/2007 10:59:05 AM	2	\$5.84
96890	WEEKLY SAFETY INSPECTION PERF		12/7/2007	12/6/2007 10:45:00 AM	0	\$5.84
97149	WEEKLY SAFETY INSPECTION PERF		12/13/2007	12/13/2007 10:52:35 AM	0	\$0.00
97210	REPAIR OF EQUIPMENT		12/6/2007		39422	\$0.00
	Comments:	CLUTCH NOT ENGAGING. MOTOR HAS TO BE CHANGED. WHEN NEW MOTOR WAS MOUNTED, THE DRIVE BELTS WERE REPLACED WITH SHORTER BELTS. WIRES AND FLEX WOULD NOT REACH THE MOTOR. EXTENDED CONDUIT AND REPLACED WIRE TO MOTOR.				
97216	REPAIR OF EQUIPMENT		12/6/2007		39422	\$265.60
	Comments:	MOTOR WANT ENGAGE CLUTCH. (TESTED) REMOVED AND REPLACED EDDIE CURRENT MOTOR.				
97221	REPAIR OF EQUIPMENT		12/7/2007		39423	\$0.00
	Comments:	LOAD MOTOR FROM PRESS 38 ONTO REPAIR TRUCK.				
97263	REPAIR OF EQUIPMENT		12/7/2007		39423	\$89.73
	Comments:	PUT FLYWHEEL COVER BACK ON PRESS.				

## Asset/Equipment Work Order History Brief

97264	REPAIR OF EQUIPMENT		12/6/2007		39422	\$113.40
	Comments: WIRE UP MOTOR. PULLED NEW WIRE TO MOTOR.					
97518	WEEKLY SAFETY INSPECTION PERF	12/20/2007	12/19/2007 10:02:31 AM		0	\$5.84
97860	WEEKLY SAFETY INSPECTION PERF	12/26/2007	12/28/2007		2	\$0.00
98079	MONTHLY PM FOR AUTOMATIC PRE	12/31/2007	12/31/2007		0	\$0.00
98080	WEEKLY SAFETY INSPECTION PERF	1/4/2008	1/7/2008 2:34:00 PM		3	\$5.84
98455	MONTHLY PM FOR AUTOMATIC PRE	1/30/2008	1/24/2008 12:37:56 PM		0	\$40.20
98799	WEEKLY SAFETY INSPECTION PERF	1/14/2008	1/17/2008 8:49:25 AM		3	\$5.84
99109	WEEKLY SAFETY INSPECTION PERF	1/24/2008	1/28/2008 12:57:35 PM		4	\$5.84
99783	MONTHLY PM FOR AUTOMATIC PRE	2/25/2008	2/15/2008 8:34:00 AM		0	\$40.20
99784	WEEKLY SAFETY INSPECTION PERF	2/4/2008	2/4/2008		0	\$5.84
100211	WEEKLY SAFETY INSPECTION PERF	2/11/2008	2/13/2008 1:48:11 PM		2	\$5.84
100416	WEEKLY SAFETY INSPECTION PERF	2/20/2008	2/22/2008 8:34:21 AM		2	\$5.84
100636	WEEKLY SAFETY INSPECTION PERF	2/29/2008	2/26/2008		0	\$5.84
101164	MONTHLY PM FOR AUTOMATIC PRE	3/17/2008	3/13/2008 10:14:32 AM		0	\$40.20
101165	WEEKLY SAFETY INSPECTION PERF	3/4/2008	3/3/2008		0	\$5.84
101559	WEEKLY SAFETY INSPECTION PERF	3/10/2008	3/10/2008		0	\$5.84
	Comments: DOWN FOR MAINTENANCE					
101595	REPAIR OF EQUIPMENT		3/7/2008 9:44:02 AM		39514	\$266.98
	Comments: BELT RAN OFF OF FLYWHEEL. AMPS TOO HIGH, MAKING NOISE FROM FLYWHEEL, REMOVED CLUTCH, CANNOT GET HUB OFF, NEED TO CUT IT. BEARINGS SOUND ROUGH.					
101621	REPAIR OF EQUIPMENT		3/6/2008		39513	\$0.00
	Comments: FLYWHEEL NOT TURNING.					
101647	REPAIR OF EQUIPMENT		3/8/2008		39515	\$613.78
	Comments: PULL GEAR'S OFF. PULLED SPLINE GEAR OFF.					
101648	REPAIR OF EQUIPMENT		3/7/2008		39514	\$546.37
	Comments: PRESS NEEDS REPAIR. WORKED ON PRESS. GOT KEY WAY CLEAN AND MOVED GEAR.					
101672	INSTALL EQUIPMENT OR OTHER ITE		3/11/2008 7:21:34 AM		39518	\$343.26
	Comments: INSTALL FLYWHEEL. HUNG FLYWHEEL ON QUILL, INSTALLED SPLINE GEAR, POLISHED KEY, NEED TO BUMP KEY IN. NEED NEW SNAP RING INSTALLED, OLD ONE IS BROKEN.					

## Asset/Equipment Work Order History Brief

101681	REPAIR OF EQUIPMENT		3/10/2008	39517	\$182.35
	Comments: PULL FLYWHEEL AND REPLACE BEARING. HELP PULL FLYWHEEL AND REPLACE BEARING.				
101683	REPAIR OF EQUIPMENT		3/10/2008	39517	\$467.25
	Comments: RE-ASSEMBLE 38 FLYWHEEL.				
101688	REPAIR OF EQUIPMENT		3/11/2008	39518	\$348.19
	Comments: FINISH UP # 38 PRESS. AND TURNED LOOSE FOR PRODUCTION.				
101700	REPAIR OF EQUIPMENT		3/11/2008	39518	\$91.18
	Comments: HELP GET PRESS RUNNING. HELP CHARLIE WALLS, JAMES WRIGHT, AND KENNETH BROWN GET PRESS RUNNING. CHECK ALL VOLTAGE COMING TO PRESS AND GOT MAIN MOTOR RUNNING.				
101708	REPAIR OF EQUIPMENT		3/11/2008	39518	\$0.00
	Comments: PRESS KEEPS SHUTTING OFF. DYE THROWING METAL OUT MAKING SAFETY LIGHT.				
101756	WEEKLY SAFETY INSPECTION PERF	3/17/2008	3/17/2008	0	\$5.84
101944	WEEKLY SAFETY INSPECTION PERF	3/24/2008	3/26/2008	2	\$5.84
102469	ANNUAL PM FOR PRESS	3/31/2008	4/25/2008 8:00:49 AM	25	\$53.60
102470	MONTHLY PM FOR AUTOMATIC PRE	4/14/2008	4/18/2008 9:39:54 AM	4	\$40.20
102471	WEEKLY SAFETY INSPECTION PERF	4/2/2008	4/4/2008 8:18:12 AM	2	\$5.84
102797	REPAIR OF EQUIPMENT		4/1/2008 7:19:14 AM	39539	\$53.60
	Comments: MAKING FUNNY NOISE. REMOVED EXPANDING METAL FROM CLUTCH.				
102905	WEEKLY SAFETY INSPECTION PERF	4/11/2008	4/7/2008	0	\$5.84
103086	WEEKLY SAFETY INSPECTION PERF	4/14/2008	4/14/2008	0	\$5.84
103420	WEEKLY SAFETY INSPECTION PERF	4/21/2008	4/23/2008 10:05:35 AM	2	\$2.92
103630	WEEKLY SAFETY INSPECTION PERF	4/30/2008	5/1/2008	1	\$2.92
103792	REPAIR OF EQUIPMENT		4/30/2008	39568	\$36.47
	Comments: FAN UP BY THE GRINDERS HAS A BAD SWITCH ON IT. NEEDS A NEW ONE. PUT A NEW CORD ON AND ADJUSTED THE FAN.				
104133	MONTHLY PM FOR AUTOMATIC PRE	5/19/2008	5/27/2008 7:40:31 AM	8	\$34.07
104134	WEEKLY SAFETY INSPECTION PERF	5/8/2008	5/9/2008 8:48:45 AM	1	\$5.84
104546	WEEKLY SAFETY INSPECTION PERF	5/16/2008	5/12/2008	0	\$5.84
104713	WEEKLY SAFETY INSPECTION PERF	5/19/2008	5/19/2008	0	\$5.84
104994	WEEKLY SAFETY INSPECTION PERF	5/26/2008	5/29/2008 3:23:44 PM	3	\$5.84

## Asset/Equipment Work Order History Brief

105450	MONTHLY PM FOR AUTOMATIC PRE	6/26/2008	7/1/2008 6:43:33 AM	5	\$40.20
105451	WEEKLY SAFETY INSPECTION PERF	6/5/2008	6/4/2008	0	\$5.84
105670	REPAIR OF EQUIPMENT		5/30/2008	39598	\$0.00
	Comments:	PROBLEM WITH LUBE SPRAYERS. CAM WAS SET TO COME ON AT 68 DEGREES AND OFF AT 70 DEGREES. OPENED WINDOW TO 78 DEGREES. ALL IS OK.			
		WORK DONE ON 5/29/08			
105836	WEEKLY SAFETY INSPECTION PERF	6/11/2008	6/13/2008 8:09:00 AM	2	\$5.84
106103	WEEKLY SAFETY INSPECTION PERF	6/20/2008	6/16/2008	0	\$5.84
106369	REPAIR OF EQUIPMENT		6/18/2008	39617	\$0.00
	Comments:	RESET TON ON TONAGE MONITOR. HAD HELP FROM JOHNNY IVY.			
106400	WEEKLY SAFETY INSPECTION PERF	6/23/2008	6/25/2008 11:34:48 AM	2	\$5.84
106857	WEEKLY SAFETY INSPECTION PERF	7/2/2008	7/2/2008 6:32:01 AM	0	\$5.59
107130	WEEKLY SAFETY INSPECTION PERF	7/9/2008	7/7/2008	0	\$5.59
107404	WEEKLY SAFETY INSPECTION PERF	7/14/2008	7/14/2008	0	\$5.59
107508	REPAIR OF EQUIPMENT		7/14/2008	39643	\$111.50
	Comments:	LIGHT BULBS OUT OVER FEED EQUIPMENT. CHANGED OUT LIGHT BULBS.			
107589	WEEKLY SAFETY INSPECTION PERF	7/21/2008	7/22/2008	1	\$5.59
108054	MONTHLY PM FOR AUTOMATIC PRE	7/31/2008	8/19/2008 7:38:17 AM	19	\$44.40
108055	WEEKLY SAFETY INSPECTION PERF	7/29/2008	7/28/2008	0	\$5.59
108529	WEEKLY SAFETY INSPECTION PERF	8/4/2008	8/6/2008	2	\$5.59
108753	WEEKLY SAFETY INSPECTION PERF	8/13/2008	8/15/2008 9:56:34 AM	2	\$4.68
109024	WEEKLY SAFETY INSPECTION PERF	8/22/2008	8/19/2008 11:14:07 AM	0	\$5.14
109226	WEEKLY SAFETY INSPECTION PERF	8/26/2008	8/27/2008	1	\$5.59
109321	REPAIR OF EQUIPMENT		8/23/2008	39683	\$68.88
	Comments:	FEEDER WILL NOT START. WIRE WAS BROKE.			
109329	REPAIR OF EQUIPMENT		8/23/2008	39683	\$345.24
	Comments:	REPLACE TWO CONTROL CABLES.			
109736	MONTHLY PM FOR AUTOMATIC PRE	9/18/2008	9/19/2008 8:05:51 AM	1	\$44.40
109737	WEEKLY SAFETY INSPECTION PERF	9/3/2008	9/9/2008	6	\$5.59

## Asset/Equipment Work Order History Brief

110205	WEEKLY SAFETY INSPECTION PERF	9/16/2008	9/15/2008	0	\$4.12
110414	WEEKLY SAFETY INSPECTION PERF	9/22/2008	9/26/2008 9:47:35 AM	4	\$4.12
110932	MONTHLY PM FOR AUTOMATIC PRE	10/20/2008	10/15/2008 7:43:40 AM	0	\$44.40
110933	WEEKLY SAFETY INSPECTION PERF	10/3/2008	10/10/2008 10:27:11 AM	7	\$5.59
111473	WEEKLY SAFETY INSPECTION PERF	10/17/2008	10/15/2008 11:35:09 AM	0	\$5.21
111707	WEEKLY SAFETY INSPECTION PERF	10/22/2008	10/24/2008 12:52:52 PM	2	\$5.59
111992	WEEKLY SAFETY INSPECTION PERF	10/31/2008	10/31/2008 8:00:55 AM	0	\$0.00
112450	MONTHLY PM FOR AUTOMATIC PRE	11/14/2008	11/26/2008 6:43:24 AM	12	\$44.40
112451	WEEKLY SAFETY INSPECTION PERF	11/7/2008	11/7/2008	0	\$5.14
112870	WEEKLY SAFETY INSPECTION PERF	11/14/2008	11/21/2008 7:37:49 AM	7	\$5.05
113063	WEEKLY SAFETY INSPECTION PERF	11/28/2008	11/26/2008 8:13:38 AM	0	\$5.59
113310	WEEKLY SAFETY INSPECTION PERF	12/3/2008	12/10/2008	7	\$5.59
113585	MONTHLY PM FOR AUTOMATIC PRE	12/26/2008	1/9/2009 7:15:25 AM	14	\$44.40
114019	WEEKLY SAFETY INSPECTION PERF	12/17/2008	12/17/2008 11:47:53 AM	0	\$5.59
114218	WEEKLY SAFETY INSPECTION PERF	12/24/2008	12/20/2008 10:39:36 AM	0	\$5.59
114500	WEEKLY SAFETY INSPECTION PERF	12/29/2008	1/5/2009	7	\$5.59
114825	WEEKLY SAFETY INSPECTION PERF	1/12/2009	1/13/2009	1	\$5.59
115100	WEEKLY SAFETY INSPECTION PERF	1/20/2009	1/20/2009	0	\$5.59
115256	WEEKLY SAFETY INSPECTION PERF	1/27/2009	1/27/2009	0	\$5.59
115462	REPAIR OF EQUIPMENT		1/26/2009	39839	\$75.22
	Comments: NUTS CAME OFF SAFETY LLIGHT. REPLACED NUTS ON SAFETY LIGHT.				
115765	MONTHLY PM FOR AUTOMATIC PRE	2/9/2009	2/3/2009 9:45:25 AM	0	\$44.40
115766	WEEKLY SAFETY INSPECTION PERF	2/3/2009	2/2/2009 8:27:52 AM	0	\$5.59
116045	REPAIR OF EQUIPMENT		1/31/2009	39844	\$91.84
	Comments: SPRAYER TIP STOPPED UP. CLEANED OUT AND FLUSHED LINE.				

## Asset/Equipment Work Order History Brief

116109	REPAIR OF EQUIPMENT		2/5/2009 8:10:07 AM	39849	\$509.40
	Comments:	WON'T STROKE. FOUND BROKEN SHAFT, REMOVED CLUTCH, HUB, BROKEN SHAFT, TOP OF BRAKE, LIGHTS, RAM IS ON TOP OF STROKE AND WILL NOT COME DOWN FOR SOME REASON. ALSO ASSISTED WITH DIE REMOVAL, ELECT. POWER LOCKED OUT. AIR IS TURNED OFF.			
116116	REPAIR OF EQUIPMENT		2/4/2009	39848	\$112.83
	Comments:	CLUTCH NOT WORKING. LOOK AT PARTS. NO REAL HELP THOUGH. CHECK VALVE. VALVE IS WORKING. I THINK SHAFT MAY BE BROKE. PASS ON TO 3RD SHIFT.			
116131	REPAIR OF EQUIPMENT		2/5/2009	39849	\$762.82
	Comments:	# 38 BROKE SHAFT. PULLED BROKEN SHAFT AND INSTALLED A REBUILT ONE. PUT CLUTCH RING AND HOUSING ON. NOT COMPLETE.			
116148	REPAIR OF EQUIPMENT		2/5/2009	39849	\$526.54
	Comments:	FINISH PUTTING BACK TOGETHER. RE-ASSEMBLED CLUTCH. HAD TO CUT OFF BO'S LOCK WITH MIKE SEAY'S PERMISSION. MASTER KEY DIDN'T FIT LOCK. RESET TOP STOP POSITION AND SET ENCODER POSITION.			
116151	CLEAN EQUIPMENT		2/6/2009 7:52:01 AM	39850	\$121.50
	Comments:	CLEAN UP MESS. CLEANED UP AROUND PRESS, REPAIRED LEAK ON OILER, PUT AWAY TOOLS, PICKED UP IN WORK SKIDS.			
116173	WEEKLY SAFETY INSPECTION PERF	2/9/2009	2/10/2009	1	\$5.59
116234	REPAIR OF EQUIPMENT		2/6/2009	39850	\$67.58
	Comments:	CHECKED PRESS # 38 FOR UNUSUAL SOUNDS, LEAKS, VIBRATION, OR ANY THING THAT MIGHT BE LOOSE. DID CHECK PRESS. TOOK ELECTRIC LIFT, WENT TO TOP. EVERYTHING LOOKED TIGHT AND RUNABLE. DID NOT SEE ANY OIL LEAKS, OR MIS-ALIGNMENT. VERY LITTLE VIBERATION. DID HAVE SOME RACKET IN CLUTCHES. I DON'T THINK THIS WILL BE ANY THING OUT OF NORMAL. TOLD OPERATOR ADOLPH PEGEES THAT IF HE SEES OR HEARS ANY THING OUT OF THE NORM. COME AND GET ME.			
116269	REPAIR OF EQUIPMENT		2/9/2009	39853	\$112.83
	Comments:	NEED LIGHT REPAIRED THAT IS BEHIND THE PRESS AND SHINES ON THE METAL SO THE OPERATOR CAN TELL IF THERE ARE BLEMISHES ON THE METAL. NEED ASAP. REPALCED LIGHT FIXTURE.			
116332	WEEKLY SAFETY INSPECTION PERF	2/17/2009	2/21/2009	4	\$5.59
117029	MONTHLY PM FOR AUTOMATIC PRE	3/5/2009	3/23/2009 7:48:01 AM	18	\$44.40
117030	WEEKLY SAFETY INSPECTION PERF	3/2/2009	3/9/2009	7	\$5.59
117635	WEEKLY SAFETY INSPECTION PERF	3/16/2009	3/16/2009	0	\$5.59
117821	WEEKLY SAFETY INSPECTION PERF	3/23/2009	3/23/2009	0	\$5.59
118215	MONTHLY PM FOR AUTOMATIC PRE	4/22/2009	4/16/2009 6:18:13 AM	0	\$44.40
118216	WEEKLY SAFETY INSPECTION PERF	3/30/2009	3/31/2009 3:36:11 PM	1	\$5.59
118492	WEEKLY SAFETY INSPECTION PERF	4/7/2009	4/7/2009 3:27:20 PM	0	\$5.59

## Asset/Equipment Work Order History Brief

118664	WEEKLY SAFETY INSPECTION PERF	4/14/2009	4/14/2009 3:25:59 PM	0	\$5.59
118891	ANNUAL PM FOR PRESS	4/27/2009	5/21/2009 6:17:05 AM	24	\$81.00
118892	WEEKLY SAFETY INSPECTION PERF	4/21/2009	4/20/2009 3:00:21 PM	0	\$5.59
119149	WEEKLY SAFETY INSPECTION PERF	4/27/2009	4/30/2009	3	\$6.48
119432	MONTHLY PM FOR AUTOMATIC PRE	5/18/2009	5/21/2009 6:17:55 AM	3	\$44.40
119915	WEEKLY SAFETY INSPECTION PERF	5/7/2009	5/13/2009 3:38:15 PM	6	\$5.59
120049	REPAIR OF EQUIPMENT		5/13/2009 8:05:18 AM	39946	\$150.85
	Comments: RUN CONDUIT FOR THE FAN, REMOVED CORD, AND REPAIRED FAN.				
120140	WEEKLY SAFETY INSPECTION PERF	5/20/2009	5/21/2009 2:55:53 PM	1	\$5.59
120365	WEEKLY SAFETY INSPECTION PERF	5/28/2009	5/28/2009 3:32:12 PM	0	\$5.59
120823	MONTHLY PM FOR AUTOMATIC PRE	6/22/2009	6/30/2009 6:10:53 AM	8	\$43.95
120824	WEEKLY SAFETY INSPECTION PERF	6/4/2009	6/2/2009 3:28:17 PM	0	\$5.59
121165	REPAIR OF EQUIPMENT		6/3/2009 10:35:18 AM	39967	\$118.27
	Comments: LEVELED RAM, ADJUSTED C'BALANCE. FROM BOTTOM OF BED TO TOP OF RAM ALL THE WAY UP 32-1/2". THE RAM ALL THE WAY DOWN 17-1/16".				
121200	WEEKLY SAFETY INSPECTION PERF	6/9/2009	6/9/2009	0	\$5.47
121223	REPAIR OF EQUIPMENT		6/5/2009	39969	\$140.20
	Comments: CHECK RAM LEVEL AND NUT ON EAST END ROD. 1/8" GAP BETWEEN NUT AND ROD WITH COUNTERBALANCE TURNED UP, TIGHTENED NUT AS MUCH AS POSSIBLE, RAM IS FAIRLY CONSISTANT AT FOUR POSITIONS AS LONG AS C/B PRESSURE IS UP, MAY NEED TO RE-DRILL HOLE FOR ROD BOLT PIN.				
121228	REPAIR OF EQUIPMENT		6/4/2009	39968	\$69.54
	Comments: LEVEL RAM				
121271	REPAIR OF EQUIPMENT		6/5/2009	39969	\$67.58
	Comments: CHECK RAM LEVEL. OK.				
121551	WEEKLY SAFETY INSPECTION PERF	6/16/2009	6/15/2009	0	\$5.47
121743	WEEKLY SAFETY INSPECTION PERF	6/22/2009	6/23/2009	1	\$5.47
121981	WEEKLY SAFETY INSPECTION PERF	6/30/2009	6/29/2009 6:22:50 AM	0	\$5.47
122318	WEEKLY SAFETY INSPECTION PERF	7/6/2009	7/7/2009	1	\$5.47
122623	REPAIR OF EQUIPMENT		7/1/2009	39995	\$142.12
	Comments: RAM OUT OF ADJUSTEMENT. TIGHTENED RIGHT NUT				
122701	REPAIR OF EQUIPMENT		7/8/2009	40002	\$67.58
	Comments: LEVELED RAM TO WITHIN 1/16"				

## Asset/Equipment Work Order History Brief

122707	REPAIR OF EQUIPMENT		7/8/2009	40002	\$36.86
	Comments: UNLEVEL RAM. CHAIN BROKE RAM OVER 1/2" OUT, SET RAM.				
122727	REPAIR OF EQUIPMENT		7/9/2009	40003	\$110.58
	Comments: LEVELED RAM				
122756	WEEKLY SAFETY INSPECTION PERF	7/14/2009	7/14/2009	0	\$5.47
122931	REPAIR OF EQUIPMENT		7/16/2009	40010	\$29.30
	Comments: PUT LUBE SEAL IN #38 LUBE SYSTEM. INTALLED SEAL.				
122993	WEEKLY SAFETY INSPECTION PERF	7/21/2009	7/20/2009 5:14:42 PM	0	\$5.47
123093	REPAIR OF EQUIPMENT		7/17/2009	40011	\$96.28
	Comments: SLIDE ADJUST NOT WORKING. REPAIRED BROKEN/CUT CABLES				
123094	REPAIR OF EQUIPMENT		7/17/2009	40011	\$110.58
	Comments: READJUST RAM LEVEL - BROKE CHAIN AGAIN AND SHORTED WIRES ON RAM MOTOR. CALLED JO HE FIXED WIRIES AND I PUT NEW CHAIN ON RAM ADJUSTMENT. OLD CAHIN HAD BEEN BROKEN TOO MANY TIMES. TRIED RAM ADJUSTED AND MOTOR WOULD NOT RUN. I CAME BACK TO SHOP AND TOLD JO. I SUPPOSE HE WILL GO AND REPAIR MOTOR, FUSES, OR WHATEVER.				
123095	REPAIR OF EQUIPMENT		7/17/2009	40011	\$59.24
	Comments: ASSIST ON 38 RAM ADJUST HEIGHT. RAM NOT LEVEL.				
123211	MONTHLY PM FOR AUTOMATIC PRE	7/30/2009	8/4/2009 6:19:34 AM	5	\$58.10
123212	WEEKLY SAFETY INSPECTION PERF	7/27/2009	7/25/2009	0	\$5.47
123654	WEEKLY SAFETY INSPECTION PERF	8/3/2009	8/3/2009	0	\$5.47
124026	WEEKLY SAFETY INSPECTION PERF	8/10/2009	8/10/2009	0	\$5.47
124207	WEEKLY SAFETY INSPECTION PERF	8/17/2009	8/17/2009 3:26:32 PM	0	\$5.47
124279	REPAIR OF EQUIPMENT		8/12/2009	40037	\$36.86
	Comments: GO W/TECH FROM PRESS DR'S AND EXAMINE PRESS 38. TECH TOOK MEASUREMENT AT PRESS AND WILL MAKE A PROPOSAL TO REPAIR.				
124441	WEEKLY SAFETY INSPECTION PERF	8/24/2009	8/24/2009	0	\$5.47
124960	MONTHLY PM FOR AUTOMATIC PRE	9/3/2009	9/10/2009 6:26:18 AM	7	\$43.78
124961	WEEKLY SAFETY INSPECTION PERF	8/31/2009	9/1/2009	1	\$10.30
125435	WEEKLY SAFETY INSPECTION PERF	9/8/2009	9/9/2009	1	\$5.47
125537	WEEKLY SAFETY INSPECTION PERF	9/16/2009	9/15/2009	0	\$4.83
125731	WEEKLY SAFETY INSPECTION PERF	9/22/2009	9/28/2009	6	\$5.47
125819	REPAIR OF EQUIPMENT		9/18/2009	40074	\$55.29
	Comments: LEVLED RAM.				

## Asset/Equipment Work Order History Brief

125967	REPAIR OF EQUIPMENT		9/24/2009		40080	\$18.43
	Comments:	NEED METAL LUBE SPRAYER REPAIRED. BUSTED HOSE - SPRAYER REPAIRED. OPS CHECK OK ACCORDING TO OPERATOR.				
126351	MONTHLY PM FOR AUTOMATIC PRE	10/12/2009	10/13/2009 6:56:38 AM		1	\$51.02
126352	WEEKLY SAFETY INSPECTION PERF	10/5/2009	10/5/2009		0	\$5.47
126736	WEEKLY SAFETY INSPECTION PERF	10/12/2009	10/12/2009 2:58:33 PM		0	\$5.47
126892	REPAIR OF EQUIPMENT		10/14/2009		40100	\$109.07
	Comments:	SLIDE ADJUST NOT WORKING. FOUND PROCESSOR FAULTED, RESET IT AND FAULTED AGAIN. FOUND SIGNAL WIRES TO SLIDE ADJUST LIMIT SWITCH WERE SKINNED. REPAIRED WIRING.				
126895	REPAIR OF EQUIPMENT		10/14/2009		40100	\$59.24
	Comments:	TIGHTENED RUBBER MOUNTS ON LIGHT CURTAIN				
126911	REPAIR OF EQUIPMENT		10/13/2009		40099	\$72.71
	Comments:	ADJUSTED BLANKING ON LIGHT CURTAIN				
126995	WEEKLY SAFETY INSPECTION PERF	10/19/2009	10/20/2009 7:36:57 AM		1	\$5.47
127047	REPAIR OF EQUIPMENT		10/17/2009		40103	\$51.41
	Comments:	NEW DIE IN PRESS, SHUT HEIGHT NOT SET PROPERLY, SET SHUT HEIGHT AND TONNAGE LIMIT				
127185	WEEKLY SAFETY INSPECTION PERF	10/27/2009	11/7/2009 8:31:10 AM		11	\$5.47
127285	REPAIR OF EQUIPMENT		10/26/2009		40112	\$72.71
	Comments:	REPAIRED AIR LINE				
127674	MONTHLY PM FOR AUTOMATIC PRE	11/12/2009	11/17/2009 10:26:17 AM		5	\$38.69
128144	WEEKLY SAFETY INSPECTION PERF	11/16/2009	11/16/2009		0	\$5.47
128383	WEEKLY SAFETY INSPECTION PERF	11/23/2009	11/23/2009		0	\$5.47
128425	REPAIR OF EQUIPMENT		11/20/2009		40137	\$126.50
	Comments:	REMOVED THE FEEDER AND THE RAM ELECTRICAL CONNECTIONS FOR THE PRESS DOCTORS SO THEY CAN REMOVE THE RAM FOR REPAIR				
128477	REPAIR OF EQUIPMENT		11/23/2009		40140	\$196.08
	Comments:	ASISTED PRESS DOCTORS WITH RAM REMOVAL				
128828	MONTHLY PM FOR AUTOMATIC PRE	12/17/2009	2/6/2010		51	\$51.02
128829	WEEKLY SAFETY INSPECTION PERF	11/30/2009	11/30/2009 1:28:58 PM		0	\$5.47
129150	WEEKLY SAFETY INSPECTION PERF	12/7/2009	12/7/2009 3:40:46 PM		0	\$5.47
129338	WEEKLY SAFETY INSPECTION PERF	12/14/2009	12/15/2009 6:27:29 AM		1	\$5.47
	Comments:	down for repair				
129589	WEEKLY SAFETY INSPECTION PERF	12/22/2009	12/21/2009 3:26:34 PM		0	\$5.47
130172	WEEKLY SAFETY INSPECTION PERF	12/28/2009	1/5/2010 3:23:11 PM		8	\$0.00

## Asset/Equipment Work Order History Brief

130450	WEEKLY SAFETY INSPECTION PERF	1/12/2010	1/12/2010 2:57:41 PM	0	\$5.47
130664	REPAIR OF EQUIPMENT		1/13/2010	40191	\$109.07
	Comments: WIRE RAM ELECTICALS				
	WIRED IN RAM ADJUST MOTOR AND LIMIT SWITCH.				
130721	WEEKLY SAFETY INSPECTION PERF	1/19/2010	1/19/2010 12:52:00 PM	0	\$5.47
130763	REPAIR OF EQUIPMENT		1/14/2010	40192	\$105.26
	Comments: CHECK OIL LEVEL PAN CHECK NOISE				
	CHECKED OIL LEVEL GOOD				
	LISTENED TO BUMPING SOUND& MAYBE COUNTER BALANCE CAUSING				
	COUNTER BALANCE SEAL LEAKING BAD				
130776	REPAIR OF EQUIPMENT		1/15/2010	40193	\$316.09
	Comments: FINISH UP FEED LINE INSTALLATION				
	ADJUSTED& INSTALLED STRAIGHTENER, INSTALLED CODNIT GUARDS FROM				
	MANDREL TO STRAIGHTER TO FEEDER, INSTALLED CABLES TO FEEDER				
	CONTROL, INSTALLED GUARD FOR FEEDER CABLES, INSTALLED,				
	(REFFINCING) POSTS FOR PLASTIC SAFETY CHAIN, CLEANED UP MESS,				
	BROUGHT EQUIPMENT BACK TO SHOP.				
130783	REPAIR OF EQUIPMENT		1/14/2010	40192	\$399.91
	Comments: PUT FEEDER, THREADING TABLE, AND STRAIGHTENER BACK IN LINE WITH				
	REPAIRED RAM.				
130786	REPAIR OF EQUIPMENT		1/15/2010	40193	\$73.72
	Comments: COUNTER BALANCE LEAKING. CHECKED ON GETTING A QUOTE FROM				
	NIAGARA FOR SEALS AND PACKING				
130794	REPAIR OF EQUIPMENT		1/14/2010	40192	\$177.72
	Comments: ASSIST PRESS DOCTORS WITH ASSEMBLY OF RAM TO PRESS.				
130907	WEEKLY SAFETY INSPECTION PERF	1/26/2010	1/25/2010 1:14:41 PM	0	\$5.47
131390	WEEKLY SAFETY INSPECTION PERF	2/1/2010	2/1/2010 12:40:16 PM	0	\$5.47
131609	REPAIR OF EQUIPMENT		2/1/2010	40210	\$55.29
	Comments: SOMETHING IN THE FEED LINE IS NOT IN ALIGNMENT WITH THE PRESS. THE				
	DIE THAT IS RUNNING NOW HAD TO BE SET AT AN ANGLE BEFORE IT WOULD				
	RUN A GOOD PART. NEED REPAIRED. (NEED ASAP)				
	WENT OUT TO 38 PRS YES THE FEEDER IS NOT PERFECT WITH SLOT IN				
	BOLSTER PLATE OFF BY ALMOST 1/8" FROM BACT TO FRONT				
	OPERATOR HAS COMENSATED FOR MIS ALIGNMENT AND SHEFFIELD AND				
	OTHERS OF AUTHORITY WANT TO WAIT TILL NEXT DIE CHANGE TO SHIM				
	FEEDER SO THAT IT WILL ALIGN WITH SLOT IN BOLSTER PLATE.				
	THEY ARE SUPPOSE TO NOTIFY US AT NEXT DIE CHANGE.				
131690	WEEKLY SAFETY INSPECTION PERF	2/8/2010	2/8/2010 12:36:45 PM	0	\$5.47
131867	WEEKLY SAFETY INSPECTION PERF	2/15/2010	2/15/2010	0	\$5.47
132090	WEEKLY SAFETY INSPECTION PERF	2/22/2010	2/23/2010 2:39:27 PM	1	\$5.47

## Asset/Equipment Work Order History Brief

132225	REPAIR OF EQUIPMENT		2/23/2010 3:10:03 PM	40232	\$106.59
	Comments:	COUNTER BALANCER HAS A BAD AIR LEAK. NEED REPAIRED. (NEED ASAP) LOCKED OUT PRS PUT SAFETY BLOCKS IN PLACE			
		TOOK PRESSURE OFF COUNTER BALANCE AND DRAINED. REMOVED PACKING AND REPLACED WITH NEW PRE LUBBED ROPE SEAL 3 PACKINGS THIS DID NOT TOTALLY STOP AIR LEAK SO WE TOOK SEAL RETAINER BACK OFF AND PUT IN 3 MORE PACKING OF ROPE SEAL. THIS ALL BUT STOPPED AIR LEAK. LET PRSS RUN FOR ABOUT 1 HOUR WENT BACK AND LUBBED SHAFT AGIN AND RETIGHTENED SEALS LEAK STOPPED AS OF NOW I DON'T THINK THIS IS A PERMANENT FIX BUT WILL GET BY FOR BETTER DAYS. ALSO CHANGED OUT 2 DEFECTIVE AIR GAUGES ON PRESSURE ADJUSTMENTS (UNLOCKED PRSS REMOVED ALL SAFETY ITEMS) TURNED BACK TO FAB.			
132655	MONTHLY PM FOR AUTOMATIC PRE	3/8/2010	3/11/2010 2:45:51 PM	3	\$43.95
132656	WEEKLY SAFETY INSPECTION PERF	3/2/2010	3/2/2010 2:57:50 PM	0	\$5.47
133039	WEEKLY SAFETY INSPECTION PERF	3/9/2010	3/8/2010	0	\$5.47
133218	WEEKLY SAFETY INSPECTION PERF	3/15/2010	3/16/2010 3:05:19 PM	1	\$5.47
133387	WEEKLY SAFETY INSPECTION PERF	3/23/2010	3/21/2010 2:16:55 PM	0	\$5.47
133637	WEEKLY SAFETY INSPECTION PERF	3/29/2010	3/31/2010 2:58:19 PM	2	\$5.47
134089	MONTHLY PM FOR AUTOMATIC PRE	4/12/2010	4/14/2010 7:40:28 AM	2	\$50.86
134090	WEEKLY SAFETY INSPECTION PERF	4/7/2010	4/6/2010 12:16:12 PM	0	\$5.47
134418	WEEKLY SAFETY INSPECTION PERF	4/13/2010	4/12/2010 3:54:38 PM	0	\$5.47
134589	WEEKLY SAFETY INSPECTION PERF	4/19/2010	4/19/2010 1:10:19 PM	0	\$5.47
134680	REPAIR OF EQUIPMENT		4/21/2010	40289	\$19.37
	Comments:	SLIDE COASTING OVER ON STOP. REPALCED REGULATOR ON COUNTERBALANCE TANK, ADJUSTED THE BRAKE TENSION.			
134710	REPAIR OF EQUIPMENT		4/22/2010	40290	\$34.20
	Comments:	REVERSED THE MOTOR TO GET OFF BOTTOM			
134751	WEEKLY SAFETY INSPECTION PERF	4/26/2010	4/28/2010 3:03:02 PM	2	\$5.47
135167	ANNUAL PM FOR PRESS	5/21/2010	5/19/2010 6:38:52 AM	0	\$58.60
135168	MONTHLY PM FOR AUTOMATIC PRE	5/14/2010	5/13/2010	0	\$58.10
135169	WEEKLY SAFETY INSPECTION PERF	5/5/2010	5/4/2010 2:54:02 PM	0	\$5.47
135564	WEEKLY SAFETY INSPECTION PERF	5/11/2010	5/10/2010 2:10:32 PM	0	\$5.47
135660	WEEKLY SAFETY INSPECTION PERF	5/17/2010	5/17/2010 1:38:50 PM	0	\$5.47

## Asset/Equipment Work Order History Brief

135844	WEEKLY SAFETY INSPECTION PERF	5/24/2010	5/24/2010 3:23:04 PM	0	\$5.47
136329	MONTHLY PM FOR AUTOMATIC PRE	6/14/2010	6/13/2010	0	\$45.15
136330	WEEKLY SAFETY INSPECTION PERF	5/31/2010	6/2/2010 3:00:17 PM	2	\$5.60
136702	WEEKLY SAFETY INSPECTION PERF	6/9/2010	6/9/2010 2:25:21 PM	0	\$5.60
136834	WEEKLY SAFETY INSPECTION PERF	6/16/2010	6/16/2010 2:56:47 PM	0	\$5.60
136986	WEEKLY SAFETY INSPECTION PERF	6/23/2010	6/23/2010 2:50:44 PM	0	\$5.60
137036	REPAIR OF EQUIPMENT		6/18/2010	40347	\$193.68
	Comments: BRAKE PAD FELL OFF. REMOVED AND REPLACED BRAKE SHOE AND ADJSUTED.				
137138	REPAIR OF EQUIPMENT		6/24/2010	40353	\$35.00
	Comments: REPLACED COUNTER				
137139	REPAIR OF EQUIPMENT		6/24/2010	40353	\$35.00
	Comments: WILL NOT STROKE. RESET ROSS VALVE AND AIR SETTINGS. OK				
137161	WEEKLY SAFETY INSPECTION PERF	6/30/2010	6/29/2010 1:04:11 PM	0	\$5.60
137600	MONTHLY PM FOR AUTOMATIC PRE	7/13/2010	8/3/2010 8:03:27 AM	21	\$45.15
137601	WEEKLY SAFETY INSPECTION PERF	7/6/2010	7/6/2010 3:13:27 PM	0	\$5.60
137929	WEEKLY SAFETY INSPECTION PERF	7/13/2010	7/15/2010 3:47:47 PM	2	\$5.60
138119	WEEKLY SAFETY INSPECTION PERF	7/22/2010	7/19/2010 3:29:27 PM	0	\$5.60
138255	WEEKLY SAFETY INSPECTION PERF	7/26/2010	7/27/2010 3:33:26 PM	1	\$5.60
138670	WEEKLY SAFETY INSPECTION PERF	8/3/2010	8/5/2010 3:44:48 PM	2	\$5.60
138939	WEEKLY SAFETY INSPECTION PERF	8/12/2010	8/18/2010 2:10:25 PM	6	\$5.60
139283	WEEKLY SAFETY INSPECTION PERF	8/25/2010	8/24/2010 4:33:42 PM	0	\$5.60
139463	MONTHLY PM FOR AUTOMATIC PRE	9/2/2010	9/8/2010 6:28:09 AM	6	\$52.95
139464	WEEKLY SAFETY INSPECTION PERF	8/31/2010	9/1/2010	1	\$5.60
139866	WEEKLY SAFETY INSPECTION PERF	9/8/2010	9/7/2010 6:18:22 AM	0	\$5.60
140112	WEEKLY SAFETY INSPECTION PERF	9/14/2010	9/11/2010	0	\$5.60
140268	WEEKLY SAFETY INSPECTION PERF	9/20/2010	9/21/2010 12:54:20 PM	1	\$5.60

## Asset/Equipment Work Order History Brief

140387	WEEKLY SAFETY INSPECTION PERF	9/28/2010	9/28/2010 3:23:08 PM	0	\$5.60
140835	MONTHLY PM FOR AUTOMATIC PRE	10/8/2010	10/7/2010 9:25:29 AM	0	\$52.95
140836	WEEKLY SAFETY INSPECTION PERF	10/5/2010	10/7/2010	2	\$5.60
141003	REPAIR OF EQUIPMENT		10/1/2010	40452	\$87.50
	Comments: SIMTEX PLC FAULT - PRSS 038				
	FOUND ALL INPUTS IN ON CONDITION REPLACED INPUT CARD RIBBEN CABLE AND MAIN PLUG UNIT. NO FIX DISCONNECTED INPUT #1 AND CYCLE PENER FAULT DISAPPEARED RESTARTED MACHINE AND OPERATION RESUMED.				
141113	WEEKLY SAFETY INSPECTION PERF	10/14/2010	10/14/2010 6:40:00 AM	0	\$5.60
141251	WEEKLY SAFETY INSPECTION PERF	10/21/2010	10/19/2010 1:10:05 PM	0	\$5.60
141393	WEEKLY SAFETY INSPECTION PERF	10/26/2010	10/27/2010	1	\$5.60
141827	MONTHLY PM FOR AUTOMATIC PRE	11/8/2010	11/20/2010	12	\$60.75
141828	WEEKLY SAFETY INSPECTION PERF	11/3/2010	11/2/2010 9:31:27 AM	0	\$5.60
142060	REPAIR OF EQUIPMENT		11/3/2010	40485	\$52.50
	Comments: SMOKING AROUND THE DRIVE MOTOR. CHECKED EVERYTHING OUT, FLYWHEEL FREE, ALL THE DRIVE BELTS ON, BRAKE NOT DRAGGING, MOTOR NOT HOT. STROKED PRESS AND OK. WATCHED IT RUN FOR A WHILE AND OKAY. THINK SOME GREASE GOT ON FLYWHEEL.				
142082	REPAIR OF EQUIPMENT		11/4/2010	40486	\$105.00
	Comments: MOTOR SMOKING & FUSE BLOWED - PRSS 038				
	CHECK ALL COULD NOT FIND REPLACED 3 FUSES				
142111	WEEKLY SAFETY INSPECTION PERF	11/9/2010	11/12/2010 9:41:24 AM	3	\$5.60
142147	REPAIR OF EQUIPMENT		11/9/2010 12:46:21 PM	40491	\$247.10
	Comments: NRA - LUBE LINE LEAKING IN CEILING - PRSS 038				
	FOUND BAD PLACE IN LINE, CUT OUT BAD SECTION, REPLACED WITH NEW PIPE, PRESSURIZED SYSTEM AND CHECKED FOR LEAKS *JLG IS PARKED AS FAR AWAY FROM FAB AS YOU CAN GET AND WE HAD TO CLEAR AISLES TO GET IT OVER THERE, ACCOUNTING FOR A LOT OF TIME HOPE FOR A MORE CONVENIENT PARKING SPOT SOME DAY				
142251	WEEKLY SAFETY INSPECTION PERF	11/19/2010	11/19/2010 9:20:13 AM	0	\$5.60
142349	REPAIR OF EQUIPMENT		11/17/2010 1:06:24 PM	40499	\$70.60
	Comments: SMOKE COMING OUT OF CONTROL PANEL - PRSS 038				
	FOUND BLOWN FUSE (200 AMP) REPLACED SAME STARTED MOTOR, SINSORED ARMS (ABOUT 30 A ON FACE LEG) STARTED DRIVE, AMPS ABOUT SAME. PRESS VIBRATION WHEN FLY WHEEL IS TURNING SOUNDS LIKE BAD BEARING LOCKED OUT DISCONNECT.				

## Asset/Equipment Work Order History Brief

142361	REPAIR OF EQUIPMENT		11/17/2010 2:54:28 PM	40499	\$105.00
	Comments: BAD MOTOR STARTER FOR RAM - PRSS 038 CHANGE OUT RAM ADJ MOTOR STARTER.				
142411	WEEKLY SAFETY INSPECTION PERF	11/26/2010	11/23/2010 3:21:00 PM	0	\$5.60
142575	WEEKLY SAFETY INSPECTION PERF	11/30/2010	12/1/2010 9:16:53 AM	1	\$5.60
142915	MONTHLY PM FOR AUTOMATIC PRE	12/20/2010	12/28/2010 6:11:08 AM	8	\$52.95
142916	WEEKLY SAFETY INSPECTION PERF	12/8/2010	12/10/2010 7:56:29 AM	2	\$5.60
143117	WEEKLY SAFETY INSPECTION PERF	12/17/2010	12/17/2010 1:49:02 PM	0	\$5.60
143264	WEEKLY SAFETY INSPECTION PERF	12/24/2010	12/28/2010 8:55:17 AM	4	\$5.60
143717	MONTHLY PM FOR AUTOMATIC PRE	1/27/2011	2/3/2011 6:58:51 AM	7	\$52.95
143718	WEEKLY SAFETY INSPECTION PERF	1/4/2011	1/4/2011	0	\$5.60
143943	REPAIR OF EQUIPMENT		1/5/2011	40548	\$70.00
	Comments: PRESS IS JAMMED REV. MOTOR& CHANGE BACK				
143972	WEEKLY SAFETY INSPECTION PERF	1/11/2011	1/13/2011 2:39:56 PM	2	\$0.00
	Comments: DOWN FOR REPAIR BY PRESS DOCTORS				
143999	REPAIR OF EQUIPMENT		1/6/2011	40549	\$0.00
	Comments: SPARKS COMING FROM FLY WHEEL FOUND GUARD / COVER HEX BOLTS FOR FLY WHEEL TIGHTENED COVER, BUT VIBRATION IS FOUND WHEN MOTOR UP TO FULL SPEED. SPARKS STILL EXIST.				
144019	REPAIR OF EQUIPMENT		1/8/2011	40551	\$140.00
	Comments: ASSISTED PRESS DOCTORS. THEY REMOVED FLYWHEEL, DRIVE SHAFT, HUB, QUILL(BRG HOUSING), CLUTCH ASSY AND TOOK TO SHOP FOR REPAIR. WE GOT ALL AVAILABLE PARTS FORM CRIB AND BUILDING J FOR REPAIRS. LOAD AND BOX PARTS TO TAKE TO SHOP FOR REPAIR LOADED AND BOXED AND HELPED LOAD THE TRUCK				
144021	REPAIR OF EQUIPMENT		1/7/2011	40550	\$105.90
	Comments: SPARKS FLYING OUT FORM UNDER FLYWHEEL COVER TURNED FLYWHEEL BY HAND TURNS EASILY BUT MAKES RUMBLING SOUND BOLT HEADS ON BEARING PLATE ARE GROUND OFF MAKES ROARING SOUND ABOVE LOW SPEED FLYWHEEL BEARINGS MUST BE BAD ALLOWING FLYWHEEL TO TRAVEL TOWARDS PRSS LOCKED OUT DISCONNECT AGAIN.				
144027	REPAIR OF EQUIPMENT		1/7/2011	40550	\$350.00
	Comments: FLY WHEEL WOBALING CHECKED OUT PRSS FLY WHEEL HAS TO COME OFF STARTED TAKING OFF GUARDS AND AIR LINES				

## Asset/Equipment Work Order History Brief

144081	REPAIR OF EQUIPMENT		1/13/2011		40556	\$52.50
	Comments: PRESS DOCTORS ARRIVED, UNLOADED REPAIRED PARTS, AND STARTED REASSEMBLY. THEY INSTALLED THE DRIVE SHAFT ASSEMBLY WITH QUILL, WE GROUND THE BEARING CAP FOR PROPER PRELOAD, INSTALLED THE FLYWHEEL ASSEMBLY, REPLACED THE SEALS AND ORINGS IN THE FLYWHEEL ASSEMBLY WITH NEW DISC LININGS, AND CLEANED UP AREA.					
144108	WEEKLY SAFETY INSPECTION PERF	1/20/2011	1/18/2011		0	\$5.60
144159	REPAIR OF EQUIPMENT		1/14/2011		40557	\$140.00
	Comments: CLEAN UP & GET READY TO RUN CLEAN UP AFTER PRSS DR					
144275	WEEKLY SAFETY INSPECTION PERF	1/25/2011	1/21/2011		0	\$5.60
144308	WEEKLY SAFETY INSPECTION PERF	1/28/2011	1/27/2011 8:14:35 AM		0	\$5.60
144517	WEEKLY SAFETY INSPECTION PERF	2/3/2011	2/3/2011		0	\$5.60
144923	WEEKLY SAFETY INSPECTION PERF	2/10/2011	2/11/2011 11:39:17 AM		1	\$5.60
145032	WEEKLY SAFETY INSPECTION PERF	2/18/2011	2/18/2011 10:56:04 AM		0	\$5.60
145252	WEEKLY SAFETY INSPECTION PERF	2/25/2011	2/24/2011		0	\$6.44
145717	MONTHLY PM FOR AUTOMATIC PRE	3/7/2011	3/24/2011		17	\$52.95
145718	WEEKLY SAFETY INSPECTION PERF	3/3/2011	3/3/2011		0	\$5.60
146021	WEEKLY SAFETY INSPECTION PERF	3/10/2011	3/18/2011 10:27:14 AM		8	\$5.60
146070	REPAIR OF EQUIPMENT		3/3/2011		40605	\$157.50
	Comments: INSTALLED ANTI-TIE DOWN RELAY.					
146230	REPAIR OF EQUIPMENT		3/16/2011		40618	\$35.00
	Comments: AIR LEAKS REPAIRED THE AIR LEAK ON THE PRESS					
146268	WEEKLY SAFETY INSPECTION PERF	3/25/2011	3/25/2011 10:12:40 AM		0	\$5.60
146384	WEEKLY SAFETY INSPECTION PERF	4/1/2011	4/2/2011 10:27:18 AM		1	\$5.60
146827	MONTHLY PM FOR AUTOMATIC PRE	4/25/2011	4/26/2011 7:14:26 AM		1	\$52.95
146952	REPAIR OF EQUIPMENT		3/30/2011 3:42:17 PM		40632	\$35.00
	Comments: WILL NOT STROKE IN INCH. KEYSWITCH IN WRONG POSITION.					
147103	WEEKLY SAFETY INSPECTION PERF	4/11/2011	4/12/2011 3:37:35 PM		1	\$5.60
147269	WEEKLY SAFETY INSPECTION PERF	4/19/2011	4/21/2011 8:03:56 AM		2	\$5.60
147379	WEEKLY SAFETY INSPECTION PERF	4/28/2011	4/27/2011 2:45:17 PM		0	\$5.60

## Asset/Equipment Work Order History Brief

147819	ANNUAL PM FOR PRESS	5/19/2011	11/5/2011	170	\$70.60
147820	MONTHLY PM FOR AUTOMATIC PRE	5/26/2011	5/20/2011 7:44:14 AM	0	\$52.95
147821	WEEKLY SAFETY INSPECTION PERF	5/4/2011	5/5/2011 1:25:24 PM	1	\$5.60
148052	REPAIR OF EQUIPMENT		5/4/2011	40667	\$35.00
	Comments: RAM BOTTOMED OUT. REVERSED MOTOR TO GET OFF BOTTOM.				
148081	WEEKLY SAFETY INSPECTION PERF	5/12/2011	5/14/2011 10:18:18 AM	2	\$5.60
148106	REPAIR OF EQUIPMENT		5/6/2011	40669	\$35.00
	Comments: PUT CHAIN BACK ON AND RESET RAM ADJUSTEMENT				
148138	REPAIR OF EQUIPMENT		5/6/2011	40669	\$17.50
	Comments: PRESS JAMMED. REVERSED MOTOR				
148338	WEEKLY SAFETY INSPECTION PERF	5/23/2011	5/27/2011 8:59:41 AM	4	\$5.60
148500	WEEKLY SAFETY INSPECTION PERF	6/3/2011	6/10/2011 9:46:11 AM	7	\$5.60
148829	MONTHLY PM FOR AUTOMATIC PRE	6/20/2011	6/30/2011 11:46:49 AM	10	\$52.95
148989	REPAIR OF EQUIPMENT		6/7/2011	40701	\$70.00
	Comments: VANISHING OIL PIPE BROKE ON TOP OF PRESS. TURNED OFF VALVE SO WE COULD RUN OTHER PRESSES. COULD NOT FIND PVC GLUE PASSED ON TO BO AND EDDIE.				
148994	REPAIR OF EQUIPMENT		6/8/2011 11:18:48 AM	40702	\$70.60
	Comments: REMOVED BROKEN VANISHING OIL FITTINGS, REPALCED WITH NEW ONES, AND CHECKED FOR LEAKS.				
149020	WEEKLY SAFETY INSPECTION PERF	6/17/2011	6/17/2011 12:36:34 PM	0	\$5.60
149185	WEEKLY SAFETY INSPECTION PERF	6/24/2011	6/24/2011 9:03:33 AM	0	\$5.60
149310	WEEKLY SAFETY INSPECTION PERF	7/1/2011	6/29/2011 1:21:20 PM	0	\$5.60
149708	WEEKLY SAFETY INSPECTION PERF	7/6/2011	7/8/2011 2:38:43 PM	2	\$5.60
149924	WEEKLY SAFETY INSPECTION PERF	7/15/2011	7/15/2011 12:34:57 PM	0	\$5.60
150095	WEEKLY SAFETY INSPECTION PERF	7/22/2011	7/21/2011 2:39:12 PM	0	\$5.60
150174	REPAIR OF EQUIPMENT		7/15/2011	40739	\$35.00
	Comments: REBUILT SOLENOID FOR VANISHING OIL				
150194	REPAIR OF EQUIPMENT		7/16/2011	40740	\$70.00
	Comments: MOVED DIES FORM 32 TO 38 AND HAD TO ADJUST THE RAM UP LIMIT				
150230	WEEKLY SAFETY INSPECTION PERF	7/28/2011	7/30/2011 9:54:49 AM	2	\$5.60
150359	REPAIR OF EQUIPMENT		7/26/2011	40750	\$35.00
	Comments: ADJUSTED RAM UPPER OT SWITCH TO GET DIE TO FIT				
150680	MONTHLY PM FOR AUTOMATIC PRE	8/1/2011	8/11/2011 7:28:04 AM	10	\$52.95

## Asset/Equipment Work Order History Brief

150824	REPAIR OF EQUIPMENT		7/26/2011		40750	\$35.00
	Comments: RASIED THE RAM OT LIMIT SWITCH					
150940	WEEKLY SAFETY INSPECTION PERF	8/8/2011		8/12/2011	4	\$5.60
151148	WEEKLY SAFETY INSPECTION PERF	8/19/2011		8/19/2011 8:14:28 AM	0	\$5.60
151272	WEEKLY SAFETY INSPECTION PERF	8/26/2011		8/25/2011	0	\$5.60
151438	WEEKLY SAFETY INSPECTION PERF	9/1/2011		9/1/2011	0	\$5.60
151531	REPAIR OF EQUIPMENT		8/29/2011		40784	\$40.50
	Comments: STUCK ON BOTTOM. REVERSED AND RAISED RAM OKAY					
151802	MONTHLY PM FOR AUTOMATIC PRE	9/12/2011		9/9/2011 6:56:00 AM	0	\$52.95
151993	WEEKLY SAFETY INSPECTION PERF	9/8/2011		9/16/2011	8	\$5.60
152101	WEEKLY SAFETY INSPECTION PERF	9/23/2011		9/26/2011	3	\$5.60
152640	MONTHLY PM FOR AUTOMATIC PRE	10/10/2011		10/22/2011 7:07:33 AM	12	\$52.95
152641	WEEKLY SAFETY INSPECTION PERF	10/3/2011		10/3/2011	0	\$5.60
152845	REPAIR OF EQUIPMENT		10/3/2011		40819	\$17.50
	Comments: RAM BOTTOMED OUT, WON'T MOVE					
152918	WEEKLY SAFETY INSPECTION PERF	10/10/2011		10/14/2011	4	\$5.60
153011	REPAIR OF EQUIPMENT		10/13/2011 8:01:31 AM		40829	\$52.50
	Comments: TONAGE UNIT MOUNTS DETERIORATED					
	-INSTALL NEW DAMPER MOUNTS					
153063	WEEKLY SAFETY INSPECTION PERF	10/21/2011		10/27/2011	6	\$5.60
153276	REPAIR OF EQUIPMENT		10/27/2011		40843	\$35.00
	Comments: BROKEN FLEX ON LIGHT CURTAIN					
	-CUT OUT BAD END AND REATTACH TO UNIT					
153600	MONTHLY PM FOR AUTOMATIC PRE	11/21/2011		11/30/2011 8:41:15 AM	9	\$52.95
153601	WEEKLY SAFETY INSPECTION PERF	11/3/2011		11/1/2011 9:41:54 AM	0	\$5.60
153838	REPAIR OF EQUIPMENT		11/3/2011 9:04:53 AM		40850	\$70.60
	Comments: NO LUBE TO PRESS					
	-CHECKED LUB SYSTEM, EVERYTHING IS WORKING, FOUND TANK WAS EMPTY, LOOKED FOR LUBE BUT FOUND NONE. WE ARE OUT OF VANISHING OIL!!!					
153872	WEEKLY SAFETY INSPECTION PERF	11/8/2011		11/11/2011	3	\$5.60

## Asset/Equipment Work Order History Brief

153954	REPAIR OF EQUIPMENT		11/10/2011		40857	\$35.00
	Comments: BROKEN SCRAP RAKE					
	-WELD HANDLE BACK TOGETHER					
154112	WEEKLY SAFETY INSPECTION PERF	11/18/2011	11/18/2011 2:28:31 PM		0	\$5.60
154303	WEEKLY SAFETY INSPECTION PERF	11/25/2011	12/2/2011 2:00:31 PM		7	\$5.60
154630	MONTHLY PM FOR AUTOMATIC PRE	12/30/2011	1/4/2012 8:05:11 AM		5	\$52.95
154631	WEEKLY SAFETY INSPECTION PERF	12/9/2011	12/13/2011		4	\$5.60
154995	WEEKLY SAFETY INSPECTION PERF	12/20/2011	12/22/2011 8:53:34 AM		2	\$5.03
155134	WEEKLY SAFETY INSPECTION PERF	12/29/2011	12/27/2011 10:37:51 AM		0	\$0.00
155420	WEEKLY SAFETY INSPECTION PERF	1/3/2012	1/6/2012 10:07:03 AM		3	\$5.60
155668	WEEKLY SAFETY INSPECTION PERF	1/13/2012	1/13/2012		0	\$5.60
155925	WEEKLY SAFETY INSPECTION PERF	1/20/2012	1/23/2012		3	\$5.60
155969	REPAIR OF EQUIPMENT		1/21/2012		40929	\$66.45
	Comments: WILL NOT START					
	WORKED WITH CHRIS TO GET RUNNING BLOWER FUSES CHECK EVERYTHING FOR SHORTS ALL OK TURN BACK ON OK					
156018	REPAIR OF EQUIPMENT		1/25/2012		40933	\$35.00
	Comments: NEED REBUILT KIT IN COUNTER BALANCE VALVE					
	INSTALLED NEW KIT					
156025	REPAIR OF EQUIPMENT		1/26/2012		40934	\$35.00
	Comments: RWM WONT REEIVE CHECK STARTER AND FREE UP REV. SIDE COPY APPLY OT LITTLE TUBE CUT NEW PROP BLOCKS					
156175	MONTHLY PM FOR AUTOMATIC PRE	2/3/2012	2/3/2012		0	\$45.15
156176	WEEKLY SAFETY INSPECTION PERF	1/30/2012	2/3/2012 10:45:46 AM		4	\$5.60
156657	WEEKLY SAFETY INSPECTION PERF	2/10/2012	2/11/2012		1	\$5.60
156962	WEEKLY SAFETY INSPECTION PERF	2/20/2012	2/17/2012 9:25:36 AM		0	\$5.60
157018	WEEKLY SAFETY INSPECTION PERF	2/24/2012	2/25/2012		1	\$5.60
157550	MONTHLY PM FOR AUTOMATIC PRE	3/5/2012	3/10/2012 6:49:44 AM		5	\$52.95
157551	WEEKLY SAFETY INSPECTION PERF	3/5/2012	3/9/2012 9:19:59 AM		4	\$5.60
157810	WEEKLY SAFETY INSPECTION PERF	3/16/2012	3/16/2012		0	\$5.60

## Asset/Equipment Work Order History Brief

157888	REPAIR OF EQUIPMENT		3/12/2012		40980	\$227.50
	Comments:	STOPPING IN AUTO				
		RUN NEW WIRE FOR THE LEFT/REAR TURNAGE MONITOR SENSOR. ALSO WE PUT NEW PALM BUTTONS ON THE BACK OF PRESS BECAUSE THE OLD ONES DIDN'T WORK PUT A NEW SAFETY PLUG ON FORNT OF PRESS WHERE ONE WAS BROKE OFF.				
158099	WEEKLY SAFETY INSPECTION PERF		3/23/2012	3/26/2012	3	\$5.60
158136	REPAIR OF EQUIPMENT		3/23/2012		40991	\$35.00
	Comments:	RAM NOT GOING ALL THE WAY DOWN				
		RESET RAM ADJ MTR STARTER, INSPEC MT AND CHAIN DRIVE CHECK OK				
158529	MONTHLY PM FOR AUTOMATIC PRE		4/9/2012	4/5/2012 7:44:12 AM	0	\$52.95
158530	WEEKLY SAFETY INSPECTION PERF		4/2/2012	4/5/2012 7:15:06 AM	3	\$5.60
158681	REPAIR OF EQUIPMENT		3/30/2012		40998	\$35.00
	Comments:	RAM ADJUSTMENT WILL NOT COME ON				
		RESET OVER LOADS PUT THE RAM WHERE OPER NEEDED IT TO GO				
158735	WEEKLY SAFETY INSPECTION PERF		4/12/2012	4/13/2012	1	\$5.60
159026	WEEKLY SAFETY INSPECTION PERF		4/20/2012	4/27/2012	7	\$5.60
159099	REPAIR OF EQUIPMENT		4/24/2012		41023	\$35.00
	Comments:	RAM ADJUSTEMENT WILL NOT WORK				
		RESET OVERLOADS AND CHECK MOTOR				
159532	MONTHLY PM FOR AUTOMATIC PRE		5/7/2012	5/4/2012 7:33:22 AM	0	\$52.95
159756	WEEKLY SAFETY INSPECTION PERF		5/4/2012	5/5/2012	1	\$5.60
159918	WEEKLY SAFETY INSPECTION PERF		5/14/2012	5/18/2012 10:15:42 AM	4	\$5.60
160020	REPAIR OF EQUIPMENT		5/15/2012		41044	\$35.00
	Comments:	PRESS WONT STROKE				
		ACCORDING TO OPERATOR PRESS STOP AND WONT FINISH STROKE PRESS NOT AT THE LOWEST OR HIGHEST POSITION CHECK FUSES AND VOLTAGE COULD NOT SEE ANYTHING WRONG EXCEPT THE OUTER BALANCE CYLINDER IS LEAKING TOO MUCH AIR				
160024	REPAIR OF EQUIPMENT		5/16/2012 8:03:57 AM		41045	\$348.35
	Comments:	PRESS QUIT IN THE MIDDLE OF RUN				
		FOUND COMPNENT LEADS BROKEN ONPC BOARD ON SYMAX SO CONTROLLER PIECED TOGETHER ANOTHER ONE BUT CANNOT GET A RUN LIGHT WITH EPRON MODULE CANNOT FND SYMAX PROGRAMMING MODULE CONTROLLER				
160032	REPAIR OF EQUIPMENT		5/16/2012		41045	\$531.60
	Comments:	PRESS WILL NOT STROKE				
		ERROR ON PLC WHEN ORIGINAL MEMORY PACK IS INSTALLED. COULDN'T GET ERROR TO RESET INPUTS , OUTPUTS AND POWER ALL CHECKED GOOD USED PROGRAM IN PRESS FILE TO REPROGRAM P.C NEED TO HAVE TOP STOP AND SINGLE STROKE WORKING.				

## Asset/Equipment Work Order History Brief

160058	REPAIR OF EQUIPMENT		5/17/2012		41046	\$199.35
	Comments:	TOP STOP IN OP				
		TRACED DOWN WIRING FROM PLC IDENTIFIED SOME OUTPUT WIRING WILL HAVE TO WAIT FOR MACHINE DOWN TIME MACHINE OO DANGEROUS WHILE ELECTRICALLY ENERGIZED				
160158	REPAIR OF EQUIPMENT		5/22/2012		41051	\$66.45
	Comments:	TOP STOP NOT WORKING				
		INTRACTED SECOND SHIFT ON IDENTIFYING CONDUCTORS IN PLC				
160221	WEEKLY SAFETY INSPECTION PERF	5/25/2012	5/29/2012		4	\$5.60
160307	REPAIR OF EQUIPMENT		5/29/2012		41058	\$122.50
	Comments:	REPROGRAM MAIN PLC				
		SEARCH INFO FOR PRESS 38 FOUND PROGRAM FOR PLC WORK ON LADDER DIAGRAM PRINT COPIES ON JOHN CLIPBOARD FIND SOME DIFFERENCES RESPECT TO THE PROGRAM ON PRESS 38 CONTROL CABINET				
160546	MONTHLY PM FOR AUTOMATIC PRE	6/4/2012	6/15/2012		11	\$52.95
160547	WEEKLY SAFETY INSPECTION PERF	6/5/2012	6/9/2012		4	\$5.60
160798	REPAIR OF EQUIPMENT		6/8/2012 8:32:08 AM		41068	\$105.90
	Comments:	TUNNAGE MONITOR FAULT				
		FOUND ERROR 23 CANNOT LOCATE MANUAL SO DON'T KNOW WHAT E23 IS RESET EVERYTHING BUT IT CAME BACK CHECKED TONN MON. FUSES SWAPPED MAIN MODULE AND RESET ERROR CLEARED BUT ID NOT RUN PRESS OPERATOR WAS SETTING UP DIE				
160935	WEEKLY SAFETY INSPECTION PERF	6/18/2012	6/16/2012		0	\$5.60
161097	WEEKLY SAFETY INSPECTION PERF	6/25/2012	6/23/2012		0	\$5.60
161469	MONTHLY PM FOR AUTOMATIC PRE	7/16/2012	7/18/2012		2	\$52.95
161470	WEEKLY SAFETY INSPECTION PERF	7/2/2012	7/3/2012 11:06:17 AM		1	\$5.60
161792	WEEKLY SAFETY INSPECTION PERF	7/10/2012	7/11/2012 11:59:03 AM		1	\$5.60
161871	REPAIR OF EQUIPMENT		7/10/2012		41100	\$560.00
	Comments:	SINGLE STROKE OPERATION WONT WORK TOP STOP WONT WORK				
		TYPE AND EDITED PROGRAM. DOWNLOAD PROGRAM TO A DIFFERENT MEMORY PACK. CHECK OPERATION MODIFY PROGRAM AS NECESSARY. NEW MODIFICATIONS TO THE PROGRAM SHOULD BE IN MEMORY PACK. SINGLE STROKE AND TOP STOP WORKING OK.				
161938	WEEKLY SAFETY INSPECTION PERF	7/18/2012	7/23/2012 3:35:37 PM		5	\$4.69

## Asset/Equipment Work Order History Brief

161995	REPAIR OF EQUIPMENT		7/14/2012		41104	\$105.00
	Comments:	RAM SEEM TO STOP IN THE WRONG POSITION IN AUTOAND SINGLE STROKE MODE				
		REVIEW DOCUMENTATION ON PLC PROGRAM CHECK CAM SWITCH RAM POSITION INPUT I00U AND I010 COME ON OFF AT THE SAME TIME BOTH INDICATE THE SAME POSITION CHECK OUTPUT RELAY FOR CONITNOUS AND SINGLE STROKE OK TOP STOP OUTPUT IS NOT IN USE 0241 LOWER RAM SPEED AND CHECK PRESS WILL STOP BETTER AT LOW SPEED CLOSE TO THE TOP POSITION MAKE SOME MODIFICATION TO THE PROGRAM AND CHECK COULD NOT MAKE IT STOP AT THE TOP UNDO MODIFICATION PROGRAM MEMORY PACK				
162005	REPAIR OF EQUIPMENT		7/16/2012		41106	\$70.00
	Comments:	RAM WONT STOP AT THE TOP OF SINGLE STORKE AND TOP STOP				
		ADJUST ROTARG CAM LIMIT SWITCHES LS2 AND L53 CHECK OPERATION AND ADJUST AS NECESSARY LS WILL COME ON AT 300 RAM WILL STOP AT THE TOP BETWEEN O AND 3				
162207	WEEKLY SAFETY INSPECTION PERF		7/30/2012	8/9/2012 10:06:36 AM	10	\$5.60
162719	MONTHLY PM FOR AUTOMATIC PRE		8/17/2012	8/15/2012 8:14:39 AM	0	\$70.28
162942	REPAIR OF EQUIPMENT			8/8/2012	41129	\$35.00
	Comments:	RAM UNLEVEL				
		ASSIST WITH CHAIN REPAIR AND INSTALLATION				
162948	REPAIR OF EQUIPMENT			8/8/2012	41129	\$29.30
	Comments:	RAM WONT ADJUST DOWN				
		CHAIN BROKE ON ADJUSTMENT MOTOR REPLACED MASTER LINK				
162962	REPAIR OF EQUIPMENT			8/9/2012	41130	\$29.30
	Comments:	OILER LEAKIKNG LUBE DISK BLEW OUT				
		POP OFF HAD POPPED REPLACED BRASS WASHER REPLACED LUBE DISK				
162987	WEEKLY SAFETY INSPECTION PERF		8/16/2012	8/31/2012 7:33:05 AM	15	\$5.60
163214	REPAIR OF EQUIPMENT			8/24/2012 7:41:13 AM	41145	\$140.57
	Comments:	FLYWHEEL NO TURN				
		MOTOR IS RUNNING BUT FLOW NOT TURN NO VOLTAGE TO EDDY CURRENT AMP CHECKED FUSES BUT ALL GOOD FOUND AUX CONTACT BLOCK ON REVERSING MLS BAD GOT IT TO WORK BUT WHEN I BROUGH CHRIS BACK TO SHOW IT HAD STOPPED AGAIN				
163608	MONTHLY PM FOR AUTOMATIC PRE		9/14/2012	9/20/2012 7:52:54 AM	6	\$52.95
163609	WEEKLY SAFETY INSPECTION PERF		9/7/2012	9/8/2012	1	\$5.60
163873	REPAIR OF EQUIPMENT			9/10/2012	41162	\$106.64
	Comments:	PRESS KEEPS SHUTTING OFF WHEN RAM STROKES CHECK AND CLEAN ALL TON OVERLOADS AND CHECK AIR TO CLUTCH OK CHECK WIRING OT ESTOPS OK IT WAS ZONE 2 ON TON OVERLOADS				
163934	WEEKLY SAFETY INSPECTION PERF		9/17/2012	9/13/2012	0	\$5.60

## Asset/Equipment Work Order History Brief

163982	WEEKLY SAFETY INSPECTION PERF	9/20/2012	9/5/2012	0	\$5.60
164060	WEEKLY SAFETY INSPECTION PERF	9/12/2012	9/28/2012 8:48:37 AM	16	\$0.00
164617	MONTHLY PM FOR AUTOMATIC PRE	10/22/2012	10/16/2012 8:13:15 AM	0	\$52.95
164618	WEEKLY SAFETY INSPECTION PERF	10/5/2012	10/4/2012	0	\$5.60
164839	REPAIR OF EQUIPMENT		10/1/2012	41183	\$66.45
	Comments: JAMMED				
	REV. MOTRO AND BROUGHT RAM UP CHECKED EVETHING OUT TOLD OPER PRESS IS OK				
164905	WEEKLY SAFETY INSPECTION PERF	10/11/2012	10/12/2012	1	\$5.60
165217	WEEKLY SAFETY INSPECTION PERF	10/19/2012	10/22/2012 12:45:23 PM	3	\$5.03
165421	WEEKLY SAFETY INSPECTION PERF	10/29/2012	11/1/2012 11:27:38 AM	3	\$5.60
165789	ANNUAL PM FOR PRESS	11/5/2012	12/5/2012	30	\$0.00
165790	MONTHLY PM FOR AUTOMATIC PRE	11/15/2012	11/14/2012 7:14:40 AM	0	\$34.90
165791	WEEKLY SAFETY INSPECTION PERF	11/8/2012	11/10/2012	2	\$5.60
166121	REPAIR OF EQUIPMENT		11/14/2012	41227	\$35.00
	Comments: NEED TO REPLACE RAM ADJUSTMENT LIMIT SWITCH CORD				
	WRITE DOWN WIRING NUMBERS COLORS LOCK DISCONNECT UNWIRE CORD CUT NEW CORD SAME LENGTH WIRE NEW CORD CHECK CONTACTS OK				
166150	REPAIR OF EQUIPMENT		11/14/2012	41227	\$35.00
	Comments: RAM WONT ADJUST DOWN				
	CHECKED SWITCH I HAD VOLTAGE ACROSS THE SWITCH. NO VOLTGE ON COIL WE FOUND THAT THE WIRE THAT GOES TO THE LIMIT SWITCH HAD GOT CAUGHT IN THE CHAIN AND NEEDED REPLACED.				
166177	WEEKLY SAFETY INSPECTION PERF	11/19/2012	11/30/2012	11	\$5.60
166630	MONTHLY PM FOR AUTOMATIC PRE	12/14/2012	12/20/2012 8:06:01 AM	6	\$34.90
166834	WEEKLY SAFETY INSPECTION PERF	12/7/2012	12/8/2012	1	\$5.60
166898	REPAIR OF EQUIPMENT		12/10/2012	41253	\$70.00
	Comments: LIGHTS BLOW OVER PRESS				
	POWER DOWN REWIRE FIXTURES AND REASSEMBLE				
166965	WEEKLY SAFETY INSPECTION PERF	12/17/2012	12/17/2012 10:54:09 AM	0	\$5.60
167422	MONTHLY PM FOR AUTOMATIC PRE	1/21/2013	2/12/2013 7:35:33 AM	22	\$89.10

## Asset/Equipment Work Order History Brief

167423	WEEKLY SAFETY INSPECTION PERF	12/24/2012	1/5/2013	12	\$5.60
167714	REPAIR OF EQUIPMENT		1/8/2013	41282	\$87.50
	Comments: FINGERS WONT WORK ON DIE IT WONT UNLOAD PART				
	CHECK AIR PRESSURE OK NO BAD AIR LEAKS UNHOOK CYLINDERS LINES VALVES WORKING OK LIMIT SWITCHES WORKING OK REMOVE BOLTS AT THE END O FCYLINDERS SHAFTS CYLINDER WILL EXTEND AND RETRACT OK PIECE AT THE END OF ONE FINGER CAME OFF FINGERS MECHANISM GOT STUCK TOOL AN DDIE NOT WORKING ON SECOND SHIFT TODAY AHD TO FIX IT MYSELF FINGERS MECHANISM WORKING OK BUT THE DIE IS SCRATCHING SOME PAINT OFF THE PART				
167723	REPAIR OF EQUIPMENT		1/9/2013 8:20:38 AM	41283	\$31.45
167724	REPAIR OF EQUIPMENT		1/8/2013	41282	\$52.50
	Comments: 3 LIGHTS OUT ABOVE PRESS				
	THE CORD THAT SUPPLIED VOLTAGE WAS SHORTED I RETERMINATED WIRES I ALSO HAD TO REPLACE 4 BULBS				
167770	WEEKLY SAFETY INSPECTION PERF	1/14/2013	1/22/2013	8	\$5.60
167970	WEEKLY SAFETY INSPECTION PERF	1/29/2013	2/5/2013	7	\$5.60
168540	REPAIR OF EQUIPMENT		2/8/2013 8:17:08 AM	41313	\$79.65
	Comments: WELEDED NEW STOP INTO RAIL				
168561	WEEKLY SAFETY INSPECTION PERF	2/12/2013	2/15/2013	3	\$5.60
168810	WEEKLY SAFETY INSPECTION PERF	2/22/2013	3/1/2013 9:38:18 AM	7	\$5.60
169209	MONTHLY PM FOR AUTOMATIC PRE	3/14/2013	3/15/2013 7:16:35 AM	1	\$104.70
169210	WEEKLY SAFETY INSPECTION PERF	3/8/2013	3/8/2013 3:59:40 PM	0	\$5.60
169394	WEEKLY SAFETY INSPECTION PERF	3/15/2013	3/12/2013	0	\$5.60
169590	WEEKLY SAFETY INSPECTION PERF	3/19/2013	3/22/2013 11:34:33 AM	3	\$5.60
169671	REPAIR OF EQUIPMENT		3/19/2013	41352	\$251.60
	Comments: OIL AND WATER LEAKS				
	REPLACED WORN OIL LUBRICATE LINES WITHIN THE PRESS RAM SYSTEM				
169795	WEEKLY SAFETY INSPECTION PERF	3/29/2013	3/28/2013 8:39:40 AM	0	\$5.60
169848	REPAIR OF EQUIPMENT		3/27/2013 7:40:51 AM	41360	\$199.80
	Comments: WATER LEAKING FROM HOSE				
	SHUT DOWN PRESS LUBE, REPAIRED LINE, STARTED LUBE AND CHECKED, FOR LEAKS				
170165	MONTHLY PM FOR AUTOMATIC PRE	4/15/2013	4/18/2013 7:55:37 AM	3	\$89.10

## Asset/Equipment Work Order History Brief

170166	WEEKLY SAFETY INSPECTION PERF	4/4/2013	4/12/2013	8	\$5.60
170662	WEEKLY SAFETY INSPECTION PERF	4/19/2013	4/22/2013	3	\$5.60
170847	WEEKLY SAFETY INSPECTION PERF	4/29/2013	4/30/2013 7:50:35 AM	1	\$5.60
171229	MONTHLY PM FOR AUTOMATIC PRE	5/20/2013	5/23/2013 8:55:49 AM	3	\$52.35
171230	WEEKLY SAFETY INSPECTION PERF	5/7/2013	5/8/2013	1	\$5.60
171415	WEEKLY SAFETY INSPECTION PERF	5/15/2013	5/20/2013	5	\$5.60
171743	WEEKLY SAFETY INSPECTION PERF	5/27/2013	5/31/2013 10:37:02 AM	4	\$5.03
171787	REPAIR OF EQUIPMENT		5/23/2013	41417	\$0.00
	Comments:	OUTLET HANGING BY SCALE AND COIL CAR ON PRESS 38. DISCONNECT POWER, REMOVED 120VAC OUTLET, AND PLUGGED HOLE.			
171846	REPAIR OF EQUIPMENT		5/30/2013	41424	\$188.70
	Comments:	LIFT TABLE			
		INSTALLED LIFTED TABLE THAT WE MODIFIED TO HELP OPERATOR FEED THE METAL IN.			
		WE HAD IT RAISED TO BE AT THE HEIGHT OF 5FT THE OPERATORS NEAREST PLUG WAS ON AN I BEAM HE SAID HE WANTED IT ALL THE WAY UP AND IF HE NEEDED IT MOVED HE WOULD JUST PLUG IT IN AND THEN UNPLUG WHEN HE WAS FINISHED OPERATOR WAS HAPPY AT THE WAY IT WAS SET UP			
172113	MONTHLY PM FOR AUTOMATIC PRE	6/24/2013	6/25/2013 7:37:54 AM	1	\$34.90
172114	WEEKLY SAFETY INSPECTION PERF	6/7/2013	6/7/2013	0	\$5.60
172442	REPAIR OF EQUIPMENT		6/10/2013	41435	\$33.23
	Comments:	PRESS JAMMED IN THE BOTTOM			
		INCREASE AIR PRESSURE ON CORNER VALVE FORE RAM ADJUSTMENT UP REVERSE MAIN MOTOR AN STROKE PRESS RAM WENT UP OK			
172574	REPAIR OF EQUIPMENT		6/10/2013	41435	\$332.25
	Comments:	NO SPEED CONTROL			
		CHANGED EDDY CURRENT DRIVE SET UP NEW DRIVE WE STILL DIDN'T HAVE SPEED CONTROL. WE CHANGED POT WIRES FROM POT WE GOT SPEED CONTROL AFTER THIS AT FIRST WE DIDNT THINK IT WAS WORKING BUT I TESTED IT AGAIN AND GAVE IT TIME TO SLOW DOWN AND IT WORKED FINE. I DON'T KNOW FOR SURE IFOTHER DRIVE IS BAD. WHEN I GET A CHANCE IM GONG TOTEST IT ON BENCH			
172575	REPAIR OF EQUIPMENT		6/12/2013	41437	\$232.58
	Comments:	PARTS TOO LONG ON ONE SIDE			
		CHECKED WITH DIAL INDICATOR WE CHECKED WITH IT JACKED UP ON BOTH SIDES ALSO IT WAS ONLY OFF A FEW THOUSANDS THEY DECIDED TO RUN PRESS AGAIN			

## Asset/Equipment Work Order History Brief

172625	REPAIR OF EQUIPMENT		6/17/2013		41442	\$52.50
	Comments: BROKEN HOSES ON PRESS REPLACED TWO PIECES OF BROKEN FLEX					
172678	WEEKLY SAFETY INSPECTION PERF	6/14/2013	6/14/2013		0	\$5.03
172706	WEEKLY SAFETY INSPECTION PERF	6/21/2013	6/25/2013 8:55:18 AM		4	\$5.60
173124	MONTHLY PM FOR AUTOMATIC PRE	7/25/2013	8/7/2013 7:57:21 AM		13	\$52.35
173125	WEEKLY SAFETY INSPECTION PERF	7/2/2013	7/8/2013		6	\$5.03
173312	REPAIR OF EQUIPMENT		6/26/2013		41451	\$15.73
	Comments: NEED KEY BOX MOUNTED ON PRESS MOUNTED KEY BOX					
173412	REPAIR OF EQUIPMENT		7/3/2013		41458	\$139.60
	Comments: SAFETY GUARD BAD MANUFACTURED AND INSTALLED GUARD					
173515	WEEKLY SAFETY INSPECTION PERF	7/15/2013	7/19/2013 11:49:37 AM		4	\$6.44
173690	WEEKLY SAFETY INSPECTION PERF	7/26/2013	7/26/2013		0	\$10.63
173925	WEEKLY SAFETY INSPECTION PERF	8/2/2013	8/1/2013		0	\$10.63
174263	WEEKLY SAFETY INSPECTION PERF	8/8/2013	8/14/2013		6	\$5.60
174469	REPAIR OF EQUIPMENT		8/1/2013		41487	\$33.23
	Comments: VANISHING OIL LEAKING FROM HOSE AN ELBOW OUT OF THE VALVE WAS LEAKING TOOK IT OFF AND REPLACED WITH A NEW ONE. ALSO MACHINE WOULDN'T START UP HAD A FUSE BLOWN REPLACED THE FUSE WITH A NEW ONE AND WORKED CORRECTLY					
174618	WEEKLY SAFETY INSPECTION PERF	8/21/2013	8/29/2013		8	\$6.44
174662	REPAIR OF EQUIPMENT		8/15/2013		41501	\$98.17
	Comments: RAM NOT ALIGNING CORRECTLY CHECKED RAM HEIGHT AND EACH CORENER CHECK SHUT HEIGHT MOTOR COULD FIND NO FAULT ON EITHER RAM OR MOTOR					
174719	REPAIR OF EQUIPMENT		8/21/2013		41507	\$133.44
	Comments: NEED TO REDUCE BREAKING TIME AFTER INTERRUPTING SAFETY LIGHT CURTAIN					
174720	REPAIR OF EQUIPMENT		8/21/2013		41507	\$98.17
	Comments: PRESS 38 BRAKE SYSTEM NOT STOPPING RAM SPINDLE TO SPECIFICATIONS ADJSUTED BOTTOM SHOE OR BRAKE TESTED FOR SURETY OF QUICK STOPPNG READJUSTED AND TOOK TEMP READING TO MAKE SPINDLE WAS NOT OVER HEATING					
175125	MONTHLY PM FOR AUTOMATIC PRE	9/6/2013	9/20/2013 7:26:15 AM		14	\$104.70
175344	WEEKLY SAFETY INSPECTION PERF	9/5/2013	9/13/2013 9:51:53 AM		8	\$0.00

## Asset/Equipment Work Order History Brief

175433	REPAIR OF EQUIPMENT		9/10/2013		41527	\$80.67
	Comments:	PRESS RAM JAMMED IN THE BOTTOM				
		STOP MAIN MOTRO RESET OVERLOAD ON SLIDE ADJUSTMENT MOTOR CONTROL REVERSE LEADS ON MAIN MOTOR MOTOR CONTORL STROKE PRESS RAM GO UP OK REVERSE MOTOR LEADS TO ORIGINAL POSITION				
175496	WEEKLY SAFETY INSPECTION PERF		9/20/2013	9/20/2013	0	\$5.60
175715	WEEKLY SAFETY INSPECTION PERF		9/27/2013	9/27/2013	0	\$5.60
176076	MONTHLY PM FOR AUTOMATIC PRE		10/21/2013	10/15/2013 7:50:30 AM	0	\$52.35
176265	WEEKLY SAFETY INSPECTION PERF		10/4/2013	10/4/2013	0	\$5.03
176490	WEEKLY SAFETY INSPECTION PERF		10/11/2013	10/15/2013	4	\$4.59
176620	REPAIR OF EQUIPMENT			10/17/2013	41564	\$349.00
	Comments:	VANISHING OIL IS LEAKING FROM ABOVE THE FEEDER				
		SOAF WAS LEAKING OIL LINE BROKE ALL TO PIECES WHILE WE TRIED TO FIX SOAF LINE MADE A BIG MESS HAD TO REPAIR BOTH LINES IN SEVERAL PLACES ALL THAT OLD LINE IS VERY BRITTLE AND SUBJECT TO BREAK ANY TIME				
177189	MONTHLY PM FOR AUTOMATIC PRE		11/14/2013	12/6/2013 8:46:46 AM	22	\$0.00
177190	WEEKLY SAFETY INSPECTION PERF		10/22/2013	11/8/2013 10:03:12 AM	17	\$0.00
177450	REPAIR OF EQUIPMENT			11/5/2013	41583	\$125.80
	Comments:	PRSS STUCK ON BOTTOM SMOKE COMING OUT MOTOR CLUTCH AREA				
		REFERENCED MANUAL DISCONNECTED EDDYS CURRENT DRIVE TESTED MOTOR OK MANUALLY ACTIVATED WORN OUT REVERSING MOTOR STARTER WAS ABLE TO GET PRESS UNSTUCK RECONNECTED EDDY CONNECT DRIVE				
177479	WEEKLY SAFETY INSPECTION PERF		11/15/2013	11/12/2013	0	\$5.60
177617	WEEKLY SAFETY INSPECTION PERF		11/19/2013	11/21/2013	2	\$5.60
177658	REPAIR OF EQUIPMENT			11/15/2013	41593	\$31.59
	Comments:	VANISHING OIL LEAKING FROM PIPE ABOVE PRESS				
		CHECK SYSTEM FOR OIL LEAK COULD NOT LOCATE A LEAK				
177679	REPAIR OF EQUIPMENT			11/18/2013	41596	\$33.36
	Comments:	CHECK FOR LEAK ON OIL LINE				
		LOOKED FOR LEAKS ON VANISHING OIL SUPPLY LINE				
177689	REPAIR OF EQUIPMENT			11/18/2013	41596	\$98.17
	Comments:	VANISHING OIL LEAK				
		ACCESSED THE LEAKING PIPE/ WE NEED " PIPEBOOT CLAMPS TO HAVE SOMETHING TO CLAMP THE PIPING OFF USED SOME RUBBER CUT TO FIT AND HOSE CLAMPS TO SLOW LEAK DOWN PVC GLUE				
177773	WEEKLY SAFETY INSPECTION PERF		11/28/2013	12/6/2013 8:56:16 AM	8	\$5.60



## Asset/Equipment Work Order History Brief

Work Order Number	Description	Start Date	End Date	Hours	Cost
180272	REPAIR OF EQUIPMENT	2/13/2014		41683	\$47.18
	Comments: WOULD START STROKING AS SOON AS LIGHT CURTAIN WAS RESET 2ND SHIFT HAD TRIED FIXING THE ANTI- TIEDOWN ON CONTROL STATION ON BACK OF PRESS. THEY BUILT THE BACK STATION IN PARELLEL WITH FRONT STATION AND MAKE IT RUN ALL THE TIME ESTOPS WOULDN'T WORK TOOK THEIR 2 WIRES OFF ANTI TIEDOWN RELAY AND IT WORKED LIKE IT WAS SUPPOSE TO WE LOOKED AT IT AND IT NEEDED ITS OWN TIE DOWN RELAY FOR THE BACK STATION				
180273	REPAIR OF EQUIPMENT	2/14/2014		41684	\$460.41
	Comments: REAR CONTROL DON'T WORK IN INCH MODE TOP STOP WILL NOT WORK. CLUTCH CONTROL IN INCH AND SINGLE IS THE SAME. PRESS WILL RUN AUTOMATIC FROM REAR CONTROL  GOT THE TOP STOP CUT INCH MODE TO WORK CORRECTLY FROM THE "FRONT STATION" MOVED THE WIRE FOR THE BACK STATION GOING TO THE LOAD TO ANOTHER TERMINAL. THAT GOT THE INCH AND TOP STOP FIXED. BUT WHEN IT WAS SWAPPED TO REMOTE SIDE THE BACK WOULD ONLY WORK IN CONT. IT WOULDN'T LET THE FRONT WORK IN REMOTE (WORKED LIKE IT SHOULD) TRIED TRIMMING DOWN THE WIRES FOR THE BACK STATION. THE BACK SHOULD'VE ONLY HAD INCH WORKING ON IT. MOVED SEVERAL WIRES AROUND TRYING TO GET IT RIGHT. HAD NO LUCK FOUND A 2 WIRE TAPED UP ON THE BACK STATION. THAT WAS FOR "INCHING" MODE. LET JOSE KNOW WHAT WAS GOING ON WITH IT. THAT THEY ONLY WANTED IT TO WORK IN INCH MODE ON BACK STATION				
180308	REPAIR OF EQUIPMENT	2/17/2014		41687	\$234.76
	Comments: BACK STATION WOULD STILL STROKE IN AUTO  TRACED DOWN WIRES AND FIGURED OUT WHICH WIRE NEEDED TO BE MOVED  MOVED THE "LOAD" WIRE OFF OF THE ANTI TIE DOWN RELAY TO 2 WIRE (WHICH IS FOR INCH MODE) BACK STATION WILL ONLY STROKE IN INCH IN ANY SETTING				
180316	REPAIR OF EQUIPMENT	2/22/2014		41692	\$35.00
	Comments: AUTO SHUTDOWN CIRCUIT  FIGURED ON SYSTEM TO BE WIRED FOR COST SAVINGS				
180375	WEEKLY SAFETY INSPECTION PERF	2/24/2014	2/24/2014	0	\$5.03
180412	REPAIR OF EQUIPMENT	2/19/2014		41689	\$157.25
	Comments: PARTS BREAKING LIGHT CURTAIN WHEN SLIDING DOWN  DECIDED TO LOWER TH SLIDE FROM THE DIE DOWN SO IT WOULD BE UNDER THE LIGHT CURTIAN FOR NOW.  HAD TO FABRICATE A LOWER STAND TO HOLD THE SLIDE SO IT COULD CLEAR THE LIGHT CURTAIN  GONNAS GET QUOTES ON NEW LIGHT CURTIAN THAT RUN VERITCAL AND HORIZONTAL				
180413	REPAIR OF EQUIPMENT	2/18/2014		41688	\$110.08
	Comments: FABRICATING A LONGERS SLIDE FOR PARTS  HE HAD STARTED DIE IN AND MEASURED OFF OF IT TO SEE HOW LONG IT NEEDED TO BE GOT BILLY TO MAKE THE SLIDE FOR ME HAD TO WELD THE END ON IT AND THE STOP ON IT TOO  TOOK OUT TO PRESS TO TRY IT OUT. PARTS THEY WERE HANGING WAS BREAKING THE LIGHT CURTAIN				
180423	REPAIR OF EQUIPMENT	2/24/2014		41694	\$35.00
	Comments: PRESS 38 AUTOMATIC SHUT OFF PROJECT  WORK ON CONTROL CIRCUIT START WIRING CONTROL CIRCUIT				

## Asset/Equipment Work Order History Brief

180453	REPAIR OF EQUIPMENT		2/25/2014		41695	\$192.50
	Comments: PRESS 38 AUTOMATIC SHUT OFF PROJECT					
	MOUNT TIMER CIRCUIT ON PRESS CONTROL CABINET WIRE TIMER CIRCUIT TO PRESS CONTROL CIRCUIT ADD CONTACT TO THE START PUSH BUTTON WIRE TIMER START TO PLS-3 SAME AS LUBE SYSTEM DID NOT HAVE TIME TO CHECK CIRCUIT OPERATION WITH PLS -3 RESTARTING THE TIMER PRSS IS READY TO RUN ILL TEST THE TIMER CIRCUIT TOMORROW ALSO CHECK TIMER OPERATION ON PRESS 30 HAD TO ADJUST LIMIT SWITCH ARM					
180475	REPAIR OF EQUIPMENT		2/26/2014		41696	\$35.00
	Comments: PRSS 38 AUTOMATIC SHUT OFF PROJECT					
	TEST TIMER CIRCUIT OPERATION WHEN THE OPERATOR WAS RUNNING THE PRESS IN DAY SHIFT TIMER CIRCUIT WORKED OK, SET TIMER TO 30 MIN					
181016	MONTHLY PM FOR AUTOMATIC PRE	3/17/2014	3/26/2014 7:34:36 AM		9	\$43.95
181017	WEEKLY SAFETY INSPECTION PERF	3/3/2014	3/4/2014		1	\$5.60
181307	WEEKLY SAFETY INSPECTION PERF	3/11/2014	3/14/2014		3	\$5.60
181546	WEEKLY SAFETY INSPECTION PERF	3/21/2014	3/20/2014		0	\$5.60
181634	WEEKLY SAFETY INSPECTION PERF	3/27/2014	3/28/2014		1	\$5.60
181815	MONTHLY PM FOR AUTOMATIC PRE	4/25/2014	4/17/2014 7:05:56 AM		0	\$52.35
181816	WEEKLY SAFETY INSPECTION PERF	4/4/2014	4/8/2014 8:05:54 AM		4	\$5.60
182158	WEEKLY SAFETY INSPECTION PERF	4/15/2014	4/11/2014		0	\$5.60
182265	WEEKLY SAFETY INSPECTION PERF	4/18/2014	4/17/2014 10:11:28 AM		0	\$10.63
182366	WEEKLY SAFETY INSPECTION PERF	4/24/2014	4/25/2014		1	\$13.03
182583	WEEKLY SAFETY INSPECTION PERF	5/2/2014	5/2/2014		0	\$0.00
182863	MONTHLY PM FOR AUTOMATIC PRE	5/19/2014	6/3/2014 7:46:21 AM		15	\$104.70
183046	REPAIR OF EQUIPMENT		5/2/2014		41761	\$201.33
	Comments: FINISHING LIGHT CURTAINS					
	WIRED UP T STAND MOUNTED LIGHT CURTAIN ON LEFT SIDE AND RAN WIRE WIRED LIGHT CURTAINS UP ALIGNED RIGHT CURTAIN					

## Asset/Equipment Work Order History Brief

183048	REPAIR OF EQUIPMENT		5/1/2014		41760	\$835.59
	Comments:	MAKE PRESS COMPLAINT WITH SAFETY CODE ALIGNED THE GUARDS ON THE FRONT OF THE PRESS FABRICATED MOUNTS FOR LIGHT CURTIANS  MADE ADJUSTABLE SLIDE MOUNT FOR REMOTE CURTAINS MOUNTED TRIM AND REC BLACK MAX RELOCATED PUSH AND PALM BUTTON STAION TO A T STAND AND PULLED NEW WIRE NEEDS 2 NEW PALM BUTTONS AND 1 ESTP BUTTON WIRED IN 120 VOLT SUPPLY POWER AND TRY AND RECV OF BLACK MAX NEED INPUT WIRED IN OT BLACK MAX AND ALIGNMENT NEEDED STAYED OVER TO GET PROJECT TO A PLACE WEHRE FIRST SHIFT COULD PICK UP				
183091	WEEKLY SAFETY INSPECTION PERF	5/9/2014	5/8/2014		0	\$5.60
183267	WEEKLY SAFETY INSPECTION PERF	5/15/2014	5/19/2014 7:36:07 AM		4	\$5.60
183340	REPAIR OF EQUIPMENT		5/19/2014		41778	\$99.68
	Comments:	LOSING POSITION ON PLS MONITOR  CHECKED CAM SWITCH SPROCKET LOOSE ON CAM SWITCH KEY WAS MISSING WE REPLACED KEY AND SET BACK TO 180				
183431	WEEKLY SAFETY INSPECTION PERF	5/26/2014	5/27/2014 7:36:54 AM		1	\$5.60
183763	WEEKLY SAFETY INSPECTION PERF	6/3/2014	6/6/2014		3	\$5.60
184077	WEEKLY SAFETY INSPECTION PERF	6/13/2014	6/14/2014		1	\$5.60
184324	WEEKLY SAFETY INSPECTION PERF	6/23/2014	6/27/2014		4	\$5.60
184561	MONTHLY PM FOR AUTOMATIC PRE	7/3/2014	7/8/2014 7:23:50 AM		5	\$43.95
184601	WEEKLY SAFETY INSPECTION PERF	7/4/2014	7/7/2014 9:52:39 AM		3	\$5.60
184981	WEEKLY SAFETY INSPECTION PERF	7/14/2014	7/21/2014 11:14:25 AM		7	\$5.60
185453	WEEKLY SAFETY INSPECTION PERF	7/28/2014	7/31/2014 3:05:18 PM		3	\$5.60
185820	MONTHLY PM FOR AUTOMATIC PRE	8/7/2014	8/5/2014 7:41:02 AM		0	\$52.35
185821	WEEKLY SAFETY INSPECTION PERF	8/7/2014	8/11/2014 8:55:20 AM		4	\$10.50
186223	WEEKLY SAFETY INSPECTION PERF	8/18/2014	8/19/2014		1	\$0.00
186432	WEEKLY SAFETY INSPECTION PERF	8/26/2014	8/26/2014 7:31:21 AM		0	\$19.94
186827	MONTHLY PM FOR AUTOMATIC PRE	9/4/2014	9/17/2014		13	\$52.35
186828	WEEKLY SAFETY INSPECTION PERF	9/2/2014	9/5/2014		3	\$10.50
187239	WEEKLY SAFETY INSPECTION PERF	9/12/2014	9/12/2014		0	\$10.50

## Asset/Equipment Work Order History Brief

187398	WEEKLY SAFETY INSPECTION PERF	9/19/2014	9/24/2014	5	\$19.94
187612	WEEKLY SAFETY INSPECTION PERF	10/1/2014	10/3/2014	2	\$19.94
187971	MONTHLY PM FOR AUTOMATIC PRE	10/17/2014	10/17/2014 7:17:07 AM	0	\$52.35
188111	WEEKLY SAFETY INSPECTION PERF	10/10/2014	10/13/2014	3	\$19.94
188180	REPAIR OF EQUIPMENT		10/7/2014	41919	\$132.90
	Comments: DIE OWNT KICK OFF PARTS				
	SET CORRECT ANGLES ON PLS TO ALLEN KICKOFF TO RETRACT BEFORE FEEDING HAD TO WIRE IN VALVE FOR KICKOFF INTO PLS CHANNEL AIR BLOW OFF I INSTALLED A RECEPTACLE SO WHEN THEY RUN THIS DIE THEY CAN PLUG VALVE UP THEY WERE TRYING TO CONTROL VALVE BY TURNING SUPPLY AIR ON AND OFF WITH CHANNEL 4 THIS DIDN'T GIVE THEM PROPER CONTROL NOW THEY STILL HAVE CONTROL OF SUPPLY AIR ON CHANNEL 4 BUT ALSO THEY HAVE 120 V RECEPTACLE CONTROLLED BY CHENNEL 4 TO CONTROL VALVE				
188309	WEEKLY SAFETY INSPECTION PERF	10/20/2014	10/24/2014	4	\$0.00
188456	WEEKLY SAFETY INSPECTION PERF	10/31/2014	11/4/2014	4	\$10.50
188842	MONTHLY PM FOR AUTOMATIC PRE	11/17/2014	12/2/2014 7:20:25 AM	15	\$52.35
189089	WEEKLY SAFETY INSPECTION PERF	11/11/2014	11/11/2014	0	\$19.94
189219	WEEKLY SAFETY INSPECTION PERF	11/18/2014	11/19/2014	1	\$10.50
189255	REPAIR OF EQUIPMENT		11/15/2014	41958	\$157.25
	Comments: NO WAY TO GET PARTS FROM PRESS TO BASKET				
	HELPED PAUL KENNEDY BUILD PART RAMP FOUND MATEIAL ASSEMBLED AND WELDED CHECKED OPERATION OK				
189324	WEEKLY SAFETY INSPECTION PERF	11/26/2014	12/5/2014 11:25:57 AM	9	\$9.44
189965	WEEKLY SAFETY INSPECTION PERF	12/12/2014	12/16/2014	4	\$19.94
190076	REPAIR OF EQUIPMENT		12/16/2014	41989	\$99.68
	Comments: NEW PARTS BREAKING THE LIGHT CURTAIN				
	SLIDE WAS AS LOW WAS IT WOULD GO AND AALREADY HAD 4 BLANKED AT THE BOTTOM TALKED WITH JERROD CRAWLEY AND WE STILL HAD ABOUT A 1/ " WE COULD MOVE IT UP				
	TOOK OFF AND REDRILLED THE HOLES AND ROMOUNTED IT MADKE SURE IT WAS LINED UP				
190093	WEEKLY SAFETY INSPECTION PERF	12/23/2014	12/23/2014	0	\$19.94
190507	ANNUAL PM FOR PRESS	1/28/2015	1/15/2015	0	\$0.00
190508	MONTHLY PM FOR AUTOMATIC PRE	1/1/2015	1/13/2015 7:29:01 AM	12	\$52.35

## Asset/Equipment Work Order History Brief

190509	WEEKLY SAFETY INSPECTION PERF	12/30/2014	1/13/2015	14	\$0.00
190800	REPAIR OF EQUIPMENT		1/7/2015	42011	\$150.40
	Comments: COUNTER BALANCE LEAKS				
	REMOVED BOTTOM CAP LOOKED TO SEE IF WE COULD PACKING IN TO SEAL LEAK COULDN'T FIND A WAY TO MAKE IT WORK WE PUT IT BACK TOGETHER AND TALKED TO BCN AGAIN ABOUT PARTS				
190821	REPAIR OF EQUIPMENT		1/6/2015	42010	\$465.15
	Comments: GET MEASUREMENTS OF THE RAM SLACK AND GET PARTS LIST				
	TOOK DIAL INDICATOR AND BOTTLE JACK AND SET UP ON RAM TO MEASURE SLACK IN THE RAM CHECKED ALL 4 CORNERS NOTICED THE COUNTER BALANCE YOKE HAD A LOT OF SLACK IN IT PULLED PIN OUT AND MADE SOME MEASUREMENTS PULLED CAP OFF ONE OF THE COUNTER BALANCE TO SEE IF THERE WAS A WAY TO STOP AIR LEAK FROM AROUND THE RAM AFTER GETTING IT APART THERE WASN'T A WAY TO FIX WITHOUT A REBUILD KIT. PUT IT BACK TOGETHER SO THEY CAN RUN THE PIECES				
190913	WEEKLY SAFETY INSPECTION PERF	1/20/2015	1/22/2015	2	\$19.94
191236	WEEKLY SAFETY INSPECTION PERF	1/29/2015	1/31/2015 10:06:24 AM	2	\$10.50
191544	MONTHLY PM FOR AUTOMATIC PRE	2/12/2015	2/12/2015 10:54:28 AM	0	\$52.35
191545	WEEKLY SAFETY INSPECTION PERF	2/9/2015	2/6/2015	0	\$10.50
191785	WEEKLY SAFETY INSPECTION PERF	2/13/2015	2/13/2015	0	\$10.50
192009	WEEKLY SAFETY INSPECTION PERF	2/20/2015	2/28/2015	8	\$10.50
192521	MONTHLY PM FOR AUTOMATIC PRE	3/16/2015	3/18/2015 7:34:14 AM	2	\$52.35
192766	WEEKLY SAFETY INSPECTION PERF	3/9/2015	3/18/2015 11:02:53 AM	9	\$10.50
192903	REPAIR OF EQUIPMENT		3/12/2015	42075	\$139.60
	Comments: MAKE SURE THAT THE EAST BULL GEAR COVER HAS AN EYE BOLT ON IT				
	REMOVED HOME MADE PIECE WELDED PIPE THREAD ONTO EYE BOLT AND INSTALLED SAME				
193060	WEEKLY SAFETY INSPECTION PERF	3/25/2015	3/30/2015	5	\$0.00
193148	REPAIR OF EQUIPMENT		3/25/2015	42088	\$31.72
	Comments: SWTICH BOX FOR NEWLY INSTALLED LIGHT IS NOT WORKING				
	THE RECEPTACLE WAS SHORTED OUT AGAINST THE COVER I INSULATED THE WIRE WITH ELECTRICAL TAPE AND RESET THE BREAKER				
193618	MONTHLY PM FOR AUTOMATIC PRE	4/17/2015	4/23/2015	6	\$53.96
193619	WEEKLY SAFETY INSPECTION PERF	4/6/2015	4/9/2015	3	\$10.50
194063	WEEKLY SAFETY INSPECTION PERF	4/16/2015	4/17/2015	1	\$10.50

## Asset/Equipment Work Order History Brief

194199	WEEKLY SAFETY INSPECTION PERF	4/24/2015	4/23/2015	0	\$19.94
194328	WEEKLY SAFETY INSPECTION PERF	4/30/2015	5/7/2015 8:39:54 AM	7	\$10.50
194679	MONTHLY PM FOR AUTOMATIC PRE	5/25/2015	5/21/2015	0	\$53.96
194925	WEEKLY SAFETY INSPECTION PERF	5/14/2015	5/20/2015 1:21:25 PM	6	\$10.50
195076	REPAIR OF EQUIPMENT		5/15/2015	42139	\$132.90
	Comments: PRESS WOULD NOT STROKE				
	CHECKED ALL ESTOPS AND LGIHT CURTAINS FOUND NOTHING WRONG CHECKED VOLTAGE TO THE CLUTCH AND HAD THE 120V WHEN PAML BUTTON WERE PRESSED CHECKED PRESSURE SWITCH FOR CLUTCH AND ADJSUTED IT AND STARTED STROKING.				
195141	WEEKLY SAFETY INSPECTION PERF	5/27/2015	5/29/2015	2	\$10.50
195593	MONTHLY PM FOR AUTOMATIC PRE	6/22/2015	6/18/2015	0	\$53.96
195594	WEEKLY SAFETY INSPECTION PERF	6/5/2015	6/5/2015	0	\$10.50
195818	REPAIR OF EQUIPMENT		6/3/2015	42158	\$17.50
	Comments: PLC FAULTED PRESS WONT RUN				
	ASSIST DAY SHIFT TO CLEAR PLC FAULT				
195838	REPAIR OF EQUIPMENT		6/3/2015	42158	\$231.61
	Comments: WONT STROKE				
	CHECKED ESTOP CIRCUIT CHECKED PRESSURE SWITCHES AND TONNAGE MONITOR WE HAD PROPER VOLTAGE ON EVERYTHING SYMAX CONTROLLER HAD AN ERRO WE RECONNECTED KEYPAD AND CLEARED ERROR PRESS STORKED FINE				
195916	WEEKLY SAFETY INSPECTION PERF	6/12/2015	6/12/2015	0	\$10.50
195983	REPAIR OF EQUIPMENT		6/11/2015	42166	\$107.93
	Comments: OIL LEAK ON EAST END A T BUL GEAR COVER				
	INSPECTED HOLE KNOCKNOUT HAS BEEN LEAKING AND IT IS GETTING WORSE WE PIG PUTTIED IT AND TOPPED OFF GEAR OIL				
196122	WEEKLY SAFETY INSPECTION PERF	6/19/2015	6/20/2015	1	\$10.50
196255	WEEKLY SAFETY INSPECTION PERF	6/29/2015	6/29/2015	0	\$10.50
196365	REPAIR OF EQUIPMENT		6/29/2015	42184	\$321.60
	Comments: PRESS GIBS RUNNING HOT INSPECT LOCATED PROBLEM, CORRECTIVE ACTION				
	CHECKED OILER PUMP FOR ADEQUATE PRESSURE TOOK OIL LINES LOOSE AND USED AIR PRESSURE TO CLEAN TUBING WE BELIVE MOST OILER TIMES ARE CLEAR SYSTEM SHOULD OI GIBS PROPERLY HOWEVER WITH PICTURES OF THE RAM ANCHOR BOLTS NUSTS LOOSEN WITH 2 COMPLETELY OFF AND 1 ALMOST SYSTEM SHOULD NOT BE PUT INOT OPERATION				

## Asset/Equipment Work Order History Brief

196679	MONTHLY PM FOR AUTOMATIC PRE	7/20/2015	9/30/2015	72	\$53.96
196680	WEEKLY SAFETY INSPECTION PERF	7/6/2015	7/9/2015	3	\$10.50
196919	REPAIR OF EQUIPMENT		7/6/2015	42191	\$39.31
	Comments: CLEAN ARAS IN AND AROUND PRSS 38				
					CLEANED SCRAP METAL FROM BED EDGES OF BOLT SLIDES AN DOFF OF FLOORING
196928	REPAIR OF EQUIPMENT		7/2/2015	42187	\$343.60
	Comments: GETTING PREPPED FOR RAM REMOVAL				
					MOVED THREAD GATE UNWIRED FEEDER CABINET AND MVOED FEEDER AND CABINET
196936	REPAIR OF EQUIPMENT		7/6/2015	42191	\$99.68
	Comments: GETTING READY FOR CONTRACTORS TO PULL RAM				
					TRACING CIRCUIT SO WE COULD RECONNECT ESTOP CIRCUIT TO GET PRESS TO STROKE DIDN'T GET IT YET NEED TO FOLLOW UP
196942	REPAIR OF EQUIPMENT		7/7/2015	42192	\$62.90
	Comments: ASSIT WITH COUTER BALANCE				
					ASSITED WITH REMOVAL OF COUNTER BALANCE
196955	REPAIR OF EQUIPMENT		7/7/2015	42192	\$294.51
	Comments: REPAIR COUNTER BALANCES				
					REMOVED PLATE FROM ROD SIDE TOOK OFF TOP PLATE AND PULLED OUT RODS REMOVED PACKING FROM CYLINDER
196966	REPAIR OF EQUIPMENT		7/7/2015	42192	\$70.00
	Comments: LOAD THE PRESS BED				
					LOADED THE PRESS BED ON A 18 WHEELER
196989	/I	7/16/2015	7/16/2015	0	\$0.00
197052	REPAIR OF EQUIPMENT		7/8/2015	42193	\$158.60
	Comments: CLEAN PISTONS CAPS NUTS AND BOLTS AND LCEAN OUT CYLINDERS				
					REPLACED SEAL ON PISTONS
					DID THE ABOVE
197055	REPAIR OF EQUIPMENT		7/8/2015	42193	\$294.51
	Comments: REBUILDING COUNTERBALANCE				
					TOOK PISTONS OFF OF RODS CLEANED PISTONS AND RODS SENT RODS OUT TOR REPAIR
					PUT SEALS IN PISTONS REMOVED BRASS SLEEVES FROM LOWER CAP PUT NEW SLEEVES IN
197244	REPAIR OF EQUIPMENT		7/22/2015	42207	\$107.93
	Comments: PULL BULL GEAR COVER				
					REMOVED ALL BUT TEN BOLTS ON COVER NEED TO HAVE COILS MOVED SO WE CAN GET TO COVER WITH BIG TOYOTA
197262	REPAIR OF EQUIPMENT		7/23/2015	42208	\$172.98
	Comments: REMOVE GEAR COVERS				
					ASSISTED WITH THE REMOVAL AND CLEANING FO GEAR COVERS
197748	REPAIR OF EQUIPMENT		7/25/2015	42210	\$15.73
	Comments: INSTALL SIGHT GLAS OF BULL GEAR COVER				
					INSTALLED AND SEALED SIGHT GLASS ON EAST BULL GEAR COVER

## Asset/Equipment Work Order History Brief

197750	REPAIR OF EQUIPMENT	7/23/2015	42208	\$620.40
	Comments: REMOVE BULL GEAR COVERS			
	REMOVED COVERS ON EAST BULL GEAR CLEANED UP COER NEED TRV OR SIMILAR SEALNT FOR FINISH SIGHT GLASS REPAIR ALSO NOTICED THAT KEYS HAVE BACKED OUT OF SHAFT 1.5 ON EAST END BULL GEAR			
197881	REPAIR OF EQUIPMENT	7/17/2015	42202	\$287.80
	Comments: DRAIN OIL FROM PRESS			
	DRAIN EAST SIDE BULL GEAR CASE DRAIN WAS STOPPED UP LOTS OF BRASS SHOWING DRAINED WESTSIDE BULL GEAR CASE DRAIN WAS CLEAR UT BRASS SOWING IOIL RECOMMENDED PULLING BOTH COVER TO INSPECT FURTHER RECOMMENDED PULING INSPECTION PLATE FOR FURTHER INSPECTION			
197987	REPAIR OF EQUIPMENT	8/6/2015	42222	\$107.93
	Comments: REPAIR GASKET WHERE IT IS LOOSE			
	SAME			
198006	REPAIR OF EQUIPMENT	8/6/2015	42222	\$215.85
	Comments: CHECK LONGITUDINAL PALLY ON CRANKSHAFT			
	PULLED CRANKSHAFT AS FAS EAST AS WE COULD WITH LIFT TRUCK. TOOK READING WITH DIAL INDIATOR THEN MOIVED CRANKSHAPFT AS FAR WEST WITH LIFT TRUCK THEN TOOK ATOHER READING THE DIFF IS .04 CLAEB HAS IT ON VIDE IF YOU ARE REALLY BORED AND WANT TO WATCH IT IT DOES SHOW IT WELL			
198380	REPAIR OF EQUIPMENT	8/26/2015	42242	\$167.90
	Comments: REINSTALLING COUNTER BALANCE			
	MOUNTED PISTONS TO RODS MOVED FEEDER OUT OF THE AY PUT ONE SIDE BACK IN			
198432	REPAIR OF EQUIPMENT	8/27/2015	42243	\$140.00
	Comments: HELP WITH REPLACING COUTER BALANCE CALL PRESS DOCTOR WITH INFOR ON SLIDE ADJUSTMENT			
	HELP WITH COUNTER BALANCE SHAFT AND CAP BACK IN CALLED PRESS DOCTORS WITH SLIDE ADJUSTMENT 12'			
199002	REPAIR OF EQUIPMENT	9/1/2015	42248	\$96.13
	Comments: ASSIT PRESS DOCTOR CONTRACTORS			
	ASSISTED CONTRACTORS WITH INSTALLATION OF REBUILT RAM FOR PRESS 38. SECURED COLLARED BOLTS TO FASTEN KNUCKLE TO DRIVE. SECURED COUNTER BALANCE BRACKETS TO RAM			
199009	REPAIR OF EQUIPMENT	9/3/2015	42250	\$351.53
	Comments: ASSISTING PRESS DOCTORS IN TESTING PRESS AFTER RAM INSTALLATION			
	FILLED BULL GEAR ON PANEL SIDE PUT 1/2 GALLON OF OIL IN EACH COUNTERBALANCE CYLINDER POWERED UP BUT DID NOT HAVE CONTROL VOLTAGE. WE FOUND A SHORT ON REAR PALM BUTTON STATION THE ENCLOSURE FOR ESTOP WAS TOO NARROW FOR THE NEW ESTOP THAT HAD BEEN INSTALLED WE REMOVED ESTOP AND REPLACED FUSE AND GOT CONTROL VOLTAGE PRESS STILL WOULDN'T STROKE DUE TO AN ERROR ON THE DYMAX WE RESET ERROR ON SYNTAX WE WERE ABLE TO STROKE IT THEN WE SET HEIGHT OF SLIDE ADJUST			
199015	REPAIR OF EQUIPMENT	9/2/2015	42249	\$140.00
	Comments: HELP WITH REBUILIDNG OL RAM			
	GOT HYD HOSES FOR LUBE SYSTEM FOR RAM AND CAM SHAFT			

## Asset/Equipment Work Order History Brief

199018	REPAIR OF EQUIPMENT		9/2/2015	42249	\$47.18
	Comments: BRACKET NEEDED FABRICATED TO MOUNT NEW LIMIT SWITCH FOR RAM ADJUST				
	FOLLOWED WHERE IT NEEDED TO BE WELDED NEW PIECE ON THE BRACKET DRILLED NEW HOLES TO MOUNT SWITCH				
199020	REPAIR OF EQUIPMENT		9/2/2015	42249	\$925.18
	Comments: INSTALL BULL GEAR COVER				
	INSTALLED COVER ON EAST END FINISHED AND FILLED GEAR BOX WITH 80W90 FILLED WEST END BULL GEAR WITH 80W90 DID NOT FILL EAST END DUE TO SILICONE NOT BEING CURED. CHRIS WILL FILL IN THE AM ALSO HELPED CHRIS LOOK FOR WIRING DIAGRAMS FOR CONTROL CIRCUIT				
199039	REPAIR OF EQUIPMENT		9/4/2015	42251	\$433.70
	Comments: REASSEMBLING EVERYTHING FROM THE BREAKDOWN				
	SET FEEDER BACK INTO PLACE BOLTED IT TO THE PRESS. CHRIS WAS CHECKING ALL THE WIRING TO GROUND TO MAKE SURE OF NO SHORTS.				
	SET THREAD GATE BACK INTO PLACE ANCHORED IT DOWN HOOKED AIRLINES BACK UP ALSO BOOTED ELECTRICAL UP TURNED AIR ON AND CHECKED THREAD GATE. WORKED GOOD				
199095	WEEKLY SAFETY INSPECTION PERF	7/23/2015	9/11/2015 8:19:29 AM	50	\$10.50
199201	WEEKLY SAFETY INSPECTION PERF	9/18/2015	9/21/2015 8:02:05 AM	3	\$0.00
199397	WEEKLY SAFETY INSPECTION PERF	9/28/2015	10/16/2015 8:07:22 AM	18	\$10.50
199503	REPAIR OF EQUIPMENT		9/29/2015	42276	\$87.71
	Comments: ASSIT WITH RAM CYCLING AND FEEDER CYCLING				
	CHECKED EDDY CURRENT BOARD OK ADJUSTED MOTOR SPEED POTENTION A METER AND RAM WEIGHT COUNTER BALANCE AIR PRESSURE RAM BEGAN CYCLING WILL NOT ADJUST SPEED				
199504	REPAIR OF EQUIPMENT		9/29/2015	42276	\$164.15
	Comments: JROD WANTEDME TO CHECK SPEED CONTROL PROBLEM ON 38				
	CHECKED WIRING COMPONENTS FOR BODY CURRENT DRIVE, OUTPUT TO CLUTCH AT CONSTANT 59V WILL NOT ADJUST REPLACED DRIVE BOARD AND ADJUSTED MINIMUM SPEED TO 5SPM ADJUSTED MAXIMUM SPEED TO 21 PSM ALSO FOUND NO 1 RELAY ON CAM LAYING IN BOITOM OF CABINET PUT IT BACKIN IS SLOT				
199553	REPAIR OF EQUIPMENT		9/30/2015	42277	\$300.80
	Comments: FINISH PUTTING EVERYTHING BACK TOGETHER				
	PUT ONE GUARD POLE BACKUP AND RAN YELLOW SAFETY DRAIN FROM MANUAL TO PRESS				
	PUT CHANNEL IRON BACK DOWN OVER THE HOSES IN THE FLOOR CLEANED UP AND PUT UP THE ESTOP THE STUFF WE HAD OUT THERE WATCHED AROUND FOR THEM TO SET THE DIE TO MAKE SURE IT WAS WORKING				
199800	MONTHLY PM FOR AUTOMATIC PRE	10/30/2015	10/29/2015	0	\$53.96
200203	REPAIR OF EQUIPMENT		10/12/2015	42289	\$33.23
	Comments: DIE WITH ITS ARCH KICKOFF IS NOT WORKING				
	PROGRAMMED THE EASIESST TIME AND TIME OFF ON CIRCUIT24				
200276	WEEKLY SAFETY INSPECTION PERF	10/23/2015	11/2/2015 10:35:20 AM	10	\$0.00

## Asset/Equipment Work Order History Brief

Work Order ID	Description	Date	Quantity	Amount
200325	REPAIR OF EQUIPMENT Comments: NEED SPROCKET FOR RAM ADJUSTMENT WENT TO TUPELO BEARING SUPPLY TO GET SPROCKET FOR 38 RAM ADJUSTMENT	10/19/2015	42296	\$15.73
200365	REPAIR OF EQUIPMENT Comments: INSTALL NEW 30 POWER CABLE REMOVED OLD CONDUIT FLEX AND CALBE REWOREKED 2ND CONDUITINSTALLED 3/0 CABLE FROMBUS BAR INTO CONTROL CABINET	10/21/2015	42298	\$234.35
200373	REPAIR OF EQUIPMENT Comments: CONTRACTORS BRAKE LEGON BUSE PLUG WE PUT IN ANOTHER BUSS PLUG WE PULLED WIRE THROUGH PULLING ELBOW TERMINATED WIRES AND WHEN I TRIED STAFF WIRED DOWN TO GET COVER ON ELBOW WE BROKE THE LASTIC ON LUG AGAIN WIRE WAS TOO BIG FOR THIS BUS THE BUS IN APT HEAVY DUTY ENOUGH TO SUPPORT WIRE	10/22/2015	42299	\$234.35
200382	REPAIR OF EQUIPMENT Comments: CHANGE 240 BUS PLUG TO 480V BUS PLUG REROUTE WIRE SUPPLY DROPS FOR PRESS USE CHANGE 240V 100 AMP BUSPLUG TO A 480 100 AMPBUS PLUG REROUTE AND CONNECTED AIR SUPPLY DROPS FOR PRESS USE BEFORE GUARDING TO BE PUT INTO PLACE	10/23/2015	42300	\$332.25
200387	REPAIR OF EQUIPMENT Comments: ASSIST WITH MOVING FENCE TO PRESS MOVED FENCE TO PRESS	10/24/2015	42301	\$31.45
200419	REPAIR OF EQUIPMENT Comments: PRE FABRICATED GUARDING READY TO BE ASEMLBEOUT PRESS 38 REMOVE OBSTACLES FROMAREA BLOPERS TRASH, AIR LINES, OLD CONTROL CABINET SORTED PREASSEMBLEDGUARDING ASSEMBELD ACCORDING TO LAY OUT PRINT BOLTED TOGETHER PLACED CAUTION TAPE AROUND MANDREL FEEDER AREA FOR SAFETY	10/24/2015	42301	\$391.60
200422	REPAIR OF EQUIPMENT Comments: REMOVE 100 AMP BUS PLUG AND REINSTALL WITH ANOTHER 100 AM PLUG REMOVED 100 AMP PLUG FORM BUS BAR INSTALLED NEVER 100 AMP BUS PLUG REWIRED AND ENGAGED POWER TO PRESS 38 SUPPLY CABINET REINSTALLED BUS PLUG AT BUS WAY 13	10/22/2015	42299	\$78.63
200428	REPAIR OF EQUIPMENT Comments: REALIGNMENT OF GUARDING AND MODIFICATION BEFORE ANCHORING BEGAN MODIFICATION ON WEST GUARDING	10/26/2015	42303	\$31.45
200430	REPAIR OF EQUIPMENT Comments: LINK GUY GIVING US NOT OVERVIEW OF THE NEW CONTROLS WENT THORUGHJAND REPLACED ABOUT TEHECONTACTS	10/26/2015	42303	\$99.68
200560	REPAIR OF EQUIPMENT Comments: STARTED MOUNTING THE GUARDS TRIED GETTING THE GUARDS IN LINE WITH THE DRAWINGS	10/26/2015	42303	\$283.30
200566	REPAIR OF EQUIPMENT Comments: GUARDING THE FEED LINE ANCHORING GUARDS MODIFYING GUARDS TO FIT LIKE WE NEED THEM TO	10/28/2015	42305	\$199.35

## Asset/Equipment Work Order History Brief

200591	REPAIR OF EQUIPMENT		10/28/2015	42305	\$183.63
	Comments: GUARDING				
	WENT BACK PUTTING 4 ANCHORS IN ALL THE PARTS WAS HELPING MODIFY THE DORS TO GET THEM HUNG REMOVED PHOTO ON FEEDER AND GOT THAT WIRED ANCHORED CABLE TRAY NOT TO FEEDER CUT A NEW TOP TO GO ON IT				
200598	REPAIR OF EQUIPMENT		10/30/2015	42307	\$46.94
	Comments: NEW GUARDING				
	HELPED WITH MAKING GUARDING				
200827	MONTHLY PM FOR AUTOMATIC PRE	11/30/2015	12/10/2015	10	\$53.96
200828	WEEKLY SAFETY INSPECTION PERF	11/9/2015		0	\$0.00
201104	REPAIR OF EQUIPMENT		11/3/2015	42311	\$46.94
	Comments: FENCING				
	ASSISTED IN FABRICATION AND INSTALLATION OF FENCING				
201112	REPAIR OF EQUIPMENT		11/4/2015	42312	\$66.45
	Comments: CONTINUE WITH MODIFICATION TO ELECTRICAL SERVICE FOR MANDREL INSPECTED SYSTEM FOR WIRING E STOP ON MANDREL ALSO FOR MANDREL COIL BED				
201119	REPAIR OF EQUIPMENT		11/3/2015	42311	\$398.70
	Comments: TRIP HAZARDS TO BE ELIMINATED				
	RUBBER AIR HOSE STRAIGHTENER CONDUIT AND REROUTED ALONG FLOORING EXISTING RUBBER AIR HOSES PLACED WITHIN OLD CABLE TRAY SECURED TO FLOOR				
201141	REPAIR OF EQUIPMENT		11/5/2015	42313	\$99.68
	Comments: MOUNT SAFETY BLOCK HOUSINGS AT DESIGNATED POINTS				
	TESTED PAINT TO ENSURE HOUSINGS WERE DRY MOUNTED EACH HOUSING AT PROXIMITY OF SAFETY BLOCK CONNECTION MODIFIED PENDANT FOR COIL BED, INSTALLED E STOP BUTTON, WIRE SYSTEM INTO CONTROL VOLTAGE TERMINAL FROM STEP DOWN TRANSFORMER				
201149	REPAIR OF EQUIPMENT		11/7/2015	42315	\$235.88
	Comments: BEGIN RUNNING CONDUIT FOR FEEDER CONTROL PANEL/ SAFETY CIRCUITS				
	RECEIVED INSTRUCTION ON CONDUIT PLACEMENT FOR SAFETY CIRCUITS AND FEEDER PANEL/WERE ABLE TO ONLY GET THE CONDUIT AND WIRING FOR THE FEEDER PANEL BOX/ SYSTEM IS SECURED				
201172	REPAIR OF EQUIPMENT		11/9/2015	42317	\$220.15
	Comments: CONTINUE ON MODIFICATIONS				
	WIRED PENDANT FINISHED PAINT SCRAP GUARD TOUCH UP PAINT ON ALL GUARDING				
201182	REPAIR OF EQUIPMENT		11/10/2015	42318	\$468.70
	Comments: MODIFICATION OF GUARDING SAFETY CIRCUIT				
	ALMOST COMPLETED CONDUIT APPLICATION FOR WIRING OF SAFETY CIRCUITS ALL ANCHORED EITHER TO FLOORING AT GUARDING				
201228	REPAIR OF EQUIPMENT		11/10/2015	42318	\$349.75
	Comments: ADDING SAFETY GUARDS				
	PUT GUARD BACK ON FEEDER. GOT SUPPLIES READY TO START RUNNING CONDUIT FOR SAFETY GATES. STARTED WIRING UP NEW PENDANT WITH FEED ROLLS ON AND OFF SWITCH. PASS ON TO SECOND SHIFT				

## Asset/Equipment Work Order History Brief

Work Order ID	Description	Date	Quantity	Amount
201229	REPAIR OF EQUIPMENT Comments: WIRE SAFETY CIRCUITS AND ESTOP WIRED SAFETY CIRCUITS AND E STOPS INTO MAIN CONTROL CABINET ALL SYSTEMS SHOULD BE RAEDY TO CHECK	11/11/2015	42319	\$498.38
201236	REPAIR OF EQUIPMENT Comments: ADDING SAFETY FEATURES FINISHED TERMINATING WIRES TO PEMBERTON FEEDER NEATENED UP WIRES IN FEEDER CABINET	11/11/2015	42319	\$52.50
201258	REPAIR OF EQUIPMENT Comments: FAB GUARD FOR CABLE TRAY AND STRAIGHTENER CLEAN UP GENERAL AREA FAB AREA AND CLEAN UP	11/12/2015	42320	\$220.15
201263	REPAIR OF EQUIPMENT Comments: TAPE AL POSSIBLE TRIP HAZARDS WITH SAFETY TAPE RE MANUFACTURED STRAIGHTENER GUARD FOR SOLID MATERIAL ESTOP NEEDING NC CONTACT FOR ADDITONAL OPERATION SWEEP AREA NOT USED/ WIPED AREAS THAT WERE TO BE TAPED/ CUT TAPE TO LENGTH AND APPLYREMANUFACTURED TOP ROLLER GUARD FOR STRAIGHTENER USING MATERIAL SOLID PIECE SLOT FOR GREASE ALIGNITES AND BOLTS PULLED WIRING FROM MANDREL COIL SLED TO STRAIGHTENER CONTORL CABINET/ ADDED TERMINAL BLOCKS AND BREAK K120V CONTROL VOLTAGE TO STRAIGHTENER AND MANDREL AND COIL SLED	11/12/2015	42320	\$561.50
201289	REPAIR OF EQUIPMENT Comments: NEED 120V OUTLET FOR LFIT TABLE MODIFY GUARDING REROUTED NEW WIRING FROM CONTROL CABINET TO STRIAGHTENER CONTROL CABINET BYPASSED TO WEST SIDE OF STRAIGHTENER AND MOUNTED MOIDIFIED GUARDING AND SCRAP SLIDE PAINTED AFTER WILL MOUNT TO STRAIGHTENER TOMROROW HAD FABRICATION LEADPERSON ASSIT WITH GUARD MODIFICATION	11/13/2015	42321	\$363.70
201294	REPAIR OF EQUIPMENT Comments: REPLACE LIFT TABLE FOOT PEDAL CORDS EXPOSED WIRING LIFT TABLE WONT GO UP JACK UP AND REFILL HYDRAULIC RESERVOIR REDO POWER CORD FOOT PEDAL CORD TRY TO REMOVE TRIP HAZARDS MAKE HOLDER FOR OPERATORS MANUAL AND MOUNT IT AT THE BACK OF LINK CONTROL CLEAN UP AREA PICK UP ALL SCRAP WIRE	11/14/2015	42322	\$210.00
201301	REPAIR OF EQUIPMENT Comments: NEED A WAY TO HANG PENDANTS STARTED MAKING THROUGHES TO SET PENDANTS IN	11/14/2015	42322	\$35.00
201304	REPAIR OF EQUIPMENT Comments: REPLACING CABLE TRAY ON MANDREL CUT WIRE FOR RUN BETWEEN COIL CART AND CONTROL PANEL	11/14/2015	42322	\$66.45
201319	REPAIR OF EQUIPMENT Comments: MOUNT EXISITING SAFETY COVERS ON STRAIGHTENER MANUFACTURE SAFETY HOUSINGS FOR PENDANTS WIHTIN SYSTEM LOCATED SEVERAL GAUGES OF SCRAP METAL BEAN SHAPPNG PROTO TYPEE OF SAFETY HOUSING DECIDED TO USE 18 GAUGE STEEL WITH MOUNTING TO ALLOW PENDANTS TO BE REMOVED STORED SAFETY\MOUNT 4 HOUSINGS FORPENDANTS AND 1 FOR METAL SNIPPS SHEARS TO BE STORED SAFELY	11/14/2015	42322	\$188.70

## Asset/Equipment Work Order History Brief

201321	REPAIR OF EQUIPMENT	11/16/2015	42324	\$47.18	
	Comments: PAINT PENDANT HOLDERS PAINTED PENDANT HOLDERS 3 COATS OF PAINT REMOVED TAPE SAFETY ORANGE IS THE COLOR PAINTED				
201359	REPAIR OF EQUIPMENT	11/19/2015	42327	\$225.60	
	Comments: ADD SAFETY SHUT OFF VALVE REPLACE HOSE AT VANISHING OIL LUBELINE TURN OFF MAIN AIR VALVE, HARD TO GET TO IT WITH THE NEW GUARDS AROUND THE PRESS REMOVE OLD BALL VALVE ADD SAFETY SHUT OFF VALVE AND STRAIGHTENE UP FITTINGS QUICK CONNECTORS AND FEEDER REGULATOR SECURE PIPE WITH BEAM CLAMPS REPLACE HOSE WITH 1/2" HARD PIPE CHECK FOR VANISHING OIL LEAKS, OK				
201494	REPAIR OF EQUIPMENT	11/25/2015	42333	\$52.50	
	Comments: SIGNS NEED MOUNTING MOUNTED SIGNS ON DOORS FORPAD				
201681	REPAIR OF EQUIPMENT	11/30/2015	42338	\$43.75	
	Comments: STATION 2 FRONT NEEDS AUTO SET UP BUTTON ADD MOMENTRAY PUSH BUTTON NO CONTRACT WIRE TO OP3 AND S59 SQUARE WIRE PARALLEL WIRING TO PS1 AND 14 RELABEL SQUARE WIRING CHECK CONTINUITY OK NEED TO CHECK OPERATON				
201695	REPAIR OF EQUIPMENT	12/1/2015	42339	\$17.50	
	Comments: STRAIGHTEN UP OVERHEAD LIGHT FIXTURE STRIAGHTEN UP LIGHT FIXTURE IN FRONT OF PRESS 38				
201970	REPAIR OF EQUIPMENT	12/9/2015	42347	\$66.45	
	Comments: NEED PLUG WIRED INOT A PLS FOR PART KICKOFF ON SAME DIES GATHERED MATERIALS AND DRILLED AND TAPPED HOLE FOR JUNCTON BAY I PASSED ON TO JOSE				
201980	REPAIR OF EQUIPMENT	12/9/2015	42347	\$113.75	
	Comments: ASSIT DAY SHIFT NEED TO ADD CONTROL FOR DIE VALVE PART KICK REWIRE MALE PLUG FOR VALVE COIL RUN CONDUIT/WIRE TO COTNROL VALVE WIRE TO PLS-6 NOCONTACT WIRE NEUTRAL 30 OZ COMMON WRIE TO 390 120V NEED TO PROGRAM PLS-6				
202263	REPAIR OF EQUIPMENT	12/16/2015	42354	\$78.63	
	Comments: STUCK ON BOTTOM INHIBIT ALARM TRIED REVERSING THE MOTOR BUT IT WOULD NOT DO ANYTHING WITH THE ALARMON SOMBOY THE SHEET HEIGHT WAS IDFFERNT FORM THE ACUTARL HEIGHJT WE CHAGNED THE SHOT HEIGHT TO THE SAME AS THE ACTUAL				
202826	ANNUAL PM FOR PRESS	1/15/2016	1/29/2016	14	\$139.60
202827	MONTHLY PM FOR AUTOMATIC PRE	1/11/2016	1/13/2016	2	\$53.96

## Asset/Equipment Work Order History Brief

203146	REPAIR OF EQUIPMENT		12/30/2015	42368	\$33.23
	Comments:	WRONG FUSES FOR RAM ADJUST MOTOR CHANGED FOR A LARGER FUSE HOLDER IT NEEDED FUSES WITH A LARGER VOLT ROTATING			
203190	REPAIR OF EQUIPMENT		1/5/2016	42374	\$33.23
	Comments:	HAD IT ON BOTTOM AND COULD NOT GET IT UP HAVE TO HOLD THEM MOTOR ENABLE AND STATER BETWEEN THE SCREEN AND HOLD BOTH OF THEM WHILE SOMEONE ELSE IN REVERSE THE STARTER DOESN'T LATCH IN REVERSE GOT IT BACK TO TOP AND SHE ADJUSTED RAM ADJUST			
203796	MONTHLY PM FOR AUTOMATIC PRE	2/12/2016	2/11/2016	0	\$53.96
204446	REPAIR OF EQUIPMENT		2/22/2016	42422	\$193.45
	Comments:	PLEASE CHECK AND LEVEL RAM AS NEEDED CHECKED LEVEL OF RAM FOUND IT OUT OF SPEC .005 ONE END OF JG WEST WAS DRY SO I FILLED IT AND STROKED IT BUT IT DIDN'T CHANGE BROKE ADJUSTMENT AND LEVELD RAM STORKED AND CHECKED AGAIN STAYS WITHIN .002 SIDE TO SIDE			
204756	MONTHLY PM FOR AUTOMATIC PRE	3/14/2016	3/11/2016	0	\$0.00
205079	REPAIR OF EQUIPMENT		3/3/2016	42432	\$40.50
	Comments:	LEVEL RAM LEVELED RAM WITH PRESS SET 70PSI GOT WITHIN .0015 STROKED SEVERAL TIMES MOVED SLIDE UP AND DOWN STROKED SEVERALMORE TIMES STILL WITHIN .0015 THAT AS CLOSE AS IVE SEEN THAT PRESS			
205883	MONTHLY PM FOR AUTOMATIC PRE	4/11/2016	4/20/2016	9	\$53.96
206132	REPAIR OF EQUIPMENT		4/5/2016	42465	\$99.68
	Comments:	LEFT SIDE SCREW CAME OUT OF BRACKET RAN SCREW BACK OUT AND PUT BACK IN BRACKET AND TIGHTENED UP			
206311	REPAIR OF EQUIPMENT		4/14/2016	42474	\$103.40
	Comments:	LUBE RESERVOIR LEAKS REPAIRED LEAK BY SWAPPING GASKET REFILLED AND HOLDING FOR NOW			
206855	MONTHLY PM FOR AUTOMATIC PRE	5/20/2016	5/24/2016	4	\$30.38
207392	REPAIR OF EQUIPMENT		5/16/2016	42506	\$201.13
	Comments:	NEW FAN AT FEEDER MADE PALTE AND MOUNTED FAN			
207396	REPAIR OF EQUIPMENT		5/16/2016	42506	\$40.50
	Comments:	PARTS LUBE QUIT WORKING FOUND COIL OFF OF VALVE PUT COIL BACK ON AND TIED IT DOWN			
207858	MONTHLY PM FOR AUTOMATIC PRE	6/23/2016	6/29/2016 7:54:08 AM	6	\$53.96
208991	MONTHLY PM FOR AUTOMATIC PRE	7/29/2016	7/22/2016 7:40:28 AM	0	\$60.75
209935	MONTHLY PM FOR AUTOMATIC PRE	8/22/2016	8/24/2016 7:35:46 AM	2	\$60.75

## Asset/Equipment Work Order History Brief

210390	REPAIR OF EQUIPMENT		8/8/2016		42590	\$15.73
	Comments:	FAULT ON INPUT 39 AND 40				
		COULDN'T FIND PRINT IN CABINET BUT AFTER TURNING POWER BACK ONIT RESET THE FAULT LOOKED UP PRINTS AND IT WAS FAULTED ON DIE BLOCK ON REAR OF PRESS				
211090	MONTHLY PM FOR AUTOMATIC PRE	9/23/2016	9/23/2016		0	\$60.75
212259	MONTHLY PM FOR AUTOMATIC PRE	10/24/2016	10/27/2016 7:57:05 AM		3	\$60.75
213171	MONTHLY PM FOR AUTOMATIC PRE	11/28/2016	11/18/2016		0	\$60.75
214050	MONTHLY PM FOR AUTOMATIC PRE	12/19/2016	12/30/2016 9:54:40 AM		11	\$60.75
214516	REPAIR OF EQUIPMENT		12/13/2016		42717	\$0.00
	Comments:	RAM ADJSUT MOTOR MAKING BAD NOISE				
		BLOWN FUSE CAUGING MTORO TO SINGLE PHASE REPLACED FUSE				
214538	REPAIR OF EQUIPMENT		12/20/2016		42724	\$0.00
	Comments:	RAM ADJUST INDEX NOT RUNNING				
		HAD TO REPLACE BLOWN FUSE				
214960	ANNUAL PM FOR PRESS	1/30/2017	4/3/2017 11:40:40 AM		63	\$139.60
214961	MONTHLY PM FOR AUTOMATIC PRE	1/30/2017	2/18/2017		19	\$60.75
215305	REPAIR OF EQUIPMENT		1/4/2017		42739	\$31.45
	Comments:	SLIDE ADJUSTMENT NO OPERATING				
		OPERATOR SUGGED SLIDE ADJUSTE WENT MOTOR CHECKED FUSES CHANGED ONE SYSTEM OK				
215487	REPAIR OF EQUIPMENT		1/20/2017		42755	\$17.50
	Comments:	RAM ADJSUT WONT MOVE				
		REPLACED FUSE IN RAM ADJUST MOTOR				
216624	MONTHLY PM FOR AUTOMATIC PRE	3/20/2017	4/3/2017 12:19:44 PM		14	\$0.00
216842	REPAIR OF EQUIPMENT		3/2/2017		42796	\$35.00
	Comments:	RAM ADJSUT WONT MOVE				
		CHECKED FUSES AND FUSES WERE GOOD CHECKEDTO SEE IF RAM ADJSUT WAS IN A BIND IT WAS TURNING FREELY FOUND A WIRE TAHTW AS BROKECOMPLETELY INTO CUT BACK AND RESTIPPRED THE INCOMING POWER CORDA ND RETERMIANTED				
216971	REPAIR OF EQUIPMENT		3/10/2017		42804	\$35.00
	Comments:	PART CATCHER NEEDS REPAIR				
		WELDED END OF CATCHER PUT A BRACE UNDERNEATH TO HELP BETTER SUPPORT PARTS I ALSO CUT AND BOLTED A PIECE OF VHMW OS PARTS WOULDN'T GET SCRATCHED OR DAMAGED				
218176	MONTHLY PM FOR AUTOMATIC PRE	5/3/2017	6/8/2017 12:54:57 PM		36	\$60.75
218419	REPAIR OF EQUIPMENT		4/27/2017		42852	\$52.50
	Comments:	ACHOR STICKING UP IN THE FLOOR				
		TOOK TORCH AND OUT ANCHOR I HAD TO DO SOME WORK ON THE TORCH				

## Asset/Equipment Work Order History Brief

218420	REPAIR OF EQUIPMENT		4/27/2017		42852	\$35.00
	Comments:	ANCHOR BOLTS STICKING UP  REMOVED ONE TRIED TO GET OTHER ONE UP BUT COULDN'T I NEED TO FOLLOW UP AND TAKE TORCH AND CUT IT OUT I PUT A CONE OVER IT UNTIL I HAD TIME				
218794	REPAIR OF EQUIPMENT		5/23/2017		42878	\$35.00
	Comments:	THREAD GATE WONT FULLY RETRACT  I DETERMINED THAT THE MANNAULLY OPERATED VALVE IS NOT EXHAUSTING I NEED TO FIND ANOTHER VALVE				
219923	MONTHLY PM FOR AUTOMATIC PRE	7/10/2017	9/1/2017 7:54:41 AM		53	\$60.75
221010	REPAIR OF EQUIPMENT		8/10/2017		42957	\$35.00
	Comments:	FAN BURNT OUT  REPLACED FAN				
221014	REPAIR OF EQUIPMENT		8/10/2017		42957	\$31.45
	Comments:	NO FAN WORKING FOR OPERATOR  CHECKED ONE FAN BURNED UP OPERATOR REQUESTED FANCHAGNE CHRIS CHANGED LAST NIGHT SEARCHED FOR CIRCUIT FOR OTHER FAN COULD NOT LOCATE THIS CIRCUIT POSSIBLE THIS CIRCUIT IS NOT CONNECTED				
222245	MONTHLY PM FOR AUTOMATIC PRE	10/2/2017	11/18/2017 11:32:37 AM		47	\$60.75
223137	MONTHLY PM FOR AUTOMATIC PRE	11/20/2017	12/21/2017		31	\$60.75
223650	REPAIR OF EQUIPMENT		11/16/2017 8:16:55 AM		43055	\$17.50
	Comments:	- LOUD NOISE FROM RAM - CHECK FOR AIR LEAKS AT THE RAM - CHECK FOR AIR LEAKS AT THE TOP OF PRESS - COULD NOT FIND THE AIR LEAK				
224744	MONTHLY PM FOR AUTOMATIC PRE	1/22/2018	2/20/2018		29	\$60.75
226136	REPAIR OF EQUIPMENT		3/2/2018		43161	\$35.00
	Comments:	Oil leak creating a slip hazard at Prss 38 Clean up spilled oil, clean the press, oil droplets, to try to fix oil leak. Hard to tell where is leaking.				
226300	MONTHLY PM FOR AUTOMATIC PRE	3/22/2018	5/3/2018		42	\$60.75
226814	ANNUAL PM FOR PRESS	4/3/2018	8/3/2018 7:50:55 AM		122	\$81.00
228117	MONTHLY PM FOR AUTOMATIC PRE	6/4/2018	7/19/2018		45	\$60.75
228517	REPAIR OF EQUIPMENT		6/19/2018		43270	\$87.50
	Comments:	Help load presses to be shipped out. Presses 32 & 38, small break presses.  Help moved presses out and loaded on 18 wheeler for shipment to another Philip plant.				
229319	MONTHLY PM FOR AUTOMATIC PRE	8/6/2018	8/17/2018		11	\$60.75

## Asset/Equipment Work Order History Brief

229906	MONTHLY PM FOR AUTOMATIC PRE	9/17/2018	10/27/2018 8:29:07 PM	40	\$60.75
231594	MONTHLY PM FOR AUTOMATIC PRE	12/21/2018	1/3/2019 7:12:04 AM	13	\$60.75
233090	MONTHLY PM FOR AUTOMATIC PRE	3/4/2019	4/24/2019 9:33:12 AM	51	\$60.75
233338	REPAIR OF EQUIPMENT		3/14/2019 2:56:05 PM	43538	\$35.00
	Comments: Vanishing oil nozzles on all the time.				
234132	MONTHLY PM FOR AUTOMATIC PRE	5/28/2019	7/16/2019 12:02:51 PM	49	\$60.75
234326	REPAIR OF EQUIPMENT		5/21/2019 10:09:56 PM	43606	\$70.00
	Comments: Material vanishing oil lubricator not working.				
234567	WEEKLY SAFETY INSPECTION PERF	6/13/2019	7/15/2019 8:54:19 AM	32	\$10.50
235359	ANNUAL PM FOR PRESS	8/5/2019	8/23/2019 1:24:03 PM	18	\$81.00
235360	WEEKLY SAFETY INSPECTION PERF	7/29/2019	8/12/2019 8:00:10 AM	14	\$10.50
235625	MONTHLY PM FOR AUTOMATIC PRE	9/3/2019	9/30/2019 7:55:06 AM	27	\$60.75
235626	WEEKLY SAFETY INSPECTION PERF	8/26/2019	9/16/2019 9:33:12 AM	21	\$10.50
235888	WEEKLY SAFETY INSPECTION PERF	9/30/2019	9/30/2019 8:19:01 AM	0	\$10.50
236076	WEEKLY SAFETY INSPECTION PERF	10/14/2019	10/17/2019 10:14:08 AM	3	\$10.50
236230	WEEKLY SAFETY INSPECTION PERF	10/31/2019	10/28/2019 3:41:47 PM	0	\$12.15
236427	MONTHLY PM FOR AUTOMATIC PRE	11/29/2019	1/9/2020 2:08:45 PM	41	\$60.75
236428	WEEKLY SAFETY INSPECTION PERF	11/11/2019	11/11/2019 3:56:32 PM	0	\$12.15
236758	WEEKLY SAFETY INSPECTION PERF	11/25/2019	12/4/2019 1:46:54 PM	9	\$12.15
236934	REPAIR OF EQUIPMENT		12/3/2019 4:24:53 PM	43802	\$121.50
	Comments: inspect press for damage				
	checked clearances on gibs, shut height comparisons, safety equipment, stroked press in inch mode, found no damage, every system appears to be working properly				
237122	WEEKLY SAFETY INSPECTION PERF	12/18/2019	1/28/2020 8:51:50 AM	41	\$12.15
237413	WEEKLY SAFETY INSPECTION PERF	2/4/2020	2/15/2020 2:35:51 PM	11	\$12.15
237762	MONTHLY PM FOR AUTOMATIC PRE	3/9/2020	3/31/2020 4:32:30 PM	22	\$60.75
237763	WEEKLY SAFETY INSPECTION PERF	3/2/2020	3/10/2020 10:09:00 AM	8	\$12.15

## Asset/Equipment Work Order History Brief

237928	WEEKLY SAFETY INSPECTION PERF	3/24/2020	3/26/2020 4:34:16 PM	2	\$12.15
238142	WEEKLY SAFETY INSPECTION PERF	4/9/2020	4/14/2020 4:20:27 PM	5	\$12.15
238474	WEEKLY SAFETY INSPECTION PERF	4/28/2020	4/30/2020 10:16:17 AM	2	\$12.15
238566	WEEKLY SAFETY INSPECTION PERF	5/14/2020	5/22/2020 10:43:18 AM	8	\$12.15
238713	MONTHLY PM FOR AUTOMATIC PRE	6/1/2020	6/10/2020 11:35:58 AM	9	\$60.75
238714	WEEKLY SAFETY INSPECTION PERF	6/8/2020	6/9/2020 2:29:25 PM	1	\$12.15
238921	WEEKLY SAFETY INSPECTION PERF	6/23/2020	7/14/2020 1:37:52 PM	21	\$12.15
239163	WEEKLY SAFETY INSPECTION PERF	7/28/2020	7/30/2020 3:04:11 PM	2	\$12.15
239491	ANNUAL PM FOR PRESS	8/24/2020	8/21/2020 11:16:08 AM	0	\$81.00
239492	MONTHLY PM FOR AUTOMATIC PRE	8/10/2020	9/2/2020 10:45:48 AM	23	\$60.75
239493	WEEKLY SAFETY INSPECTION PERF	8/12/2020	8/20/2020 4:35:44 PM	8	\$12.15
239801	WEEKLY SAFETY INSPECTION PERF	9/3/2020	9/21/2020 8:50:26 AM	18	\$12.15
239984	WEEKLY SAFETY INSPECTION PERF	9/17/2020	9/18/2020 7:29:01 AM	1	\$12.15
240134	MONTHLY PM FOR AUTOMATIC PRE	10/30/2020	11/5/2020 8:47:23 AM	6	\$60.75
240135	WEEKLY SAFETY INSPECTION PERF	10/5/2020	10/22/2020 10:17:35 AM	17	\$12.15
240390	WEEKLY SAFETY INSPECTION PERF	11/5/2020	11/5/2020 9:58:37 AM	0	\$12.15
240484	WEEKLY SAFETY INSPECTION PERF	11/19/2020	11/19/2020 10:53:04 AM	0	\$12.15
240674	WEEKLY SAFETY INSPECTION PERF	12/3/2020	12/7/2020 8:18:09 AM	4	\$12.15
240909	MONTHLY PM FOR AUTOMATIC PRE	1/4/2021	2/9/2021 10:57:21 AM	36	\$60.75
240910	WEEKLY SAFETY INSPECTION PERF	12/21/2020	1/25/2021 10:50:25 AM	35	\$12.15
241181	WEEKLY SAFETY INSPECTION PERF	2/23/2021	3/2/2021 10:12:08 AM	7	\$12.15
241406	WEEKLY SAFETY INSPECTION PERF	3/16/2021	3/16/2021 1:06:17 PM	0	\$12.15

## Asset/Equipment Work Order History Brief

241501	REPAIR OF EQUIPMENT	2/25/2021 3:45:00 PM	44252	\$1,858.25
	Comments: slide fault, will not clear			
	troubleshoot faults, corrected serial port issues, replaced auto set up module to no effect, replaced encoder/resolver, error cleared. Recalibrated slide, turned it loose.			
241520	REPAIR OF EQUIPMENT	4/8/2021 4:15:09 PM	44294	\$243.00
	Comments: wont hold air pressure			
	adjusted air press switch, started another compressor, adjusted pressure setting minimums on link control			
Totals For: <b>PRSS 038</b>		Total WOs: 1376	Total Cost:	\$71,346.00

**Asset ID: PRSS 038.0**      **Asset: SAFETY LIGHTS**

Work Order ID	Description	Scheduled Date	Completed Date	Days Past Due	Total Cost
2600	REPAIR SAFETY LIGHT ELECTRICAL		6/14/2000 2:08:27 PM	36691	\$10.17
6866	INSTALL SAFETY LIGHTS (NEW)		10/28/2000	36827	\$68.23
17761	REPAIR AND ADJUST		10/15/2001	37179	\$20.67
21037	REPLACE		2/11/2002	37298	\$35.96
28270	REPAIR SAFETY LIGHTS		9/12/2002 3:39:31 PM	37511	\$11.09
45550	REPAIR		4/8/2004 6:58:58 AM	38085	\$0.00
49452	REPAIR		8/4/2005	38568	\$0.00
124401	REPAIR OF EQUIPMENT		8/19/2009	40044	\$34.20
	Comments: ADJUSTED SAFETY LIGHTS.				
127333	REPAIR OF EQUIPMENT		10/28/2009	40114	\$51.30
	Comments: PARTS FROM DIE GETTING IN SAFETY LIGHT. MOVED DIE BACK 2"				
128471	REPAIR OF EQUIPMENT		11/23/2009	40140	\$363.55
	Comments: MOVED LIGHT CURTAIN OUT TO ALLOW NEW FBF DIE. HAD TO FABRICATE BRACKETS AND MOVE RUN BAR AS WELL.				
128504	REPAIR OF EQUIPMENT		11/24/2009	40141	\$68.40
	Comments: RAN NEW FLEX AND CONRTEOL WIRE				
172418	REPAIR OF EQUIPMENT		6/7/2013	41432	\$132.90
	Comments: RAM WON'T ADJUST AND PRESS WONT SLOW DOWN				
	FOUND THAT THE GUARD FOR RAM ADJUST WAS SHORTED WE FIXED CORD AN GOT IT OUT OF THE WAY.				
	WE CHECKED POT FOR SPEED POT WORKED FINE IT WAS TO IF VARIED CORRECTLY AND BOTH SIDES ADDED UP CORRECTLY. WE CHECKED SUPPLY VOLTAGE FOR DIRVE IT WAS CORRECT THE OUTPUT VOLTAGE WAS 56V IT WOULD NOT GO DOWN WHEN POT WAS TURNED POT WAS SHROTED TO A SCREW IN CABINET				
190053	REPAIR OF EQUIPMENT		12/15/2014	41988	\$33.23
	Comments: PARTS GETTNG IN LIGHT CURTAIN				
	OPERATOR WANTED US TO BLANK ANOTHER SENSOR CURTAIN ALREADY HAD THE MAX NUMBER OF BLANKS WE LOWERED THE ADJUSTEABLE TABLE TO GET PART OUT OF LIGHT CURTAIN				

## Asset/Equipment Work Order History Brief

Totals For: **PRSS 038.0** Total WOs: 13 Total Cost: \$829.68

**Asset ID: PRSS 038.1**      **Asset: FEEDER WITH ELECTRICAL CONTROLS**

Work Order ID	Description	Scheduled Date	Completed Date	Days Past Due	Total Cost
308	MONTHLY PM FOR FEEDER	4/5/2000	4/11/2000 10:14:43 AM	6	\$0.00
1034	REPAIR		4/28/2000	36644	\$20.03
1289	MONTHLY PM FOR FEEDER	5/11/2000	5/11/2000 7:34:09 AM	0	\$9.71
2421	MONTHLY PM FOR FEEDER	6/12/2000	6/27/2000 9:49:42 AM	15	\$9.94
3629	REPAIR RUN LIGHT		7/14/2000	36721	\$19.96
3667	ALINE AND ADJUST AIR PRESSURE		7/19/2000 6:05:35 AM	36726	\$63.48
3806	MONTHLY PM FOR FEEDER	7/27/2000	8/4/2000 6:12:07 AM	8	\$9.94
3955	REPAIR CHAIN		7/28/2000 5:45:17 AM	36735	\$35.61
5101	MONTHLY PM FOR FEEDER	9/5/2000	9/13/2000 6:30:19 AM	8	\$10.10
5195	REPAIR FEED		9/5/2000 9:33:40 AM	36774	\$0.00
5424	REPAIR LOW AIR PRESSURE		9/11/2000	36780	\$20.29
5580	REPAIR WIRING		9/15/2000	36784	\$0.00
6198	MONTHLY PM FOR FEEDER	10/13/2000	10/30/2000 1:29:26 PM	17	\$10.10
6228	REPAIR		10/6/2000	36805	\$11.99
6275	REPAIR ELECTRICAL WIRING		10/9/2000	36808	\$101.45
6495	REPAIR WIRING		10/16/2000 8:59:55 AM	36815	\$0.00
7588	MONTHLY PM FOR FEEDER	11/29/2000	12/12/2000 8:57:04 AM	13	\$10.10
7959	REPAIR BROKEN ELECT WIRE		12/6/2000	36866	\$121.74
8759	MONTHLY PM FOR FEEDER	1/11/2001	1/10/2001 8:07:30 AM	0	\$10.10
9687	MONTHLY PM FOR FEEDER	2/9/2001	3/27/2001 6:13:17 AM	46	\$10.10
10032	REPLACE BATTERY		2/13/2001	36935	\$89.56

## Asset/Equipment Work Order History Brief

10311	REPLACE BATTERY		2/19/2001		36941	\$20.29
11256	REPAIR		3/23/2001 9:07:32 AM		36973	\$0.00
12183	MONTHLY PM FOR FEEDER	4/26/2001	5/4/2001 8:05:37 AM		8	\$10.10
13550	MONTHLY PM FOR FEEDER	6/4/2001	6/7/2001 9:53:01 AM		3	\$10.10
14800	MONTHLY PM FOR FEEDER	7/9/2001	7/27/2001 6:50:55 AM		18	\$0.00
14962	REPLACE FILTER AND REGULATOR		7/12/2001		37084	\$52.29
15109	NSTALL 2 BOARDS ON FEEDER		7/14/2001		37086	\$27.29
15142	REPAIR		7/17/2001 3:42:53 PM		37089	\$19.91
16445	REPAIR SWITCH TO HIGHT ADJUST		8/24/2001		37127	\$40.58
16513	MONTHLY PM FOR FEEDER	8/27/2001	9/6/2001 1:26:53 PM		10	\$0.00
16914	REPAIR		9/12/2001 1:28:09 PM		37146	\$30.30
16946	REPAIR		9/14/2001 6:39:03 AM		37148	\$20.20
17531	MONTHLY PM FOR FEEDER	10/8/2001	11/27/2001 7:04:31 AM		50	\$0.00
19638	MONTHLY PM FOR FEEDER	1/1/2002	1/3/2002 8:50:52 AM		2	\$0.00
20105	ADJUST ROLLS		1/11/2002		37267	\$20.67
20708	MONTHLY PM FOR FEEDER	2/4/2002	2/6/2002 3:19:39 PM		2	\$10.10
20806	REPAIR WIRING		2/2/2002		37289	\$56.64
21606	MONTHLY PM FOR FEEDER	3/8/2002	3/8/2002 2:58:48 PM		0	\$10.10
22209	REALINE WITH PRESS		3/19/2002		37334	\$134.34
22830	MONTHLY PM FOR FEEDER	4/8/2002	4/8/2002 10:58:43 AM		0	\$10.10
23671	MONTHLY PM FOR FEEDER	5/8/2002	5/10/2002		2	\$10.10
24275	REPAIR HIGHT ADJUSTMENT		5/17/2002		37393	\$20.67
24914	MONTHLY PM FOR FEEDER	6/10/2002	6/26/2002 9:04:21 AM		16	\$10.85

## Asset/Equipment Work Order History Brief

25555	REPAIR		6/25/2002		37432	\$47.95
26185	REPAIR CHAIN		7/13/2002		37450	\$68.04
26255	REPAIR		7/17/2002		37454	\$21.41
26287	REPLACE CONTROL BATTERY		7/18/2002		37455	\$21.79
26294	REPAIR		7/19/2002		37456	\$47.95
26347	MONTHLY PM FOR FEEDER	7/26/2002	7/22/2002 8:47:35 AM		0	\$0.00
27262	REPAIR		8/12/2002		37480	\$22.31
27390	MONTHLY PM FOR FEEDER	8/21/2002	9/4/2002 8:41:17 AM		14	\$10.85
27842	REPAIR ELECTRICAL		8/28/2002		37496	\$108.95
28842	MONTHLY PM FOR FEEDER	10/4/2002	10/4/2002 7:16:22 AM		0	\$0.00
29863	ANNUAL PM FOR FEEDER	11/1/2002	2/19/2003 9:22:49 AM		110	\$49.66
30018	MONTHLY PM FOR FEEDER	11/4/2002	11/6/2002 12:40:43 PM		2	\$10.85
30734	MONTHLY PM FOR FEEDER	12/6/2002	12/5/2002 3:00:17 PM		0	\$10.85
31271	REPAIR		12/12/2002 9:17:50 AM		37602	\$42.82
31774	MONTHLY PM FOR FEEDER	1/6/2003	2/18/2003 6:39:31 AM		43	\$0.00
32135	REPAIR HIGHT ADJUSTMENT		1/11/2003		37632	\$96.60
32136	REPAIR HIGHT ADJUSTMENT		1/11/2003		37632	\$30.60
32139	WORK ON HIGHT CONTROL		1/11/2003		37632	\$30.59
32205	REPAIR		1/15/2003		37636	\$164.50
32347	REPAIR HIGHT ADJUSTMENT		1/23/2003		37644	\$66.51
32692	RAISE FEEDER		2/4/2003		37656	\$22.31
33544	REPLACE HIGHT CONTROL		3/1/2003		37681	\$546.84
33862	MONTHLY PM FOR FEEDER	3/20/2003	3/18/2003 7:07:22 AM		0	\$10.85

## Asset/Equipment Work Order History Brief

34255	REPAIR POWER SUPPLY			3/26/2003	37706	\$22.31
34794	REPAIR			4/8/2003	37719	\$22.31
34872	MONTHLY PM FOR FEEDER	4/17/2003	4/15/2003 10:17:39 AM		0	\$10.85
34951	REPAIR			4/10/2003	37721	\$22.31
34973	REPAIR			4/14/2003	37725	\$33.47
35471	REPAIR			4/30/2003	37741	\$22.31
35670	REPAIR			5/1/2003	37742	\$22.31
35703	REPAIR			5/6/2003	37747	\$86.80
35782	MONTHLY PM FOR FEEDER	5/15/2003	5/13/2003 12:56:21 PM		0	\$0.00
35918	REPAIR			5/12/2003	37753	\$22.31
35967	REPAIR		5/15/2003 8:40:25 AM		37756	\$43.40
35971	REPAIR			5/15/2003	37756	\$22.31
36643	MONTHLY PM FOR FEEDER	6/12/2003	6/18/2003 11:16:05 AM		6	\$10.85
37769	MONTHLY PM FOR FEEDER	7/18/2003	8/4/2003 8:25:06 AM		17	\$10.85
37888	REPAIR			7/17/2003	37819	\$22.17
38076	REPAIR			7/21/2003	37823	\$133.86
38078	INSTALL FAN IN CON TROL BOX			7/21/2003	37823	\$44.62
38632	REPAIR			8/12/2003	37845	\$44.34
38668	REPAIR		8/15/2003 7:30:04 AM		37848	\$0.00
38999	REPAIR			8/26/2003	37859	\$44.34
39054	REPAIR			8/28/2003	37861	\$156.17
39070	MONTHLY PM FOR FEEDER	9/3/2003	9/22/2003 11:43:59 AM		19	\$10.85
39211	REPAIR			9/3/2003	37867	\$22.31

## Asset/Equipment Work Order History Brief

39573	REPAIR		9/15/2003 9:29:56 AM	37879	\$0.00
39594	REPAIR		9/15/2003	37879	\$22.17
39615	REPAIR		9/17/2003	37881	\$22.17
39936	REPAIR		9/26/2003	37890	\$22.31
40167	REPAIR		10/6/2003	37900	\$44.34
40350	REPAIR		10/13/2003	37907	\$22.17
40356	REPAIR		10/13/2003	37907	\$33.26
40452	MONTHLY PM FOR FEEDER	10/22/2003	10/28/2003	6	\$10.85
41717	MONTHLY PM FOR FEEDER	12/1/2003	12/4/2003 9:57:11 AM	3	\$10.85
42297	REPLACE BATTERY		12/11/2003	37966	\$22.31
42471	MONTHLY PM FOR FEEDER	1/5/2004	1/15/2004 1:42:12 PM	10	\$10.85
43375	REPAIR		1/29/2004	38015	\$22.17
43938	MONTHLY PM FOR FEEDER	2/16/2004	2/24/2004	8	\$10.85
43996	ANNUAL PM FOR FEEDER	2/19/2004	2/26/2004 6:19:20 AM	7	\$0.00
44127	REPAIR		2/18/2004	38035	\$22.17
44528	REPAIR JOG BUTTON		3/5/2004	38051	\$65.37
44951	MONTHLY PM FOR FEEDER	3/25/2004	3/26/2004 9:59:10 AM	1	\$10.85
45380	REPAIR (BLOWN FUSE)		3/30/2004	38076	\$21.79
45743	REPAIR (ELECTRICAL PROBLEM W/		4/12/2004	38089	\$283.27
45758	REPAIR		4/13/2004	38090	\$87.16
45804	REPAIR		4/15/2004	38092	\$22.17
45954	REPAIR		4/21/2004 6:54:48 AM	38098	\$43.40
46019	MONTHLY PM FOR FEEDER	4/26/2004	4/27/2004 10:01:39 AM	1	\$0.00

## Asset/Equipment Work Order History Brief

46327	REPAIR		4/30/2004		38107	\$33.26
46333	REPAIR ( ELECTRICAL CABLE SHOR		4/30/2004		38107	\$66.65
46845	REPAIR		5/17/2004		38124	\$33.26
46966	MONTHLY PM FOR FEEDER	5/27/2004	5/27/2004		0	\$10.85
47240	REPAIR ELECTRICAL WIRING		5/27/2004		38134	\$94.00
47253	REPAIR		5/28/2004		38135	\$10.85
47293	REPAIR		6/2/2004		38140	\$47.95
47587	REPAIR		6/10/2004		38148	\$44.34
48101	MONTHLY PM FOR FEEDER	6/28/2004	6/28/2004		0	\$10.85
48541	REPAIR		7/9/2004 3:11:47 PM		38177	\$49.66
48963	MONTHLY PM FOR FEEDER	7/28/2004	7/27/2004 1:20:50 PM		0	\$10.85
49411	REPAIR		8/9/2004		38208	\$55.43
49486	REPAIR		8/7/2004		38206	\$35.16
49827	MONTHLY PM FOR FEEDER	8/26/2004	9/2/2004 1:57:54 PM		7	\$10.85
49915	CLEAN VALVE		8/20/2004		38219	\$22.17
50561	REPAIR		9/13/2004		38243	\$47.81
50562	REPAIR		9/13/2004		38243	\$140.24
51065	MONTHLY PM FOR FEEDER	10/4/2004	10/7/2004 10:49:40 AM		3	\$10.85
51214	REPAIR		10/8/2004 4:46:05 PM		38268	\$0.00
52180	MONTHLY PM FOR FEEDER	11/8/2004	11/15/2004 11:00:42 AM		7	\$11.36
53269	MONTHLY PM FOR FEEDER	12/15/2004	12/22/2004 3:55:38 PM		7	\$11.36
53593	REPAIR		12/21/2004		38342	\$113.40
53623	REPAIR		12/22/2004		38343	\$22.68

## Asset/Equipment Work Order History Brief

54213	MONTHLY PM FOR FEEDER	1/21/2005	1/20/2005 10:57:36 AM	0	\$0.00
54680	REPAIR		2/2/2005 3:38:15 PM	38385	\$22.68
54905	REPAIR		2/9/2005	38392	\$113.40
54909	REPAIR		2/9/2005	38392	\$49.04
55146	REPAIR		2/10/2005	38393	\$22.68
55196	REPAIR E-STOP		2/15/2005	38398	\$26.22
55213	REPLACE E-STOP		2/16/2005	38399	\$26.22
55289	ANNUAL PM FOR FEEDER	2/25/2005	3/24/2005 7:48:57 AM	27	\$56.78
55290	MONTHLY PM FOR FEEDER	2/21/2005	2/22/2005 11:09:50 AM	1	\$0.00
55544	REPAIR		2/28/2005	38411	\$45.36
55576	INSTALLED FEEDER CABLES		3/1/2005	38412	\$34.23
55607	REPAIR		3/4/2005 8:20:22 AM	38415	\$48.93
55769	REPAIR ELECTRICAL WIRING		3/7/2005	38418	\$113.75
55772	REPAIR UP AND DOWN CONTROLS		3/7/2005	38418	\$56.70
56057	REPAIR (CABLE BAD)		3/14/2005	38425	\$44.60
56064	REPAIR		3/15/2005	38426	\$52.44
56148	MONTHLY PM FOR FEEDER	3/24/2005	3/28/2005 2:15:18 PM	4	\$11.36
56217	REPAIR (REPLACE FUSE)		3/17/2005	38428	\$26.22
56378	REPAIR BROKEN ELECTRICAL WIRE		3/28/2005	38439	\$22.68
57209	MONTHLY PM FOR FEEDER	4/27/2005	4/28/2005 12:53:25 PM	1	\$11.36
57296	REPAIR OF EQUIPMENT		4/25/2005	38467	\$223.76
57869	REPLACED BATTERY ON FEEDER C		5/17/2005	38489	\$22.75
58281	MONTHLY PM FOR FEEDER	5/30/2005	6/1/2005	2	\$11.36

## Asset/Equipment Work Order History Brief

58395	FEEDER NEEDED LEVELING		6/3/2005 8:18:44 AM	38506	\$52.44
	Comments: LEVELED FEEDER				
58396	REPAIR OF EQUIPMENT		5/31/2005	38503	\$26.22
	Comments: LEVELED FEEDER				
59067	REPAIR OF EQUIPMENT		6/16/2005	38519	\$97.80
	Comments: WON'T HOLD METAL. REPLACED BAD REGULATOR.				
59255	MONTHLY PM FOR FEEDER	7/1/2005	6/29/2005 1:43:39 PM	0	\$22.71
60024	REPAIR OF EQUIPMENT		7/18/2005	38551	\$47.33
	Comments: FEEDER NOT WORKING. FUSED.				
60169	MONTHLY PM FOR FEEDER	7/29/2005	8/1/2005 9:07:24 AM	3	\$11.36
60715	CLEAN EQUIPMENT		8/10/2005	38574	\$78.66
	Comments: TAKE REGULATOR AND CLUTCH VALVE OFF EAST SIDE. CLEAN AND ADJUST.				
61168	REPAIR OF EQUIPMENT		8/23/2005 6:48:53 AM	38587	\$0.00
	Comments: REPLACED FUSE IN FEEDER				
61169	REPAIR OF EQUIPMENT		8/23/2005 7:06:27 AM	38587	\$0.00
	Comments: FEEDER NOR WORKING. BLOW FUSE.				
61340	MONTHLY PM FOR FEEDER	8/31/2005	8/31/2005 7:20:02 AM	0	\$0.00
62207	MONTHLY PM FOR FEEDER	9/30/2005	9/27/2005 7:19:32 AM	0	\$11.36
62312	REPAIR OF EQUIPMENT		9/28/2005	38623	\$49.04
	Comments: REPLACE FUSE IN CONTROL PANEL.				
63176	MONTHLY PM FOR FEEDER	10/27/2005	10/27/2005 7:12:11 AM	0	\$11.36
63483	REPAIR OF EQUIPMENT		10/31/2005	38656	\$22.68
	Comments: MODIFY PARTS FOR FEEDER.				
64285	MONTHLY PM FOR FEEDER	11/28/2005	12/1/2005 8:15:43 AM	3	\$11.36
65544	MONTHLY PM FOR FEEDER	1/2/2006	1/25/2006 6:11:23 AM	23	\$11.36
66081	REPAIR OF EQUIPMENT		1/23/2006	38740	\$0.00
	Comments: FEDDER STOPED WORKING. CHECK WIRE. OK. FUSE BLOWN. REPLACED RUSE. RUNNING AGAIN.				
66602	REPAIR OF EQUIPMENT		2/10/2006 8:22:10 AM	38758	\$22.71
	Comments: FEEDER MOTOR BURNED UP. NEED NEW ONE.				
66976	MONTHLY PM FOR FEEDER	2/24/2006	3/2/2006 6:15:14 AM	6	\$11.36
67899	REPAIR OF EQUIPMENT		3/16/2006 6:19:00 AM	38792	\$45.42
	Comments: FEEDER NOT WORKING. BLOWN FUSES.				
68074	ANNUAL PM FOR FEEDER	3/24/2006	4/7/2006 10:53:38 AM	14	\$56.78
68581	MONTHLY PM FOR FEEDER	4/3/2006	4/6/2006 8:09:47 AM	3	\$11.36
68927	REPAIR OF EQUIPMENT		4/8/2006	38815	\$62.46
	Comments: FEEDER WILL NOT RUN. BROKE WIRE.				

## Asset/Equipment Work Order History Brief

69996	MONTHLY PM FOR FEEDER	5/8/2006	5/11/2006 7:58:39 AM	3	\$0.00
71434	MONTHLY PM FOR FEEDER	6/12/2006	6/12/2006 7:49:35 AM	0	\$11.36
71781	REPAIR OF EQUIPMENT		6/19/2006	38887	\$56.84
	Comments: FEEDER IS STOPPING AND STARTING.				
72041	REPAIR OF EQUIPMENT		6/23/2006	38891	\$34.23
	Comments: FEEDER QUITTING. INSTALL NEW FAN IN CONTROL CABINET.				
72491	MONTHLY PM FOR FEEDER	7/12/2006	7/12/2006 10:30:27 AM	0	\$11.36
72596	REPAIR OF EQUIPMENT		7/6/2006	38904	\$68.46
	Comments: CHECKED UNIT. FOUND NO PROBLEM. WITH FEEDER. PROBLEM IS IN CAM. RESET PARAMETERS ON CAM, BUT NOT WORKING PROPERLY. CLEARED CAM OF ALL PARAMETERS AND STATED OVER WITH ALL NEW SETTINGS. OK.				
73385	REPAIR OF EQUIPMENT		7/26/2006	38924	\$34.02
	Comments: FEEDER QUIT (E-STOP) START LIGHT CONTROL WOULDN'T COME ON. POSSIBLE RESET BUTTON TRIPPED.				
73784	MONTHLY PM FOR FEEDER	8/11/2006	8/14/2006	3	\$11.36
73978	REPAIR OF EQUIPMENT		8/3/2006	38932	\$34.02
	Comments: FEEDER QUIT. CHAIN OFF. LINE UP AND STRAIGHTEN				
74019	REPAIR OF EQUIPMENT		8/8/2006	38937	\$26.22
	Comments: FEEDER WON'T STAY ON.				
74750	REPAIR OF EQUIPMENT		8/24/2006	38953	\$22.82
	Comments: WILL NOT FEED, SHOWING E-STOP ERROR. CHECK ALL E-STOP CIRCUITS. FOUND OPEN SET OF CONTACTS, PULL CONTROLLER, FOUND BLOWN RESISTOR. REPLAECED RESISTOR.				
74753	REPAIR OF EQUIPMENT		8/24/2006	38953	\$34.02
	Comments: PUT DRIVE UNIT BACK IN AND IS RUNNING.				
74758	REPAIR OF EQUIPMENT		8/23/2006	38952	\$0.00
	Comments: FEEDER QUIT. CYCLED POWER AND RESTARTED FEEDER.				
75042	REPAIR OF EQUIPMENT		8/29/2006	38958	\$22.82
	Comments: FEEDER NOT WORKING. RESET FEEDER. OK. CLEAN OUT CAM SETTINGS AND RESET.				
75540	MONTHLY PM FOR FEEDER	9/13/2006	9/13/2006 7:49:58 AM	0	\$5.68
76430	REPAIR OF EQUIPMENT		9/26/2006	38986	\$11.34
	Comments: EXPOSED WIRE IN LIQUITITE FLEX FROM FEEDER CONTROL TO STRAIGHTENER. LOCATED PROBLEM SPOTTER BY SAFETY COMMITTEE, WILL HAVE TO SHUT DOWN PRESS FOR THIS ONE.				
76469	REPAIR OF EQUIPMENT		9/27/2006	38987	\$0.00
	Comments: REPLACE FUSE IN FEEDER.				
76771	REPAIR OF EQUIPMENT		10/2/2006	38992	\$0.00
	Comments: FEEDER WON'T STAY RUNNING. E-STOP FAULT. CHECK 27 AM REGULATOR, IT WAS GOOD. CHECK WIRES AT E-STOP, IT STARTED WORKING AGAIN. BUT I DON'T THINK I DID ANYTHING.				
76802	REPAIR OF EQUIPMENT		10/3/2006	38993	\$0.00
	Comments: PROBLEM WITH FEEDER. FEEDER RUNNING AGAIN. SAME THING AS TODAY.				
76811	REPAIR OF EQUIPMENT		10/3/2006	38993	\$91.00
	Comments: FEEDER QUIT. LOW VOLTAGE ON E-STOP INPUT, WORKING AT THIS TIME, SUSPECT DRY CONTACTS HAVE HIGH RESISTANCEY.				

## Asset/Equipment Work Order History Brief

76840	REPAIR OF EQUIPMENT	10/4/2006	38994	\$170.10
	Comments: E-STOP ERROR. EMERGENCY STOP ERROR. ATTEMPTED BYPASSING SAFETY INTERLOCKS ON DRIVE CONTROLLERS. DOESN'T HELP. FIND WIRE NUMBER 24 SHORTED, BUT UNABLE TO LOCATE EXACT LOCATION OF SHORT.			
76849	REPAIR OF EQUIPMENT	10/4/2006	38994	\$0.00
	Comments: TALKED WITH BO AND JERROD. LOOK AT A FEW THINGS THEN TOOK OUT CONTROLLER. STARTED CHECKING THE FRONT SIDE BOARD, FOUND NO DEFECT WITH IT. TOOK COVER OFF AND FOUND WHERE THE SMOKE GOT OUT CHIPS IC-119-IC116-IC-93 AND IC 97 WHERE A LITTLE COOKED.			
76877	REPAIR OF EQUIPMENT	10/5/2006	38995	\$45.36
	Comments: REMOVE SOT AND AXIS CONTROLLER AND PACKAGED FOR SHIPMENT.			
76998	MONTHLY PM FOR FEEDER	10/13/2006 10/23/2006 6:20:57 AM	10	\$0.00
78231	REPAIR OF EQUIPMENT	10/31/2006	39021	\$0.00
	Comments: WORK WITH BO, DAVID, AND JERROD. JERROD HAD ME PULL 4 MORE WIRES 2-TO THE STRAIGHTENER AND 2 TO THE PRESS THAT WAS A LOT OF FUN. LOOKED AT MOTOR AND I THINK IT IS WIRED RIGHT. WENT BACK OVER WHAT HAD BEEN HOOKED UP SO FAR, I DID NOT NOOK UP NEW WIRING PUT FLEX BACK IN TRIAD AND I LABELED WIRES A AND B IN PRESS AND 9 AND 10 STRAIGHTENER.			
78237	REPAIR OF EQUIPMENT	10/31/2006	39021	\$158.76
	Comments: PULL WIRE AND TERMINATE.			
78254	REPAIR OF EQUIPMENT	11/1/2006	39022	\$0.00
	Comments: WORKED WITH OPERATOR. HE WAS NOT ABLE TO GET IT TO RUN. CALLED KEN AND TRIED TO CALL VENDOR. NO ONE HOME. I LOOKED IN SOME OF THE OTHER BOOKS, WENT AND LOOKED AT OTHER FEED CONTROLS, WHEN SWITCH IS IN THE RUN MODE, THERE IS A STOP CIRCUIT THAT COME ON. I HAD A LOT OF OTHER THINGS GOING ON TONIGHT SO IT WAS HARD TO STAY ON THIS PRESS.			
78259	INSTALL EQUIPMENT OR OTHER ITE	11/1/2006	39022	\$216.09
	Comments: FEEDER INSTALL. FINISH WIRING AND CLEAN UP, POWER UP AND CHECK OUT.			
78264	INSTALL EQUIPMENT OR OTHER ITE	10/30/2006	39020	\$205.38
	Comments: FEEDER INSTALLATION			
78282	REPAIR OF EQUIPMENT	11/2/2006	39023	\$216.23
	Comments: REMOUNT AND ADJUST PHOTO EYE. CHECK ALL SAFETY CIRCUITS, SET FEEDER AND TEST. CLEAN UP			
78290	REPAIR OF EQUIPMENT	11/2/2006	39023	\$0.00
	Comments: HAVING TROUBLE WITH ADJUSTMENT. LOOKED TO SEE HOW TO CHANGE SETTING FROM .010 TO .001. WE GET TI ADJUSTED SO THEY WOULD RUN BUT IT STILL NEEDS TO BE CHANGED.			
78879	REPAIR OF EQUIPMENT	11/13/2006	39034	\$0.00
	Comments: FEEDER WON'T GO UP OR DOWN. REPLACED BLOWN FUSE.			
78899	REPAIR OF EQUIPMENT	11/14/2006	39035	\$22.82
	Comments: PROBLEM WITH FEEDER. CONTROL ERROR SEE H1 DISPLAY H1 FAULT F-02 23			
	I CHECK FUSE, I LOOKED FOR LOOSE CONNECTION, I WENT AND LOOKED THRU BOOK FOR PRESS 32. THE FAULT CODE IS NOT IN THERE. I LEFT THE H1 DRIVE BOOK OUT ON YOUR TABLE. SOMEONE MAY HAVE TO CALL ROWE TOMORROW.			
	INVESTIGATE- OPERATOR HAD ALREADY CLEARED FAULT.			
79014	MONTHLY PM FOR FEEDER	11/22/2006 11/29/2006 6:17:51 AM	7	\$0.00

## Asset/Equipment Work Order History Brief

80187	REPAIR OF EQUIPMENT		12/14/2006	39065	\$52.44
	Comments: PROBLEM WITH FEEDER. LEVELED FEEDER WITH PRESS. 1/4" CLOSER ON 1 SIDE.				
80427	REPAIR OF EQUIPMENT		12/15/2006	39066	\$91.00
	Comments: CHECK DISTANCE OF FEEDER TO BACK OF PRESS. NOT THE SAME ON BOTH SIDES.				
80497	REPAIR OF EQUIPMENT		12/20/2006	39071	\$136.50
	Comments: FEEDER DOESN'T WORK. CYCLE STOP WILL NOT CLEAR. ERROR ON DRIVE, SUSPECT DRIVE DAMAGED, CALLING FACTORY REP FOR ASSISTANCE.				
80506	REPAIR OF EQUIPMENT		12/20/2006	39071	\$0.00
	Comments: FEEDER RUNNING REVERSE. CHECKED PARAMETERS. FOUND B014 WRONG, CHANGED TO CORRECT SETTING (ACCORDING TO PARAMETER LIST) AFTER CHANGE F288 APPEARED ON H1 DISPLAY. TECH SUPPORT SAID OUR PARAMETER LIST WAS WRONG SO I CHANGED B014 BACK TO 0000. GOT BACK TO ORIGINAL PROBLEM. TO CORRECT RUNNING IN REVERSE, I CHANGED THE FEED LENGTH FROM -5 INCHES TO + 5 INCHES.				
80721	MONTHLY PM FOR FEEDER	12/29/2006	1/6/2007	8	\$11.36
81148	REPAIR OF EQUIPMENT		1/5/2007	39087	\$22.68
	Comments: FEED LENGTH IS NEGATIVE. SHOWED OPERATOR AND SUPERVISOR HOW TO CHANGE FROM NEGATIVE NUMBER TO POSITIVE NUMBER.				
82326	MONTHLY PM FOR FEEDER	2/5/2007	2/8/2007 8:25:32 AM	3	\$13.40
82661	REPAIR OF EQUIPMENT		2/5/2007	39118	\$36.47
	Comments: LINE UP STRAIGHTENER. MOVED. EVERYBODY HAPPY.				
82673	REPAIR OF EQUIPMENT		2/7/2007	39120	\$0.00
	Comments: FEEDER INCREASING BY .010 INSTEAD OF .001. NO PROBLEM FOUND.				
84215	MONTHLY PM FOR FEEDER	3/12/2007	3/12/2007 10:12:28 AM	0	\$0.00
84401	REPAIR OF EQUIPMENT		3/13/2007	39154	\$0.00
	Comments: PROBLEM WITH FEEDER CONTROL. CHECKED. NO PROBLEM FOUND.				
85165	REPAIR OF EQUIPMENT		3/28/2007	39169	\$0.00
	Comments: FEEDER NOT FEEDING UP ON ONE SIDE. CHANGE PART FEED 10 TH RUNNING GOOD.				
85570	ANNUAL PM FOR FEEDER	4/9/2007	4/13/2007 8:22:54 AM	4	\$67.00
85571	MONTHLY PM FOR FEEDER	4/11/2007	4/10/2007 10:03:58 AM	0	\$13.40
86035	REPAIR OF EQUIPMENT		4/13/2007	39185	\$11.34
	Comments: RESET FEEDER				
86531	REPAIR OF EQUIPMENT		4/25/2007	39197	\$36.13
	Comments: EXPOSED WIRE LEADING TO FEEDER CONTROL/UP AND DOWN. REPAIRED.				
86943	MONTHLY PM FOR FEEDER	5/10/2007	5/16/2007 9:55:27 AM	6	\$13.40
88608	MONTHLY PM FOR FEEDER	6/15/2007	6/13/2007 8:07:42 AM	0	\$13.40
89240	REPAIR OF EQUIPMENT		6/19/2007	39252	\$31.25
	Comments: HAND HELD CONTROL ON FEEDER WON'T JOG IN REVERSE. WIRE BROKEN IN CORD. CUT BACK AND NUMBER.				

## Asset/Equipment Work Order History Brief

89972	MONTHLY PM FOR FEEDER	7/13/2007	7/11/2007 8:13:27 AM	0	\$18.07
90420	REPAIR OF EQUIPMENT		7/16/2007	39279	\$0.00
	Comments:	PRESS KEEPS STOPPING EVERY THIRTY MINUTES. BATCH COUNTER SET TO 100, CHANGED TO 99999. NO FURTHER PROBLEMS.			
91250	MONTHLY PM FOR FEEDER	8/10/2007	8/14/2007 8:45:44 AM	4	\$13.40
92833	MONTHLY PM FOR FEEDER	9/13/2007	9/8/2007	0	\$18.07
94187	MONTHLY PM FOR FEEDER	10/8/2007	10/18/2007 10:24:02 AM	10	\$13.40
96310	MONTHLY PM FOR FEEDER	11/19/2007	11/30/2007 10:30:06 AM	11	\$18.07
96724	CLEAN EQUIPMENT		11/26/2007	39412	\$0.00
	Comments:	CLEAN OIL OUT OF PLUGS ON VALVE ON FEEDER.			
97050	REPAIR OF EQUIPMENT		12/5/2007	39421	\$0.00
	Comments:	PILOT VALVE IS STICKING. OIL VALVE.			
98081	MONTHLY PM FOR FEEDER	12/31/2007	12/31/2007	0	\$0.00
98456	MONTHLY PM FOR FEEDER	1/30/2008	1/24/2008 12:38:56 PM	0	\$13.40
99785	MONTHLY PM FOR FEEDER	2/25/2008	2/13/2008	0	\$16.69
101166	MONTHLY PM FOR FEEDER	3/14/2008	3/13/2008 10:10:38 AM	0	\$13.40
102098	REPAIR OF EQUIPMENT		3/25/2008	39532	\$108.39
	Comments:	NOT FEEDING ALL THE TIME. SET POINTS NEEDS TO BE ADJUSTED ON PILOT AND FEED. THE SET POINTS ARE OPPOSITE OF SHEET AT PRESS.			
102472	ANNUAL PM FOR FEEDER	3/31/2008	4/25/2008 7:56:01 AM	25	\$56.70
102473	MONTHLY PM FOR FEEDER	4/14/2008	4/18/2008 9:41:17 AM	4	\$13.40
102848	REPAIR OF EQUIPMENT		4/1/2008	39539	\$0.00
	Comments:	WILL NOT ADJUST UP AND DOWN. REPLACED BLOWN FUSE.			
104135	MONTHLY PM FOR FEEDER	5/19/2008	5/27/2008 7:41:52 AM	8	\$11.36
105452	MONTHLY PM FOR FEEDER	6/26/2008	7/1/2008 6:44:29 AM	5	\$13.40
108056	MONTHLY PM FOR FEEDER	7/31/2008	8/19/2008 7:43:58 AM	19	\$14.80
108853	INSTALL EQUIPMENT OR OTHER ITE		8/9/2008 11:10:13 AM	39669	\$184.20
	Comments:	INSTALL EXHAUST (MUFFIN FAN) IN FEEDER CONTROL CABINET. INSTALLED FAN AND INTAKE WILL WIRE LATER.			
108980	INSTALL EQUIPMENT OR OTHER ITE		8/14/2008 9:53:08 AM	39674	\$40.50
	Comments:	INSTALL T "STAT AND WIRING FOR RAN ON FEEDER CABINET.			
109316	REPAIR OF EQUIPMENT		8/22/2008	39682	\$52.44
	Comments:	FEED WILL NOT FEED. WIRE WAS BROKE. REPLACED.			

## Asset/Equipment Work Order History Brief

109738	MONTHLY PM FOR FEEDER	9/18/2008	9/19/2008 8:06:22 AM	1	\$14.80
110019	REPAIR OF EQUIPMENT		9/2/2008	39693	\$17.42
	Comments: WRONG PARAMETERS. HELPED OPERATOR GET THE CORRECT PARAMETERS.				
110934	MONTHLY PM FOR FEEDER	10/20/2008	10/15/2008 7:44:17 AM	0	\$14.80
112452	MONTHLY PM FOR FEEDER	11/14/2008	11/26/2008 6:44:56 AM	12	\$14.80
113586	MONTHLY PM FOR FEEDER	12/26/2008	1/9/2009 7:16:08 AM	14	\$14.80
115767	MONTHLY PM FOR FEEDER	2/9/2009	2/3/2009 9:46:16 AM	0	\$14.80
117031	MONTHLY PM FOR FEEDER	3/5/2009	3/23/2009 7:48:35 AM	18	\$14.80
118217	MONTHLY PM FOR FEEDER	4/22/2009	4/16/2009 6:19:00 AM	0	\$14.80
118893	ANNUAL PM FOR FEEDER	4/27/2009	5/21/2009 6:16:36 AM	24	\$101.25
119433	MONTHLY PM FOR FEEDER	5/18/2009	5/21/2009 6:18:27 AM	3	\$14.80
120825	MONTHLY PM FOR FEEDER	6/22/2009	6/30/2009 6:14:45 AM	8	\$19.37
123213	MONTHLY PM FOR FEEDER	7/30/2009	8/4/2009 6:21:06 AM	5	\$19.37
124962	MONTHLY PM FOR FEEDER	9/3/2009	9/10/2009 6:27:13 AM	7	\$14.59
126353	MONTHLY PM FOR FEEDER	10/12/2009	10/13/2009 6:57:29 AM	1	\$17.01
127675	MONTHLY PM FOR FEEDER	11/12/2009	11/17/2009 10:27:05 AM	5	\$25.79
128439	REPAIR OF EQUIPMENT		11/20/2009	40137	\$102.60
	Comments: REMOVED FEEDER TO READY RAM FOR REMOVAL.				
128830	MONTHLY PM FOR FEEDER	12/17/2009	2/6/2010	51	\$19.37
131586	REPAIR OF EQUIPMENT		1/30/2010	40208	\$17.10
	Comments: REPAIRED J-BOX AND MADE COVER LATCH				
131636	REPAIR OF EQUIPMENT		2/2/2010 1:18:01 PM	40211	\$213.18
	Comments: ALIGN FEEDER WITH DIE SLOT IN BOLSTER PLATE				
	SET BOLSTER PLATE TO FEEDER SHIMMED FEEDER TO CORRECT LOCATION OPERATOR SET DIE (4 FEET ALUM) PARTS LOOK GOOD AND DIE RUNS WELL.				
132657	MONTHLY PM FOR FEEDER	3/8/2010	3/11/2010 2:44:35 PM	3	\$19.37
134091	MONTHLY PM FOR FEEDER	4/12/2010	4/14/2010 7:47:29 AM	2	\$19.37

## Asset/Equipment Work Order History Brief

135170	ANNUAL PM FOR FEEDER	5/21/2010	5/19/2010 6:39:50 AM	0	\$96.83
135171	MONTHLY PM FOR FEEDER	5/14/2010	5/13/2010	0	\$19.37
136331	MONTHLY PM FOR FEEDER	6/14/2010	6/13/2010	0	\$15.05
137602	MONTHLY PM FOR FEEDER	7/13/2010	8/3/2010 6:51:11 AM	21	\$20.25
139465	MONTHLY PM FOR FEEDER	9/2/2010	9/8/2010 6:31:08 AM	6	\$20.25
140837	MONTHLY PM FOR FEEDER	10/8/2010	10/7/2010 9:26:34 AM	0	\$20.25
141282	REPAIR OF EQUIPMENT		10/16/2010	40467	\$70.00
	Comments:	FEEDER NOT FEEDING. REPAIRED WIRING IN PENDANT			
141419	REPAIR OF EQUIPMENT		10/23/2010	40474	\$37.63
	Comments:	FEEDER PENDANT JOG NOT WORKING. OPERATOR SAID NO PROBLEMS			
141829	MONTHLY PM FOR FEEDER	11/8/2010	11/20/2010	12	\$20.25
142003	REPAIR OF EQUIPMENT		10/29/2010	40480	\$105.00
	Comments:	NRA THE HAND HELD FEED CONTROL DOES NOT WORK CORRECTLY - PRSS 038			
		REPLACED PENDANT& CABLE.			
142917	MONTHLY PM FOR FEEDER	12/20/2010	12/28/2010 6:13:29 AM	8	\$20.25
143719	MONTHLY PM FOR FEEDER	1/27/2011	2/3/2011 6:59:23 AM	7	\$15.05
144335	REPAIR OF EQUIPMENT		1/22/2011	40565	\$35.00
	Comments:	FEEDER WILL NOT FEED UP			
		REWIRED HAND CONTROLLER			
145719	MONTHLY PM FOR FEEDER	3/7/2011	3/24/2011	17	\$20.25
145889	REPAIR OF EQUIPMENT		2/26/2011	40600	\$353.00
	Comments:	FEEDER QUIT WORKING IN THE MIDDLE OF RUN			
		STARTED WITH ROLLS NOT OPENING IN ANY MODE THEN FAULT ON DRIVE, FINALLY BOT CLEAR, FOUND OPEN DIOPE ON CR202 COIL, DISCONNECTED DIODE, REPLACED RELAY, GOT TO WORK IN MANUAL , BUT NOT AUTO, PUT OL.D RELAY BACK, SAME SITUATION, 24 VPC ON CR 202 COIL ALL THE TIME, SWITCH IS WORKING ?? HAVE SIGNAL TO PLS BUT NOT BACK, CHECK PLS RELAY - IT FINE, CHANGED CAM CONTROLLER, WILL NOT ACCEPT PROGRAMMING, CHANGED WITH ANOTHER - SAME THING MEANWHILE HAVE LOST FEED. HAD IT EARLIER ?? PUT ORIGINAL CAM BACK IN, AT LEAST IT ACCEPTS PROGRAM CHANGES, NOW PRESS RUNS BUT FEEDER DOES NOT GET INPUTS SAYS WAITING ON PRESS OR SOMETIMES E-STOP ACTIVE, NEED TO START OVER!!			
145894	REPAIR OF EQUIPMENT		2/26/2011	40600	\$70.00
	Comments:	FEEDER NOT WORKING			
		FEEDER DRIVE FAULTED HAD TO RESET HOPPENED TO BE WORKING WE DID NOT HAVE A OPERATOR TO FULLY TRY OUT PRESS			

## Asset/Equipment Work Order History Brief

145915	REPAIR OF EQUIPMENT		2/28/2011		40602	\$131.35
	Comments:	STILL HAS SOME PROBLEM FROM FRIDAY				
		STARTED FROM SCRATCH, TAKING EACH PROBLEM INDIVIDUALLY THIS TIME. 1. PILOT ROLL DOES NOT WORK IN AUTO - FOUND BAC REALY ON PLS CONTROLLER, REPLACED RELAY 2. FEED 0 LOST - CHECKED RESOLVER INPUTS/OUTPUTS, CHECKED CABLE, CHECKED INPUTS TO DRIVE, INTERLOCK TO STRAIGHTNEER AND COIL LOOP NOT PRESENT, RESTARTED STRAIGHTENER, CLEAR DRIVE FAULT, FEEDER WORKS NOW.				
146197	REPAIR OF EQUIPMENT		3/15/2011		40617	\$70.00
	Comments:	FEED PILOT VALVE NOT WORKING				
		HAD TO CHECK THE SETTING THEY WELL OFF AND ALSO SHUT THE FEED DOWN STARTED BACK UP STAYED WITH IT WITH ROY IT FINALLY GOT IT ADJ SO IT WOULD FEED RIGHT				
146828	MONTHLY PM FOR FEEDER	4/25/2011	4/26/2011 7:11:06 AM		1	\$20.25
147822	ANNUAL PM FOR FEEDER	5/19/2011	11/5/2011		170	\$101.25
147823	MONTHLY PM FOR FEEDER	5/26/2011	5/20/2011 7:46:44 AM		0	\$20.25
148830	MONTHLY PM FOR FEEDER	6/20/2011	6/30/2011 11:49:14 AM		10	\$20.25
149227	REPAIR OF EQUIPMENT		6/17/2011		40711	\$35.00
	Comments:	REPALCED BROKEN BOLT HOLDING FEEDER TO PRESS, RELAINED FEEDER TO PRESS.				
150681	MONTHLY PM FOR FEEDER	8/1/2011	8/11/2011 7:29:05 AM		10	\$20.25
151803	MONTHLY PM FOR FEEDER	9/12/2011	9/9/2011 6:59:30 AM		0	\$20.25
152358	REPAIR OF EQUIPMENT		9/27/2011 8:58:14 AM		40813	\$70.00
	Comments:	COIL NOT ENTERING FEEDER WITH ENOUGH SPEED				
152642	MONTHLY PM FOR FEEDER	10/10/2011	10/22/2011 7:08:34 AM		12	\$20.25
152899	REPAIR OF EQUIPMENT		10/6/2011		40822	\$35.00
	Comments:	OPERATOR ACCIDENTALLY BROKE FEEDER CONTROL SCREEN				
152980	REPAIR OF EQUIPMENT		10/11/2011		40827	\$35.00
	Comments:	WON'T FEED				
		- CHECK CONTROLS, RAISED AIR PRESSURE AT THE PRESS ENTRANCE FOR METAL				
153122	REPAIR OF EQUIPMENT		10/19/2011		40835	\$52.50
	Comments:	SEVERED REMOTE FEEDER CONTROL CORD				
		-LOOK UP CORD ON COMPUTER, TIE IN NEW CORD				
153602	MONTHLY PM FOR FEEDER	11/21/2011	11/30/2011 8:48:52 AM		9	\$20.25
154632	MONTHLY PM FOR FEEDER	12/30/2011	1/4/2012 8:09:03 AM		5	\$20.25
156177	MONTHLY PM FOR FEEDER	2/3/2012	2/3/2012		0	\$15.05
157552	MONTHLY PM FOR FEEDER	3/5/2012	3/10/2012 6:53:55 AM		5	\$20.25

## Asset/Equipment Work Order History Brief

157736	REPAIR OF EQUIPMENT		3/6/2012	40974	\$17.50
	Comments:	FEEDING PROBLEM AIR LEAK PROBLEM			
		FIX AIR LEAK ON FEEDER CYLINDERS			
157774	REPAIR OF EQUIPMENT		3/7/2012	40975	\$87.50
	Comments:	PRESS FEEDER ISNT FEDDING CORRECT AMOUNT			
		FOUND METAL FEEDING INTO PRESS DIE AT INCONSISTENT SHORT LENGTH. REMOVED CARERS AND OBTAINED CIRCUMFURENCE OF DRIVER ROLLERS. COMMANDED FEEDER AT 12" TO FEED FEEDER WORK CORRECTLY OPERATOR MOVED TO ANOTHER JOB WITH H.G LIGHTER GUAGE MATERIAL PROBLEM DIDN'T OCCUR			
157780	REPAIR OF EQUIPMENT		3/7/2012	40975	\$17.50
	Comments:	PRESS NOT FEEDING THE RIGHT LENGTH			
		JOHN MARKED COLLAR AND RAN WITH NO METAL IN IT. IT WAS FEEDING CORRECTLY WITHOUT METAL. THE OPERATOR CHANGED OVER TO A DIFFERENT METAL IT WORKED GOOD ON THINNER METAL I THINK SOMETHING IS POSSIBL SLIPPING UNDER A LOAD			
158531	MONTHLY PM FOR FEEDER	4/9/2012	4/5/2012 7:43:29 AM	0	\$20.25
158841	REPAIR OF EQUIPMENT		4/11/2012	41010	\$17.50
	Comments:	FEEDER LOCKED UP ON SCREEN			
		REBOOTED AND TESTED			
159533	MONTHLY PM FOR FEEDER	5/7/2012	5/4/2012 7:35:03 AM	0	\$20.25
160145	REPAIR OF EQUIPMENT		5/22/2012	41051	\$52.50
	Comments:	FEEDER JOG FWD/ REV PENNANT INSOLATION CORD CAME OFF			
		REPLACE PENDANT CORD REMOE WIRE NUTS AND WIRE DIRECTLY TO TERMINAL STRIP CHECK OPERATION			
160548	MONTHLY PM FOR FEEDER	6/4/2012	6/15/2012	11	\$20.25
161471	MONTHLY PM FOR FEEDER	7/16/2012	7/18/2012	2	\$15.05
162720	MONTHLY PM FOR FEEDER	8/17/2012	8/15/2012 8:15:57 AM	0	\$26.88
163610	MONTHLY PM FOR FEEDER	9/14/2012	9/20/2012 8:13:48 AM	6	\$20.25
164619	MONTHLY PM FOR FEEDER	10/22/2012	10/16/2012 8:15:47 AM	0	\$20.25
164851	REPAIR OF EQUIPMENT		10/2/2012	41184	\$157.50
	Comments:	FEEDER IS NOT WORKING PROPERLY			
		CONTROLS HAVE A SHORT ON WIRE 24 CHECK ALL FLEX PIPE FROM CONTROL BOX WIRES WAS OFF IN HAND CONTROL TO JOG FORWARD AND REV. RECONNECTED ALL WIRES AND CHECK FOR BROKE WIRES CHECK ALL WIRES ON COIL CART AND WIRES GOING TO THE PRESS REPAIRED 2 WIRES ON COL CART CHASED SHORT DOWN TO THE PROGRAMMING CONTROLLER.			

## Asset/Equipment Work Order History Brief

164864	REPAIR OF EQUIPMENT		10/2/2012		41184	\$140.00
	Comments:	DISPLAY WONT COME ON				
		CHECK 24VOLTAGE 46V DISCONNECT DISPLAY X1& X2 PORT 24 VDC OK CONTROLLER WONT COME ON USE ANOTHER 24VDC POWER SUPPLY CONTROLLER CAME ON DISPLAY WONT COME ON DIPSLAY X2 PORT SHORTED SOMEWHERE REPLACE DISPLAY USE THE ONE FROM 32 FEEDER CONTROLLER AND DISPLAY CAME ON FEEDER WORKED OK SOME KEYS LABELS WONT MATCH SAME FUNCTION BUT NEED TO RELABEL KEYS ON NEW DISPLAY WORKED OK MANUAL/AUTOMATIC				
164873	REPAIR OF EQUIPMENT		10/3/2012		41185	\$87.50
	Comments:	FEEDER CONTROLLER WILL NTO GO INTO AUTO				
		CHECKED ALL WIRING AND SHOWED OPER. HOW TO USE MARKED ALL BUTTONS WHERE OPER WOULD KNOW WHAT TO HIT TO PUT IN AUTO AND HOW TO STOP AND SINGLE CYCLE SENT OLD CONTROLLER OUT FOR REPIAR ASAP				
165792	ANNUAL PM FOR FEEDER		11/5/2012	12/5/2012	30	\$0.00
165793	MONTHLY PM FOR FEEDER		11/15/2012	11/14/2012 7:09:28 AM	0	\$20.25
166631	MONTHLY PM FOR FEEDER		12/14/2012	12/20/2012 7:51:56 AM	6	\$20.25
167424	MONTHLY PM FOR FEEDER		1/21/2013	2/12/2013 7:38:23 AM	22	\$20.25
167932	REPAIR OF EQUIPMENT		1/23/2013		41297	\$35.00
	Comments:	REMOTE CORD SEVERED				
		TIE IN NEW CORD				
168764	REPAIR OF EQUIPMENT		2/19/2013		41324	\$105.00
	Comments:	FEED ANGLE LOST DURING CYCLE				
		CHECKED OPERATION OF SONAR SWITCH IT WAS OPERATING NORMALLY I GOT PRINTS TO FIND WHAT WAS TELLING FEEDER THAT RAM WAS IN CORRECT POSITION TO FEED. THE FEEDER GETS AN INPUT FROM THE PLS CONTROLLER. THAT GIVES THE FEED ANGLE. I CHECKED RELAYS ON CONTROLLERS. ONE OF THE RELAYS HAD A BURNT CONTACT I REPLACED THE RELAY AND WATCHED OPERATION FOR ABOUT 1 HOUR WITH MY METER ON IT TO TRY AND SEE IF I WOULD LOOSE VOLTAGE DURING CYCLE. IT WAS CYCLING CORRECTLY.				
169211	MONTHLY PM FOR FEEDER		3/14/2013	3/15/2013 7:23:56 AM	1	\$20.25
170167	MONTHLY PM FOR FEEDER		4/15/2013	4/18/2013 7:57:12 AM	3	\$20.25
170684	REPAIR OF EQUIPMENT		4/16/2013		41380	\$183.63
	Comments:	FEEDER AND PRESS ARE NOT COMMUNITATING FEEDER SYAS ANGLE IS MISSING BUT IT SI IN THERE				
		CHECKED 24 V SIGNAL ON FEED ANGLE INPUT I DIDT HAVE 24 V I CHECKED RELAYS ON PLC BOARD RELAYS WERE GOOD CYCLING POWER SEVERAL TIMES WE FINALLY GO 24 V ON OUR INPUT AND PRESS WORKED				

## Asset/Equipment Work Order History Brief

170725	REPAIR OF EQUIPMENT		4/17/2013	41381	\$233.88
	Comments:	FEED ANGLE MISSING			
		CHECKED POWER SUPPLY. POWER SUPPLY HAD CORRECT VOLTAGE. I CHANGED OUTPUT ON PLS BECAUSE I WASN'T GETTING MY VOLTAGE BACK ON WIRE 114 THROUGH MY PLS THIS DIDN'T HELP FINALLY I FOUND THAT WIRE 24 THAT FEEDS CIRCUIT WAS IN A TERMINAL STOP THAT WAS BENT AND NOT HOLDING WIRE GOOD. THIS WAS HARD TO FIND BECAUSE WHEN I WAS TESTING I WAS STICKING MY LEAD IN TERMANL STRIP AND CLOSING IT ON WIRE I RETERMINATED WIRE 24 AND THIS SOLVED THE PROBLEM			
170729	REPAIR OF EQUIPMENT		4/19/2013	41383	\$140.00
	Comments:	DOSENT GO INTO AUTO EVERYTIME PALM BUTTONS ARE DEPRESSED			
		FOUND THAT INPUT 3 WASN'T MAKING WHEN THE PRESS WAS MESSING UP I TRACED INPUT 3 TO THE CLUTCH PRESSURE SWITCH AND THE COUNTER BALANCE PRESSURE SWITCH. WAS THE PRESS WOULDN'T GO INTO AUTO. I ADJUSTED THE COUNTER BALANCE PRESSURE AND IT FIXED THE PROBLEM			
171231	MONTHLY PM FOR FEEDER	5/20/2013	5/23/2013 8:51:03 AM	3	\$20.25
171354	REPAIR OF EQUIPMENT		5/3/2013	41397	\$70.00
	Comments:	FEED LENGTH WONT CHECK			
		STROKE PRESS AND TRY TO CHANGE LENGTH SEVERALTIMES SAVE DATA AND LIGHT WILL CHANGE ON FEED DATA SCREEN BUT IT WONT CHANGE ON THE MAIN MENU SCREEN			
		THE OPERATOR A FIRMS THAT THE PART RUNING CAUSES THE PROBLEM FIND LOOSE CONNECTOR ON SCREEN BUT IT DID NOT MAKE A DIFFERENCE THERE AER 19 JOBS STORED ON FEEDER WE DID NOT REPLACE THE FEEDER SCREEN PENDANT			
171375	REPAIR OF EQUIPMENT		5/6/2013	41400	\$199.35
	Comments:	FEEDER NOT FEEDING CORRECTLY WANT FEED PAST 1.5 INCHES			
		CHECKED FEED LENGTH AND ENCODER WHERE MEASURING CORRECTLY TRIED TO CHECK PARAMETERS HAD TROULBE GETTING INTO PARAMETER MADE FINALLY JUMPED INPUT OUT AND GOT INTO PARAMETERS MODE FOUND MAXIMUM FEED LENGTH SET TO 10.565 CHANGED TO 60" CHECKED OPERATION OK			
172115	MONTHLY PM FOR FEEDER	6/24/2013	6/25/2013 7:39:12 AM	1	\$20.25
173126	MONTHLY PM FOR FEEDER	7/25/2013	8/7/2013 8:00:07 AM	13	\$20.25
175126	MONTHLY PM FOR FEEDER	9/6/2013	9/20/2013 7:28:44 AM	14	\$20.25
175459	REPAIR OF EQUIPMENT		9/11/2013	41528	\$251.60
	Comments:	SWAPPING FEEDER DISPLAY			
		RECEIVED REFURBISHED REPAIRED DISPLAY AND INSTALLED IN PLACE COVERT DISPLAY COULD OT GET 24 VAC WORKING ACROSS CONTROL CIRCUIT REMOVED AND REINSTALLED THE BACK UP DISPLAY			
176077	MONTHLY PM FOR FEEDER	10/21/2013	10/15/2013 7:53:24 AM	0	\$20.25
177191	MONTHLY PM FOR FEEDER	11/14/2013	12/6/2013 8:46:26 AM	22	\$20.25
178092	ANNUAL PM FOR FEEDER	12/5/2013	1/29/2014	55	\$101.25

## Asset/Equipment Work Order History Brief

178610	REPAIR OF EQUIPMENT		12/20/2013		41628	\$33.23
	Comments: NEEDS GUARDS ON FEEDER MOUNTED GUARD					
178870	MONTHLY PM FOR FEEDER	1/6/2014	1/14/2014 7:44:23 AM		8	\$20.25
179143	REPAIR OF EQUIPMENT		1/8/2014		41647	\$33.23
	Comments: BAD DISPLAY LINES IN SCREEN GOT PART NUMBER FOR DISPLAY AND GIVE TO JERROD					
179844	MONTHLY PM FOR FEEDER	2/13/2014	2/13/2014 8:21:53 AM		0	\$20.25
180086	REPAIR OF EQUIPMENT		2/5/2014		41675	\$66.45
	Comments: REPLACE FEEDER INTERFACE. CONTROLLER SET PARAMETERS SAME					
180148	REPAIR OF EQUIPMENT		2/6/2014		41676	\$81.00
	Comments: WONT FEED WAITING FOR FEED ANGLE WONT TURN PARAMETERS AND FOUND CAM WAS 'OFF" TURNED RAM "ON" AND REBOOTED BUT NO IT WONT INITIALIZE. FAULTS E3 AND F22 ON AMP BUT CANNOT LOCATE MANUAL					
180163	REPAIR OF EQUIPMENT		2/7/2014		41677	\$299.03
	Comments: BTV06 PANEL FAULTED WENT THROUGH PARAMETERS HAD TO CHAGNE 2 PARAMETERS. FAULTED CLEARED BUT STILL WOULD NOT WORK IT SAIDE WAITING FOR FEED ANGLE CHECKED INPUT OFF OF PLS. WE HAD INPUT GOT BOOK FOR DRIVE AND FOUND PARAMETER LIST HOOKED AT FEED ANGLE MONITORING THE PARAMETER WEA DIFFERENT THAN ON THE LIST WE HAD WE CHAGNED PARMAETERS ANDFEEDER WORKED					
181018	MONTHLY PM FOR FEEDER	3/17/2014	3/26/2014 7:36:53 AM		9	\$20.25
181817	MONTHLY PM FOR FEEDER	4/25/2014	4/17/2014 7:04:40 AM		0	\$20.25
182864	MONTHLY PM FOR FEEDER	5/19/2014	6/3/2014 7:45:11 AM		15	\$20.25
184562	MONTHLY PM FOR FEEDER	7/3/2014	7/8/2014 7:24:18 AM		5	\$20.25
185822	MONTHLY PM FOR FEEDER	8/7/2014	8/5/2014 7:42:42 AM		0	\$20.25
186829	MONTHLY PM FOR FEEDER	9/4/2014	9/18/2014 7:25:22 AM		14	\$40.50
187972	MONTHLY PM FOR FEEDER	10/20/2014	10/17/2014 7:18:34 AM		0	\$40.50
188843	MONTHLY PM FOR FEEDER	11/17/2014	12/2/2014 7:21:38 AM		15	\$40.50
190510	ANNUAL PM FOR FEEDER	1/29/2015	1/15/2015		0	\$0.00
190511	MONTHLY PM FOR FEEDER	1/1/2015	1/13/2015 7:30:06 AM		12	\$40.50
191546	MONTHLY PM FOR FEEDER	2/12/2015	2/12/2015 10:55:07 AM		0	\$40.50

## Asset/Equipment Work Order History Brief

192522	MONTHLY PM FOR FEEDER	3/16/2015	3/18/2015 7:35:11 AM	2	\$40.50
193620	MONTHLY PM FOR FEEDER	4/17/2015	4/23/2015	6	\$20.25
194680	MONTHLY PM FOR FEEDER	5/25/2015	5/21/2015	0	\$31.45
195595	MONTHLY PM FOR FEEDER	6/22/2015	6/18/2015	0	\$40.50
196681	MONTHLY PM FOR FEEDER	7/20/2015	9/30/2015	72	\$40.50
199042	REPAIR OF EQUIPMENT		9/4/2015	42251	\$35.00
	Comments: FEEDER SCREEN WONT COME ON				
	TURN POWER ON CHECK 29 VAC 480 AC ALL OK FEEDER DRIVE CONTROLLER WONT COME ON DRIVE CONTROLLER INDICATOR LIGHT WONT COME ON CHECK ALL FUSES OK				
199077	REPAIR OF EQUIPMENT		9/8/2015	42255	\$265.80
	Comments: CHECKING FEEDS CIRCUITS FOR SHORTS				
	FOUND THE WIRE THAT SHORTED OUT THE OPERATOR TERMINAL AND DRIVE IT WAS 24VDC SUPPLY WIRE. AN ESTOP WAS INSTALLED WHILE THE PRESS HAS BEEN DOWN IT WAS AN 1 7/8 BIT PM ON A 1 3/4 BOX THE ESTOP WAS DIRECTLY SHORTED THE CONTROL VOLTAGE FOR PRESS WAS IMPROPERLY FUSED. IT HAS A 30 AMP FUSE BUT REWIRED AT 12 WHEN CIRCUIT WAS ENERGIZED IT MELTED ESTOP WIRE #700 AND 701 WITH THIS 120 V BEING PUT ACROSS THE 24VCD SUPPLY IT SHORTED THE OPEARATOR TERMINAL AND THE DRIVE FIXED WIRING INSPECTED ALL WIRING REPLACED OPERATOR TERMIAL ENERGIZED CABIENT TO CHECK VOLTAGES EVERHTING LOOKED GOOD WAITING ON DRIVE TO BE REPAIRED.				
199269	REPAIR OF EQUIPMENT		9/16/2015	42263	\$211.65
	Comments: E 103 FEEDER ERROR				
	POWER UP FEEDER TRY TO LOAD PARAMTERS BUT DRIVE ERROR WONT CLEAR ERROR CLEAR OUT WHEN CONNECTING SERVOMOTOR POWER AND FEEDBACK DRIVE ERROR E0103 CAME ON TRACE ERROR TO POR X210 CHECK ALL THE OUTPUTS TO GROUND OK ONLY 2 OUTPUTS IN USE REMOVED RELAYS AND UNWIRE DIODES ERROR WONT CLEAR CHECK SERVO MOTOR CONNECTOR TO GROUND ALL OK COULD NOT FIND THE PROBLEM I DID NOT POWER UP PRESS CONTROL				
199270	REPAIR OF EQUIPMENT		9/16/2015	42263	\$101.25
	Comments: OUTPUT FAULT FROM DRIVE				
	CHECKED WIRING AND CABLES PROBLEM APPEARS TO BE IN DRIVE				
199274	REPAIR OF EQUIPMENT		9/17/2015	42264	\$70.00
	Comments: E-0103 OUTPUT OVERLOADED				
	ASSIST DAY SHIFT				
	UNWIRE AND REMOVE FEEDER DRIVE READY TO SWAP FOR 29 FEEDER DRIVE CANCELED REWIRE 38 FEEDER DRIVE AND CHECK FOR SHORTS AT PORTS X2 X3 HAD TO REMOVE DRIVE TO SEND IT OUT				

## Asset/Equipment Work Order History Brief

199471	REPAIR OF EQUIPMENT		9/26/2015		42273	\$52.50
	Comments:	FEEDS NOT FEEDING  ASSITED IN TRYING TO FIND PROBLEM OF WHY SERVO WONT MOVE WHEN GETTING THE INPUT				
199485	REPAIR OF EQUIPMENT		9/28/2015		42275	\$450.04
	Comments:	TROUBLESHOOTING FEEDER  WENT THORUGH PARAMETERS LOOKING FOR SOMETHING OUT OF PLACE CHANGED SOME PARAMETERS AROUND TRYING TO GET IT TO TEST HAD NO LUCK WITH THAT GOT GINGER TO PULL UP PAST WORK ORDER FROM 1-1-13 TO 9-26-15 AND FOUND THE ONE WERE THE FEEDER MESSED UP THE LAST ITME BUTDIDNT SAY WHICH PARAMETER IT WAS THAT WAS CHANGED CHECKED AND TRACED THE WIRING TO MAKE SURE IT WAS HOOKED UP RIGHT ACCORDING TO WIRE NUMBERS THE PARAMETERS WE CHANGED WERE SET BACK TO THEIR ORIGINAL SETTING				
199499	REPAIR OF EQUIPMENT		9/28/2015		42275	\$0.00
	Comments:	FEEDER WONT RUN IN AUTO  VERIFY DRIVE INPUTS FOUND LOOSE WIRES TO FIX IT CHECK FEED ANGLE PLS 24VDC OK VERIFY ALL PARMAETERS CHANGE PARAMETER 16 HAD TO TURN ON STRAIGHTENER CONTROL TO CLEAR STOP UNCOVER PHOTO EYE AT FEEDER IT CAUSES A STOP CONDITION COULD NOT FIND THE PROBLEM				
199801	MONTHLY PM FOR FEEDER		10/30/2015	10/30/2015 7:50:06 AM	0	\$40.50
200829	MONTHLY PM FOR FEEDER		11/30/2015	12/10/2015	10	\$40.50
202828	ANNUAL PM FOR FEEDER		1/15/2016	1/29/2016	14	\$101.25
202829	MONTHLY PM FOR FEEDER		1/11/2016	1/14/2016 7:36:13 AM	3	\$40.50
203929	MONTHLY PM FOR FEEDER		2/15/2016	2/11/2016	0	\$40.50
204757	MONTHLY PM FOR FEEDER		3/14/2016	3/11/2016	0	\$0.00
205884	MONTHLY PM FOR FEEDER		4/11/2016	4/20/2016	9	\$40.50
206096	REPAIR OF EQUIPMENT		4/1/2016		42461	\$185.40
	Comments:	FEEDER IS GETTING ERROR (F2 28) excessive deviation  TRIED CHANGING SPEED, ACRELAND DECEL BUT NOTHING HELPED THE ERROR MESSAGE SAID THAT THE LAG IS TOO GREAT IN THE MONITORING WINDOW. TRIED CHANGING PARAMETER A115 TO SEE IF IT AFFECTED IT BUT IT DIDN'T HELP IT IS ORGINIALY SET AT 10 WITH A MAX SETTING OF 30 I TRIED UP TO 50 AND NOTHING CHANGED. I SET BACK TO ORIGINAL SETTING THE MEAL WILL FEED BETTER AT TIME. SOMETMES IT FAULTS BEFORE SHEET EVER MOVES IT SEEMS TO BE IN A BIND I GOT WITH JERROD AND WE LOOKED AT IT NEED TO FOLLOW UP				

## Asset/Equipment Work Order History Brief

206127	REPAIR OF EQUIPMENT		4/4/2016	42464	\$169.68
	Comments:	FAULT ON FEEDER EXCESSIVE DEVIATION			
		FEEDER WAS RUNNING FINE WITH NOT METAL BUT WHEN WE PUT METAL IN IT WAS FAULTING OUT WE FOUND ABOUT 6 1/4 PLATES JAMMED BEHIND ROLLER THE OPERATOR USES THEM ON GUIDE ROLLERS. THYE MUST HAVE FELL DOWN IN GAP EITHER ABOVE ROLLER WE REMOVED BOTTOM PLATED AND REMOVED ALL DEBIRS. IT RAN FINE AFTERWARDS THERE'S ANOTHER ISSUE WE NEED TO FOLLOW UP ON. JOHNNY BROUGHT TO OUR ATTENTION THAT ONE OF THE SCREW JACKS FOR UP AND DOWN IS BROKE			
206169	REPAIR OF EQUIPMENT		4/7/2016	42467	\$33.23
	Comments:	METAL HANGING ON CROSSMANDEL IN FEEDER BOLT BEING BROKE IN ONE SIDE			
		REMOVED OBSTRUCTION			
206856	MONTHLY PM FOR FEEDER	5/20/2016	5/24/2016	4	\$0.00
207342	REPAIR OF EQUIPMENT		5/11/2016	42501	\$47.18
	Comments:	SAYS FEEDER IS NOT HOLDING THE METAL			
		METAL COULD BE SLIDE IN AND OUT OF FEEDER PILOT WASN'T HOLDING THE METAL AFTER CHECKING EVERYTHING I LOOKED ON LIMIT SWITCH SCREEN TO FIND THE PILOT RELEASE WAS OPEN WAS TO MCUH CHANGED THE ANGLES ON IT AND FIXED THE PROBLEM			
207859	MONTHLY PM FOR FEEDER	6/23/2016	6/29/2016 7:55:19 AM	6	\$40.50
208992	MONTHLY PM FOR FEEDER	7/29/2016	7/21/2016	0	\$40.50
209936	MONTHLY PM FOR FEEDER	8/22/2016	8/24/2016 8:03:34 AM	2	\$40.50
211091	MONTHLY PM FOR FEEDER	9/23/2016	9/23/2016 7:36:20 AM	0	\$40.50
212260	MONTHLY PM FOR FEEDER	10/24/2016	10/27/2016 7:57:22 AM	3	\$40.50
213172	MONTHLY PM FOR FEEDER	11/28/2016	11/18/2016	0	\$40.50
214051	MONTHLY PM FOR FEEDER	12/19/2016	12/30/2016 9:54:48 AM	11	\$40.50
214962	ANNUAL PM FOR FEEDER	1/30/2017	4/3/2017 11:40:57 AM	63	\$0.00
214963	MONTHLY PM FOR FEEDER	1/30/2017	2/18/2017	19	\$0.00
215343	REPAIR OF EQUIPMENT		1/11/2017	42746	\$52.50
	Comments:	[PLEASE REPAIR JACK SCREWS FOR FEEDER HEIGHT ADJUSTMET BOTH SIDES ARE BROKE			
		REMOVED OLD SCREW JACK GOT BROKE PIECE OF SHAFT OUT OF MOUNT LOOKED FOR ANOTHER JACK BUT WE DIDN'T HAVE ON GAVETO PAUL TO ORDER			
215478	REPAIR OF EQUIPMENT		1/21/2017	42756	\$17.50
	Comments:	RAM ADJUST WONT MOVE			
		REPLACED FUSE			

## Asset/Equipment Work Order History Brief

215496	REPAIR OF EQUIPMENT		1/19/2017		42754	\$17.50
	Comments:	FEEDER WONT RAISE  REPLACED FUSE IN ORDER TO RAISE TOLD OPERATOR THAT UNITL WE GET SCREWJACK FIXED THEY SHOULD CALL US TO ASSIT IN RIASING OR LOWERING				
216625	MONTHLY PM FOR FEEDER		3/20/2017	4/3/2017 12:19:56 PM	14	\$40.50
217913	REPAIR OF EQUIPMENT			4/25/2017	42850	\$35.00
	Comments:	OPERATOR CANT LOWER FEEDER  PUT SCREWJACK BACK INTO THE MOUNT AND LOWERED IT DOWN				
218177	MONTHLY PM FOR FEEDER		5/3/2017	6/9/2017 10:10:42 AM	37	\$40.50
218643	REPAIR OF EQUIPMENT			5/8/2017	42863	\$431.93
	Comments:	NEED LEFT SIDE SCREWJACK REPLACED ON FEEDER  WELDED BRACKET BACK ON WE PUT SCREWJACK IN AND TESTED THE LEFTSIDE WAS GOING UP FASTER THAN THE RIGHT SIDE WE HAD TO REMOVE IT AGAIN AND REMOVE THE SCREW AND PUT IT IN OLD JACK THE RATIO WASN'T CORRECT ON NEW ONE WE RAN IT ALL THE WAY UP AND DWON WE VERIFIED OPERATION OF UPPER LOWER LIMIT SWTICH				
218826	REPAIR OF EQUIPMENT			5/24/2017	42879	\$17.50
	Comments:	THREAD GATE NOT CLOSING ALL THE WAY  REPLACED THE MOV ON THREAD GATE				
219924	MONTHLY PM FOR FEEDER		7/10/2017	9/1/2017 7:57:11 AM	53	\$40.50
222246	MONTHLY PM FOR FEEDER		10/2/2017	11/18/2017 11:32:48 AM	47	\$40.50
223138	MONTHLY PM FOR FEEDER		11/20/2017	12/21/2017	31	\$40.50
224745	MONTHLY PM FOR FEEDER		1/22/2018	2/20/2018	29	\$40.50
226815	ANNUAL PM FOR FEEDER		4/3/2018	8/3/2018 7:51:10 AM	122	\$101.25
227493	QUARTERLY PM FOR FEEDER		5/21/2018	5/3/2018	0	\$40.50
227697	REPAIR OF EQUIPMENT			4/30/2018	43220	\$15.73
	Comments:	Feeder lift cylinders stuck in down postion. Exhausted air supply to allow cylinders to bleed off excess of air, condensation and or oil from cavity. After a few momments attached air supply cyclinders began operating normally.				
229320	QUARTERLY PM FOR FEEDER		8/1/2018	8/16/2018	15	\$40.50
231083	QUARTERLY PM FOR FEEDER		11/14/2018	12/6/2018 11:40:29 PM	22	\$40.50
233091	QUARTERLY PM FOR FEEDER		3/6/2019	4/24/2019	49	\$40.50
234941	QUARTERLY PM FOR FEEDER		7/22/2019	8/7/2019 3:43:52 PM	16	\$40.50
235361	ANNUAL PM FOR FEEDER		8/5/2019	8/26/2019 1:30:20 PM	21	\$101.25

## Asset/Equipment Work Order History Brief

236429	QUARTERLY PM FOR FEEDER	11/5/2019	12/2/2019 9:45:54 AM	27	\$40.50
237764	QUARTERLY PM FOR FEEDER	3/2/2020	3/10/2020 10:09:13 AM	8	\$40.50
238715	QUARTERLY PM FOR FEEDER	6/8/2020	6/10/2020 11:37:00 AM	2	\$40.50
239494	ANNUAL PM FOR FEEDER	8/25/2020	8/21/2020 11:17:28 AM	0	\$101.25
239802	QUARTERLY PM FOR FEEDER	9/8/2020	10/1/2020 2:39:34 PM	23	\$40.50
240911	QUARTERLY PM FOR FEEDER	1/4/2021	2/9/2021 10:57:36 AM	36	\$40.50
Totals For: <b>PRSS 038.1</b>		Total WOs: 426		Total Cost:	<u>\$18,864.15</u>

**Asset ID: PRSS 038.2**      **Asset: STRAIGHTNER**

Work Order ID	Description	Scheduled Date	Completed Date	Days Past Due	Total Cost
309	MONTHLY PM FOR STREIGHTNER	4/5/2000	4/11/2000 10:11:07 AM	6	\$0.00
1290	MONTHLY PM FOR STREIGHTNER	5/11/2000	5/11/2000 7:32:53 AM	0	\$9.71
2422	MONTHLY PM FOR STREIGHTNER	6/12/2000	6/27/2000 9:29:54 AM	15	\$9.94
3807	MONTHLY PM FOR STREIGHTNER	7/27/2000	8/4/2000 6:10:42 AM	8	\$9.94
5102	MONTHLY PM FOR STREIGHTNER	9/5/2000	9/13/2000 6:26:17 AM	8	\$10.10
6199	MONTHLY PM FOR STREIGHTNER	10/13/2000	10/30/2000 1:29:49 PM	17	\$10.10
7276	RESET ELECTRICAL SYSTEM		11/15/2000 7:05:18 AM	36845	\$40.40
7277	REPAIR RETIGHTENED LOOSE WIRI		11/15/2000 7:06:28 AM	36845	\$0.00
7589	MONTHLY PM FOR STREIGHTNER	11/29/2000	12/12/2000 8:51:55 AM	13	\$10.10
8760	MONTHLY PM FOR STREIGHTNER	1/11/2001	1/10/2001 8:08:14 AM	0	\$10.10
9573	REPAIR ELECTRICAL		1/31/2001	36922	\$0.00
9688	MONTHLY PM FOR STREIGHTNER	2/9/2001	2/26/2001 10:27:52 AM	17	\$0.00
11347	MONTHLY PM FOR STREIGHTNER	3/28/2001	3/29/2001 11:19:52 AM	1	\$10.10
11756	REPAIR AIR LIFTS		4/5/2001 10:00:56 AM	36986	\$0.00
12442	MONTHLY PM FOR STREIGHTNER	4/30/2001	5/4/2001 8:06:04 AM	4	\$10.10

## Asset/Equipment Work Order History Brief

13499	CHANGE OUT PRINTED BOARD TO		5/31/2001		37042	\$47.94
13512	CHECK AND REPAIR		5/31/2001		37042	\$82.68
13551	MONTHLY PM FOR STREIGHTNER	6/4/2001	6/7/2001 9:55:10 AM		3	\$10.10
13620	REPAIR		6/1/2001		37043	\$14.16
13654	REPLACE CONTROL CARDS AND RE		6/4/2001		37046	\$47.94
13663	INSTALL NEW CONTROL BOARDS		6/4/2001		37046	\$93.02
13882	CALIBRATE SPEED CONTROL		6/7/2001		37049	\$20.67
13896	READJUST SPEED CONTROL		6/7/2001		37049	\$23.97
14254	REPAIR		6/19/2001 9:15:07 AM		37061	\$0.00
14801	MONTHLY PM FOR STREIGHTNER	7/9/2001	7/27/2001 6:51:12 AM		18	\$0.00
16514	MONTHLY PM FOR STREIGHTNER	8/27/2001	9/6/2001 1:27:13 PM		10	\$0.00
17532	MONTHLY PM FOR STREIGHTNER	10/8/2001	11/27/2001		50	\$0.00
18575	MONTHLY PM FOR STREIGHTNER	11/12/2001	11/27/2001 7:07:04 AM		15	\$0.00
19639	MONTHLY PM FOR STREIGHTNER	1/1/2002	1/3/2002 8:51:17 AM		2	\$0.00
20709	MONTHLY PM FOR STREIGHTNER	2/4/2002	2/6/2002 3:17:15 PM		2	\$10.10
21607	MONTHLY PM FOR STREIGHTNER	3/8/2002	3/8/2002 2:55:16 PM		0	\$10.10
22831	MONTHLY PM FOR STREIGHTNER	4/8/2002	4/8/2002 11:01:13 AM		0	\$10.10
23672	MONTHLY PM FOR STREIGHTNER	5/8/2002	5/10/2002		2	\$10.10
24915	MONTHLY PM FOR STREIGHTNER	6/10/2002	3/6/2003 12:59:12 PM		269	\$10.85
29864	ANNUAL PM FOR STRAIGHTNER	11/1/2002	11/27/2002		26	\$0.00
29980	REPLACE GUARDING		10/31/2002		37560	\$21.41
32895	REPAIR		2/10/2003		37662	\$65.37
34579	MONTHLY PM FOR STREIGHTNER	4/7/2003	4/10/2003 3:23:09 PM		3	\$10.85

## Asset/Equipment Work Order History Brief

34785	REPAIR		4/8/2003		37719	\$33.26
35783	MONTHLY PM FOR STREIGHTNER	5/12/2003	5/13/2003 12:56:42 PM		1	\$0.00
36644	MONTHLY PM FOR STREIGHTNER	6/12/2003	6/18/2003 11:21:14 AM		6	\$10.85
37770	MONTHLY PM FOR STREIGHTNER	7/18/2003	8/4/2003 8:30:41 AM		17	\$10.85
39071	MONTHLY PM FOR STREIGHTNER	9/3/2003	9/22/2003 11:47:48 AM		19	\$10.85
40453	MONTHLY PM FOR STREIGHTNER	10/22/2003	10/28/2003		6	\$10.85
41718	MONTHLY PM FOR STREIGHTNER	12/1/2003	12/4/2003 10:00:26 AM		3	\$10.85
41777	ANNUAL PM FOR STRAIGHTNER	12/1/2003	12/6/2003		5	\$30.38
42472	MONTHLY PM FOR STREIGHTNER	1/5/2004	1/15/2004 1:45:00 PM		10	\$10.85
43939	MONTHLY PM FOR STREIGHTNER	2/16/2004	2/24/2004		8	\$10.85
44714	REPAIR		3/11/2004 7:07:41 AM		38057	\$43.40
44952	MONTHLY PM FOR STREIGHTNER	3/25/2004	3/26/2004 9:44:25 AM		1	\$0.00
46020	MONTHLY PM FOR STREIGHTNER	4/26/2004	4/27/2004 10:00:11 AM		1	\$0.00
46967	MONTHLY PM FOR STREIGHTNER	5/27/2004	5/27/2004		0	\$10.85
48102	MONTHLY PM FOR STREIGHTNER	6/28/2004	6/28/2004		0	\$10.85
48964	MONTHLY PM FOR STREIGHTNER	7/28/2004	7/27/2004 1:21:13 PM		0	\$10.85
49828	MONTHLY PM FOR STREIGHTNER	8/26/2004	9/2/2004 1:56:14 PM		7	\$10.85
51066	MONTHLY PM FOR STREIGHTNER	10/4/2004	10/7/2004 11:09:42 AM		3	\$10.85
52181	MONTHLY PM FOR STREIGHTNER	11/8/2004	11/15/2004 11:06:15 AM		7	\$11.36
53032	ANNUAL PM FOR STRAIGHTNER	12/6/2004	12/13/2004 9:05:06 AM		7	\$22.71
53270	MONTHLY PM FOR STREIGHTNER	12/15/2004	12/22/2004 3:54:53 PM		7	\$11.36
54214	MONTHLY PM FOR STREIGHTNER	1/21/2005	1/20/2005 10:57:56 AM		0	\$0.00
55291	MONTHLY PM FOR STREIGHTNER	2/21/2005	2/22/2005 11:10:15 AM		1	\$0.00

## Asset/Equipment Work Order History Brief

56149	MONTHLY PM FOR STREIGHTNER	3/24/2005	3/28/2005 2:17:40 PM	4	\$11.36
57210	MONTHLY PM FOR STREIGHTNER	4/27/2005	4/28/2005 12:55:39 PM	1	\$11.36
58282	MONTHLY PM FOR STREIGHTNER	5/30/2005	6/1/2005	2	\$11.36
59256	MONTHLY PM FOR STREIGHTNER	7/1/2005	6/29/2005 1:43:09 PM	0	\$22.71
60170	MONTHLY PM FOR STREIGHTNER	7/29/2005	8/1/2005 8:59:03 AM	3	\$11.36
61341	MONTHLY PM FOR STREIGHTNER	8/31/2005	8/31/2005 7:19:30 AM	0	\$0.00
61612	REPAIR OF EQUIPMENT		9/1/2005	38596	\$34.23
	Comments: NOT ROLLING METAL OFF OF MANDREL CORRECT. CHECK UNIT. NOT GETTING SIGNAL TO OPERATE VALVE WHEN STRAIGHTENER IS ENGAGED.				
62208	MONTHLY PM FOR STREIGHTNER	9/30/2005	9/27/2005 7:15:02 AM	0	\$11.36
63177	MONTHLY PM FOR STREIGHTNER	10/27/2005	10/27/2005 7:11:39 AM	0	\$11.36
64286	MONTHLY PM FOR STREIGHTNER	11/28/2005	12/1/2005 8:15:03 AM	3	\$11.36
64786	ANNUAL PM FOR STRAIGHTNER	12/13/2005	12/15/2005 5:53:10 AM	2	\$22.71
65545	MONTHLY PM FOR STREIGHTNER	1/2/2006	1/25/2006 6:09:56 AM	23	\$11.36
66977	MONTHLY PM FOR STREIGHTNER	2/24/2006	3/2/2006 6:10:59 AM	6	\$11.36
68582	MONTHLY PM FOR STREIGHTNER	4/3/2006	4/6/2006 8:10:19 AM	3	\$11.36
69997	MONTHLY PM FOR STREIGHTNER	5/8/2006	5/11/2006 7:59:36 AM	3	\$0.00
71435	MONTHLY PM FOR STREIGHTNER	6/12/2006	6/12/2006 7:51:15 AM	0	\$11.36
72492	MONTHLY PM FOR STREIGHTNER	7/12/2006	7/12/2006 10:31:15 AM	0	\$11.36
73785	MONTHLY PM FOR STREIGHTNER	8/11/2006	8/10/2006	0	\$0.00
75541	MONTHLY PM FOR STREIGHTNER	9/11/2006	9/13/2006 7:50:26 AM	2	\$5.68
76999	MONTHLY PM FOR STREIGHTNER	10/13/2006	10/23/2006 6:21:44 AM	10	\$0.00
79015	MONTHLY PM FOR STREIGHTNER	11/22/2006	11/29/2006 6:17:02 AM	7	\$0.00
79954	ANNUAL PM FOR STRAIGHTNER	12/15/2006	12/13/2006 6:33:59 AM	0	\$0.00
80722	MONTHLY PM FOR STREIGHTNER	12/29/2006	1/6/2007	8	\$11.36

## Asset/Equipment Work Order History Brief

81626	REPAIR OF EQUIPMENT		1/19/2007 6:37:45 AM	39101	\$26.80
	Comments:	CHECK STRAIGHTENER. IT IS OUT OF LINE. PUT BACK IN LINE.			
82119	REPAIR OF EQUIPMENT		1/25/2007	39107	\$22.68
	Comments:	QUARED UP STRAIGHTENER.			
82327	MONTHLY PM FOR STREIGHTNER	2/5/2007	2/8/2007 8:26:08 AM	3	\$13.40
84216	MONTHLY PM FOR STREIGHTNER	3/12/2007	3/12/2007 10:12:05 AM	0	\$0.00
85572	MONTHLY PM FOR STREIGHTNER	4/11/2007	4/10/2007 10:01:07 AM	0	\$13.40
86944	MONTHLY PM FOR STREIGHTNER	5/10/2007	5/16/2007 9:56:01 AM	6	\$13.40
87113	REPAIR OF EQUIPMENT		5/8/2007	39210	\$90.72
	Comments:	STRAIGHTENER WON'T RUN. TROUBLESHOT TO DRIVE, REMOVED DRIVE FROM CABINET. ARC FLASHED FROM DRIVE, BLOWS FUSES, FOUND BURNT PLACE ON DRIVE.			
87139	REPAIR OF EQUIPMENT		5/9/2007	39211	\$68.04
	Comments:	PROBLEM WITH STRAIGHTENER. CREEPS. ADJUSTED SETTING/CHANGED PARAMETERS, ADJUSTED COILTEK, STILL CREEPS. MIGHT BE A LITTLE SLOWER BUT IT STILL CREEPS			
87154	REPAIR OF EQUIPMENT		5/10/2007	39212	\$0.00
	Comments:	DRIVE NOT WORKING. SWAPPED DRIVES AND DE-BUGGED.			
88609	MONTHLY PM FOR STREIGHTNER	6/15/2007	6/13/2007 8:04:09 AM	0	\$13.40
89973	MONTHLY PM FOR STREIGHTNER	7/13/2007	7/12/2007 8:23:44 AM	0	\$13.40
91487	MONTHLY PM FOR STREIGHTNER	8/13/2007	8/16/2007 6:40:09 AM	3	\$18.07
93113	MONTHLY PM FOR STREIGHTNER	9/17/2007	9/18/2007 11:33:36 AM	1	\$18.07
93406	REPAIR OF EQUIPMENT		9/21/2007 7:52:57 AM	39346	\$163.10
	Comments:	WELD ON NEW METAL FLATTNER FOR 38 PRESS.			
93431	REPAIR OF EQUIPMENT		9/20/2007	39345	\$136.08
	Comments:	BUILT FRAME FOR TENSIONSING ROLLER BETWEEN DECOILER AND STRAIGHTENER.			
94516	MONTHLY PM FOR STREIGHTNER	10/18/2007	10/19/2007 9:44:30 AM	1	\$6.97
96311	MONTHLY PM FOR STREIGHTNER	11/19/2007	11/30/2007 10:25:40 AM	11	\$18.07
98082	MONTHLY PM FOR STREIGHTNER	12/31/2007	12/31/2007	0	\$0.00
98457	MONTHLY PM FOR STREIGHTNER	1/30/2008	1/24/2008 12:39:37 PM	0	\$13.40
99786	MONTHLY PM FOR STREIGHTNER	2/25/2008	2/13/2008	0	\$16.69
101167	MONTHLY PM FOR STREIGHTNER	3/14/2008	3/13/2008 10:10:12 AM	0	\$13.40
102474	ANNUAL PM FOR STRAIGHTNER	3/31/2008	4/25/2008 8:01:35 AM	25	\$26.80

## Asset/Equipment Work Order History Brief

102475	MONTHLY PM FOR STREIGHTNER	4/14/2008	4/18/2008 9:41:49 AM	4	\$13.40
104136	MONTHLY PM FOR STREIGHTNER	5/19/2008	5/27/2008 7:43:07 AM	8	\$11.36
105453	MONTHLY PM FOR STREIGHTNER	6/26/2008	7/1/2008 6:45:01 AM	5	\$13.40
108057	MONTHLY PM FOR STREIGHTNER	7/31/2008	8/19/2008 7:44:32 AM	19	\$14.80
109739	MONTHLY PM FOR STREIGHTNER	9/18/2008	9/19/2008 8:07:23 AM	1	\$14.80
110935	MONTHLY PM FOR STREIGHTNER	10/20/2008	10/15/2008 7:44:50 AM	0	\$14.80
112453	MONTHLY PM FOR STREIGHTNER	11/14/2008	11/26/2008 6:46:02 AM	12	\$14.80
113587	MONTHLY PM FOR STREIGHTNER	12/26/2008	1/9/2009 7:16:42 AM	14	\$14.80
115768	MONTHLY PM FOR STREIGHTNER	2/9/2009	2/3/2009 9:50:21 AM	0	\$14.80
117032	MONTHLY PM FOR STREIGHTNER	3/5/2009	3/23/2009 7:49:12 AM	18	\$14.80
118218	MONTHLY PM FOR STREIGHTNER	4/22/2009	4/16/2009 6:19:42 AM	0	\$14.80
118894	ANNUAL PM FOR STRAIGHTNER	4/27/2009	5/21/2009 6:15:33 AM	24	\$40.50
119434	MONTHLY PM FOR STREIGHTNER	5/18/2009	5/21/2009 6:18:53 AM	3	\$14.80
120826	MONTHLY PM FOR STREIGHTNER	6/22/2009	6/30/2009 6:14:11 AM	8	\$19.37
123214	MONTHLY PM FOR STREIGHTNER	7/30/2009	8/4/2009 6:23:19 AM	5	\$14.65
124963	MONTHLY PM FOR STREIGHTNER	9/3/2009	9/10/2009 6:27:55 AM	7	\$14.59
126354	MONTHLY PM FOR STREIGHTNER	10/12/2009	10/13/2009 6:58:21 AM	1	\$17.01
127676	MONTHLY PM FOR STREIGHTNER	11/12/2009	11/17/2009 10:53:57 AM	5	\$25.79
128831	MONTHLY PM FOR STREIGHTNER	12/17/2009	2/6/2010	51	\$19.37
132658	MONTHLY PM FOR STREIGHTNER	3/8/2010	3/11/2010 2:45:27 PM	3	\$14.65
134092	MONTHLY PM FOR STREIGHTNER	4/12/2010	4/14/2010 7:45:39 AM	2	\$19.37
135172	ANNUAL PM FOR STRAIGHTNER	5/21/2010	5/19/2010 6:37:43 AM	0	\$29.30
135173	MONTHLY PM FOR STREIGHTNER	5/14/2010	5/13/2010	0	\$19.37

## Asset/Equipment Work Order History Brief

136332	MONTHLY PM FOR STREIGHTNER	6/14/2010	6/13/2010	0	\$15.05
137603	MONTHLY PM FOR STREIGHTNER	7/13/2010	8/3/2010 6:51:37 AM	21	\$20.25
139466	MONTHLY PM FOR STREIGHTNER	9/2/2010	9/8/2010 6:27:37 AM	6	\$15.05
140838	MONTHLY PM FOR STREIGHTNER	10/8/2010	10/7/2010 9:24:10 AM	0	\$15.05
141830	MONTHLY PM FOR STREIGHTNER	11/8/2010	11/20/2010	12	\$20.25
142918	MONTHLY PM FOR STREIGHTNER	12/20/2010	12/28/2010 6:07:36 AM	8	\$15.05
143720	MONTHLY PM FOR STREIGHTNER	1/27/2011	2/3/2011 6:59:57 AM	7	\$15.05
145720	MONTHLY PM FOR STREIGHTNER	3/7/2011	3/24/2011	17	\$20.25
146829	MONTHLY PM FOR STREIGHTNER	4/25/2011	4/26/2011 7:11:30 AM	1	\$20.25
147824	ANNUAL PM FOR STRAIGHTNER	5/19/2011	11/5/2011	170	\$30.10
147825	MONTHLY PM FOR STREIGHTNER	5/26/2011	5/20/2011 7:23:37 AM	0	\$15.05
148403	REPAIR OF EQUIPMENT		5/23/2011 3:09:24 PM	40686	\$20.25
	Comments: WILL NOT RUN. RESET DRIVE FAULT.				
148831	MONTHLY PM FOR STREIGHTNER	6/20/2011	6/30/2011 11:48:35 AM	10	\$20.25
150682	MONTHLY PM FOR STREIGHTNER	8/1/2011	8/11/2011 7:27:13 AM	10	\$15.05
151804	MONTHLY PM FOR STREIGHTNER	9/12/2011	9/9/2011 6:53:22 AM	0	\$15.05
152643	MONTHLY PM FOR STREIGHTNER	10/10/2011	10/22/2011 7:10:51 AM	12	\$15.05
153603	MONTHLY PM FOR STREIGHTNER	11/21/2011	11/30/2011 8:48:26 AM	9	\$20.25
154633	MONTHLY PM FOR STREIGHTNER	12/30/2011	1/4/2012 8:00:48 AM	5	\$15.05
156178	MONTHLY PM FOR STREIGHTNER	2/3/2012	2/3/2012	0	\$15.05
156856	REPAIR OF EQUIPMENT		2/13/2012 8:06:24 AM	40952	\$28.35
	Comments: WONT RUN				
	RESET FAULT ON DRIVE ADJUSTED UNCOILER TO ASSIST STRAIGHTNER				
157553	MONTHLY PM FOR STREIGHTNER	3/5/2012	3/10/2012 6:50:53 AM	5	\$20.25
158532	MONTHLY PM FOR STREIGHTNER	4/9/2012	4/5/2012 7:45:04 AM	0	\$15.05

## Asset/Equipment Work Order History Brief

159081	REPAIR OF EQUIPMENT		4/23/2012		41022	\$47.18
	Comments:	REPAIR SAFETY BARRIERS ON FEED LINE REMOVED AND REPAIRED PIPE BALLARDS THAT SAFETY BARRIER CHAINS ARE HUNG FROM REINSTALLED				
159534	MONTHLY PM FOR STREIGHTNER	5/7/2012	5/4/2012 7:34:31 AM		0	\$20.25
159988	REPAIR OF EQUIPMENT		5/14/2012		41043	\$35.00
	Comments:	STRAIGHTNER WONT OPEN IN MANUAL MODE METAL WONT GO THROUGH STRAIGHTNER ROLLERS CHECK ROLLERS OPERATION THEY WORKED FINE METAL ACTUALLY GO THROUGH ROLLERS BUT HITTING SOMETHING FORCE TO OPEN METAL WENT THROUGH STRAIGHTNER PRESS RUN FINE REST OF 2ND SHIFT				
160549	MONTHLY PM FOR STREIGHTNER	6/4/2012	6/15/2012		11	\$20.25
161472	MONTHLY PM FOR STREIGHTNER	7/16/2012	7/18/2012		2	\$20.25
162721	MONTHLY PM FOR STREIGHTNER	8/17/2012	8/15/2012 8:13:08 AM		0	\$19.98
163611	MONTHLY PM FOR STREIGHTNER	9/14/2012	9/20/2012 8:13:26 AM		6	\$20.25
164620	MONTHLY PM FOR STREIGHTNER	10/22/2012	10/16/2012 8:11:56 AM		0	\$15.05
165794	ANNUAL PM FOR STRAIGHTNER	11/5/2012	12/5/2012		30	\$0.00
165795	MONTHLY PM FOR STREIGHTNER	11/15/2012	11/14/2012 7:09:48 AM		0	\$20.25
166632	MONTHLY PM FOR STREIGHTNER	12/14/2012	12/20/2012 8:05:12 AM		6	\$14.85
167425	MONTHLY PM FOR STREIGHTNER	1/21/2013	2/12/2013 7:34:50 AM		22	\$14.65
167899	REPAIR OF EQUIPMENT		1/18/2013		41292	\$70.00
	Comments:	STRAIGHTENER DOWN CHECK FOR PROPER CONTROL POSITION CHECK VOLTAGE FUSE BLOWN REPLACE				
169212	MONTHLY PM FOR STREIGHTNER	3/14/2013	3/15/2013 7:23:33 AM		1	\$20.25
170168	MONTHLY PM FOR STREIGHTNER	4/15/2013	4/18/2013 7:58:46 AM		3	\$20.25
171232	MONTHLY PM FOR STREIGHTNER	5/20/2013	5/23/2013 8:52:09 AM		3	\$20.25
172116	MONTHLY PM FOR STREIGHTNER	6/24/2013	6/25/2013 7:39:46 AM		1	\$20.25
173127	MONTHLY PM FOR STREIGHTNER	7/25/2013	8/7/2013 7:59:46 AM		13	\$20.25
175127	MONTHLY PM FOR STREIGHTNER	9/6/2013	9/20/2013 7:27:47 AM		14	\$20.25
176078	MONTHLY PM FOR STREIGHTNER	10/21/2013	10/15/2013 7:53:04 AM		0	\$20.25

## Asset/Equipment Work Order History Brief

177192	MONTHLY PM FOR STREIGHTNER	11/14/2013	12/6/2013 8:44:47 AM	22	\$0.00	
178093	ANNUAL PM FOR STRAIGHTNER	12/5/2013	1/30/2014 7:45:47 AM	56	\$0.00	
178871	MONTHLY PM FOR STREIGHTNER	1/6/2014	1/14/2014 7:43:58 AM	8	\$20.25	
179845	MONTHLY PM FOR STREIGHTNER	2/13/2014	2/13/2014 8:20:29 AM	0	\$20.25	
181019	MONTHLY PM FOR STREIGHTNER	3/17/2014	3/26/2014 7:32:42 AM	9	\$14.65	
181818	MONTHLY PM FOR STREIGHTNER	4/25/2014	4/17/2014 7:07:30 AM	0	\$14.65	
182865	MONTHLY PM FOR STREIGHTNER	5/19/2014	6/3/2014 7:45:26 AM	15	\$20.25	
184563	MONTHLY PM FOR STREIGHTNER	7/3/2014	7/8/2014 7:17:24 AM	5	\$14.65	
185823	MONTHLY PM FOR STREIGHTNER	8/7/2014	8/5/2014 7:42:15 AM	0	\$40.50	
186830	MONTHLY PM FOR STREIGHTNER	9/4/2014	9/18/2014 7:25:10 AM	14	\$40.50	
187973	MONTHLY PM FOR STREIGHTNER	10/20/2014	10/17/2014 7:18:12 AM	0	\$40.50	
188844	MONTHLY PM FOR STREIGHTNER	11/17/2014	12/2/2014 7:21:13 AM	15	\$40.50	
190512	ANNUAL PM FOR STRAIGHTNER	1/30/2015	1/20/2015	0	\$31.45	
190513	MONTHLY PM FOR STREIGHTNER	1/1/2015	1/13/2015 7:29:55 AM	12	\$40.50	
191547	MONTHLY PM FOR STREIGHTNER	2/12/2015	2/12/2015 10:54:53 AM	0	\$40.50	
192523	MONTHLY PM FOR STREIGHTNER	3/16/2015	3/18/2015 7:34:41 AM	2	\$40.50	
193621	MONTHLY PM FOR STREIGHTNER	4/17/2015	4/23/2015	6	\$35.98	
193908	REPAIR OF EQUIPMENT		4/7/2015	42101	\$122.50	
	Comments:	PLEASE EXTEND CORD ON HANDHELD STRAIGHTENER CONTROL				
		OPERATOR NEEDS TO EXTEND STRAIGHTENER PENDANT TO FEEDER COULD NOT FIND A COIL CORD LONG ENOUGH RUN SOME CONDUIT TO ADD PENDANT CLOSE TO FEEDER RUN WIRE AND ADD PENDANT CHECK OPERATIO OK				
194681	MONTHLY PM FOR STREIGHTNER	5/25/2015	5/21/2015	0	\$31.45	
195596	MONTHLY PM FOR STREIGHTNER	6/22/2015	6/18/2015	0	\$40.50	
196682	MONTHLY PM FOR STREIGHTNER	7/20/2015	9/30/2015	72	\$40.50	

## Asset/Equipment Work Order History Brief

199802	MONTHLY PM FOR STREIGHTNER	10/30/2015	10/29/152	0	\$0.00
200830	MONTHLY PM FOR STREIGHTNER	11/28/152	12/10/2015	680458	\$0.00
202830	ANNUAL PM FOR STRAIGHTNER	1/20/2016	1/29/2016	9	\$40.50
202831	MONTHLY PM FOR STREIGHTNER	1/11/2016	1/14/2016 7:36:02 AM	3	\$40.50
203930	MONTHLY PM FOR STREIGHTNER	2/15/2016	2/11/2016	0	\$40.50
204758	MONTHLY PM FOR STREIGHTNER	3/14/2016	3/11/2016	0	\$40.50
205190	REPAIR OF EQUIPMENT		3/10/2016	42439	\$66.45
	Comments: WIRE PULLED OUT OF STRAIGHTENER PENDANT				
	PUT WIRES BACK IN PENDANT AND TERMINATED AFTER FIGUING OUT WHICH ONE WENT WEHRE TURNED POWER ON AND REPLACED FUSE WORK LIKE IT SHOULD				
205885	MONTHLY PM FOR STREIGHTNER	4/11/2016	4/20/2016	9	\$0.00
206857	MONTHLY PM FOR STREIGHTNER	5/20/2016	5/24/2016	4	\$0.00
207860	MONTHLY PM FOR STREIGHTNER	6/23/2016	6/28/2016	5	\$0.00
208993	MONTHLY PM FOR STREIGHTNER	7/28/2016	7/21/2016	0	\$0.00
209937	MONTHLY PM FOR STREIGHTNER	8/22/2016	8/24/2016 8:03:22 AM	2	\$40.50
211092	MONTHLY PM FOR STREIGHTNER	9/23/2016	9/23/2016 7:36:31 AM	0	\$40.50
212261	MONTHLY PM FOR STREIGHTNER	10/24/2016	10/27/2016 7:57:34 AM	3	\$40.50
213173	MONTHLY PM FOR STREIGHTNER	11/28/2016	11/17/2016	0	\$40.50
214052	MONTHLY PM FOR STREIGHTNER	12/19/2016	12/30/2016 9:54:56 AM	11	\$40.50
214964	ANNUAL PM FOR STRAIGHTNER	1/30/2017	4/3/2017 11:41:10 AM	63	\$0.00
214965	MONTHLY PM FOR STREIGHTNER	1/30/2017	2/18/2017	19	\$0.00
216626	MONTHLY PM FOR STREIGHTNER	3/20/2017	4/3/2017 12:20:08 PM	14	\$40.50
218178	MONTHLY PM FOR STREIGHTNER	5/3/2017	6/9/2017 10:10:32 AM	37	\$40.50
219925	MONTHLY PM FOR STREIGHTNER	7/10/2017	9/1/2017 7:57:02 AM	53	\$40.50
222247	MONTHLY PM FOR STREIGHTNER	10/2/2017	11/18/2017 11:33:00 AM	47	\$40.50

## Asset/Equipment Work Order History Brief

223139	MONTHLY PM FOR STREIGHTNER	11/20/2017	12/21/2017	31	\$40.50
224746	MONTHLY PM FOR STREIGHTNER	1/22/2018	2/20/2018	29	\$40.50
226816	ANNUAL PM FOR STRAIGHTNER	4/3/2018	8/3/2018 7:51:29 AM	122	\$40.50
227494	QUARTERLY PM FOR STREIGHTNER	5/21/2018	5/3/2018	0	\$40.50
229321	QUARTERLY PM FOR STREIGHTNER	8/1/2018	8/16/2018	15	\$40.50
231084	QUARTERLY PM FOR STREIGHTNER	11/14/2018	12/6/2018 11:41:09 PM	22	\$40.50
233092	QUARTERLY PM FOR STREIGHTNER	3/6/2019	4/24/2019	49	\$40.50
234942	QUARTERLY PM FOR STREIGHTNER	7/22/2019	8/7/2019 3:45:08 PM	16	\$40.50
235362	ANNUAL PM FOR STRAIGHTNER	8/5/2019	8/27/2019 1:51:25 PM	22	\$40.50
236430	QUARTERLY PM FOR STREIGHTNER	11/5/2019	12/2/2019 9:46:07 AM	27	\$40.50
237765	QUARTERLY PM FOR STREIGHTNER	3/2/2020	3/10/2020 10:09:29 AM	8	\$40.50
238716	QUARTERLY PM FOR STREIGHTNER	6/8/2020	6/10/2020 11:37:36 AM	2	\$40.50
239495	ANNUAL PM FOR STRAIGHTNER	8/26/2020	8/21/2020 11:18:46 AM	0	\$40.50
239803	QUARTERLY PM FOR STREIGHTNER	9/8/2020	10/1/2020 2:39:50 PM	23	\$40.50
240912	QUARTERLY PM FOR STREIGHTNER	1/4/2021	2/9/2021 10:57:49 AM	36	\$40.50
Totals For: <b>PRSS 038.2</b>		Total WOs: 229		Total Cost:	<u>\$4,998.48</u>

**Asset ID: PRSS 038.3      Asset: COIL MANDREL 10000 LB CAP**

Work Order ID	Description	Scheduled Date	Completed Date	Days Past Due	Total Cost
310	MONTHLY PM ON COIL MANDREL	4/5/2000	4/11/2000 10:14:03 AM	6	\$0.00
1291	MONTHLY PM ON COIL MANDREL	5/11/2000	5/11/2000 7:39:07 AM	0	\$4.86
2423	MONTHLY PM ON COIL MANDREL	6/12/2000	6/27/2000 9:48:01 AM	15	\$4.97
3808	MONTHLY PM ON COIL MANDREL	7/27/2000	8/4/2000 6:15:12 AM	8	\$4.97
5103	MONTHLY PM ON COIL MANDREL	9/5/2000	9/13/2000 6:29:32 AM	8	\$5.05
6200	MONTHLY PM ON COIL MANDREL	10/13/2000	10/30/2000 1:28:51 PM	17	\$5.05

## Asset/Equipment Work Order History Brief

7018	REPAIR		11/3/2000		36833	\$20.81
7590	MONTHLY PM ON COIL MANDREL	11/29/2000	12/12/2000 8:48:22 AM		13	\$5.05
8761	MONTHLY PM ON COIL MANDREL	1/11/2001	1/10/2001 8:03:56 AM		0	\$5.05
8906	REPAIR		1/11/2001		36902	\$23.97
9689	MONTHLY PM ON COIL MANDREL	2/9/2001	2/26/2001 10:31:25 AM		17	\$0.00
11348	MONTHLY PM ON COIL MANDREL	3/28/2001	3/29/2001 11:12:51 AM		1	\$5.05
12443	MONTHLY PM ON COIL MANDREL	4/30/2001	5/4/2001 8:11:26 AM		4	\$5.05
13552	MONTHLY PM ON COIL MANDREL	6/4/2001	6/7/2001 9:51:47 AM		3	\$5.05
14802	MONTHLY PM ON COIL MANDREL	7/9/2001	7/27/2001 6:54:02 AM		18	\$0.00
16515	MONTHLY PM ON COIL MANDREL	8/27/2001	9/6/2001 1:27:33 PM		10	\$0.00
17533	MONTHLY PM ON COIL MANDREL	10/8/2001	11/27/2001 6:58:34 AM		50	\$0.00
19640	MONTHLY PM ON COIL MANDREL	1/1/2002	1/25/2002 2:10:18 PM		24	\$0.00
21369	MONTHLY PM ON COIL MANDREL	2/25/2002	2/26/2002 10:52:50 AM		1	\$5.05
22318	MONTHLY PM ON COIL MANDREL	3/28/2002	3/27/2002		0	\$0.00
23319	MONTHLY PM ON COIL MANDREL	4/26/2002	4/29/2002 10:54:27 AM		3	\$0.00
24419	MONTHLY PM ON COIL MANDREL	5/29/2002	5/28/2002 10:56:48 AM		0	\$0.00
25438	MONTHLY PM ON COIL MANDREL	6/27/2002	6/26/2002 8:42:05 AM		0	\$5.43
26348	MONTHLY PM FOR COIL MANDREL	7/26/2002	7/22/2002 8:52:49 AM		0	\$0.00
27391	MONTHLY PM ON COIL MANDREL	8/21/2002	9/4/2002 9:14:23 AM		14	\$5.43
28843	MONTHLY PM ON COIL MANDREL	10/4/2002	10/4/2002 7:16:02 AM		0	\$0.00
30019	MONTHLY PM ON COIL MANDREL	11/4/2002	11/6/2002 11:40:31 AM		2	\$5.43
30097	REPAIR FLEX TRACK		11/1/2002		37561	\$44.62
30735	MONTHLY PM ON COIL MANDREL	12/6/2002	12/5/2002 2:29:43 PM		0	\$5.43

## Asset/Equipment Work Order History Brief

31775	MONTHLY PM ON COIL MANDREL	1/6/2003	2/18/2003 6:39:54 AM	43	\$0.00
33863	MONTHLY PM ON COIL MANDREL	3/20/2003	3/18/2003 7:06:53 AM	0	\$5.43
34873	MONTHLY PM ON COIL MANDREL	4/17/2003	4/15/2003 10:21:00 AM	0	\$5.43
35784	MONTHLY PM ON COIL MANDREL	5/15/2003	5/13/2003 12:57:05 PM	0	\$0.00
36645	MONTHLY PM ON COIL MANDREL	6/12/2003	6/18/2003 11:21:35 AM	6	\$5.43
37771	MONTHLY PM ON COIL MANDREL	7/18/2003	8/4/2003 8:26:04 AM	17	\$5.43
39072	MONTHLY PM ON COIL MANDREL	9/3/2003	9/22/2003 11:43:40 AM	19	\$5.43
40454	MONTHLY PM ON COIL MANDREL	10/22/2003	10/28/2003	6	\$5.43
41719	MONTHLY PM ON COIL MANDREL	12/1/2003	12/4/2003 9:56:48 AM	3	\$5.43
42473	MONTHLY PM ON COIL MANDREL	1/5/2004	1/15/2004 1:41:53 PM	10	\$5.43
43883	REPAIR		2/12/2004 10:26:43 AM	38029	\$43.40
43940	MONTHLY PM ON COIL MANDREL	2/16/2004	2/24/2004	8	\$5.43
44953	MONTHLY PM ON COIL MANDREL	3/25/2004	3/26/2004 9:43:22 AM	1	\$0.00
46021	MONTHLY PM ON COIL MANDREL	4/26/2004	4/27/2004 10:01:21 AM	1	\$0.00
46968	MONTHLY PM ON COIL MANDREL	5/27/2004	5/27/2004	0	\$5.43
48103	MONTHLY PM ON COIL MANDREL	6/28/2004	6/28/2004	0	\$5.43
48965	MONTHLY PM ON COIL MANDREL	7/28/2004	7/27/2004 1:21:53 PM	0	\$5.43
49829	MONTHLY PM ON COIL MANDREL	8/26/2004	9/2/2004 1:56:59 PM	7	\$5.43
51067	MONTHLY PM ON COIL MANDREL	10/4/2004	10/7/2004 10:46:55 AM	3	\$5.43
52182	MONTHLY PM ON COIL MANDREL	11/8/2004	11/15/2004 11:01:53 AM	7	\$5.68
52576	REPAIR		11/19/2004	38310	\$0.00
53271	MONTHLY PM ON COIL MANDREL	12/15/2004	12/22/2004 3:53:13 PM	7	\$5.68
54215	MONTHLY PM ON COIL MANDREL	1/21/2005	1/20/2005 10:56:57 AM	0	\$0.00

## Asset/Equipment Work Order History Brief

55292	MONTHLY PM ON COIL MANDREL	2/21/2005	2/22/2005 11:10:34 AM	1	\$0.00
55591	REPAIR ELECTRICAL (SHORTED OU		3/2/2005	38413	\$26.22
55612	REPAIR		3/4/2005 8:30:53 AM	38415	\$48.93
56150	MONTHLY PM ON COIL MANDREL	3/24/2005	3/28/2005 2:19:42 PM	4	\$5.68
57211	MONTHLY PM ON COIL MANDREL	4/27/2005	4/28/2005 12:53:12 PM	1	\$5.68
57469	REPAIR MANDRELL (BLOWN FUSE)		5/2/2005	38474	\$26.22
58283	MONTHLY PM ON COIL MANDREL	5/30/2005	6/1/2005	2	\$5.68
59257	MONTHLY PM ON COIL MANDREL	7/1/2005	6/29/2005 1:41:38 PM	0	\$11.36
60171	MONTHLY PM ON COIL MANDREL	7/29/2005	8/1/2005 8:58:01 AM	3	\$5.68
61342	MONTHLY PM ON COIL MANDREL	8/31/2005	9/8/2005 7:56:09 AM	8	\$5.68
62696	MONTHLY PM ON COIL MANDREL	10/10/2005	10/13/2005 7:13:35 AM	3	\$0.00
63872	MONTHLY PM ON COIL MANDREL	11/14/2005	11/22/2005 6:37:44 AM	8	\$0.00
64926	REPAIR OF EQUIPMENT		12/15/2005 6:42:20 AM	38701	\$26.22
	Comments: MANDRELL QUIT RUNNING. FOUND FUSE BLOWN.				
65020	MONTHLY PM ON COIL MANDREL	12/22/2005	12/23/2005 8:00:20 AM	1	\$5.68
66002	MONTHLY PM ON COIL MANDREL	1/23/2006	1/25/2006 6:04:48 AM	2	\$0.00
66978	MONTHLY PM ON COIL MANDREL	2/24/2006	3/2/2006 6:10:22 AM	6	\$5.90
68583	MONTHLY PM ON COIL MANDREL	4/3/2006	4/6/2006 8:10:53 AM	3	\$5.90
69998	MONTHLY PM ON COIL MANDREL	5/8/2006	5/11/2006 7:59:08 AM	3	\$0.00
71436	MONTHLY PM ON COIL MANDREL	6/12/2006	6/12/2006 7:50:42 AM	0	\$5.90
72493	MONTHLY PM ON COIL MANDREL	7/12/2006	7/12/2006 10:29:38 AM	0	\$5.90
72927	REPAIR OF EQUIPMENT		7/17/2006	38915	\$0.00
	Comments: PLC WAS HOT AND NOT WORKING. LET COOL DOWN AND STARTED LOOKING AT WIRE AND FUSE. N/C CONTACT WAS BROKE ON OVERLOAD. WE DID NOT HAVE ANY LIKE THE ONES THAT WERE ON THERE SO USED A SET OF AB.				
73786	MONTHLY PM ON COIL MANDREL	8/11/2006	8/10/2006	0	\$0.00
75542	MONTHLY PM ON COIL MANDREL	9/11/2006	9/13/2006 7:51:01 AM	2	\$2.95

## Asset/Equipment Work Order History Brief

77000	MONTHLY PM ON COIL MANDREL	10/13/2006	10/23/2006 6:21:21 AM	10	\$0.00
79016	MONTHLY PM ON COIL MANDREL	11/22/2006	11/29/2006 6:16:17 AM	7	\$0.00
80723	MONTHLY PM ON COIL MANDREL	12/29/2006	1/6/2007	8	\$5.90
82196	REPAIR OF EQUIPMENT		1/29/2007	39111	\$36.47
	Comments: AFFIX CHAIN GUARD POLE TO FLOOR- NEXT TO THE MANDREL. DRILLED AND INSTALL POLE BACK IN PLACE.				
82328	MONTHLY PM ON COIL MANDREL	2/5/2007	2/8/2007 8:26:39 AM	3	\$6.97
84217	MONTHLY PM ON COIL MANDREL	3/12/2007	3/12/2007 10:11:40 AM	0	\$0.00
85573	MONTHLY PM ON COIL MANDREL	4/11/2007	4/10/2007 10:01:34 AM	0	\$6.97
86945	MONTHLY PM ON COIL MANDREL	5/10/2007	5/16/2007 9:56:36 AM	6	\$6.97
88417	REPAIR OF EQUIPMENT		6/5/2007	39238	\$30.62
	Comments: PRESS SQUEALING. CLUTCH NOT ENGAGED ENOUGH ON MANDREL.				
88610	MONTHLY PM ON COIL MANDREL	6/15/2007	6/13/2007 8:04:40 AM	0	\$6.97
89974	MONTHLY PM ON COIL MANDREL	7/13/2007	7/12/2007 8:20:40 AM	0	\$9.03
91488	MONTHLY PM ON COIL MANDREL	8/13/2007	8/16/2007 6:40:41 AM	3	\$9.03
93114	MONTHLY PM ON COIL MANDREL	9/17/2007	9/18/2007 11:34:13 AM	1	\$9.03
93633	REPAIR OF EQUIPMENT		9/22/2007	39347	\$184.24
	Comments: INSTALL ROLLER ASSY. BETWEEN COIL MANDREL AND STRAIGHTENER ON # 38 PRESS. DID INSTALL, MOUNT, ADJUST, AND CLEANED ROLLER ASSY.				
94517	MONTHLY PM ON COIL MANDREL	10/18/2007	10/19/2007 9:46:17 AM	1	\$6.97
96312	MONTHLY PM ON COIL MANDREL	11/19/2007	11/30/2007 10:21:59 AM	11	\$9.03
98083	MONTHLY PM ON COIL MANDREL	12/31/2007	12/31/2007	0	\$0.00
98458	MONTHLY PM ON COIL MANDREL	1/30/2008	1/24/2008 12:40:18 PM	0	\$6.97
99787	MONTHLY PM ON COIL MANDREL	2/25/2008	2/13/2008	0	\$8.68
101168	MONTHLY PM ON COIL MANDREL	3/14/2008	3/13/2008 10:09:40 AM	0	\$6.97
102476	MONTHLY PM ON COIL MANDREL	4/14/2008	4/18/2008 9:42:58 AM	4	\$6.97
102716	ANNUAL PM FOR MANDREL		4/25/2008 7:58:42 AM	39563	\$40.20
104137	MONTHLY PM ON COIL MANDREL	5/19/2008	5/27/2008 7:43:54 AM	8	\$5.68

## Asset/Equipment Work Order History Brief

105454	MONTHLY PM ON COIL MANDREL	6/26/2008	7/1/2008 6:45:48 AM	5	\$6.97
108058	MONTHLY PM ON COIL MANDREL	7/31/2008	8/19/2008 7:45:04 AM	19	\$7.70
109740	MONTHLY PM ON COIL MANDREL	9/18/2008	9/19/2008 8:07:56 AM	1	\$7.70
110936	MONTHLY PM ON COIL MANDREL	10/20/2008	10/15/2008 7:45:49 AM	0	\$7.70
112454	MONTHLY PM ON COIL MANDREL	11/14/2008	11/26/2008 6:47:34 AM	12	\$7.70
113588	MONTHLY PM ON COIL MANDREL	12/26/2008	1/9/2009 7:17:26 AM	14	\$7.70
115769	MONTHLY PM ON COIL MANDREL	2/9/2009	2/3/2009 9:50:55 AM	0	\$7.70
117033	MONTHLY PM ON COIL MANDREL	3/5/2009	3/23/2009 7:49:46 AM	18	\$7.70
118219	MONTHLY PM ON COIL MANDREL	4/22/2009	4/16/2009 6:20:21 AM	0	\$7.10
118985	ANNUAL PM FOR MANDREL	4/27/2009	5/21/2009 6:14:59 AM	24	\$60.75
119435	MONTHLY PM ON COIL MANDREL	5/18/2009	5/21/2009 6:19:26 AM	3	\$7.40
119779	REPAIR OF EQUIPMENT		5/2/2009	39935	\$297.65
	Comments: UNCRATED HOLD DOWN ARM. STARTED LOOKING AT HOW TO MOUNT IT.				
120827	MONTHLY PM ON COIL MANDREL	6/22/2009	6/30/2009 6:13:32 AM	8	\$9.68
123215	MONTHLY PM ON COIL MANDREL	7/30/2009	8/4/2009 6:22:54 AM	5	\$7.33
124964	MONTHLY PM ON COIL MANDREL	9/3/2009	9/10/2009 6:28:45 AM	7	\$7.30
126355	MONTHLY PM ON COIL MANDREL	10/12/2009	10/13/2009 6:59:04 AM	1	\$8.84
127677	MONTHLY PM ON COIL MANDREL	11/12/2009	11/17/2009 10:55:17 AM	5	\$12.90
128832	MONTHLY PM ON COIL MANDREL	12/17/2009	2/6/2010	51	\$8.50
129046	REPAIR OF EQUIPMENT		11/25/2009	40142	\$290.84
	Comments: REMOVED CONTROL CABINET, WIRING, AND BRACKET FROM MANDREL IN PREARATION FOR HOLD DOWN ARM INSTALLATION				
129068	REPAIR OF EQUIPMENT		11/30/2009	40147	\$526.30
	Comments: INSTALLED HOLD DOWN ARM ON MANDREL				
129069	REPAIR OF EQUIPMENT		11/30/2009	40147	\$474.77
	Comments: WIRE CONTROLS BACK IN AFTER HOLD DOWN ARM INSTALLATION. REPAIRED BROKEN IDLER SPROCKET. WILL TEST WHEN WE ARE ABLE TO POWER UP.				
130791	REPAIR OF EQUIPMENT		1/15/2010	40193	\$239.40
	Comments: DEAD HEAD ON TRASFORMER. COULD NOT FIND PRINTS. WILL ASK JERROD.				

## Asset/Equipment Work Order History Brief

130814	REPAIR OF EQUIPMENT	1/15/2010	40193	\$181.78	
	Comments: FOUND WIRE IN WRONG SPOT. FOUND TWO RELAYS IN MANDREL WERE WRONG. NEED A/B RELAYS 700-HF32A1.				
130816	REPAIR OF EQUIPMENT	1/16/2010	40194	\$51.30	
	Comments: INSTALLED RELAYS IN Y2 AND Y3. STILL WOULD NOT WORK. CHECKED RELAYS ON SHELF AND THEY WERE BAD, PUT IN TWO NEW ONES AND THEY WORKED.				
130829	REPAIR OF EQUIPMENT	1/19/2010	40197	\$129.04	
	Comments: COIL MANDREL STUCK, COIL WONT COME OFF				
	LOOSEMED MANDREL MANUALLY, FOUND MADREL CONTROLS OPERATING BACKWARDS, FWP/REV& CONT/EXP WERE REVERSED, SWAPPED TWO LEGS OF 480V INPUT, PROBLEM IS CORRECTED.				
130832	REPAIR OF EQUIPMENT	1/18/2010	40196	\$57.77	
	Comments: MANDREL HUNG UP				
	TRIED TO FREE BUT COULDN'T WAIT FOR 3RD SHIFT TO HELP				
131576	REPAIR OF EQUIPMENT	1/28/2010	40206	\$145.42	
	Comments: PENDANT CORD GOT CUT.				
	REPLACED PENDANT AND CORD. TESTED AND WORKED.				
131579	REPAIR OF EQUIPMENT	1/29/2010	40207	\$36.36	
	Comments: COIL CART WONT MOVE				
	DEBRIS ON TRACK. REMOVED DEBRIS. WORKS GOOD				
131581	REPAIR OF EQUIPMENT	1/29/2010	40207	\$110.58	
	Comments: REROUTE AIR HOSE				
	DID REROUTE AIR HOSE AND SATISFIED DON GENTRY				
132659	MONTHLY PM ON COIL MANDREL	3/8/2010	3/11/2010 2:46:29 PM	3	\$7.33
134093	MONTHLY PM ON COIL MANDREL	4/12/2010	4/14/2010 7:45:09 AM	2	\$9.68
135174	ANNUAL PM FOR MANDREL	5/21/2010	5/19/2010 6:39:25 AM	0	\$58.10
135175	MONTHLY PM ON COIL MANDREL	5/14/2010	5/13/2010	0	\$9.68
136333	MONTHLY PM ON COIL MANDREL	6/14/2010	6/13/2010	0	\$7.53
137604	MONTHLY PM ON COIL MANDREL	7/13/2010	8/3/2010 6:52:04 AM	21	\$10.13
139467	MONTHLY PM ON COIL MANDREL	9/2/2010	9/8/2010 6:27:17 AM	6	\$7.53

## Asset/Equipment Work Order History Brief

140839	MONTHLY PM ON COIL MANDREL	10/8/2010	10/7/2010 9:23:54 AM	0	\$7.53
141831	MONTHLY PM ON COIL MANDREL	11/8/2010	11/20/2010	12	\$10.13
142919	MONTHLY PM ON COIL MANDREL	12/20/2010	12/28/2010 6:13:02 AM	8	\$10.13
143721	MONTHLY PM ON COIL MANDREL	1/27/2011	2/3/2011 7:00:24 AM	7	\$7.53
145721	MONTHLY PM ON COIL MANDREL	3/7/2011	3/24/2011	17	\$7.53
146075	REPAIR OF EQUIPMENT		3/7/2011	40609	\$70.00
	Comments: COIL CAR CAME OFF TRACK - NRA				
	PUT BACK ON TRACK				
146830	MONTHLY PM ON COIL MANDREL	4/25/2011	4/26/2011 7:20:10 AM	1	\$7.53
147826	ANNUAL PM FOR MANDREL	5/19/2011	11/5/2011	170	\$45.15
147827	MONTHLY PM ON COIL MANDREL	5/26/2011	5/20/2011 7:23:13 AM	0	\$7.53
148832	MONTHLY PM ON COIL MANDREL	6/20/2011	6/30/2011 11:44:23 AM	10	\$7.53
150683	MONTHLY PM ON COIL MANDREL	8/1/2011	8/11/2011 7:26:45 AM	10	\$15.05
151805	MONTHLY PM ON COIL MANDREL	9/12/2011	9/9/2011 6:52:57 AM	0	\$15.05
152644	MONTHLY PM ON COIL MANDREL	10/10/2011	10/22/2011 7:11:23 AM	12	\$20.25
153604	MONTHLY PM ON COIL MANDREL	11/21/2011	11/30/2011 8:47:58 AM	9	\$20.25
154634	MONTHLY PM ON COIL MANDREL	12/30/2011	1/4/2012 8:08:12 AM	5	\$20.25
156179	MONTHLY PM ON COIL MANDREL	2/3/2012	2/3/2012	0	\$15.05
157554	MONTHLY PM ON COIL MANDREL	3/5/2012	3/10/2012 6:50:39 AM	5	\$20.25
158533	MONTHLY PM ON COIL MANDREL	4/9/2012	4/5/2012 7:45:24 AM	0	\$15.05
159535	MONTHLY PM ON COIL MANDREL	5/7/2012	5/4/2012 8:02:51 AM	0	\$0.00
160550	MONTHLY PM ON COIL MANDREL	6/4/2012	6/15/2012	11	\$15.05
161473	MONTHLY PM ON COIL MANDREL	7/16/2012	7/18/2012	2	\$15.05
162722	MONTHLY PM ON COIL MANDREL	8/17/2012	8/15/2012 8:13:32 AM	0	\$19.98
163612	MONTHLY PM ON COIL MANDREL	9/14/2012	9/20/2012 7:52:00 AM	6	\$15.05

## Asset/Equipment Work Order History Brief

164621	MONTHLY PM ON COIL MANDREL	10/22/2012	10/16/2012 8:15:23 AM	0	\$0.00
165796	ANNUAL PM FOR MANDREL	11/5/2012	12/5/2012	30	\$0.00
165797	MONTHLY PM ON COIL MANDREL	11/15/2012	11/14/2012 7:10:11 AM	0	\$20.25
166633	MONTHLY PM ON COIL MANDREL	12/14/2012	12/20/2012 8:04:18 AM	6	\$14.85
167426	MONTHLY PM ON COIL MANDREL	1/21/2013	2/12/2013 7:34:28 AM	22	\$14.65
169213	MONTHLY PM ON COIL MANDREL	3/14/2013	3/15/2013 7:15:15 AM	1	\$14.65
170169	MONTHLY PM ON COIL MANDREL	4/15/2013	4/18/2013 7:57:57 AM	3	\$20.25
171233	MONTHLY PM ON COIL MANDREL	5/20/2013	5/23/2013 8:52:35 AM	3	\$20.25
171778	REPAIR OF EQUIPMENT		5/23/2013	41417	\$0.00
	Comments:	FOUND AND REMOVED LIFT TABLE FROM BUILDING J. STARTED PREPARING THE LIFT FOR PLACEMENT BETWEEN MANDREL AND STRAIGHTENER.			
171827	REPAIR OF EQUIPMENT		5/29/2013	41423	\$314.50
	Comments:	BUILDING THE LIFT TABLE UP SO IT WILL GO UP TO 5 FT IN HEIGHT THEN HELPED ROLL THE METAL TO THE INFEED			
		TOOK A WORKING LIFT TABLE AND RAISED IT ALL THE WAY UP IT ONLY WENT UP TO 3 1/2 FEET			
		TOOK ANGLE IRON AND ADDED TO THE TOP OF IT TO BE ABLE TO GET THE 5 FT HEIGHT WE NEEDED			
		WELDED EVERYTHING UP AND WAS READY TO INSTALL THE TOP TO TI BEFORE WE LEFT			
172117	MONTHLY PM ON COIL MANDREL	6/24/2013	6/25/2013 7:40:26 AM	1	\$20.25
173128	MONTHLY PM ON COIL MANDREL	7/25/2013	8/7/2013 7:59:26 AM	13	\$20.25
175128	MONTHLY PM ON COIL MANDREL	9/6/2013	9/20/2013 7:27:23 AM	14	\$0.00
176079	MONTHLY PM ON COIL MANDREL	10/21/2013	10/15/2013 7:52:45 AM	0	\$20.25
177193	MONTHLY PM ON COIL MANDREL	11/14/2013	12/6/2013 8:45:19 AM	22	\$14.65
178094	ANNUAL PM FOR MANDREL	12/5/2013	1/29/2014	55	\$0.00
178872	MONTHLY PM ON COIL MANDREL	1/6/2014	1/14/2014 7:35:33 AM	8	\$0.00
179846	MONTHLY PM ON COIL MANDREL	2/13/2014	2/13/2014 8:19:52 AM	0	\$14.65
181020	MONTHLY PM ON COIL MANDREL	3/17/2014	3/26/2014 7:32:16 AM	9	\$14.65
181819	MONTHLY PM ON COIL MANDREL	4/25/2014	4/17/2014 7:07:41 AM	0	\$20.25
182866	MONTHLY PM ON COIL MANDREL	5/19/2014	6/3/2014 7:53:19 AM	15	\$14.65

## Asset/Equipment Work Order History Brief

184564	MONTHLY PM ON COIL MANDREL	7/3/2014	7/8/2014 7:17:11 AM	5	\$20.25
185824	MONTHLY PM ON COIL MANDREL	8/7/2014	8/5/2014 7:39:58 AM	0	\$14.65
186831	MONTHLY PM ON COIL MANDREL	9/4/2014	9/17/2014	13	\$29.30
187974	MONTHLY PM ON COIL MANDREL	10/17/2014	10/17/2014 7:16:48 AM	0	\$14.65
188845	MONTHLY PM ON COIL MANDREL	11/17/2014	12/2/2014 7:19:35 AM	15	\$29.30
190514	ANNUAL PM FOR MANDREL	1/29/2015	1/29/2015	0	\$47.18
190515	MONTHLY PM ON COIL MANDREL	1/1/2015	1/13/2015 7:28:08 AM	12	\$29.30
191548	MONTHLY PM ON COIL MANDREL	2/12/2015	2/12/2015 10:53:29 AM	0	\$29.30
192524	MONTHLY PM ON COIL MANDREL	3/16/2015	3/18/2015 7:33:02 AM	2	\$29.30
193622	MONTHLY PM ON COIL MANDREL	4/17/2015	4/23/2015	6	\$71.95
194682	MONTHLY PM ON COIL MANDREL	5/25/2015	5/21/2015	0	\$31.45
195597	MONTHLY PM ON COIL MANDREL	6/22/2015	6/18/2015	0	\$40.50
196683	MONTHLY PM ON COIL MANDREL	7/20/2015	9/30/2015	72	\$40.50
199803	MONTHLY PM ON COIL MANDREL	10/30/2015	10/29/2015	0	\$31.45
200831	MONTHLY PM ON COIL MANDREL	11/30/2015	11/14/2015	0	\$40.50
201842	MONTHLY PM ON COIL MANDREL	12/14/2015	12/30/2015 10:15:47 AM	16	\$40.50
202832	ANNUAL PM FOR MANDREL	1/29/2016	1/29/2016	0	\$60.75
202833	MONTHLY PM ON COIL MANDREL	1/29/2016	1/13/2016	0	\$31.45
203797	MONTHLY PM ON COIL MANDREL	2/12/2016	2/11/2016	0	\$31.45
204759	MONTHLY PM ON COIL MANDREL	3/14/2016	3/11/2016	0	\$40.50
205886	MONTHLY PM ON COIL MANDREL	4/11/2016	4/20/2016	9	\$0.00
206858	MONTHLY PM ON COIL MANDREL	5/20/2016	5/24/2016	4	\$0.00
207861	MONTHLY PM ON COIL MANDREL	6/23/2016	6/28/2016	5	\$40.50

## Asset/Equipment Work Order History Brief

208994	MONTHLY PM ON COIL MANDREL	7/28/2016	7/22/2016 7:43:57 AM	0	\$40.50
209430	REPAIR OF EQUIPMENT		7/13/2016	42564	\$33.23
	Comments: MANDREL WONT RUN IN FWD/REVE				
	CHECK ALL VOLTAGE AND THE SWITCH WAS WORKING CORRECTLY				
	FOUND THE OVERLOADS TRIPPED ON THE MOTOR STARTER				
	RAN OK				
209938	MONTHLY PM ON COIL MANDREL	8/22/2016	8/23/2016	1	\$0.00
211093	MONTHLY PM ON COIL MANDREL	9/22/2016	9/23/2016 7:36:51 AM	1	\$40.50
212262	MONTHLY PM ON COIL MANDREL	10/24/2016	10/27/2016 7:57:45 AM	3	\$40.50
213174	MONTHLY PM ON COIL MANDREL	11/28/2016	11/17/2016	0	\$40.50
214053	MONTHLY PM ON COIL MANDREL	12/19/2016	12/30/2016 11:52:54 AM	11	\$40.50
214966	ANNUAL PM FOR MANDREL	1/30/2017	4/3/2017 11:41:24 AM	63	\$0.00
215558	MONTHLY PM ON COIL MANDREL	1/30/2017	2/18/2017	19	\$40.50
216627	MONTHLY PM ON COIL MANDREL	3/20/2017	4/3/2017 12:20:20 PM	14	\$40.50
218179	MONTHLY PM ON COIL MANDREL	5/3/2017	6/9/2017 10:10:06 AM	37	\$40.50
219926	MONTHLY PM ON COIL MANDREL	7/10/2017	8/31/2017	52	\$40.50
222248	MONTHLY PM ON COIL MANDREL	10/2/2017	11/18/2017 11:33:16 AM	47	\$40.50
223140	MONTHLY PM ON COIL MANDREL	11/20/2017	12/21/2017	31	\$40.50
224747	MONTHLY PM ON COIL MANDREL	1/22/2018	2/20/2018	29	\$35.00
226110	REPAIR OF EQUIPMENT		2/28/2018	43159	\$17.50
	Comments: The coil mandrel wont raise or lower. It went past limit.				
	Manually brought it down and then it worked fine.				
226817	ANNUAL PM FOR MANDREL	4/3/2018	8/3/2018 7:51:49 AM	122	\$60.75
227495	QUARTERLY PM ON COIL MANDREL	5/21/2018	5/3/2018	0	\$40.50
229322	QUARTERLY PM ON COIL MANDREL	8/1/2018	8/16/2018	15	\$40.50
231085	QUARTERLY PM ON COIL MANDREL	11/14/2018	12/6/2018 11:41:38 PM	22	\$40.50
233093	QUARTERLY PM ON COIL MANDREL	3/6/2019	4/24/2019	49	\$40.50
234943	QUARTERLY PM ON COIL MANDREL	7/22/2019	8/7/2019 3:47:08 PM	16	\$40.50

## Asset/Equipment Work Order History Brief

235363	ANNUAL PM FOR MANDREL	8/5/2019	8/27/2019 1:52:21 PM	22	\$60.75
236431	QUARTERLY PM ON COIL MANDREL	11/5/2019	12/2/2019 9:47:10 AM	27	\$40.50
237766	QUARTERLY PM ON COIL MANDREL	3/2/2020	3/10/2020 10:09:46 AM	8	\$40.50
238717	QUARTERLY PM ON COIL MANDREL	6/8/2020	6/10/2020 11:38:23 AM	2	\$40.50
239496	ANNUAL PM FOR MANDREL	8/26/2020	8/21/2020 11:19:12 AM	0	\$60.75
239804	QUARTERLY PM ON COIL MANDREL	9/8/2020	10/1/2020 2:40:43 PM	23	\$40.50
240913	QUARTERLY PM ON COIL MANDREL	1/4/2021	2/9/2021 10:58:04 AM	36	\$40.50
Totals For: <b>PRSS 038.3</b>		Total WOs: 230		Total Cost:	\$6,551.11

**Asset ID: PRSS 038.4**      **Asset: COIL CAR 12000 LF CAP**

Work Order ID	Description	Scheduled Date	Completed Date	Days Past Due	Total Cost
311	MONTHLY PM FOR COIL CAR	4/5/2000	4/11/2000 10:14:23 AM	6	\$0.00
1292	MONTHLY PM FOR COIL CAR	5/11/2000	5/11/2000 7:34:31 AM	0	\$9.71
2424	MONTHLY PM FOR COIL CAR	6/12/2000	6/27/2000 9:29:33 AM	15	\$9.94
3809	MONTHLY PM FOR COIL CAR	7/27/2000	8/4/2000 6:17:02 AM	8	\$9.94
5104	MONTHLY PM FOR COIL CAR	9/5/2000	9/13/2000 6:29:56 AM	8	\$10.10
6201	MONTHLY PM FOR COIL CAR	10/13/2000	10/30/2000 1:33:18 PM	17	\$10.10
7591	MONTHLY PM FOR COIL CAR	11/29/2000	12/12/2000 8:48:05 AM	13	\$10.10
8762	MONTHLY PM FOR COIL CAR	1/11/2001	1/10/2001 8:06:06 AM	0	\$10.10
9690	MONTHLY PM FOR COIL CAR	2/9/2001	2/26/2001 10:32:14 AM	17	\$0.00
11349	MONTHLY PM FOR COIL CAR	3/28/2001	3/29/2001 11:14:22 AM	1	\$10.10
12444	MONTHLY PM FOR COIL CAR	4/30/2001	5/4/2001 8:11:46 AM	4	\$10.10
13434	REPAIR ELECT CABLE		5/25/2001	37036	\$20.81
13553	MONTHLY PM FOR COIL CAR	6/4/2001	6/7/2001 9:52:41 AM	3	\$10.10
14803	MONTHLY PM FOR COIL CAR	7/9/2001	7/27/2001 6:54:24 AM	18	\$0.00

## Asset/Equipment Work Order History Brief

16516	MONTHLY PM FOR COIL CAR	8/27/2001	9/6/2001 1:27:50 PM	10	\$0.00
16573	REPAIR		8/28/2001	37131	\$40.40
17077	REPAIR		9/17/2001 1:30:58 PM	37151	\$19.91
17088	REPAIR ELECTRICAL CORD		9/17/2001	37151	\$44.78
17534	MONTHLY PM FOR COIL CAR	10/8/2001	11/27/2001 6:58:13 AM	50	\$0.00
19641	MONTHLY PM FOR COIL CAR	1/1/2002	1/25/2002 2:09:58 PM	24	\$0.00
19952	REPAIR CHAIN		1/9/2002 2:39:33 PM	37265	\$0.00
21370	MONTHLY PM FOR COIL CAR	2/25/2002	2/26/2002 10:53:06 AM	1	\$10.10
22319	MONTHLY PM FOR COIL CAR	3/28/2002	3/27/2002	0	\$10.10
23320	MONTHLY PM FOR COIL CAR	4/26/2002	4/29/2002 10:53:56 AM	3	\$0.00
24420	MONTHLY PM FOR COIL CAR	5/29/2002	5/28/2002 10:56:30 AM	0	\$0.00
25439	MONTHLY PM FOR COIL CAR	6/27/2002	6/26/2002 9:04:43 AM	0	\$10.85
26349	MONTHLY PM FOR COIL CAR	7/26/2002	7/22/2002 8:47:54 AM	0	\$0.00
27392	MONTHLY PM FOR COIL CAR	8/21/2002	9/4/2002 9:14:44 AM	14	\$10.85
28844	MONTHLY PM FOR COIL CAR	10/4/2002	10/4/2002 7:15:37 AM	0	\$0.00
28975	REPAIR ELECT CORD		10/1/2002	37530	\$44.34
30020	MONTHLY PM FOR COIL CAR	11/4/2002	11/6/2002 11:40:52 AM	2	\$10.85
30736	MONTHLY PM FOR COIL CAR	12/6/2002	12/5/2002 2:29:22 PM	0	\$10.85
31776	MONTHLY PM FOR COIL CAR	1/6/2003	2/18/2003 6:37:07 AM	43	\$10.85
33864	MONTHLY PM FOR COIL CAR	3/20/2003	3/18/2003 7:10:11 AM	0	\$10.85
34874	MONTHLY PM FOR COIL CAR	4/17/2003	4/15/2003 10:20:42 AM	0	\$10.85
35785	MONTHLY PM FOR COIL CAR	5/15/2003	5/13/2003 12:57:29 PM	0	\$0.00
36646	MONTHLY PM FOR COIL CAR	6/12/2003	6/18/2003 11:15:29 AM	6	\$10.85

## Asset/Equipment Work Order History Brief

36876	REPLACE DRIVE BELT		6/10/2003		37782	\$22.31
37772	MONTHLY PM FOR COIL CAR	7/18/2003		8/4/2003 8:25:37 AM	17	\$10.85
39073	MONTHLY PM FOR COIL CAR	9/3/2003		9/22/2003 11:42:07 AM	19	\$10.85
40455	MONTHLY PM FOR COIL CAR	10/22/2003		10/28/2003	6	\$10.85
41720	MONTHLY PM FOR COIL CAR	12/1/2003		12/4/2003 9:58:38 AM	3	\$10.85
42474	MONTHLY PM FOR COIL CAR	1/5/2004		1/15/2004 1:44:45 PM	10	\$10.85
43941	MONTHLY PM FOR COIL CAR	2/16/2004		2/24/2004	8	\$10.85
44726	REPAIR			3/10/2004	38056	\$43.58
44954	MONTHLY PM FOR COIL CAR	3/25/2004		3/26/2004 9:43:43 AM	1	\$0.00
46022	MONTHLY PM FOR COIL CAR	4/26/2004		4/27/2004 9:59:45 AM	1	\$0.00
46211	REPAIR CHAIN			4/29/2004	38106	\$133.44
46215	REPAIR			4/29/2004	38106	\$111.20
46969	MONTHLY PM FOR COIL CAR	5/27/2004		5/27/2004	0	\$10.85
48104	MONTHLY PM FOR COIL CAR	6/28/2004		6/28/2004	0	\$10.85
48966	MONTHLY PM FOR COIL CAR	7/28/2004		7/27/2004 1:25:53 PM	0	\$10.85
49239	REPAIR			7/31/2004	38199	\$30.38
49830	MONTHLY PM FOR COIL CAR	8/26/2004		9/2/2004 2:38:54 PM	7	\$10.85
51068	MONTHLY PM FOR COIL CAR	10/4/2004		10/7/2004 10:48:43 AM	3	\$10.85
52183	MONTHLY PM FOR COIL CAR	11/8/2004		11/15/2004 11:05:54 AM	7	\$11.36
52538	REPAIR CONTROL CORD			11/15/2004	38306	\$143.72
53272	MONTHLY PM FOR COIL CAR	12/15/2004		1/21/2005	37	\$11.36
55293	MONTHLY PM FOR COIL CAR	2/21/2005		2/22/2005 11:23:06 AM	1	\$0.00
56151	MONTHLY PM FOR COIL CAR	3/24/2005		3/28/2005 2:14:47 PM	4	\$11.36

## Asset/Equipment Work Order History Brief

56231	REPAIR (BLOWN FUSE)		3/21/2005 12:38:05 PM	38432	\$45.42
56614	REPLACE CONTACTS		4/6/2005	38448	\$68.32
57212	MONTHLY PM FOR COIL CAR	4/27/2005	4/28/2005 12:55:25 PM	1	\$11.36
58284	MONTHLY PM FOR COIL CAR	5/30/2005	6/1/2005	2	\$11.36
59258	MONTHLY PM FOR COIL CAR	7/1/2005	6/29/2005 1:42:14 PM	0	\$22.71
59570	REPAIR OF EQUIPMENT		7/5/2005	38538	\$22.82
	Comments: REPLACED TWO FUSES				
60172	MONTHLY PM FOR COIL CAR	7/29/2005	8/1/2005 9:06:31 AM	3	\$11.36
60241	REPAIR OF EQUIPMENT		7/22/2005	38555	\$0.00
	Comments: COIL CART WON'T GO UP OR DOWN. REPLACED BLOWN FUSE.				
61343	MONTHLY PM FOR COIL CAR	8/31/2005	9/7/2005 6:39:15 AM	7	\$0.00
62434	MONTHLY PM FOR COIL CAR	10/7/2005	10/6/2005 6:58:43 AM	0	\$0.00
63615	MONTHLY PM FOR COIL CAR	11/7/2005	11/10/2005 6:10:56 AM	3	\$11.36
64787	MONTHLY PM FOR COIL CAR	12/12/2005	12/15/2005 5:49:32 AM	3	\$11.36
65817	MONTHLY PM FOR COIL CAR	1/16/2006	1/25/2006 6:10:59 AM	9	\$11.36
66979	MONTHLY PM FOR COIL CAR	2/24/2006	3/2/2006 6:09:48 AM	6	\$11.36
67356	REPAIR OF EQUIPMENT		2/24/2006	38772	\$185.50
	Comments: BIG CHAIN HUNG UP THAT MAKES IT GO UP AND SOWN. NEED NEW REEL.				
67404	REPAIR OF EQUIPMENT		2/28/2006	38776	\$181.68
	Comments: PULLER ON THE REEL LOCKED UP. ADJUST REEL, UNLOCK PULLER. WORKING GOOD				
68584	MONTHLY PM FOR COIL CAR	4/3/2006	4/6/2006 8:11:24 AM	3	\$11.36
68944	REPAIR OF EQUIPMENT		4/10/2006 6:47:39 AM	38817	\$22.71
	Comments: COIL CAR NOT WORKING. BLOWN FUSE.				
69999	MONTHLY PM FOR COIL CAR	5/8/2006	5/11/2006 8:00:26 AM	3	\$0.00
70085	REPAIR OF EQUIPMENT		5/5/2006	38842	\$0.00
	Comments: CHECK AND REPAIR. COIL CART WON'T GO IN OR OUT. CHECK FUSES, REPLACED FUSE.				
71437	MONTHLY PM FOR COIL CAR	6/12/2006	6/12/2006 7:50:08 AM	0	\$11.36
72494	MONTHLY PM FOR COIL CAR	7/12/2006	7/11/2006 7:54:17 AM	0	\$0.00
73787	MONTHLY PM FOR COIL CAR	8/10/2006	8/10/2006	0	\$0.00

## Asset/Equipment Work Order History Brief

75543	MONTHLY PM FOR COIL CAR	9/11/2006	9/13/2006 7:51:28 AM	2	\$5.68
77001	MONTHLY PM FOR COIL CAR	10/13/2006	10/23/2006 6:22:09 AM	10	\$0.00
79017	MONTHLY PM FOR COIL CAR	11/22/2006	11/29/2006 6:15:30 AM	7	\$0.00
80724	MONTHLY PM FOR COIL CAR	12/29/2006	1/6/2007	8	\$11.36
82329	MONTHLY PM FOR COIL CAR	2/5/2007	2/8/2007 8:20:14 AM	3	\$13.40
84218	MONTHLY PM FOR COIL CAR	3/12/2007	3/12/2007 10:12:52 AM	0	\$0.00
85574	MONTHLY PM FOR COIL CAR	4/11/2007	4/10/2007 10:04:34 AM	0	\$19.08
86946	MONTHLY PM FOR COIL CAR	5/10/2007	5/16/2007 9:57:58 AM	6	\$13.40
88611	MONTHLY PM FOR COIL CAR	6/15/2007	6/13/2007 8:22:06 AM	0	\$13.40
89975	MONTHLY PM FOR COIL CAR	7/13/2007	7/12/2007 8:24:47 AM	0	\$13.40
91489	MONTHLY PM FOR COIL CAR	8/13/2007	8/16/2007 6:41:30 AM	3	\$18.07
93115	MONTHLY PM FOR COIL CAR	9/17/2007	9/18/2007 11:33:55 AM	1	\$18.07
94518	MONTHLY PM FOR COIL CAR	10/18/2007	10/19/2007 9:46:47 AM	1	\$13.40
96313	MONTHLY PM FOR COIL CAR	11/19/2007	11/30/2007 10:26:12 AM	11	\$18.07
98084	MONTHLY PM FOR COIL CAR	12/31/2007	12/31/2007	0	\$0.00
98459	MONTHLY PM FOR COIL CAR	1/30/2008	1/24/2008 12:41:02 PM	0	\$13.40
99788	MONTHLY PM FOR COIL CAR	2/25/2008	2/13/2008	0	\$16.69
101169	MONTHLY PM FOR COIL CAR	3/14/2008	3/13/2008 10:09:10 AM	0	\$13.40
102477	MONTHLY PM FOR COIL CAR	4/14/2008	4/18/2008 9:43:54 AM	4	\$13.40
104138	MONTHLY PM FOR COIL CAR	5/19/2008	5/27/2008 7:44:45 AM	8	\$13.40
105455	MONTHLY PM FOR COIL CAR	6/26/2008	7/1/2008 6:46:34 AM	5	\$13.40
108059	MONTHLY PM FOR COIL CAR	7/31/2008	8/19/2008 7:45:45 AM	19	\$14.80
108602	REPAIR OF EQUIPMENT		7/31/2008	39660	\$64.24
	Comments:	COIL CAR NOT WORKING (WILL NOT GO DOWN) THEY HAD IT UP TOO FAR PUT ALL COVERS BACK ON (WORKS FINE)			

## Asset/Equipment Work Order History Brief

109741	MONTHLY PM FOR COIL CAR	9/18/2008	9/19/2008 8:08:25 AM	1	\$14.80
110937	MONTHLY PM FOR COIL CAR	10/20/2008	10/15/2008 7:46:42 AM	0	\$14.80
112455	MONTHLY PM FOR COIL CAR	11/14/2008	11/26/2008 6:49:59 AM	12	\$14.80
113589	MONTHLY PM FOR COIL CAR	12/26/2008	1/9/2009 7:17:57 AM	14	\$14.80
115770	MONTHLY PM FOR COIL CAR	2/9/2009	2/3/2009 9:51:50 AM	0	\$14.80
117034	MONTHLY PM FOR COIL CAR	3/5/2009	3/23/2009 7:50:52 AM	18	\$14.80
118220	MONTHLY PM FOR COIL CAR	4/22/2009	4/16/2009 6:21:28 AM	0	\$14.80
119436	MONTHLY PM FOR COIL CAR	5/18/2009	5/21/2009 6:19:59 AM	3	\$14.80
120828	MONTHLY PM FOR COIL CAR	6/22/2009	6/30/2009 6:12:52 AM	8	\$19.37
123216	MONTHLY PM FOR COIL CAR	7/30/2009	8/4/2009 6:23:45 AM	5	\$14.65
123272	REPAIR OF EQUIPMENT		7/23/2009	40017	\$19.26
	Comments: COIL CART WILL NOT LOWER. MANUALLY LOWERED AND TRIED PUSH BUTTONS AGAIN. COULDN'T FIND ANYTHING WRONG.				
124965	MONTHLY PM FOR COIL CAR	9/3/2009	9/10/2009 6:29:36 AM	7	\$14.59
126356	MONTHLY PM FOR COIL CAR	10/12/2009	10/13/2009 6:59:54 AM	1	\$17.01
127678	MONTHLY PM FOR COIL CAR	11/12/2009	11/17/2009 10:56:07 AM	5	\$25.79
128833	MONTHLY PM FOR COIL CAR	12/17/2009	2/6/2010	51	\$17.01
132660	MONTHLY PM FOR COIL CAR	3/8/2010	3/11/2010 2:46:11 PM	3	\$14.65
134094	MONTHLY PM FOR COIL CAR	4/12/2010	4/14/2010 7:44:35 AM	2	\$19.37
135176	MONTHLY PM FOR COIL CAR	5/14/2010	5/13/2010	0	\$19.37
136334	MONTHLY PM FOR COIL CAR	6/14/2010	6/13/2010	0	\$15.05
137605	MONTHLY PM FOR COIL CAR	7/13/2010	8/3/2010 6:52:35 AM	21	\$20.25
139468	MONTHLY PM FOR COIL CAR	9/2/2010	9/8/2010 6:26:59 AM	6	\$15.05
140840	MONTHLY PM FOR COIL CAR	10/8/2010	10/7/2010 9:23:38 AM	0	\$15.05
141832	MONTHLY PM FOR COIL CAR	11/8/2010	11/20/2010	12	\$20.25

## Asset/Equipment Work Order History Brief

142920	MONTHLY PM FOR COIL CAR	12/20/2010	12/28/2010 6:07:00 AM	8	\$15.05
143722	MONTHLY PM FOR COIL CAR	1/27/2011	2/3/2011 7:01:09 AM	7	\$15.05
145722	MONTHLY PM FOR COIL CAR	3/7/2011	3/24/2011	17	\$15.05
146831	MONTHLY PM FOR COIL CAR	4/25/2011	4/26/2011 7:20:58 AM	1	\$15.05
147297	REPAIR OF EQUIPMENT		4/14/2011	40647	\$70.00
	Comments: COIL CAR OFF TRACKS. BROKE POSITIVE STOP WELDED BACK ON. ADJUSTED				
147828	MONTHLY PM FOR COIL CAR	5/26/2011	5/20/2011 7:22:33 AM	0	\$15.05
148044	REPAIR OF EQUIPMENT		5/5/2011 7:27:23 AM	40668	\$30.38
	Comments: COIL CAR GOT CROSSWAYS ON TRACKS. PUT BACK AND CHECKED TRAVEL				
148833	MONTHLY PM FOR COIL CAR	6/20/2011	6/30/2011 11:43:56 AM	10	\$15.05
150684	MONTHLY PM FOR COIL CAR	8/1/2011	8/11/2011 7:26:14 AM	10	\$15.05
151806	MONTHLY PM FOR COIL CAR	9/12/2011	9/9/2011 6:59:02 AM	0	\$20.25
152645	MONTHLY PM FOR COIL CAR	10/10/2011	10/22/2011 7:12:04 AM	12	\$20.25
153128	REPAIR OF EQUIPMENT		10/19/2011	40835	\$70.00
	Comments: COIL CAR WILL NOT COME OUT (NEED REPAIRED ASAP)				
	-BROKE WIRES IN HAND CONTROLLER, REWIRED				
153605	MONTHLY PM FOR COIL CAR	11/21/2011	11/30/2011 8:47:36 AM	9	\$20.25
154635	MONTHLY PM FOR COIL CAR	12/30/2011	1/4/2012 8:07:30 AM	5	\$20.25
156180	MONTHLY PM FOR COIL CAR	2/3/2012	2/3/2012	0	\$15.05
157555	MONTHLY PM FOR COIL CAR	3/5/2012	3/10/2012 6:50:23 AM	5	\$20.25
157898	REPAIR OF EQUIPMENT		3/13/2012	40981	\$97.65
	Comments: IT WONT WORK IT QUIT WORKING				
	CHECK ALL THE FUSES				
	MOTOR STARTER OVERLAOD WAS TRIPPED, RESET IT, UNCOLLER WONT WORK IT WAS LOCK, FREE UNCOILER AND IT WORKED FINE				
158534	MONTHLY PM FOR COIL CAR	4/9/2012	4/5/2012 7:45:45 AM	0	\$15.05
159536	MONTHLY PM FOR COIL CAR	5/7/2012	5/4/2012 8:02:26 AM	0	\$0.00
160551	MONTHLY PM FOR COIL CAR	6/4/2012	6/15/2012	11	\$0.00
161474	MONTHLY PM FOR COIL CAR	7/16/2012	7/18/2012	2	\$15.05

## Asset/Equipment Work Order History Brief

162723	MONTHLY PM FOR COIL CAR	8/17/2012	8/15/2012 8:13:59 AM	0	\$19.98
163613	MONTHLY PM FOR COIL CAR	9/14/2012	9/20/2012 7:52:25 AM	6	\$15.05
164622	MONTHLY PM FOR COIL CAR	10/22/2012	10/16/2012 8:14:46 AM	0	\$15.05
165488	REPAIR OF EQUIPMENT		10/30/2012	41212	\$99.90
	Comments: CAR SLIPS DURING TRAINER FOUND ALL NUTS ON TRACK LIOOSE ADJUSTED TRACKAND TIGHTENED NUTS TESTED WITH A COIL ON CAR				
165798	MONTHLY PM FOR COIL CAR	11/15/2012	11/14/2012 7:11:16 AM	0	\$20.25
166634	MONTHLY PM FOR COIL CAR	12/14/2012	12/20/2012 8:02:44 AM	6	\$14.85
167427	MONTHLY PM FOR COIL CAR	1/21/2013	2/12/2013 7:33:58 AM	22	\$14.65
169214	MONTHLY PM FOR COIL CAR	3/14/2013	3/15/2013 7:23:14 AM	1	\$20.25
170170	MONTHLY PM FOR COIL CAR	4/15/2013	4/18/2013 7:57:36 AM	3	\$20.25
171234	MONTHLY PM FOR COIL CAR	5/20/2013	5/23/2013 8:53:35 AM	3	\$20.25
172118	MONTHLY PM FOR COIL CAR	6/24/2013	6/25/2013 7:41:09 AM	1	\$20.25
173129	MONTHLY PM FOR COIL CAR	7/25/2013	8/7/2013 7:59:04 AM	13	\$20.25
175129	MONTHLY PM FOR COIL CAR	9/6/2013	9/20/2013 7:27:03 AM	14	\$20.25
176080	MONTHLY PM FOR COIL CAR	10/21/2013	10/15/2013 7:52:24 AM	0	\$20.25
177194	MONTHLY PM FOR COIL CAR	11/14/2013	12/6/2013 8:45:40 AM	22	\$14.65
178873	MONTHLY PM FOR COIL CAR	1/6/2014	1/14/2014 7:35:21 AM	8	\$14.65
179847	MONTHLY PM FOR COIL CAR	2/13/2014	2/13/2014 8:19:43 AM	0	\$14.65
181021	MONTHLY PM FOR COIL CAR	3/17/2014	3/26/2014 7:31:24 AM	9	\$14.65
181820	MONTHLY PM FOR COIL CAR	4/25/2014	4/17/2014 7:08:01 AM	0	\$14.65
182867	MONTHLY PM FOR COIL CAR	5/19/2014	6/3/2014 7:52:56 AM	15	\$14.65
184565	MONTHLY PM FOR COIL CAR	7/3/2014	7/8/2014 7:16:44 AM	5	\$14.65
185825	MONTHLY PM FOR COIL CAR	8/7/2014	8/5/2014 7:39:25 AM	0	\$29.30
186832	MONTHLY PM FOR COIL CAR	9/4/2014	9/17/2014	13	\$29.30

## Asset/Equipment Work Order History Brief

187975	MONTHLY PM FOR COIL CAR	10/17/2014	10/17/2014 7:16:23 AM	0	\$40.50
188539	REPAIR OF EQUIPMENT		10/27/2014	41939	\$31.45
	Comments:	CART FOR COIL WOULD DO EVERYTHING BUT GO IN COIL CAR			
		SONNY COULDN'T GET THE CART TO GO IN. I COULD MAKE IT GO IN BY HOLDING THE RELAY IN. TOOK THE PENDANT APART AND CHECKED THE PUSH BUTTON AND N.O WASN'T CLOSING WHEN THE BUTTON WAS PUSHED. TOOK THE CONTACTS OFF AND PUT A NEW CONTACT ON IT. WORKED FINE AFTER THAT.			
188846	MONTHLY PM FOR COIL CAR	11/17/2014	12/2/2014 7:20:05 AM	15	\$29.30
190516	MONTHLY PM FOR COIL CAR	1/1/2015	1/13/2015 7:27:49 AM	12	\$29.30
191549	MONTHLY PM FOR COIL CAR	2/12/2015	2/12/2015 10:53:14 AM	0	\$29.30
192525	MONTHLY PM FOR COIL CAR	3/16/2015	3/18/2015 7:33:26 AM	2	\$0.00
193623	MONTHLY PM FOR COIL CAR	4/17/2015	4/23/2015	6	\$0.00
194683	MONTHLY PM FOR COIL CAR	5/25/2015	5/21/2015	0	\$31.45
195598	MONTHLY PM FOR COIL CAR	6/22/2015	6/18/2015	0	\$40.50
196684	MONTHLY PM FOR COIL CAR	7/20/2015	9/30/2015	72	\$31.45
199804	MONTHLY PM FOR COIL CAR	10/30/2015	10/29/2015	0	\$31.45
200832	MONTHLY PM FOR COIL CAR	11/30/2015	12/11/2015 7:51:48 AM	11	\$40.50
202834	MONTHLY PM FOR COIL CAR	1/11/2016	1/13/2016	2	\$31.45
203465	REPAIR OF EQUIPMENT		1/25/2016	42394	\$82.18
	Comments:	PRSS 38 COIL CART WONT GO IN OR OUT CHECK OVERLOAD AND VOLTAGE IT WAS OK TOOK COVER OFF OF DRIVE BELT ON MOTOR WAS OFF TIMING PULLEY ON MOTOR WAS LOOSENED BRAKE PULLED PULLEY OFF AND TOOK TO CHUCK AND HE FOUND ONE PUT NEW ONE ON AND RUNS GOOD			
203798	MONTHLY PM FOR COIL CAR	2/12/2016	2/11/2016	0	\$0.00
204760	MONTHLY PM FOR COIL CAR	3/14/2016	3/11/2016	0	\$40.50
205887	MONTHLY PM FOR COIL CAR	4/11/2016	4/20/2016	9	\$31.45
206859	MONTHLY PM FOR COIL CAR	5/20/2016	5/24/2016	4	\$0.00
207862	MONTHLY PM FOR COIL CAR	6/23/2016	6/28/2016	5	\$40.50
208995	MONTHLY PM FOR COIL CAR	7/28/2016	7/21/2016	0	\$0.00

## Asset/Equipment Work Order History Brief

209939	MONTHLY PM FOR COIL CAR	8/22/2016	8/23/2016	1	\$0.00
211094	MONTHLY PM FOR COIL CAR	9/22/2016	9/23/2016 7:37:02 AM	1	\$40.50
212263	MONTHLY PM FOR COIL CAR	10/24/2016	10/27/2016 7:58:09 AM	3	\$40.50
213175	MONTHLY PM FOR COIL CAR	11/28/2016	11/17/2016	0	\$0.00
214054	MONTHLY PM FOR COIL CAR	12/19/2016	12/19/2016	0	\$40.50
214967	MONTHLY PM FOR COIL CAR	1/18/2017	2/18/2017	31	\$0.00
216628	MONTHLY PM FOR COIL CAR	3/20/2017	4/3/2017 12:20:34 PM	14	\$40.50
218180	MONTHLY PM FOR COIL CAR	5/3/2017	6/9/2017 10:10:21 AM	37	\$40.50
219927	MONTHLY PM FOR COIL CAR	7/10/2017	9/1/2017 7:56:38 AM	53	\$40.50
222249	MONTHLY PM FOR COIL CAR	10/2/2017	11/18/2017 11:33:47 AM	47	\$40.50
223141	MONTHLY PM FOR COIL CAR	11/20/2017	12/21/2017	31	\$40.50
224748	MONTHLY PM FOR COIL CAR	1/22/2018	2/20/2018	29	\$40.50
227496	QUARTERLY PM FOR COIL CAR	5/21/2018	5/3/2018	0	\$40.50
229323	QUARTERLY PM FOR COIL CAR	8/1/2018	8/16/2018	15	\$40.50
231086	QUARTERLY PM FOR COIL CAR	11/14/2018	12/6/2018 11:42:09 PM	22	\$40.50
233094	QUARTERLY PM FOR COIL CAR	3/6/2019	4/24/2019	49	\$40.50
234944	QUARTERLY PM FOR COIL CAR	7/22/2019	8/7/2019 3:48:32 PM	16	\$40.50
236432	QUARTERLY PM FOR COIL CAR	11/5/2019	12/2/2019 9:47:24 AM	27	\$40.50
237767	QUARTERLY PM FOR COIL CAR	3/2/2020	3/10/2020 10:09:59 AM	8	\$40.50
238718	QUARTERLY PM FOR COIL CAR	6/8/2020	6/10/2020 11:39:19 AM	2	\$40.50
239805	QUARTERLY PM FOR COIL CAR	9/8/2020	10/1/2020 2:40:58 PM	23	\$40.50
240914	QUARTERLY PM FOR COIL CAR	1/4/2021	2/9/2021 10:58:17 AM	36	\$40.50
Totals For: <b>PRSS 038.4</b>		Total WOs: 215		Total Cost:	<u>\$4,725.23</u>

## Asset/Equipment Work Order History Brief

Asset ID: PRSS 038.5		Asset: THREAD GATE MAX WIDTH 50"			
Work Order ID	Description	Scheduled Date	Completed Date	Days Past Due	Total Cost
312	MONTHLY PM FOR THREAD GATE	4/5/2000	4/11/2000 10:10:27 AM	6	\$0.00
1293	MONTHLY PM FOR THREAD GATE	5/11/2000	5/11/2000 7:36:51 AM	0	\$4.86
2425	MONTHLY PM FOR THREAD GATE	6/12/2000	6/27/2000 9:49:04 AM	15	\$4.97
3810	MONTHLY PM FOR THREAD GATE	7/27/2000	8/4/2000 6:17:29 AM	8	\$4.97
5105	MONTHLY PM FOR THREAD GATE	9/5/2000	9/13/2000 6:26:59 AM	8	\$5.05
6202	MONTHLY PM FOR THREAD GATE	10/13/2000	10/30/2000 1:33:02 PM	17	\$5.05
7592	MONTHLY PM FOR THREAD GATE	11/29/2000	12/12/2000 8:52:13 AM	13	\$5.05
8763	MONTHLY PM FOR THREAD GATE	1/11/2001	1/10/2001 8:08:29 AM	0	\$5.05
9691	MONTHLY PM FOR THREAD GATE	2/9/2001	2/26/2001 10:31:46 AM	17	\$0.00
11350	MONTHLY PM FOR THREAD GATE	3/28/2001	3/29/2001 11:12:29 AM	1	\$5.05
12445	MONTHLY PM FOR THREAD GATE	4/30/2001	5/4/2001 8:11:07 AM	4	\$5.05
13554	MONTHLY PM FOR THREAD GATE	6/4/2001	6/7/2001 9:53:59 AM	3	\$5.05
14804	MONTHLY PM FOR THREAD GATE	7/9/2001	7/27/2001 6:54:48 AM	18	\$0.00
16517	MONTHLY PM FOR THREAD GATE	8/27/2001	9/18/2001 6:23:06 AM	22	\$5.05
17785	MONTHLY PM FOR THREAD GATE	10/18/2001	12/13/2001 7:14:20 AM	56	\$5.05
20033	MONTHLY PM FOR THREAD GATE	1/14/2002	1/25/2002 2:09:36 PM	11	\$0.00
21371	MONTHLY PM FOR THREAD GATE	2/25/2002	2/26/2002 10:57:09 AM	1	\$5.05
22320	MONTHLY PM FOR THREAD GATE	3/28/2002	3/27/2002	0	\$5.05
23321	MONTHLY PM FOR THREAD GATE	4/26/2002	4/29/2002 10:29:17 AM	3	\$0.00
24421	MONTHLY PM FOR THREAD GATE	5/29/2002	5/28/2002 10:56:06 AM	0	\$0.00
25440	MONTHLY PM FOR THREAD GATE	6/27/2002	6/26/2002 9:08:13 AM	0	\$5.43
26350	MONTHLY PM FOR THREAD GATE	7/26/2002	7/22/2002 8:53:42 AM	0	\$0.00

## Asset/Equipment Work Order History Brief

27393	MONTHLY PM FOR THREAD GATE	8/21/2002	9/4/2002 9:10:30 AM	14	\$5.43
28845	MONTHLY PM FOR THREAD GATE	10/4/2002	10/4/2002 9:36:24 AM	0	\$5.43
30021	MONTHLY PM FOR THREAD GATE	11/4/2002	11/6/2002 12:41:02 PM	2	\$5.43
30737	MONTHLY PM FOR THREAD GATE	12/6/2002	12/5/2002 3:00:00 PM	0	\$5.43
31777	MONTHLY PM FOR THREAD GATE	1/6/2003	2/18/2003 6:37:25 AM	43	\$5.43
33865	MONTHLY PM FOR THREAD GATE	3/20/2003	3/18/2003 7:09:53 AM	0	\$5.43
34875	MONTHLY PM FOR THREAD GATE	4/17/2003	4/15/2003 10:18:00 AM	0	\$5.43
35786	MONTHLY PM FOR THREAD GATE	5/15/2003	5/13/2003 12:57:45 PM	0	\$0.00
36647	MONTHLY PM FOR THREAD GATE	6/12/2003	6/18/2003 11:11:48 AM	6	\$5.43
37773	MONTHLY PM FOR THREAD GATE	7/18/2003	8/4/2003 8:31:01 AM	17	\$5.43
39074	MONTHLY PM FOR THREAD GATE	9/3/2003	9/22/2003 11:47:25 AM	19	\$5.43
40456	MONTHLY PM FOR THREAD GATE	10/22/2003	10/28/2003	6	\$5.43
41721	MONTHLY PM FOR THREAD GATE	12/1/2003	12/4/2003 9:59:03 AM	3	\$5.43
42475	MONTHLY PM FOR THREAD GATE	1/5/2004	1/15/2004 1:44:28 PM	10	\$5.43
43942	MONTHLY PM FOR THREAD GATE	2/16/2004	2/24/2004	8	\$5.43
44955	MONTHLY PM FOR THREAD GATE	3/25/2004	3/26/2004 9:44:05 AM	1	\$0.00
46023	MONTHLY PM FOR THREAD GATE	4/26/2004	4/27/2004 9:59:26 AM	1	\$0.00
46970	MONTHLY PM FOR THREAD GATE	5/27/2004	5/27/2004	0	\$5.43
48105	MONTHLY PM FOR THREAD GATE	6/28/2004	6/28/2004	0	\$5.43
48967	MONTHLY PM FOR THREAD GATE	7/28/2004	7/27/2004 2:46:44 PM	0	\$5.43
49831	MONTHLY PM FOR THREAD GATE	8/26/2004	9/2/2004 1:54:49 PM	7	\$5.43
51069	MONTHLY PM FOR THREAD GATE	10/4/2004	10/7/2004 11:09:20 AM	3	\$5.43
52184	MONTHLY PM FOR THREAD GATE	11/8/2004	11/15/2004 10:59:25 AM	7	\$5.68

## Asset/Equipment Work Order History Brief

53273	MONTHLY PM FOR THREAD GATE	12/15/2004	12/22/2004 3:57:46 PM	7	\$5.68
54216	MONTHLY PM FOR THREAD GATE	1/21/2005	1/20/2005 10:56:32 AM	0	\$0.00
55294	MONTHLY PM FOR THREAD GATE	2/21/2005	2/22/2005 11:23:31 AM	1	\$0.00
56152	MONTHLY PM FOR THREAD GATE	3/24/2005	3/28/2005 2:15:04 PM	4	\$5.68
57213	MONTHLY PM FOR THREAD GATE	4/27/2005	4/28/2005 12:52:52 PM	1	\$5.68
58285	MONTHLY PM FOR THREAD GATE	5/30/2005	6/1/2005	2	\$5.68
59259	MONTHLY PM FOR THREAD GATE	7/1/2005	6/29/2005 1:42:41 PM	0	\$11.36
60173	MONTHLY PM FOR THREAD GATE	7/29/2005	8/1/2005 9:05:22 AM	3	\$5.68
61344	MONTHLY PM FOR THREAD GATE	8/31/2005	9/8/2005 7:56:43 AM	8	\$5.68
62697	MONTHLY PM FOR THREAD GATE	10/10/2005	10/13/2005 7:14:22 AM	3	\$0.00
63873	MONTHLY PM FOR THREAD GATE	11/14/2005	11/22/2005 6:33:37 AM	8	\$0.00
65021	MONTHLY PM FOR THREAD GATE	12/22/2005	12/23/2005 7:58:04 AM	1	\$5.68
66003	MONTHLY PM FOR THREAD GATE	1/23/2006	1/25/2006 6:04:23 AM	2	\$0.00
66980	MONTHLY PM FOR THREAD GATE	2/24/2006	3/2/2006 6:15:47 AM	6	\$5.90
68585	MONTHLY PM FOR THREAD GATE	4/3/2006	4/6/2006 8:05:28 AM	3	\$5.90
70000	MONTHLY PM FOR THREAD GATE	5/8/2006	5/11/2006 8:00:00 AM	3	\$0.00
71438	MONTHLY PM FOR THREAD GATE	6/12/2006	6/12/2006 7:51:52 AM	0	\$5.90
72495	MONTHLY PM FOR THREAD GATE	7/12/2006	7/12/2006 10:11:08 AM	0	\$5.90
73788	MONTHLY PM FOR THREAD GATE	8/11/2006	8/10/2006	0	\$0.00
75544	MONTHLY PM FOR THREAD GATE	9/11/2006	9/13/2006 7:52:15 AM	2	\$2.95
77002	MONTHLY PM FOR THREAD GATE	10/13/2006	10/23/2006 6:22:30 AM	10	\$0.00
79018	MONTHLY PM FOR THREAD GATE	11/22/2006	11/29/2006 6:14:43 AM	7	\$0.00
80725	MONTHLY PM FOR THREAD GATE	12/29/2006	1/6/2007	8	\$5.90

## Asset/Equipment Work Order History Brief

82330	MONTHLY PM FOR THREAD GATE	2/5/2007	2/8/2007 8:20:41 AM	3	\$6.97
84219	MONTHLY PM FOR THREAD GATE	3/12/2007	3/12/2007 10:13:15 AM	0	\$0.00
85575	MONTHLY PM FOR THREAD GATE	4/11/2007	4/10/2007 10:05:04 AM	0	\$6.97
86947	MONTHLY PM FOR THREAD GATE	5/10/2007	5/16/2007 9:50:48 AM	6	\$6.97
88612	MONTHLY PM FOR THREAD GATE	6/15/2007	6/13/2007 8:22:48 AM	0	\$6.97
89976	MONTHLY PM FOR THREAD GATE	7/13/2007	7/12/2007 8:24:14 AM	0	\$6.97
91490	MONTHLY PM FOR THREAD GATE	8/13/2007	8/16/2007 6:42:12 AM	3	\$9.03
93116	MONTHLY PM FOR THREAD GATE	9/17/2007	9/18/2007 11:34:36 AM	1	\$9.03
94519	MONTHLY PM FOR THREAD GATE	10/18/2007	10/19/2007 9:47:15 AM	1	\$6.97
96314	MONTHLY PM FOR THREAD GATE	11/19/2007	11/30/2007 10:22:26 AM	11	\$9.03
98085	MONTHLY PM FOR THREAD GATE	12/31/2007	12/31/2007	0	\$0.00
98460	MONTHLY PM FOR THREAD GATE	1/30/2008	1/24/2008 12:41:42 PM	0	\$6.97
99789	MONTHLY PM FOR THREAD GATE	2/25/2008	2/13/2008	0	\$8.68
101170	MONTHLY PM FOR THREAD GATE	3/14/2008	3/13/2008 10:08:40 AM	0	\$6.97
102478	MONTHLY PM FOR THREAD GATE	4/14/2008	4/18/2008 9:43:26 AM	4	\$6.97
104139	MONTHLY PM FOR THREAD GATE	5/19/2008	5/27/2008 7:45:45 AM	8	\$5.68
105456	MONTHLY PM FOR THREAD GATE	6/26/2008	7/1/2008 6:48:16 AM	5	\$13.39
108060	MONTHLY PM FOR THREAD GATE	7/31/2008	8/19/2008 7:46:50 AM	19	\$14.80
109742	MONTHLY PM FOR THREAD GATE	9/18/2008	9/19/2008 8:08:57 AM	1	\$14.80
110938	MONTHLY PM FOR THREAD GATE	10/20/2008	10/15/2008 7:47:23 AM	0	\$14.80
112456	MONTHLY PM FOR THREAD GATE	11/14/2008	11/26/2008 6:50:54 AM	12	\$14.80
113590	MONTHLY PM FOR THREAD GATE	12/26/2008	1/9/2009 7:18:31 AM	14	\$14.80
115771	MONTHLY PM FOR THREAD GATE	2/9/2009	2/3/2009 9:59:58 AM	0	\$14.80

## Asset/Equipment Work Order History Brief

117035	MONTHLY PM FOR THREAD GATE	3/5/2009	3/23/2009 7:51:29 AM	18	\$14.80
118221	MONTHLY PM FOR THREAD GATE	4/22/2009	4/16/2009 6:22:35 AM	0	\$14.80
119437	MONTHLY PM FOR THREAD GATE	5/18/2009	5/21/2009 6:13:05 AM	3	\$20.25
120829	MONTHLY PM FOR THREAD GATE	6/22/2009	6/30/2009 6:12:03 AM	8	\$19.37
123217	MONTHLY PM FOR THREAD GATE	7/30/2009	8/4/2009 6:21:33 AM	5	\$19.37
124966	MONTHLY PM FOR THREAD GATE	9/3/2009	9/10/2009 6:32:09 AM	7	\$16.95
126357	MONTHLY PM FOR THREAD GATE	10/12/2009	10/13/2009 7:00:44 AM	1	\$8.84
127679	MONTHLY PM FOR THREAD GATE	11/12/2009	11/17/2009 10:56:56 AM	5	\$15.25
128834	MONTHLY PM FOR THREAD GATE	12/17/2009	2/6/2010	51	\$9.68
132661	MONTHLY PM FOR THREAD GATE	3/8/2010	3/11/2010 2:44:53 PM	3	\$9.68
134095	MONTHLY PM FOR THREAD GATE	4/12/2010	4/14/2010 7:43:54 AM	2	\$9.68
135177	MONTHLY PM FOR THREAD GATE	5/14/2010	5/13/2010	0	\$9.68
136335	MONTHLY PM FOR THREAD GATE	6/14/2010	6/13/2010	0	\$7.53
137606	MONTHLY PM FOR THREAD GATE	7/13/2010	8/3/2010 6:52:53 AM	21	\$10.13
139469	MONTHLY PM FOR THREAD GATE	9/2/2010	9/8/2010 6:32:41 AM	6	\$10.13
140841	MONTHLY PM FOR THREAD GATE	10/8/2010	10/7/2010 9:26:18 AM	0	\$10.13
141833	MONTHLY PM FOR THREAD GATE	11/8/2010	11/20/2010	12	\$10.13
142921	MONTHLY PM FOR THREAD GATE	12/20/2010	12/28/2010 6:12:38 AM	8	\$10.13
143723	MONTHLY PM FOR THREAD GATE	1/27/2011	2/3/2011 6:57:16 AM	7	\$10.13
145723	MONTHLY PM FOR THREAD GATE	3/7/2011	3/24/2011	17	\$10.13
146832	MONTHLY PM FOR THREAD GATE	4/25/2011	4/26/2011 7:11:57 AM	1	\$10.13
147829	MONTHLY PM FOR THREAD GATE	5/26/2011	5/20/2011 7:46:11 AM	0	\$10.13
148834	MONTHLY PM FOR THREAD GATE	6/20/2011	6/30/2011 11:48:08 AM	10	\$10.13

## Asset/Equipment Work Order History Brief

150685	MONTHLY PM FOR THREAD GATE	8/1/2011	8/11/2011 7:28:33 AM	10	\$10.13
151807	MONTHLY PM FOR THREAD GATE	9/12/2011	9/9/2011 6:58:35 AM	0	\$10.13
152646	MONTHLY PM FOR THREAD GATE	10/10/2011	10/22/2011 7:20:09 AM	12	\$10.13
153606	MONTHLY PM FOR THREAD GATE	11/21/2011	11/30/2011 8:47:05 AM	9	\$10.13
154636	MONTHLY PM FOR THREAD GATE	12/30/2011	1/4/2012 8:06:38 AM	5	\$10.13
156181	MONTHLY PM FOR THREAD GATE	2/3/2012	2/3/2012	0	\$10.13
157556	MONTHLY PM FOR THREAD GATE	3/5/2012	3/10/2012 6:50:04 AM	5	\$10.13
158535	MONTHLY PM FOR THREAD GATE	4/9/2012	4/5/2012 7:43:06 AM	0	\$10.13
159537	MONTHLY PM FOR THREAD GATE	5/7/2012	5/4/2012 7:33:51 AM	0	\$10.13
160552	MONTHLY PM FOR THREAD GATE	6/4/2012	6/15/2012	11	\$10.13
161475	MONTHLY PM FOR THREAD GATE	7/16/2012	7/18/2012	2	\$10.13
162724	MONTHLY PM FOR THREAD GATE	8/17/2012	8/15/2012 8:15:33 AM	0	\$13.44
163614	MONTHLY PM FOR THREAD GATE	9/14/2012	9/20/2012 8:05:19 AM	6	\$40.50
164623	MONTHLY PM FOR THREAD GATE	10/22/2012	10/16/2012 8:14:21 AM	0	\$10.13
165799	MONTHLY PM FOR THREAD GATE	11/15/2012	11/14/2012 7:11:41 AM	0	\$10.13
166635	MONTHLY PM FOR THREAD GATE	12/14/2012	12/20/2012 7:53:23 AM	6	\$10.13
167428	MONTHLY PM FOR THREAD GATE	1/21/2013	2/12/2013 7:38:50 AM	22	\$10.13
169215	MONTHLY PM FOR THREAD GATE	3/14/2013	3/15/2013 7:22:54 AM	1	\$10.13
170171	MONTHLY PM FOR THREAD GATE	4/15/2013	4/18/2013 8:20:53 AM	3	\$10.13
171235	MONTHLY PM FOR THREAD GATE	5/20/2013	5/23/2013 8:53:55 AM	3	\$10.13
172119	MONTHLY PM FOR THREAD GATE	6/24/2013	6/25/2013 7:30:57 AM	1	\$10.13
173130	MONTHLY PM FOR THREAD GATE	7/25/2013	8/7/2013 7:58:42 AM	13	\$10.13
175130	MONTHLY PM FOR THREAD GATE	9/6/2013	9/20/2013 7:26:39 AM	14	\$10.13

## Asset/Equipment Work Order History Brief

176081	MONTHLY PM FOR THREAD GATE	10/21/2013	10/15/2013 7:51:29 AM	0	\$10.13
177195	MONTHLY PM FOR THREAD GATE	11/14/2013	12/6/2013 8:46:37 AM	22	\$10.13
178874	MONTHLY PM FOR THREAD GATE	1/6/2014	1/14/2014 7:43:23 AM	8	\$10.13
179848	MONTHLY PM FOR THREAD GATE	2/13/2014	2/13/2014 8:21:40 AM	0	\$10.13
181022	MONTHLY PM FOR THREAD GATE	3/17/2014	3/26/2014 7:36:36 AM	9	\$10.13
181821	MONTHLY PM FOR THREAD GATE	4/25/2014	4/17/2014 7:04:50 AM	0	\$10.13
182868	MONTHLY PM FOR THREAD GATE	5/19/2014	6/3/2014 7:45:43 AM	15	\$10.13
184566	MONTHLY PM FOR THREAD GATE	7/3/2014	7/8/2014 7:24:08 AM	5	\$10.13
185826	MONTHLY PM FOR THREAD GATE	8/7/2014	8/5/2014 7:41:34 AM	0	\$10.13
186833	MONTHLY PM FOR THREAD GATE	9/4/2014	9/18/2014 7:24:59 AM	14	\$10.13
187976	MONTHLY PM FOR THREAD GATE	10/20/2014	10/17/2014 7:17:56 AM	0	\$10.13
188847	MONTHLY PM FOR THREAD GATE	11/17/2014	12/2/2014 7:21:26 AM	15	\$10.13
190517	MONTHLY PM FOR THREAD GATE	1/1/2015	1/13/2015 7:29:33 AM	12	\$8.75
191550	MONTHLY PM FOR THREAD GATE	2/12/2015	2/12/2015 10:52:45 AM	0	\$7.33
192526	MONTHLY PM FOR THREAD GATE	3/16/2015	3/18/2015 7:33:49 AM	2	\$7.33
193624	MONTHLY PM FOR THREAD GATE	4/17/2015	4/24/2015 8:46:17 AM	7	\$8.75
194684	MONTHLY PM FOR THREAD GATE	5/25/2015	5/21/2015	0	\$7.86
195599	MONTHLY PM FOR THREAD GATE	6/22/2015	6/18/2015	0	\$10.13
196685	MONTHLY PM FOR THREAD GATE	7/20/2015	9/30/2015	72	\$10.13
199805	MONTHLY PM FOR THREAD GATE	10/30/2015	10/29/2015	0	\$8.75
200833	MONTHLY PM FOR THREAD GATE	11/30/2015	12/11/2015 7:49:55 AM	11	\$8.75
202835	MONTHLY PM FOR THREAD GATE	1/11/2016	1/14/2016 7:35:50 AM	3	\$8.75
203931	MONTHLY PM FOR THREAD GATE	2/15/2016	2/11/2016	0	\$10.13

## Asset/Equipment Work Order History Brief

204761	MONTHLY PM FOR THREAD GATE	3/14/2016	3/11/2016	0	\$8.75
205888	MONTHLY PM FOR THREAD GATE	4/11/2016	4/20/2016	9	\$0.00
206860	MONTHLY PM FOR THREAD GATE	5/20/2016	5/24/2016	4	\$10.13
207863	MONTHLY PM FOR THREAD GATE	6/23/2016	6/28/2016	5	\$10.13
208996	MONTHLY PM FOR THREAD GATE	7/28/2016	7/21/2016	0	\$8.75
209940	MONTHLY PM FOR THREAD GATE	8/22/2016	8/23/2016	1	\$40.50
211095	MONTHLY PM FOR THREAD GATE	9/22/2016	9/23/2016 7:36:41 AM	1	\$40.50
212264	MONTHLY PM FOR THREAD GATE	10/24/2016	10/27/2016 7:57:56 AM	3	\$40.50
213176	MONTHLY PM FOR THREAD GATE	11/28/2016	11/18/2016 8:56:55 AM	0	\$40.50
214055	MONTHLY PM FOR THREAD GATE	12/19/2016	12/19/2016	0	\$40.50
214968	MONTHLY PM FOR THREAD GATE	1/18/2017	2/18/2017	31	\$60.75
216629	MONTHLY PM FOR THREAD GATE	3/20/2017	4/3/2017 12:20:47 PM	14	\$40.50
218181	MONTHLY PM FOR THREAD GATE	5/3/2017	6/13/2017 12:58:15 PM	41	\$40.50
219928	MONTHLY PM FOR THREAD GATE	7/13/2017	9/1/2017 7:56:22 AM	50	\$40.50
222250	MONTHLY PM FOR THREAD GATE	10/2/2017	11/18/2017 11:33:58 AM	47	\$20.25
223142	MONTHLY PM FOR THREAD GATE	11/20/2017	12/21/2017	31	\$20.25
224749	MONTHLY PM FOR THREAD GATE	1/22/2018	2/20/2018	29	\$20.25
227497	QUARTERLY PM FOR THREAD GATE	5/21/2018	5/3/2018	0	\$20.25
229324	QUARTERLY PM FOR THREAD GATE	8/1/2018	8/16/2018	15	\$20.25
231087	QUARTERLY PM FOR THREAD GATE	11/14/2018	12/6/2018 11:42:50 PM	22	\$20.25
233095	QUARTERLY PM FOR THREAD GATE	3/6/2019	4/24/2019	49	\$20.25
234945	QUARTERLY PM FOR THREAD GATE	7/22/2019	8/7/2019 3:56:11 PM	16	\$20.25
236433	QUARTERLY PM FOR THREAD GATE	11/5/2019	12/2/2019 9:47:39 AM	27	\$20.25

## Asset/Equipment Work Order History Brief

237768	QUARTERLY PM FOR THREAD GATE	3/2/2020	3/10/2020 10:10:12 AM	8	\$20.25
238719	QUARTERLY PM FOR THREAD GATE	6/8/2020	6/10/2020 11:39:51 AM	2	\$20.25
239806	QUARTERLY PM FOR THREAD GATE	9/8/2020	10/1/2020 2:41:13 PM	23	\$20.25
240915	QUARTERLY PM FOR THREAD GATE	1/4/2021	2/9/2021 10:58:35 AM	36	\$20.25
Totals For: <b>PRSS 038.5</b>		Total WOs: 187		Total Cost:	\$1,922.03
Report Totals:		Total Assets:	7	\$109,236.67	

Selection SQL: Asset.ID Like "prss 038\*"