

Asset/Equipment Work Order History Brief

Asset ID: WASH 006		Asset: GAT THREE STAGE PRE-TREAT WASHER				
Work Order ID	Description	Scheduled Date	Completed Date	Days Past Due	Total Cost	
167687	REPAIR OF EQUIPMENT		1/4/2013	41278	\$465.15	
	Comments: RUN POWER AND AIR AND REPAIR BROKE WATER LINE					
	RUN 110 VOLTS TO WASHER (WHERE Brent R) WANTED TO PUT IT					
	RUN AIR LINE TO PUMP FOR BRENT R					
	REPAIRED BROKE WATER LINE REFILL WATER LINE 3 STATION					
167688	REPAIR OF EQUIPMENT		1/2/2013	41276	\$60.75	
	Comments: WASHER WONT START					
	REBOOTED CONTROLS FINALLY GOT FAULTS CLEARED AND STARTED					
	WASHER					
167690	REPAIR OF EQUIPMENT		1/3/2013	41277	\$449.55	
	Comments: RUN AIR LINE FOR SKIMMER					
	RAN 1/2" AIR LINE FOR SKIMMER					
167691	REPAIR OF EQUIPMENT		1/2/2013	41276	\$149.85	
	Comments: BUSS PLUG UNDER OLD WASHER HAS NO COVER					
	MADE PLASTIC COVER AND INSTALLED ON BUSS PLUG					
167815	REPAIR OF EQUIPMENT		1/8/2013	41282	\$52.50	
	Comments: NEED TO RUN SOME PIPE FOR DRAIN					
	RUN DVC 2 PIPE FOR DRAIN					
169813	REPAIR OF EQUIPMENT		3/20/2013	41353	\$280.00	
	Comments: RESEARCH AUTO CUTOFF FOR OIL SKIMMING DRUM PUMP					
170515	REPAIR OF EQUIPMENT		4/12/2013 8:12:37 AM	41376	\$499.50	
	Comments: MOVE EYE WASH STATION MOVE FIRE EXTINGUISHER MOVE DRIP PAN AND					
	NOTCH SO ITS SITS LEVEL					
	COMPLETED ALL OF THE ABOVE					
171392	REPAIR OF EQUIPMENT		5/8/2013	41402	\$31.45	
	Comments: CHEMICAL PUMP DISPLAY GONE BAD					
	REPLACED PUMP					
172537	REPAIR OF EQUIPMENT		6/14/2013	41439	\$232.58	
	Comments: ADD POWER OUTLET 120VAC FOR FLOW METER DUMP					
	TRY TO FIND 120AC CIRCUIT					
	DECIDE TO RUN FROM CIRCUIT ONLY FOR PAINT WASHER SINGLE LOAD ON					
	CIRCUIT RUN CONDUIT					
	STILL NEED TO RUN WIRE					
172548	REPAIR OF EQUIPMENT		6/15/2013	41440	\$125.80	
	Comments: INSTALL FLOW METER ON OUTLET					
	PULLED 3/12GA FOR GFCI PLUG					
	LOOKED FOR FITTINGS TO INSTALL METER (DID NOT HAVE ANY)					
172588	REPAIR OF EQUIPMENT		6/17/2013	41442	\$94.35	
	Comments: NEED TO MEASURE WASTE WATER FROM RINSE TANK					
	RAN TO SOUTHERN PIPE AND ATTATINED THE CORRECT FITTINGS					
	INSTALLED FLOW METER					

Asset/Equipment Work Order History Brief

173609	REPAIR OF EQUIPMENT	7/16/2013	41471	\$94.35
	Comments: PLEASE INSTALL HEAVY OIL VACUUM SYSTEM ON THE SMARK SKIM HOLDING TANK			
	INSTALLED NEW PIPING AND VENTUR MADE BRACKET FOR PRESSURE REGULATOR AND VALVE MOUNTED REGULATOR VALVE ASSEMBLY AND PLUMBED			
173711	REPAIR OF EQUIPMENT	7/20/2013	41475	\$534.65
	Comments: ADD SPILL CONTAINMENT FOR NEW OIL SKIMMER			
	CUT AND WELDED 2" ANGLE IRON TO BUILD STAND TO ELEVATE TANK 14" PAINTED FRAME REMOVED SKIMMER TANK CLEANED AND REMOUNTED TANK USING NEW STAND REPLUMBED AND ADDED SPILL CONTAINMENT			
173766	REPAIR OF EQUIPMENT	7/22/2013	41477	\$393.13
	Comments: WIRING SKIMMER CONTROL BOX			
	BUILT STAND FOR CONTROL BOX FROM 2" CHANNEL AND FLAT BAR WIRED OUT TESTED CONTROL BOX MOUNTED AND WIRED BOX NEAR SKIMMER			
173775	REPAIR OF EQUIPMENT	7/23/2013	41478	\$251.60
	Comments: FINISHING CONTROLS			
	FINISHED PLUMBING VALVE A VENTURI CHECKED OPERATION OK			
173970	REPAIR OF EQUIPMENT	7/30/2013	41485	\$31.45
	Comments: SPILL CONTAINMENT			
	MOVED CHEMICAL CONTAINER TO SPILL CONTAINMENT AREA			
	EXTENDED LINES			
173983	REPAIR OF EQUIPMENT	7/29/2013	41484	\$62.90
	Comments: SPILL CONTAINMENT			
	MOVED CHEMICAL BARREL TO SPILL CONTAINMENT AREA			
	ADDED NEW LINES TO REACH BARRELL			
174527	REPAIR OF EQUIPMENT	8/6/2013	41492	\$33.23
	Comments: NOT PUMPING INTO ONE OF THE TANKS THE WEIGHT HAD FELL OFF OF ONE OF THE LINES			
	PUT A TEE IN LINE TO WEIGHT IT DOWN			
174822	REPAIR OF EQUIPMENT	8/27/2013	41513	\$23.59
	Comments: REMOVE OIL SKIMMINGS FROM BARREL RACK			
	MADE SURE WASTE OIL HAD PROPER LABEL FOR TRANSPORT REMOVE TO DRUM TO ASSIGNED AREA			
175457	REPAIR OF EQUIPMENT	9/11/2013	41528	\$70.00
	Comments: PLEASE CLEAN OUT THE PUMP BETWEEN THE WASHER			
	CLEAN OUT PUMP AND REPAIRED OK			
175707	REPAIR OF EQUIPMENT	9/23/2013	41540	\$70.00
	Comments: PUMP WILL NOT WORK			
	REPRIMED PUMP TIMES CLEAN OUT LINES			
175753	REPAIR OF EQUIPMENT	9/25/2013	41542	\$87.50
	Comments: SKIMMING PUMP WILL NOT PUMP TOOK TAKE UP PIPE OUT CLEAN AND REPAIRED PUMP WORKS OK			

Asset/Equipment Work Order History Brief

176674	REPAIR OF EQUIPMENT	10/17/2013	41564	\$35.00
	Comments: CHANGE OUT SKIMMING DRUM			
	CHANGED OUT DRUMS FOR THE SKIMMING OIL			
177519	REPAIR OF EQUIPMENT	11/8/2013	41586	\$87.50
	Comments: REPLUMB PUM FROM WASHER TO SHIMMING TANK			
	REPLUMBED PUMP CLEAN OUT PLASTIC PIPE AND PUMP			
177730	REPAIR OF EQUIPMENT	11/22/2013 8:33:11 AM	41600	\$295.48
	Comments: RAISE THROUGH AND PLUMB			
	REMOVED ROUGH FROM STAND WORKED ON FABRICAING A NEW STAND			
177734	REPAIR OF EQUIPMENT	11/21/2013	41599	\$309.43
	Comments: NEED RAISED TO WASH RISERS IN			
	FINISHED WELDING STAND FOR TROUGH			
	MOUNTED TROUGH TO STAND STILL NEED TO PUT DRAIN IN AND PAINT			
178341	REPAIR OF EQUIPMENT	12/2/2013	41610	\$264.03
	Comments: NEED WASHING RISERS			
	PAINTED THROUGH AND MOUNTED CHAIN DRILLED HOLES AND ANCHORED			
	DOWN AND PLUMBED IN CAPPED OFF HOLE IN FLOOR			
178368	REPAIR OF EQUIPMENT	12/10/2013	41618	\$233.88
	Comments: GET PUMPS WORKING			
	SKIMMER PUMP CLEAN OUT PIPE AND CHANGE OUT TWO DRUMS IT SI			
	WORKING (PUMPING) LET TAMMY KNOW IT WAS WORKING			
178589	REPAIR OF EQUIPMENT	12/18/2013	41626	\$66.45
	Comments: NOT SKIMMING			
	REMOVED SKIMMER AND LBOCKED OUT			
179051	REPAIR OF EQUIPMENT	1/6/2014	41645	\$70.00
	Comments: CHANGE OUT SKIMMING OIL DRUM			
	CHANGED OIL DRUM			
179334	REPAIR OF EQUIPMENT	1/17/2014	41656	\$196.34
	Comments: INSPECT WASHER ENTRANCE FAN SYSTEM FOR VIBRATION AND DEFAULTS			
	AIR CURTAIN			
	DISCOVERED THAT THE BEARINGSHAD WORN ALSO THE FAN BALANCE HAD			
	WORN SEVERLY AND DAMAGE WAS UNABLE TO BE REPLACED OR FIXED			
180172	REPAIR OF EQUIPMENT	2/7/2014	41677	\$99.68
	Comments: NOT PUMPING			
	REPLACED HOSE ON PUMP ALSO WE HAD TO CLEAN SKIMMER			
180266	REPAIR OF EQUIPMENT	2/13/2014	41683	\$409.39
	Comments: REMOVE AIR CURTAIN FAN			
	REMOVED AIR CURTAIN FAN AND HOUSING. ALSO REMOVED FORM FROM			
	HOUSING. CLEANED SHAFT UP. CLEANED FAN. CLEANED SOME ON FAN			
	HOUSING			
180271	REPAIR OF EQUIPMENT	2/13/2014	41683	\$587.81
	Comments: PUTTING EXHUAST FAN ON ENTRACE SIDE BACK TOGETHER			
	GOT OLD SHAFT OUT. HAD TO GET ANOTHER BEARING BECAUSE THERE WAS			
	ONLY ONE THAT CAME WITH NEW SHAFT			
	GOT NEW BEARINGS AND SHAFT INSTALLED AND TO EVERYTHING LOCKED			
	DOWN TIGHT. ADJUSTED PULLEY AND TIED BELT UP			
	FIXED IT UP AND STILL HAD WHATEVER TO IT INSPECTED IT AND SEEMED TO			
	BE SQUIRREL CAGE CAUSING THE VIBRATION			
	DECIDED TO TAKE DOWN AND CLEAN CAGE UP. AND TAKE CAGE AND GET IT			
	BALANCED 2ND SHIFT WAS GONNA TAKE DOWN			

Asset/Equipment Work Order History Brief

180287	REPAIR OF EQUIPMENT	2/17/2014	41687	\$182.06
	Comments: REPLACE #1 STATION FAN AND HOUSING			
	REPLACED AND BOLTED IN PLACE FAN AND HOUSING ON 1 STATION ON TOP OF WASHER			
180298	REPAIR OF EQUIPMENT	2/19/2014 7:54:57 AM	41689	\$431.68
	Comments: BEARINGS IN MOTOR WERENT GOOD			
	REMOVED MOTOR FROM ASSEMBLY REPLACED BEARING MOTOR ON TEST BENCH ALIGNED BELTS AND MOTOR BROUGHT BACK TO PLANT AND CLEANED HOUSING			
180330	REPAIR OF EQUIPMENT	2/20/2014	41690	\$315.85
	Comments: NEED GRATES IN WASHER			
	FABRICATED AND INSTALLED EXPANDED METAL GRATES			
180354	REPAIR OF EQUIPMENT	2/20/2014	41690	\$62.90
	Comments: MAKE WALK WAY GRATE FOR INTERNAL WASHER 1 ZONE			
	ASSEMBLED GRATING FOR WALK WAY TO ASSIST PRODUCTION PERSONNEL FOR CLEANING PURPOSE			
181244	REPAIR OF EQUIPMENT	3/5/2014	41703	\$531.60
	Comments: PLEASE INSTALL ROPE SKIMMER ON STAGE 1 OF THE POWDER PAINT WASHER			
	FLA FOR MOTOR IS 7.4 AMP WHILE RUNNING WE MEASURED IT RUNNING 6.8 AMPS CIRCUIT IN CONTROL CABINET ON 120V MEASURED ONLY (5 AMPS) WE RAN 10 V CIRCUIT FROM RECEPTACLE FOR AUTOMATIC SKIMMER LEFT OLD SKIMMER RUNNING FOR THE NIGHT IT IS PLUGED INTO A RECEPTACLE NO ON OFF SWITCH NOR IS IT ON A RELAY (YET) ! WILL ATTEMPT TO FINISH PROCESS BY 3-6-14			
181293	REPAIR OF EQUIPMENT	3/6/2014	41704	\$500.15
	Comments: PLACE SKIMMER ON AUTO ELECTRICAL SHUTDOWN TURN ON SEQUENCE			
	USED 1 KVA TRANSFORMER TO APPLY ELECTRICAL SOURCE FOR SLUDGE SKIMMER/ MOUNTED TO EXTERIOR OF PANEL PLACE MOTOR STARTER FOR SKIMMER MOTOR/ WIRED NECESSARY SYSTEM FOR AUTO ON OFF SEQUENCE			
181486	REPAIR OF EQUIPMENT	3/17/2014	41715	\$122.50
	Comments: CLEANED UP AND REMOVED OIL SEE ABOUT A TANK FOR SKIMMING OIL REMOVED 5 GAL CAN OF SKIMMING OIL AND WATER AND CLEAN UP MEASURE FOR A TANK FOR SKIMMING OIL			
182042	REPAIR OF EQUIPMENT	4/2/2014	41731	\$70.00
	Comments: LOCATE SKIMMING TANK			
	STARTED TRYING TO LOCATE TANK AND GET READY TO HOOK UP			
182080	REPAIR OF EQUIPMENT	4/4/2014	41733	\$253.76
	Comments: NEED SKIMMER PLUMBED TO TANKS			
	FIGURED WAY OF DOING THE PROJECT WENT AND GOT MATERIALS FROM SOUTHERN PIPE AND MCCULLOUGH STEEL FABRICATED MOUNT FOR MOTOR AND PUMP TO SIT ON			
182099	REPAIR OF EQUIPMENT	4/7/2014	41736	\$52.50
	Comments: DRAW SKIMMING OIL TANK			
	DRAINED SKIMMING OIL/WATER OUT OF TANK GOT READY TO BE PULLED OUT GOT DRUM READY TO BE OUT LABELED CLEANED UP AREA			
182127	REPAIR OF EQUIPMENT	4/9/2014	41738	\$398.70
	Comments: HOOK UP SKIMMING OIL TANK PUMP			
	STARTED PLUMBING SKIMMING OIL TANK ON WATER TANK #1			

Asset/Equipment Work Order History Brief

182185	REPAIR OF EQUIPMENT	4/10/2014	41739	\$210.00
	Comments: HOOK UP SKIMMING PUMPS HOOKED UP DRAIN TO THE SKIMMING TANK AND RUN PIPE FOR PUMP TO HOLDING TANK/DRUM			
182190	REPAIR OF EQUIPMENT	4/11/2014	41740	\$70.00
	Comments: HOOK UP PUMP			
	PLUMBED IN FLOW AND PUMP TO DRUM			
182196	REPAIR OF EQUIPMENT	4/10/2014	41739	\$424.13
	Comments: NEW SKIMMER SYSTEM			
	HAVE TO RUN WIRE AGAIN IN ORDER TO CONTROL PUMP STILL NOT FINISH REMOVED POWER CORD FROM NEW SKIMMER MOTOR AND ADD FLE CONDUIT AND RUN POWER FROM CONTROL BOX RUN FLEX FOR LEVEL SWITCH ON BARREL			
182201	REPAIR OF EQUIPMENT	4/11/2014	41740	\$785.23
	Comments: NEW SKIMMER SYSTEM			
	HAVE TO RUN WIRE AGAIN TO CONTROL OLD SKIMMER AND PUMP WIRE PUMP AND LEVEL SWITCH WIRE SOLENOID FOR PNEUMATIC PUMP, NEW SKIMMER MOTOR BOTH FLOW SWITCHES TANK AND BARRELL NEED TO ADJUST FLOW SWITCH ON TANK TOO LOW CHECK CONTROL ON NEW SKIMMER AND PNEUMATIC PUMP IT WORKED OK NEED TO FINISH CONTROL ON NEW PUMP AND OLD SKIMMER			
182231	REPAIR OF EQUIPMENT	4/14/2014	41743	\$157.50
	Comments: GET PUMP PLUMBED IN AND GET POWER TO SKIMMING OIL SKIMMER AND AIR TO TRANSFER PUMP			
	PLUMBED IN PUMP TO HOLDING TANK FIRST STAGE HOOKED UP POWER TO SKIMMER AND AIR TO TRANSFER PUMP SECOND STAGE			
182249	REPAIR OF EQUIPMENT	4/14/2014	41743	\$456.93
	Comments: NEW SKIMMER SYSTEM PROJECT			
	FINISH UP WIRING CONTROL CIRCUIT, HAD TO MAKE SOME CHANGES, SAME AS WIRING DIAGRAM ATTACHED HAD TO RUN 12WAG WIRE FOR PUMP NEUTRAL ADD QUICK CONNECTORS ON ALL CONDUCTIVE PROBE SENSORS NEED TO BE SURE THE FLOAT SWITCH WILL WORK PROPERLY NEED TO ADD WIRING LABELS TWO SELECTOR SWITCHES ON CONTROL CABINET LEFT HAND SELECTOR OPERATES OLD SKIMMER/DISCHARGE PUMP RIGHT HAND SELECTOR OPERATES SKIMMER/ PNEUMATIC PUMP ADD JUMPER ON MASTER RELAY ME TO HAVE POWER ON SKIMMER CONTROL WHEN THE WASHER IS RUNNING CONTROL CIRCUIT IS READY, JUST NEED TO CHECK FLOAT SWITCH OPERATION			
182308	REPAIR OF EQUIPMENT	4/16/2014	41745	\$17.50
	Comments: NEW SKIMMER SYSTEM			
	MODIFY CONTROL CIRCUIT OLD SKIMMER HAVE POWER ALL THE TIME TOGGLE SWITCH IS THE ONLY CONTROL TOP SKIMMER MOTOR			
182329	REPAIR OF EQUIPMENT	4/21/2014	41750	\$87.50
	Comments: NEW SKIMMER SYSTEM PROJECT			
	ADD INDICATOR LIGHTS FOR FULL BARREL/DRUMS INDICATOR LIGHTS AND SENSORS HAVE POWER WHEN WASHER IS RUNNING BUT THE SKIMMER WON'T RUN UNLESS WASHER IS NOT RUNNING			

Asset/Equipment Work Order History Brief

182436	REPAIR OF EQUIPMENT	4/23/2014	41752	\$52.50
	Comments: CHANGE OUT DRUM OF SKIMMING OIL			
	CHANGED OT DRUMANDPUT IN STORAGE AREA CLAENUP AROUND PLANT HOLDING AREA			
183035	REPAIR OF EQUIPMENT	5/2/2014	41761	\$0.00
	Comments: CHANGE OUT SKIMMING OIL DRUM ON PUMPING TANK			
	CHANGE DRUM AND RESET PUMP CHECK FLOAT WILLHAVE TO WORK ON TOO MCUHWATER BEING PUMPED INOT DRUMS ??? HOW ????			
183140	REPAIR OF EQUIPMENT	5/12/2014 7:59:09 AM	41771	\$60.75
	Comments: ASSIT PAINT WITH WASHER			
	PERFORMED VARIOUS TASK TO ASSIST PAINT DEPT			
183141	REPAIR OF EQUIPMENT	5/10/2014	41769	\$431.93
	Comments: CLEAN ZONE 1 SOLUTION TANKS AND REFILL WITH WATER			
	USED SQUEEGY TO GET SLUDGE TO OPENING USED WET VAC TO REMVOED SLUDGE FILL CONTIANMENT BARRELS WITH SLUDGE REFILLED SOLTUION TANK CLEANED AREA			
183142	REPAIR OF EQUIPMENT	5/10/2014	41769	\$81.00
	Comments: PUMPO SLUDGE OUT OF WASHER TANK PUMPED OUT TANKS			
183143	REPAIR OF EQUIPMENT	5/9/2014	41768	\$505.36
	Comments: PAINT WASH TANK RELEASING			
	USING AIR PUMP REMOVED SLUGE AND WATER WASHER INOT 9 55 GALLON DRUMS			
183148	REPAIR OF EQUIPMENT	5/10/2014	41769	\$367.50
	Comments: CLEAN OUT WASHER TANKS			
	CLEAN OUT HOUSE TANK AND STARTED CLEANING OUT WASH TANK			
183155	REPAIR OF EQUIPMENT	5/8/2014	41767	\$35.00
	Comments: CHANGE OUT DRUM OF SKIMMING OIL			
	CHANGED OUT DRUM OF SKIMMING OIL, LABELED AND TOOK TO STORAGE ARA BY BUILDING J			
183166	REPAIR OF EQUIPMENT	5/12/2014	41771	\$132.90
	Comments: DRUMS OF SKIMMING OIL FROM TANK CLEANING OVER WEEKEND			
	LABELED AND PUT UP 10 DRUMS OF SKIMMING OIL DRUMS			
183206	REPAIR OF EQUIPMENT	5/13/2014	41772	\$166.13
	Comments: CHANGE OUT SKIMMING OIL DRUM DRUM FULL			
	CHANGED OUT LABELED AND STORAGE INVENTROY ALL DRUMS 24 SKIMMING OIL 2 USED OIL 10 SKIDS PLASTIC			
183324	REPAIR OF EQUIPMENT	5/16/2014	41775	\$31.59
	Comments: MOVE FULL CONTAINES OF SKIM OIL			
	MOVED BARREL TO DESIGNATED AREA AND REPLACED WITH NEW BARREL			
183487	REPAIR OF EQUIPMENT	5/23/2014	41782	\$113.63
	Comments: EXTEND SLUDGE DRAIN FROM SYSTEM2			
	DRAINED AND CLEANED SLUDGE TANK REMOVED WATER RETURN LINE BEGAN HARD PIPING FOR THE OTHER USEABLE WATER FROM SYTEM 2			

Asset/Equipment Work Order History Brief

184155	REPAIR OF EQUIPMENT	6/11/2014	41801	\$99.68
	Comments: BOTH BARRELS ARE FULL ON THE SKIMME PLEASE CHANGE OUT PUT UPNEW DRUMS AND STORED FULL DRUMS			
185166	REPAIR OF EQUIPMENT	7/9/2014	41829	\$35.00
	Comments: SKIMMER SYSTEM NOT WORKING AT NIGHT CHECK SKIMMER SYSTEM IT WAS WORKING ADJUSTE AND CLEAN LVEL SWITCH ON NEW SKIMMER SEPERATION SYSTEM WATER LEVEL DID NOT GO UP NOT PUMPING ENOUGH WATER INCREASE AIR PRESSURE ON PUMP WATER LEVEL ON TANK IS STILL ALITTLE BIT LOW			
186187	REPAIR OF EQUIPMENT	8/12/2014	41863	\$109.84
	Comments: CHEMICAL PUMP LEAK TOOK COVER OFF OF PUMP AND REMOVED SPLIT HOSE SEARCHED FOR REPLACEMENT HOSE IN BRENTS OFFICE REPLACED HOSE AND REASSEMBLED PUMP			
186295	REPAIR OF EQUIPMENT	8/14/2014	41865	\$99.68
	Comments: REMOVE OIL SKIN BARREL FORM WASHER AREA REMOVED SKIMMING OIL DRUM AND CHEMICAL BARRERSFROM PAINT WASHER AREA			
187036	REPAIR OF EQUIPMENT	8/28/2014	41879	\$66.45
	Comments: WASHER CHEMICAL PUMP LEAKING TALKED TO BRENT HE WAS ORDERING MORE HOSES 8/28/14			
187322	REPAIR OF EQUIPMENT	9/8/2014	41890	\$52.50
	Comments: CHEMICAL PUMP WILLNOT WORK TOOK APART AND REPLACED HOSE AND CHECK OPERATION OK			
187517	REPAIR OF EQUIPMENT	9/22/2014	41904	\$267.33
	Comments: SLUDGE TANK OVERILLED SLUDGE SEPERATOR NEED SOME MODIFICATIONS INSPECTED SLUDGE PUMP FLOAT OK WORKING CHECKED FUSES OK CHECKED ALL SLUDGE LINES FOR STOPPAGE(CLEANED EACH LINE UISNG AIR PRESSURE) MODIFIED SLUDGE EXTRACTION DROP LINE TO BARRELL TO STOP CLOGS FROM DEVELOPING			
187572	REPAIR OF EQUIPMENT	9/24/2014	41906	\$126.34
	Comments: NEED BETTER WALKING INTO WASHER PUT IN NEW GRATES EXPANDED METAL			
187578	REPAIR OF EQUIPMENT	9/24/2014	41906	\$31.45
	Comments: INSPECT WASTE SLUDGE SYSTEM TO ENSURE OF PROPER OPERATION CHECKED NEW SLUDGE DRIAN FOR PROPER DRAINAGE INSPECTED NEW FLOAT EXTRATOR IN SLUDGE ACCUMLATION TANK OK			
187588	REPAIR OF EQUIPMENT	9/23/2014	41905	\$47.18
	Comments: INSPECT WASHER SLUDGE SYSTEM AND MOUNT NEW SKIMMER EXTRACTIONS ADJSUTED CHEMICAL PUMP 2 TO ENSURE CHEMICALS FLOWING PROPERLY MOUNTED SLUDGE FLOAT EXTRACTION DEVICE INOT SKIMMER PUMP 2 TANK			
187645	REPAIR OF EQUIPMENT	9/25/2014	41907	\$31.45
	Comments: USE SCHEMATIC DRAWINGS TO DETERMINE WHERE TO MOUNT SKIMMER MOTOR			

Asset/Equipment Work Order History Brief

188146	REPAIR OF EQUIPMENT	10/3/2014	41915	\$35.00
	Comments: REPLACE PUMP CHEMICAL PUMP			
	SAME			
188176	REPAIR OF EQUIPMENT	10/6/2014	41918	\$94.35
	Comments: CHEMICAL PUMP SLUDGE WASTE SYSTEM			
	SWAPPED LINES ON RIGHT SIDE PUMP SUCITON WAS ON WRONG TUBE INSPECTED SLUDGE WASTE TANK PUMP AND FLOAT TO SEE IF OPERATION WAS			
188192	REPAIR OF EQUIPMENT	10/7/2014	41919	\$97.90
	Comments: MONITOR WAHSEY SYSTEM SLUDGE TANK			
	MADE ADJUSTMENTS TO SLUDGE TANK PUMP FLOAT TESTED TO ENSURE OPERATION WOULD WORK			
188404	REPAIR OF EQUIPMENT	10/20/2014	41932	\$66.45
	Comments: REMOVE SKIMMER WASTE FROM SLUDGE SYSTEM			
	AFTER BEING LABELED TOOK DRUM TO PROPER LOCATION FOR STORAGE			
188513	REPAIR OF EQUIPMENT	10/23/2014	41935	\$52.50
	Comments: OIL SKIMMER PUTTING TOO MUCH WATER ON DRUM			
	ASSIST DAY SHIFT MONITOR/CHECK OIL SKIMMER OPERATION SOME FOAM ON SKIMMER TANK LET IT EMPTY AND REFILL TANKS IT STILL HAS TOO MUCH FOAM ON IT			
188514	REPAIR OF EQUIPMENT	10/23/2014	41935	\$248.30
	Comments: RESERVIOR FULL SLUDGE BARREL FILLING WITH WATER INSTEAD OF OIL			
	INSPECTED PUMP FOR PROPER OPERATION/DRAINED RESERVOIR MANUALLY FROM PANEL VIEW INSPECTED DRAIN LINES FOR CLOGS INSPECTED SLUDGE RESERVIOR FOR LEAKS CORRECT OPERATION			
188520	REPAIR OF EQUIPMENT		0	\$97.90
	Comments: WASHER SLUDGE SYSTEM AND BARREL NEEDING INSPECTED			
	CHECK BARREL (OK) FOR MOJNIGNG/HAD TO CHANGE DRUM BYB END OF SHIFT INSPECTED SLUDGE RESERVIOR,FILL-RAN SYSTEM IN MANUAL TO EMPTY RESIVOUIR			
188528	REPAIR OF EQUIPMENT	10/25/2014	41937	\$510.30
	Comments: INSPECT ALL SKIMMER SYSTEMS TO ENSURE PROPER OPERATION ADJUSTED LEVEL FO SKIMMER 1 (DIAPHRAM) INSPECTED SLUDGE RESEVOIR ON 2 SKIMMER CLEANED RESERVOIR FOR SLUDGE SKIMMER DRAIN FLUID FROM SLUDGE PUMPED OVERFLOW WASTE CONTAINERS INTO LABELED DRUM FILLED SLUDGE RESERVOIR FOR OIL REMOVAL ON PUMP 1			
188543	REPAIR OF EQUIPMENT	10/27/2014	41939	\$132.90
	Comments: INSPECT WASTE FROM WASHER			
	WASHER SYSTEM OK STORED WASTE FROM WASHER IN PROPER LOCATION LOCATED BARREL LIFTS FROM J BUILDING PLACED IN SHOP AREA FOR CLEANING			
189058	REPAIR OF EQUIPMENT	11/5/2014	41948	\$70.00
	Comments: SEPARATOR TANK SLUDGE.WATER OVERFLOW			
	ADD OLD SKIMMER MOTOR OT THE AUTOMATIC CIRCUIT REMOVE TOGGLE SWITCH ADD CONTROL CABINET PRINT TO THE MAIN CONTROL CABINET CHECK OPERATION OK			

Asset/Equipment Work Order History Brief

189187	REPAIR OF EQUIPMENT	11/12/2014	41955	\$66.45	
	Comments: REMOVE SLUDGE BARREL				
	INSPECTED SKIMMER SYSTEM REMOVED FULL SLUDGE BARREL AND REPLACED				
189428	REPAIR OF EQUIPMENT	11/21/2014	41964	\$99.68	
	Comments: INSPECTED SKIMMER SYSTEM FOR CORRECT OPERATION REMOVE SKIMMING OIL				
189874	REPAIR OF EQUIPMENT	12/3/2014	41976	\$410.61	
	Comments: PLEASE INSTALL 4 ADDITIONALSAFETY GRATES IN WASHER STAGE 1				
	CUT EXPANDED METAL FROM FLOOR OF WASHER REMOVED MIDDLE RUNNER TO MAKE ROOM FOR GRATES MODIFIED TOW FITTING GRATES TO FIT TACK WLEDED STAINLESS EXPANDED METAL IN WASHER				
189875	REPAIR OF EQUIPMENT	12/2/2014	41975	\$62.90	
	Comments: REMOVE SKIMMER DRUM AT WASTE STATION FOR WASHER				
	REMOVED SKIMMER WASTE FROM WASHER WASTE AREA				
190068	REPAIR OF EQUIPMENT	12/16/2014	41989	\$62.90	
	Comments: NEITHER ARE WORKING				
	BLOWN FUSE FOUND BOTH VALVES FROM DISCHARGE TANK BOX TO SKIMMER BY THE LEKOS COMPRESSOR WILL ONE OT HOLDING DRUM SHUT OFF OVERLOOKING PUMP OPENED ONE TO HOLDING TANK CHECKED OPERATION OK				
190069	REPAIR OF EQUIPMENT	12/15/2014	41988	\$40.50	
	Comments: SKIMMER INOP				
	FOUND BLOWN FUSE REPLACED SAME BLEW FUSE IMMEDIATELY SUSPECT SKIMMER MOTOR				
190874	REPAIR OF EQUIPMENT	1/14/2015	42018	\$52.50	
	Comments: CHECK SKIMMING PUMP AND DRUMS				
	CHECKED PUMP FOR LEAKS NO LEAKS DRUMS WIRE NOT FULL SHOULD HAVE TO CHANGE OUT SKIMMING OIL DRUM 1/15/15 WILL CHECK IN AM				
191089	GENERAL AUTOMATIC TRANSFER C	12/30/2014	1/23/2015 11:33:07 AM	24	\$0.00
191090	GENERAL AUTOMATIC TRANSFER	1/22/2015	1/23/2015 11:33:17 AM	1	\$0.00
191091	GENERAL AUTOMATIC TRANSFER C	1/30/2015	2/3/2015	4	\$0.00
191704	GENERAL AUTOMATIC TRANSFER	2/23/2015	2/25/2015 7:17:16 AM	2	\$0.00
191922	GAT PAINT WASHER WEEKLY PM	2/10/2015	2/27/2015 9:17:22 AM	17	\$0.00
192038	REPAIR OF EQUIPMENT	2/18/2015	42053	\$23.59	
	Comments: CHECK SKIMMER SYSTEM				
	INSPECTED SKIMMER SYSTEM TO MAKE SURE EVERYTHING IS OPERATING CORRECTLY				
192140	REPAIR OF EQUIPMENT	2/25/2015	42060	\$52.50	
	Comments: CHANGE OUT A DURM OF SKIMING WATER OIL GOT READY TO CHANGE OUT, IT WAS NOT READY TO CHANGE YET				

Asset/Equipment Work Order History Brief

192695	GAT PAINT WASHER WEEKLY PM	3/6/2015	3/5/2015	0	\$0.00
192696	GAT PAINT WASHER MONTHLY PM	3/27/2015	4/1/2015 12:20:08 PM	5	\$40.50
192749	REPAIR OF EQUIPMENT		3/3/2015	42066	\$52.50
	Comments: CHANGE OUT DRUM OF SKIMMING OIL STORE SKIMMING OIL BY BUILDING J CHANGED OUT DRUM OF SKIMMING OIL STORED DRUM OF SKIMMING OIL TO STORAGE AREA HAZARD WASTE STORAGE AREA				
193041	REPAIR OF EQUIPMENT		3/18/2015	42081	\$221.93
	Comments: STAIRS AND RAILS ON PAINT WASHER BOLTED RAIL MOUNTED STAIRS MOUNTED RAIL WELDED RAIL STAINLESSLY				
193095	REPAIR OF EQUIPMENT		3/20/2015	42083	\$498.89
	Comments: INSTALL NEW GRATED METAL ON WASHER FLOOR MEASURED CUT WITH TORCH INSTALLED IN PROPER LOCATION				
193101	REPAIR OF EQUIPMENT		3/21/2015	42084	\$69.80
	Comments: CANNOT START WASHER SEVERAL FAULTS ON WASHER, CLEANED FAULTS BUT THEY KEEP RETURNING NOTICED NEW WIRING FOR LIGHT RECEPTACLE DISCONNECTED ASSOCIATED WIRING UNTIL FAULT STAYS OFF PROBABLY DISCONNECTED TWO MCUH CLEARED FAULTS STARTED WASHER ITS NOT GOOD IDEA TO MIX AC DC CONTROLS WITH EXTERNAL RECEPTACLE POWER THIS HAPPENED BEFORE ON SAME CABINET LETS RUN RECEPT. POWER SEPARATELY				
193102	REPAIR OF EQUIPMENT		3/20/2015	42083	\$210.00
	Comments: NEED TO ADD DOCK LIGHT ON SOUTH END OF TANK FINISH UP MOUNTING RAIL CALEB SMITH MOUNT DOCK LIGHT HAD TO FIND THE RIGHT BULB RUN CONDUIT AND WIRE FOR GFCI OUTLET WIRE TO STEP DOWN TRANSFORMER ON WASHER CONTROL CABINET 1 KVA CHECK LIGHT OPERATION OK PULLING 1.1 AMP				
193103	REPAIR OF EQUIPMENT		3/21/2015	42084	\$87.50
	Comments: WASHER WON'T START IN AUTO SKIMMER SYSTEM WON'T COME ON REWIRE GFCI FOR DOCK LIGHT REWIRE PUMP REWIRE GFCI TO 20 A BREAKER 5 CHECK GFCI OK CHECK WASHER RUNS IN AUTO OK				
193287	GAT PAINT WASHER WEEKLY PM	3/12/2015	3/30/2015	18	\$69.80
193307	REPAIR OF EQUIPMENT		3/27/2015	42090	\$62.90
	Comments: THE NEW GATES WE HAVE IN THE WASHER ARE MOVING APART FROM EACH OTHER AND LEAVING A GAP TO WHERE YOU CAN WEDGE YOUR FOOT IN MEASURED GAP FOR FITTING NON CORROSIVE RUST PROOF SPACER ON GRATES EITHER STAINLESS OR ALUMINUM WILL CONSULT BRENT FOR EITHER ORDERING METAL OR USING SOMETHING IN HOUSE				
193824	GAT PAINT WASHER WEEKLY PM	4/6/2015	4/6/2015	0	\$31.45
193825	GAT PAINT WASHER MONTHLY PM	5/1/2015	5/1/2015	0	\$40.50
193956	GAT PAINT WASHER WEEKLY PM	4/13/2015	4/13/2015	0	\$71.95

Asset/Equipment Work Order History Brief

194007	REPAIR OF EQUIPMENT	4/13/2015	42107	\$199.35	
	Comments: REMOE OLD RUNNERS PLACE GRATED RUNNERS WITHIN WASHER				
	MEASURED CUT AND PLACED GRATED PLATES WITHIN WASHER AREA TO MAE IT SLIP RESIST				
194008	REPAIR OF EQUIPMENT	4/13/2015	42107	\$107.93	
	Comments: INSTALL STAINLESS STEEL WALDWAY				
	ASSISTED 2ND SHFIT WITH WALKWAY INSTALL				
194103	GAT PAINT WASHER WEEKLY PM	4/20/2015	4/21/2015 7:33:55 AM	1	\$71.95
194234	GAT PAINT WASHER WEEKLY PM	4/28/2015	4/28/2015 7:33:16 AM	0	\$0.00
194250	REPAIR OF EQUIPMENT	4/22/2015	42116	\$70.00	
	Comments: GET BIG WATER PUMP READY TO RUN AND PUMP				
	OILED AND CLEANED INSIDE PUMP RUN WATER THROUGH READY TO USE GOT THE PUMP OUT OF THE BUILING J				
194877	GAT PAINT WASHER WEEKLY PM	5/5/2015	5/4/2015	0	\$71.95
194911	REPAIR OF EQUIPMENT	5/5/2015	42129	\$132.90	
	Comments: PUMP NOT PUMPING				
	CLEANED LINES, BECAUSE THEY HAD A WHIT BUILD UP REPLACED TUBE ON PUMP PURGED SYSTEMA ND WATCHED OPERATION HAD TO CLEAN A DOUBLE TIMES TO GET ALL DIEBRIS OUT				
194919	REPAIR OF EQUIPMENT	5/7/2015	42131	\$107.93	
	Comments: PUT UP BARRIER IN SOUTH GREEN PARKING LOT				
	BLOCKED SOUTH LOT AND PART OF MIDDLE LOTBY THE WINDOW				
194938	GAT PAINT WASHER WEEKLY PM	5/11/2015	5/11/2015	0	\$71.95
194940	REPAIR OF EQUIPMENT	5/7/2015	42131	\$113.63	
	Comments: CHEMICAL NOT PUMPING CHEMICALS				
	THE CHEMICALS WOULD COME ALL THE WAY TO THE PUMP BUT WOULD NEVER CYCLE THROUGH THE PUMP TOOK LINES OFF AND HELD FINGERS ON LINES AND THE ONE WAS SACKING RIGHT BUT THE OTHERE HAD NO OUTPUT PUT HAS BACK ON THE BARREL SIDE AND PUMPEDTHE CHEMICALS TO THE PUMP BUT NOT THROUGH IT TALKED TO BRENT AND HE HAD GIVEN YOGI SOME REPLACEMENT HOSES FOR THAT PUMP FOUND THEM AND STEVE WAS GONNA PUMP THEM FOUND THE PUMP BEHIND CHUCK DON'T THINK IT HAD EVER BEEN SENT OUT (NOT FOR SURE)				
194949	REPAIR OF EQUIPMENT	5/7/2015	42131	\$166.13	
	Comments: CHEMICAL PUMP FOR ZONE 2 NETWORK				
	CHECKED CHEMICAL PUMP FOR PROPER OPERATION CYCLING SEQUENCE WAS OFF PUMP 1 CYCLE PUMP 2 WAS OFF DUE TO DRAINING OF WASHER PUMP 1 WOULD NOT PULL CHEMICAL INTO SYSTEM CHANGED CHEMICAL FEED LINE AND WASHER SUPPLY LINES OLD LINES WERE CLOGGED				
194960	REPAIR OF EQUIPMENT	5/9/2015	42133	\$70.00	
	Comments: HELP WITH THE WASHER				
	FIINISH CLEANING THE FIRST TANK AND PUMPED OUT FILLED BACK UP WITH WATER AND CHEMICAL FINSIHED CLEANING THE SECOND STAGE TANK THEY WILL FILL WITH WATER MONDAY				

Asset/Equipment Work Order History Brief

194983	REPAIR OF EQUIPMENT		5/11/2015		42135	\$52.50
	Comments:	CHNGE OUT DRUM OF SKIMMING OIL				
		CHANGED OUT ONE DRUM OF SKIMMING OIL AND LABELED AND STORED IN STORAGE AREA				
194989	REPAIR OF EQUIPMENT		5/11/2015		42135	\$33.23
	Comments:	READ TO START WASHER BACK UP				
		WE PUT THE SLUDGE PUMP BACK IN PLACE AND SKID THE LINDS IN PLACE TO KEEP THAT MISTO FOWATER FORM GETTING EVERYWHERE				
194998	REPAIR OF EQUIPMENT		5/12/2015		42136	\$63.44
	Comments:	ONE OF THE CHEMICAL PUMP HAS STOPPED WORKING ON THE WASHER PLEASE HELP WITH THIS ISSUE ASAP				
		CHANGED SETTINGS TO GET THE PUMP PRIMED				
195047	GAT PAINT WASHER WEEKLY PM	5/18/2015	5/18/2015		0	\$71.95
195170	GAT PAINT WASHER WEEKLY PM	5/25/2015	5/27/2015 8:00:24 AM		2	\$0.00
195295	GAT PAINT WASHER MONTHLY PM	6/1/2015	6/15/2015		14	\$71.95
195795	GAT PAINT WASHER WEEKLY PM	6/3/2015	6/2/2015 12:41:59 PM		0	\$0.00
195816	GAT PAINT WASHER WEEKLY PM	6/9/2015	6/8/2015		0	\$71.95
195952	GAT PAINT WASHER WEEKLY PM	6/15/2015	6/15/2015		0	\$71.95
195958	REPAIR OF EQUIPMENT		6/9/2015		42164	\$52.50
	Comments:	CHANGE OUT DRUM OF SKIMMING OIL				
		CHANGE OUT DRUM OF SKIMMING OIL LABEL AND STORED PUT EMPTY DRUM OVER AT PAINT AND LABELED				
196168	GAT PAINT WASHER WEEKLY PM	6/22/2015	6/22/2015		0	\$15.73
196207	REPAIR OF EQUIPMENT		6/18/2015		42173	\$47.18
	Comments:	INSPECT WASHER SLUDGE REMOVAL SYSTEM				
		INSPECTED SYSTEM SLUDGE SYSTEM DRAINAGE SOME WATER RUN OFF SPILLED ON BARREL				
196298	GAT PAINT WASHER WEEKLY PM	6/29/2015	6/29/2015		0	\$66.45
196319	REPAIR OF EQUIPMENT		6/23/2015		42178	\$52.50
	Comments:	THE 55 GALLON SLUDGE BARREL ON THE PAINT WASHER NEEDS TO BE DUMPED				
		CHANGE OUT SKIMMINGDRUM SHOWED MICHAEL JOHNSONS THE DRUM WAS ONLY 1/2 FULL SHOWED MICHAEL J TAMMY C MAMIE S THE DRUM DI NOT NEED CHANGING.				
196323	REPAIR OF EQUIPMENT		6/24/2015		42179	\$33.36
	Comments:	NOT PUMPING TO LOW ENOUGH LEVEL				
		MOVED PUMP ACTIVITOR TO MAKE IT COME ON				

Asset/Equipment Work Order History Brief

196327	REPAIR OF EQUIPMENT	6/24/2015	42179	\$132.90	
	Comments: REPLACE SCREENS TANK UNDER OIL SKIMMER				
	MOVE OIL SKIMME REPLACE SCREENS ON TANKPNEUMATIC PUMP FOR LSUDGE TANK NOT WORKING CHECK CONTROL CIRUCIT SLUDGE TANK LEVEL SWITCH NC CONTACT NOT WORKING REPLACE LEVEL SWITCH SKIMMER SYSTEM WORKED OK NEED NEW LEVEL SWITCH				
196330	REPAIR OF EQUIPMENT	6/25/2015	42180	\$166.13	
	Comments: FOLLOWING UP WITH SECOND SHIFT				
	CHECKED HIGH LEVEL SWITCH FOR OLD SKIMMER DRUM SWITCH IS BAD GOT ONE ORDERED ALSO CHECKED SLUDGE PUMP FLOAT WAS WORKING BUT HAD TO BE MIGGLED TO ACTIVATE. IM GONNA KEEP AN EYE ON IT AND REPLACE IT IF NECESSARY				
196350	REPAIR OF EQUIPMENT	6/26/2015	42181	\$66.45	
	Comments: REPLACE BAD LEVEL RINIRON AT SLUDGE BARREL				
	SAME HADTORE REPLACE QUICK CONNECTOR CHECK OPERATION OK				
196377	REPAIR OF EQUIPMENT	6/29/2015	42184	\$180.48	
	Comments: FLOAT NOT WORKING PROPERLY				
	CHANGED FLOAT OUT				
196378	REPAIR OF EQUIPMENT	6/30/2015	42185	\$0.00	
	Comments: INSPECT SKIMMER SYSTEMS FOR CORRECT OPERATION				
	CHECKED BOTH SKIMMERS FOR CORECT OPERATION OK				
196384	REPAIR OF EQUIPMENT	6/30/2015	42185	\$0.00	
	Comments: ONE OF THE CHEMCIAL PUMPS HAS STOPPED WORKING ON THE WATER REPLACED HOSE AND PRIMED PUMP				
196392	REPAIR OF EQUIPMENT	6/30/2015	42185	\$52.50	
	Comments: CHECK THE CHE PUMP				
	CHECK THE PUMP WATCHED IT WORK CHECK TO MAKE SURE IT WAS PUMPING OK TOOK THE END CAPS OFF MADE SURE THE ROLLERS WAS WORKING THEY WERE. OK				
196910	GAT PAINT WASHER WEEKLY PM	7/6/2015	7/6/2015	0	\$71.95
196911	GAT PAINT WASHER MONTHLY PM	7/15/2015	7/15/2015	0	\$71.95
197021	GAT PAINT WASHER WEEKLY PM	7/13/2015	7/13/2015	0	\$71.95
197046	REPAIR OF EQUIPMENT	7/9/2015	42194	\$99.68	
	Comments: SKIMMER TANK OVERFLOW				
	REMOVED 3/4 PVC CHECK VALVE CHECK FLOW, WATER FLOWS IN BOTH DIRECTIONS NEED TO REPLACE CHECK VALVE ADJSUTE LEVEL SWITCH AT SKIMMER TANK TURN ONN VALVE AT WATER SLUDGE PUMP				

Asset/Equipment Work Order History Brief

197062	REPAIR OF EQUIPMENT	7/8/2015	42193	\$166.13	
	Comments: SKIMMER BARREL NEEDING REPLACED				
	CHECKED SYSTEM SKIMMER SYSTEM HAD BEEN OPERATING WHILE WASHER SYSTEM WAS ON WASHING PRODUCT TURNED SKIMMER SYTEM OFF REMOVED FULL BARREL AND REPLACED WITH EMPY TOOK FULL SKIMMER BARREL TO PROPER STORAGE AREA JOSE WIRED SYSTEMD SO THAT IF PUMP ON THE WASHER WAS ON THE SKIMMER WOULD BE OFF				
197064	REPAIR OF EQUIPMENT	7/9/2015	42194	\$111.85	
	Comments: TANK UNDER WASHER WAS RUNNING				
	JOSE HAD REWIRED SO ALLTHE PUMPS HAD TO BE OFF FOR THE SKIMMER TO RUN SO EMPLOYEES CANT RUN SKIMMER TO DRAIN THE TANK I MADE THE CONTACT TO PULL THE SLUDGE DOWN AND WITHIN 30 MINUTES IT WAS BACK FULL THOUGHT IT WAS COMING FROM THE SKIMMER SIDE KEN AND I LOOKED AT IT AND WAS WONDERINGJERROD CRAWLEY ORDERED A NEW CHECK VALVE MOVED THE WIRE BACK SO THAT WHEN SPRAY 2 WAS OFF SKIMMER SYSTEM WOULD RUN				
197211	GAT PAINT WASHER WEEKLY PM	7/20/2015	7/21/2015	1	\$71.95
197241	GAT PAINT WASHER WEEKLY PM	7/28/2015	7/27/2015	0	\$71.95
197741	GAT PAINT WASHER WEEKLY PM	8/3/2015	8/3/2015	0	\$71.95
197742	GAT PAINT WASHER MONTHLY PM	8/14/2015	8/21/2015 7:17:56 AM	7	\$71.95
197825	REPAIR OF EQUIPMENT	7/29/2015	42214	\$52.50	
	Comments: SLUGE BARREL NEEDS TO BE DUMPED CHANGED TO DRUMS OF SKIMMING OIL				
197946	GAT PAINT WASHER WEEKLY PM	8/10/2015	8/11/2015	1	\$71.95
198118	GAT PAINT WASHER WEEKLY PM	8/18/2015	8/18/2015 7:58:11 AM	0	\$71.95
198226	GAT PAINT WASHER WEEKLY PM	8/25/2015	8/25/2015 8:14:18 AM	0	\$71.95
198369	GAT PAINT WASHER WEEKLY PM	9/1/2015	8/31/2015	0	\$71.95
198447	REPAIR OF EQUIPMENT	8/31/2015	42247	\$145.08	
	Comments: ONE OF THE CHEMICAL PUMPS HAS STOPPED WORKING ON THE WASHER SKIMMER PUMP 1 STOPPED OPERATING				
	INSPECTED SYSTEM PUMP PRESSURE LINE OK RAN PUMP SYSTEM DISCOVERED BUILDUP OF CHEMICAL ON FEED LINE IN FEED LINE AND ON FEED LINE WEIGHT CLEANED TAKING USING AIR AND PROB				
	PNEUMATIC SKIMMER [UMP NOT WORK CHECK FOR VOLTAGE SUPPLY RELAY SENSORS CHECKED SUPPLYIWIING BROKE AT CONNECTION FOR SKIMMER TANK				
198949	GAT PAINT WASHER WEEKLY PM	9/7/2015	9/10/2015 7:25:58 AM	3	\$71.95
198950	GAT PAINT WASHER MONTHLY PM	9/21/2015	9/29/2015 7:57:12 AM	8	\$71.95

Asset/Equipment Work Order History Brief

198985	REPAIR OF EQUIPMENT		9/1/2015	42248	\$35.00
	Comments: ONE OF THE CHEMICAL PUMPS HAS STOPPED WORKING AT THE WASHER FLUSHED OUT HOSES AND FITTINGS WHEN AHEAD AND CHANGE OUT HOSES KEEP OLD ONES ALL OK				
199119	GAT PAINT WASHER WEEKLY PM	9/17/2015	9/14/2015	0	\$71.95
199233	GAT PAINT WASHER WEEKLY PM	9/21/2015	9/21/2015	0	\$71.95
199423	GAT PAINT WASHER WEEKLY PM	9/28/2015	9/28/2015	0	\$71.95
199983	GAT PAINT WASHER WEEKLY PM	10/5/2015	10/5/2015	0	\$71.95
199984	GAT PAINT WASHER MONTHLY PM	10/29/2015	10/28/2015	0	\$71.95
200125	GAT PAINT WASHER WEEKLY PM	10/12/2015	10/12/2015	0	\$71.95
200235	GAT PAINT WASHER WEEKLY PM	10/19/2015	10/19/2015	0	\$0.00
200546	GAT PAINT WASHER WEEKLY PM	10/26/2015	11/2/2015	7	\$71.95
201022	GAT PAINT WASHER MONTHLY PM	11/27/2015	12/8/2015 7:47:38 AM	11	\$71.95
201087	GAT PAINT WASHER WEEKLY PM	11/9/2015	11/9/2015	0	\$71.95
201225	GAT PAINT WASHER WEEKLY PM	11/16/2015	11/16/2015	0	\$71.95
201455	GAT PAINT WASHER WEEKLY PM	11/23/2015	12/1/2015 7:39:05 AM	8	\$71.95
201664	GAT THREE STAGE PRE TREAT WA	12/1/2015	12/30/2015 8:47:54 AM	29	\$40.50
201783	GAT PAINT WASHER WEEKLY PM	12/8/2015	12/8/2015 7:47:56 AM	0	\$71.95
201960	GAT PAINT WASHER WEEKLY PM	12/15/2015	12/15/2015 7:53:04 AM	0	\$71.95
202227	GAT PAINT WASHER WEEKLY PM	12/22/2015	12/21/2015	0	\$71.95
202348	GAT PAINT WASHER WEEKLY PM	12/28/2015	12/28/2015	0	\$71.95
203076	GAT PAINT WASHER WEEKLY PM	1/4/2016	1/5/2016 7:43:43 AM	1	\$71.95
203077	GAT PAINT WASHER MONTHLY PM	1/7/2016	1/6/2016	0	\$71.95
203220	GAT PAINT WASHER WEEKLY PM	1/12/2016	1/11/2016	0	\$71.95
203279	GAT PAINT WASHER WEEKLY PM	1/18/2016	1/20/2016 7:43:06 AM	2	\$71.95

Asset/Equipment Work Order History Brief

203428	GAT PAINT WASHER WEEKLY PM	1/27/2016	2/1/2016	5	\$0.00
203456	REPAIR OF EQUIPMENT		1/25/2016	42394	\$71.95
	Comments: PM WASHER				
	PERFORMED WASHER PM				
203665	GAT PAINT WASHER MONTHLY PM	2/5/2016	2/9/2016 7:45:42 AM	4	\$71.95
203720	REPAIR OF EQUIPMENT		2/1/2016	42401	\$71.95
	Comments: PERFORMED WEEKLY PM				
203813	GAT PAINT WASHER WEEKLY PM	2/8/2016	2/8/2016	0	\$71.95
203978	GAT PAINT WASHER WEEKLY PM	2/15/2016	2/15/2016	0	\$71.95
204041	REPAIR OF EQUIPMENT		2/11/2016	42411	\$11.74
	Comments: THE WASHER WOULD NOT SHUT OFF				
	GOT A CALL SAYING THAT THE WASHERS WOULD NOT SHUT OFF				
	FOUND THAT THE SCREEN WAS LOCKED UP				
	REBOOTED THE HMI SCREEN				
	TESTED THE FUNCTIONS ON THE HMI AND EVERYTHING IS WORKING				
	PROPERLY NOW				
204048	REPAIR OF EQUIPMENT		2/11/2016	42411	\$52.50
	Comments: PUMP WONT WORK				
	REPLACE PUMP AT SLUDGE TANK				
	CHECK OPERATION IT WONT WORK				
	CHANGE ROTATION IT WORKED OK				
204339	GAT PAINT WASHER WEEKLY PM	2/22/2016	2/22/2016	0	\$71.95
204443	GAT PAINT WASHER WEEKLY PM	2/29/2016	2/29/2016	0	\$31.45
204946	GAT PAINT WASHER MONTHLY PM	3/10/2016	3/7/2016	0	\$31.45
205056	GAT PAINT WASHER WEEKLY PM	3/7/2016	3/7/2016	0	\$40.50
205152	REPAIR OF EQUIPMENT		3/7/2016	42436	\$17.50
	Comments: WE NEED SOMEONE TO REPAIR ELECTRICAL LINE BRACKET ON THE PAINT WASHER				
	BOLT ON CONDUIT CLAMPTO UNISTRUT				
	ADD SELF TAPPER SCREW SO IT WONT SLIDE OFF AGAIN FROMUNISTRUT				
205183	GAT PAINT WASHER WEEKLY PM	3/14/2016	3/14/2016	0	\$31.45
205362	GAT PAINT WASHER WEEKLY PM	3/21/2016	3/21/2016	0	\$71.95
205493	GAT PAINT WASHER WEEKLY PM	3/28/2016	3/28/2016	0	\$0.00
205630	GAT PAINT WASHER MONTHLY PM	4/6/2016	4/11/2016	5	\$31.45
206038	GAT PAINT WASHER WEEKLY PM	4/4/2016	4/4/2016	0	\$31.45

Asset/Equipment Work Order History Brief

206123	GAT PAINT WASHER WEEKLY PM	4/11/2016	4/11/2016	0	\$71.95
206274	GAT PAINT WASHER WEEKLY PM	4/18/2016	4/18/2016	0	\$31.45
206455	GAT PAINT WASHER WEEKLY PM	4/25/2016	4/25/2016	0	\$31.45
207079	GAT PAINT WASHER WEEKLY PM	5/2/2016	5/9/2016	7	\$31.45
207080	GAT PAINT WASHER MONTHLY PM	5/11/2016	5/16/2016	5	\$71.95
207284	GAT PAINT WASHER WEEKLY PM	5/16/2016	5/16/2016	0	\$71.95
207375	REPAIR OF EQUIPMENT		5/17/2016	42507	\$35.00
	Comments: PNEUMATC PUMP NOT WORKING SKIMMER TANK HALF WAY EMPTY CLEAN UP LEVEL SWITCH SOLENOID VALVE HAS POWER BUT PNEUMATIC PUMP WONT WORK INCREASE AIR PRESSURE TO PUMP PUMP STARTED WORKING ADJUST AIR PRESSURE AND CHECK OPERATION OK				
207455	GAT PAINT WASHER WEEKLY PM	5/23/2016	5/23/2016	0	\$0.00
207557	GAT PAINT WASHER WEEKLY PM	5/30/2016	5/31/2016	1	\$0.00
208046	GAT PAINT WASHER MONTHLY PM	6/15/2016	6/21/2016 8:15:15 AM	6	\$71.95
208231	GAT PAINT WASHER WEEKLY PM	6/7/2016	6/14/2016 7:25:49 AM	7	\$71.95
208264	REPAIR OF EQUIPMENT		6/2/2016	42523	\$35.00
	Comments: CLEANING WASHER HELPED PUMP WASHER OUT COULD NOT RUN CONVEYOR CAUSE IT WAS LOADED NEEDTO OPEN BRUSHES IN PAINT CONVEYOR BEFORE RUNNIG SCISSOR LIFT IS IN PAINT WASHER AREA				
208265	REPAIR OF EQUIPMENT		6/3/2016	42524	\$40.50
	Comments: KEEP AN EYE ON CONTRACTORS AT WASHER DONE				
208288	REPAIR OF EQUIPMENT		6/4/2016	42525	\$280.00
	Comments: REFILLED WASHER TANK WITH WATER GET READY FOR PRDODUCTION 6 6 16 FILLED WITH WATER AND HELP P AINT LINE EMPLOYEE WITH CHEMICALS TOOK BRUSHES OFF OF THE CHAIN				
208289	REPAIR OF EQUIPMENT		6/3/2016	42524	\$199.35
	Comments: PUMP OUT WASHER PUMPED ALLTANKS OUT TO A ATANKER TRUCK				
208492	GAT PAINT WASHER WEEKLY PM	6/21/2016	6/21/2016 8:15:44 AM	0	\$71.95
208624	GAT PAINT WASHER WEEKLY PM	6/28/2016	6/27/2016	0	\$0.00
209185	GAT PAINT WASHER WEEKLY PM	7/4/2016	7/5/2016	1	\$81.00

Asset/Equipment Work Order History Brief

209186	GAT PAINT WASHER MONTHLY PM	7/21/2016	7/18/2016	0	\$0.00
209334	GAT PAINT WASHER WEEKLY PM	7/12/2016	7/11/2016	0	\$0.00
209364	REPAIR OF EQUIPMENT		7/8/2016	42559	\$78.63
	Comments: ASSIT CHEMICAL CONTRACTOR				
	ASSISTED SONNY WITH NEW CHEMICAL APPLICATION SYSTEM DRILLED HOLES THROUGH STAINLESS PLATES ON ZONES 1 AND 2				
209560	GAT PAINT WASHER WEEKLY PM	7/18/2016	7/25/2016	7	\$40.50
210161	GAT PAINT WASHER WEEKLY PM	8/1/2016	8/4/2016 6:12:37 AM	3	\$71.95
210162	GAT PAINT WASHER MONTHLY PM	8/17/2016	8/16/2016	0	\$71.95
210271	REPAIR OF EQUIPMENT		7/21/2016	42572	\$0.00
	Comments: CHANGED OUT FLOW METER PUT OTHER ON CHUCK DESK TO BE SENT OUT				
210340	GAT PAINT WASHER WEEKLY PM	8/11/2016	8/9/2016 8:11:27 AM	0	\$71.95
210461	GAT PAINT WASHER WEEKLY PM	8/16/2016	8/16/2016	0	\$71.95
210658	REPAIR OF EQUIPMENT		8/22/2016	42604	\$40.50
	Comments: PM				
210841	GAT PAINT WASHER WEEKLY PM	8/29/2016	8/30/2016 8:17:08 AM	1	\$71.95
211312	GAT PAINT WASHER WEEKLY PM	9/6/2016	9/7/2016 7:44:59 AM	1	\$71.95
211313	GAT PAINT WASHER MONTHLY PM	9/15/2016	9/20/2016 10:11:11 AM	5	\$71.95
211457	GAT PAINT WASHER WEEKLY PM	9/14/2016	9/13/2016 10:11:52 AM	0	\$71.95
211613	GAT PAINT WASHER WEEKLY PM	9/20/2016	9/20/2016 10:10:53 AM	0	\$71.95
211658	REPAIR OF EQUIPMENT		9/17/2016	42630	\$359.68
	Comments: REMOVE WASTE TANK FROM WASHER				
	ALIGNED WASTE SPILL CONTAINER FOR WASHER CHEMICALS WITE SLUG OIL DISASSEMBLED TANK AND STAND FROM WASHER REMOVED PIPING AND ELECTRICAL CONTROLS				
211769	GAT PAINT WASHER WEEKLY PM	9/27/2016	9/26/2016	0	\$71.95
211870	REPAIR OF EQUIPMENT		9/29/2016	42642	\$164.29
	Comments: STEPS ON OUTSIDE OF WAHSEER NEED TO BE OSHA COMPLAINT				
	FURTHER INVESTIGATION OSHA REQUIREMENTS AND REGULATIONS DETERMINE THAT THE STEPS CAN BE CLASSIFIED AS FIXED LADDERS COME UP WITH PLAN FOR MODIFYING LADDERS TO MEET REQUIREMENTS REMOVED 1 LADDER AND BEGAN MODIFYING WILL COMPLETE AT ANOTHER TIME				

Asset/Equipment Work Order History Brief

211887	REPAIR OF EQUIPMENT		9/28/2016	42641	\$35.21
	Comments:	STEPS ON WASHER NEED TO BE OSHA COMPLIANT			
		INSPECTED STEPS REFERRED TO OSHA REQUIREMENTS AND FIXED STAIRS CAME UP WITH PLAN TO CONSTRUCT STAIRS THAT ARE COMPLIANT			
211921	GAT PAINT WASHER WEEKLY PM	10/3/2016	10/3/2016	0	\$40.50
212433	GAT PAINT WASHER WEEKLY PM	10/10/2016	10/10/2016	0	\$40.50
212434	GAT PAINT WASHER MONTHLY PM	10/20/2016	10/24/2016	4	\$71.95
212506	REPAIR OF EQUIPMENT		10/3/2016	42646	\$0.00
	Comments:	NEED LADDERS TO MEET REGULATION			
		RESULT ONE TO SPEC PARTED IT PUT SLIP TOAPE ON IT AND MOUNTED BCK TO PAINT WASHER			
212514	REPAIR OF EQUIPMENT		10/6/2016	42649	\$70.41
	Comments:	FIXED LADDER MODIFICATION			
		CONTINUED MODIFYING LADDES TO MEET OSHA REQUIREMENTS BEGAN PLANNING FOR ADDITON OF HANDRAILS ACCORDING TO OSHA REQUIREMENTS			
212528	REPAIR OF EQUIPMENT		10/5/2016	42648	\$129.09
	Comments:	FIXED LADDER MODIFICATION			
		CONTINUED MODIFYING LADDER ON WASHER MET WITH LINDA DAVIS ALBOUT WORKERS CONCERN WITH LADDERS IT WAS DECIED TO ADD HANDRAIL NEXT TO LADDER FOR WORKERS TO ASSIT WITH ENTRANCE AND EXIT OFWASHER			
212560	REPAIR OF EQUIPMENT		10/7/2016	42650	\$105.62
	Comments:	FIXED LADDER MODIFICATIONS			
		COMPLETED LADDER MODIFICATIONS			
212632	GAT PAINT WASHER WEEKLY PM	10/17/2016	10/17/2016	0	\$71.95
212769	GAT PAINT WASHER WEEKLY PM	10/24/2016	10/24/2016	0	\$71.95
212895	GAT PAINT WASHER WEEKLY PM	10/31/2016	11/1/2016 8:09:38 AM	1	\$71.95
213345	GAT PAINT WASHER MONTHLY PM	11/23/2016	11/22/2016 8:33:01 AM	0	\$71.95
213450	GAT PAINT WASHER WEEKLY PM	11/8/2016	11/8/2016 7:40:55 AM	0	\$71.95
213572	GAT PAINT WASHER WEEKLY PM	11/15/2016	11/15/2016 8:10:21 AM	0	\$71.95
213684	GAT PAINT WASHER WEEKLY PM	11/22/2016	11/22/2016 8:33:11 AM	0	\$71.95
213770	GAT PAINT WASHER WEEKLY PM	11/29/2016	11/28/2016	0	\$40.50
214220	GAT THREE STAGE PRE TREAT WA	12/29/2016	12/30/2016 10:08:32 AM	1	\$40.50
214256	GAT PAINT WASHER WEEKLY PM	12/5/2016	12/5/2016	0	\$71.95

Asset/Equipment Work Order History Brief

214257	GAT PAINT WASHER MONTHLY PM	12/22/2016	12/30/2016 9:58:52 AM	8	\$71.95
214382	GAT PAINT WASHER WEEKLY PM	12/12/2016	12/12/2016	0	\$40.50
214494	GAT PAINT WASHER WEEKLY PM	12/19/2016	12/20/2016 11:21:56 AM	1	\$71.95
214643	GAT PAINT WASHER WEEKLY PM	12/27/2016	12/27/2016	0	\$40.50
215166	GAT PAINT WASHER WEEKLY PM	1/3/2017	1/5/2017	2	\$71.95
215167	GAT PAINT WASHER MONTHLY PM	1/30/2017	2/3/2017 11:22:53 AM	4	\$71.95
215292	GAT PAINT WASHER WEEKLY PM	1/12/2017	1/10/2017	0	\$40.50
215388	GAT PAINT WASHER WEEKLY PM	1/17/2017	1/17/2017	0	\$81.00
215460	GAT PAINT WASHER WEEKLY PM	1/24/2017	1/23/2017	0	\$81.00
215599	GAT PAINT WASHER WEEKLY PM	1/30/2017	1/30/2017	0	\$112.45
215902	GAT PAINT WASHER WEEKLY PM	2/6/2017	2/7/2017 8:11:39 AM	1	\$81.00
216137	GAT PAINT WASHER WEEKLY PM	2/14/2017	2/14/2017	0	\$81.00
216236	GAT PAINT WASHER WEEKLY PM	2/21/2017	2/20/2017	0	\$81.00
216367	GAT PAINT WASHER WEEKLY PM	2/27/2017	2/28/2017 7:43:50 AM	1	\$81.00
216763	GAT PAINT WASHER WEEKLY PM	3/7/2017	3/8/2017 8:06:38 AM	1	\$81.00
216764	GAT PAINT WASHER MONTHLY PM	3/6/2017	4/3/2017 12:01:05 PM	28	\$71.95
216958	GAT PAINT WASHER WEEKLY PM	3/15/2017	3/15/2017 7:50:01 AM	0	\$81.00
217058	GAT PAINT WASHER WEEKLY PM	3/22/2017	3/22/2017 8:14:57 AM	0	\$81.00
217168	GAT PAINT WASHER WEEKLY PM	3/29/2017	4/3/2017 1:22:03 PM	5	\$81.00
217691	GAT PAINT WASHER WEEKLY PM	4/10/2017	4/11/2017	1	\$93.15
217694	REPAIR OF EQUIPMENT		4/4/2017	42829	\$43.19
	Comments: GRATES CAUGHT BY HANGER				
	STAINLESS STEEL GRATE HUNG INTO DRIVE CHAIN MANUALLY REVERSED CHAIN TO REMOVE GRATE				
217785	GAT PAINT WASHER WEEKLY PM	4/18/2017	4/20/2017 8:24:37 AM	2	\$81.00

Asset/Equipment Work Order History Brief

217863	GAT PAINT WASHER WEEKLY PM	4/27/2017	4/27/2017 8:12:06 AM	0	\$81.00
218351	GAT PAINT WASHER WEEKLY PM	5/4/2017	5/3/2017 11:27:11 AM	0	\$81.00
218352	GAT PAINT WASHER MONTHLY PM	5/3/2017	6/15/2017 8:58:15 AM	43	\$71.95
218496	GAT PAINT WASHER WEEKLY PM	5/10/2017	5/11/2017	1	\$121.50
218557	GAT PAINT WASHER WEEKLY PM	5/18/2017	5/17/2017 8:49:54 AM	0	\$81.00
218704	GAT PAINT WASHER WEEKLY PM	5/24/2017	5/24/2017 8:16:46 AM	0	\$81.00
218816	GAT PAINT WASHER WEEKLY PM	5/31/2017	5/31/2017	0	\$121.50
218828	REPAIR OF EQUIPMENT		5/26/2017	42881	\$140.00
	Comments: ASSIST CONTRACTOR WORKING ON PAINT WASHER				
	SAME CLEAN UP WATER SPILL REPLACE BAD ARI REGULATOR IN PAINT ROOM				
219333	GAT PAINT WASHER WEEKLY PM	6/7/2017	6/7/2017 8:00:41 AM	0	\$81.00
219382	GAT PAINT WASHER WEEKLY PM	6/14/2017	6/14/2017 11:47:47 AM	0	\$81.00
219480	GAT PAINT WASHER WEEKLY PM	6/21/2017	6/20/2017	0	\$81.00
219557	GAT PAINT WASHER WEEKLY PM	6/27/2017	7/12/2017 11:20:27 AM	15	\$81.00
220056	GAT PAINT WASHER MONTHLY PM	7/17/2017	8/15/2017	29	\$112.45
220194	GAT PAINT WASHER WEEKLY PM	7/19/2017		0	\$81.00
220766	GAT PAINT WASHER WEEKLY PM	8/1/2017	7/31/2017	0	\$81.00
220875	GAT PAINT WASHER WEEKLY PM	8/7/2017	8/9/2017 12:44:37 PM	2	\$81.00
221006	GAT PAINT WASHER WEEKLY PM	8/16/2017	8/15/2017 10:25:12 AM	0	\$81.00
221077	GAT PAINT WASHER WEEKLY PM	8/22/2017	8/22/2017 12:38:27 PM	0	\$81.00
221158	GAT PAINT WASHER WEEKLY PM	8/29/2017	8/31/2017 7:48:42 AM	2	\$81.00
221544	GAT PAINT WASHER WEEKLY PM	9/7/2017	9/6/2017	0	\$81.00
221545	GAT PAINT WASHER MONTHLY PM	9/14/2017	9/29/2017 7:45:13 AM	15	\$71.95
221736	GAT PAINT WASHER WEEKLY PM	9/13/2017	9/12/2017 8:41:37 AM	0	\$81.00

Asset/Equipment Work Order History Brief

221800	GAT PAINT WASHER WEEKLY PM	9/19/2017	9/19/2017 7:43:35 AM	0	\$81.00
221912	GAT PAINT WASHER WEEKLY PM	9/26/2017	9/25/2017	0	\$121.50
222383	GAT PAINT WASHER WEEKLY PM	10/2/2017	10/3/2017 12:55:43 PM	1	\$81.00
222384	GAT PAINT WASHER MONTHLY PM	10/30/2017	11/21/2017 7:57:20 AM	22	\$81.00
222518	GAT PAINT WASHER WEEKLY PM	10/10/2017	10/10/2017 12:45:11 PM	0	\$81.00
222656	GAT PAINT WASHER WEEKLY PM	10/17/2017	10/16/2017 8:02:35 AM	0	\$81.00
222801	GAT PAINT WASHER WEEKLY PM	10/23/2017	10/23/2017 7:32:48 AM	0	\$81.00
222911	GAT PAINT WASHER WEEKLY PM	10/30/2017	10/31/2017 6:25:25 AM	1	\$81.00
223314	GAT PAINT WASHER WEEKLY PM	11/7/2017	11/6/2017 9:03:36 AM	0	\$81.00
223576	GAT PAINT WASHER WEEKLY PM	11/13/2017	11/14/2017 9:45:51 AM	1	\$81.00
223616	GAT PAINT WASHER WEEKLY PM	11/21/2017	11/20/2017 8:03:42 AM	0	\$81.00
223783	GAT PAINT WASHER WEEKLY PM	11/27/2017	11/30/2017 8:56:16 AM	3	\$81.00
224085	GAT PAINT WASHER WEEKLY PM	12/7/2017	12/11/2017 8:44:25 AM	4	\$81.00
224086	GAT PAINT WASHER MONTHLY PM	12/21/2017	12/21/2017	0	\$40.50
224263	REPAIR OF EQUIPMENT		12/13/2017 7:30:55 AM	43082	\$52.50
	Comments: - ADD 1/4 - 14 X 1 1/2 DRILL POINT SCREWS				
224324	GAT PAINT WASHER WEEKLY PM	12/18/2017		0	\$81.00
224333	REPAIR OF EQUIPMENT		12/18/2017 8:24:32 AM	43087	\$0.00
	Comments: Performed weekly P.M.				
224903	GAT THREE STAGE PRE TREAT WA	1/1/2018	5/7/2018	126	\$31.45
224935	GAT PAINT WASHER MONTHLY PM	1/22/2018	1/30/2018 9:01:28 AM	8	\$40.50
225072	GAT PAINT WASHER WEEKLY PM	12/25/2017	1/8/2018	14	\$81.00
225073	GAT PAINT WASHER WEEKLY PM	1/15/2018	1/18/2018	3	\$81.00
225189	GAT PAINT WASHER WEEKLY PM	1/25/2018	1/24/2018	0	\$81.00
225389	GAT PAINT WASHER WEEKLY PM	1/31/2018	2/5/2018	5	\$81.00

Asset/Equipment Work Order History Brief

225453	LUBE AND CHECK FOR WEAR AND		1/30/2018 9:41:12 AM	43130	\$20.25
	Comments: weekly pm				
225739	GAT PAINT WASHER MONTHLY PM	3/1/2018	3/21/2018	20	\$40.50
225887	GAT PAINT WASHER WEEKLY PM	2/12/2018	2/12/2018	0	\$81.00
225977	GAT PAINT WASHER WEEKLY PM	2/19/2018	2/19/2018	0	\$81.00
226068	GAT PAINT WASHER WEEKLY PM	2/26/2018	3/2/2018 3:51:57 PM	4	\$81.00
226383	GAT PAINT WASHER WEEKLY PM	3/9/2018	3/5/2018	0	\$81.00
226493	GAT PAINT WASHER WEEKLY PM	3/12/2018	3/12/2018	0	\$81.00
226556	GAT PAINT WASHER WEEKLY PM	3/19/2018	3/19/2018	0	\$81.00
226658	GAT PAINT WASHER WEEKLY PM	3/26/2018	3/26/2018	0	\$81.00
226934	GAT PAINT WASHER MONTHLY PM	4/20/2018	5/15/2018	25	\$81.00
227051	GAT PAINT WASHER WEEKLY PM	4/2/2018	4/9/2018	7	\$81.00
227195	GAT PAINT WASHER WEEKLY PM	4/16/2018	4/16/2018	0	\$81.00
227271	GAT PAINT WASHER WEEKLY PM	4/23/2018	4/24/2018	1	\$81.00
227642	GAT PAINT WASHER WEEKLY PM	5/1/2018	5/7/2018	6	\$81.00
227718	REPAIR OF EQUIPMENT		4/30/2018	43220	\$81.00
	Comments: Weekly PM. Perform weekly PM. Washer was running from day shift.				
227734	REPAIR OF EQUIPMENT		5/3/2018	43223	\$245.00
	Comments: Add air nozzles. Run air drop, 1/2" iron pipe. Add air regulator, air filter, mount it to the frame. Run 1/2" EMT conduit for solenoid valve power, 120VAC. Not finish.				
227745	REPAIR OF EQUIPMENT		5/4/2018	43224	\$157.50
	Comments: Add air nozzles to paint washer entrance. Make bracket to mount nozzles. Finish up air line to nozzles. Finish up conduit run and pull solenoid control wire. Wire to 120VAC control at junction box. Only need to terminate solenoid wiring.				
227746	REPAIR OF EQUIPMENT		5/4/2018	43224	\$175.00
	Comments: Pump washer out into tanker truck. 6000 gallons. Washer and river tanks. Empty the washer tanks into a tanker truck. Pump all water out of the paint washer and rinse tanks. Cleaned all tanks out slugs.				
227790	GAT PAINT WASHER WEEKLY PM	5/14/2018	5/15/2018	1	\$81.00
227881	GAT PAINT WASHER WEEKLY PM	5/22/2018	5/21/2018	0	\$81.00
227958	GAT PAINT WASHER WEEKLY PM	5/28/2018	5/29/2018	1	\$81.00

Asset/Equipment Work Order History Brief

228218	GAT PAINT WASHER WEEKLY PM	6/5/2018	6/4/2018	0	\$81.00
228219	GAT PAINT WASHER MONTHLY PM	6/14/2018	8/1/2018	48	\$81.00
228332	GAT PAINT WASHER WEEKLY PM	6/11/2018	6/11/2018	0	\$81.00
228420	GAT PAINT WASHER WEEKLY PM	6/18/2018	6/19/2018	1	\$81.00
228551	GAT PAINT WASHER WEEKLY PM	6/26/2018	7/5/2018 7:18:12 AM	9	\$81.00
228825	GAT PAINT WASHER WEEKLY PM	7/12/2018	7/18/2018	6	\$81.00
228987	GAT PAINT WASHER WEEKLY PM	7/25/2018	7/23/2018	0	\$81.00
229047	GAT PAINT WASHER WEEKLY PM	7/30/2018	8/1/2018	2	\$81.00
229447	GAT PAINT WASHER WEEKLY PM	8/8/2018	8/8/2018	0	\$81.00
229448	GAT PAINT WASHER MONTHLY PM	8/31/2018	9/25/2018	25	\$81.00
229531	GAT PAINT WASHER WEEKLY PM	8/15/2018	8/13/2018	0	\$81.00
229638	GAT PAINT WASHER WEEKLY PM	8/20/2018	8/21/2018	1	\$81.00
229642	GAT PAINT WASHER WEEKLY PM	8/28/2018	8/31/2018 10:51:41 AM	3	\$81.00
229978	GAT PAINT WASHER WEEKLY PM	9/7/2018	9/5/2018	0	\$81.00
230041	GAT PAINT WASHER WEEKLY PM	9/12/2018	9/18/2018	6	\$81.00
230180	GAT PAINT WASHER WEEKLY PM	9/25/2018	9/25/2018	0	\$81.00
230529	GAT PAINT WASHER WEEKLY PM	10/2/2018	10/2/2018 8:24:43 AM	0	\$81.00
230530	GAT PAINT WASHER MONTHLY PM	10/25/2018	11/14/2018 7:48:27 AM	20	\$81.00
230712	GAT PAINT WASHER WEEKLY PM	10/9/2018	10/8/2018 10:35:41 PM	0	\$81.00
230783	GAT PAINT WASHER WEEKLY PM	10/15/2018	10/15/2018 9:57:29 PM	0	\$81.00
230864	GAT PAINT WASHER WEEKLY PM	10/22/2018	10/22/2018 10:23:07 PM	0	\$81.00
230934	GAT PAINT WASHER WEEKLY PM	10/29/2018	10/30/2018 11:50:04 PM	1	\$81.00
231145	GAT PAINT WASHER WEEKLY PM	11/6/2018	11/12/2018 3:25:40 AM	6	\$81.00

Asset/Equipment Work Order History Brief

231376	GAT PAINT WASHER WEEKLY PM	11/19/2018	11/28/2018 11:40:12 PM	9	\$81.00
231719	GAT PAINT WASHER WEEKLY PM	12/5/2018	12/3/2018 11:44:11 PM	0	\$81.00
231720	GAT PAINT WASHER MONTHLY PM	12/3/2018	12/13/2018 11:57:42 PM	10	\$81.00
231744	REPAIR OF EQUIPMENT		12/3/2018 11:48:51 PM	43437	\$20.25
	Comments: checked exhaust fan, motor seems to be source of noise				
231747	REPAIR OF EQUIPMENT		12/4/2018 11:42:56 PM	43438	\$261.50
	Comments: removed and replaced bad air curtain motor at entrance to washer.				
231824	GAT PAINT WASHER WEEKLY PM	12/10/2018	12/12/2018 11:09:13 PM	2	\$81.00
232188	GAT PAINT WASHER WEEKLY PM	12/19/2018	1/3/2019 8:09:45 AM	15	\$81.00
232189	GAT PAINT WASHER MONTHLY PM	1/14/2019	1/23/2019 11:47:41 PM	9	\$81.00
232249	GAT PAINT WASHER WEEKLY PM	1/10/2019	1/7/2019 2:49:43 AM	0	\$81.00
232328	REPAIR OF EQUIPMENT		1/14/2019 12:38:20 AM	43479	\$81.00
	Comments: weekly PM				
232379	GAT PAINT WASHER WEEKLY PM	1/14/2019	1/23/2019 11:48:32 PM	9	\$81.00
232425	GAT PAINT WASHER WEEKLY PM	1/30/2019	1/29/2019 9:44:27 PM	0	\$81.00
232689	GAT PAINT WASHER WEEKLY PM	2/5/2019	2/5/2019 11:41:53 PM	0	\$81.00
232690	GAT PAINT WASHER MONTHLY PM	2/22/2019	2/27/2019 11:26:42 PM	5	\$81.00
232760	GAT PAINT WASHER WEEKLY PM	2/12/2019	2/12/2019 1:19:57 AM	0	\$81.00
232847	GAT PAINT WASHER WEEKLY PM	2/19/2019	2/19/2019 11:32:54 PM	0	\$81.00
232913	GAT PAINT WASHER WEEKLY PM	2/26/2019	2/25/2019 9:44:14 PM	0	\$81.00
233193	GAT PAINT WASHER WEEKLY PM	3/4/2019	3/5/2019 11:07:17 PM	1	\$81.00
233194	GAT PAINT WASHER MONTHLY PM	3/29/2019	4/29/2019 2:28:12 PM	31	\$81.00
233305	GAT PAINT WASHER WEEKLY PM	3/12/2019	3/12/2019 11:30:02 PM	0	\$81.00
233411	GAT PAINT WASHER WEEKLY PM	3/19/2019	3/29/2019 9:40:16 AM	10	\$81.00
233445	REPAIR OF EQUIPMENT		3/26/2019 11:53:34 PM	43550	\$81.00
	Comments: weekly pm				

Asset/Equipment Work Order History Brief

233797	GAT PAINT WASHER WEEKLY PM	4/5/2019	4/1/2019 11:31:43 PM	0	\$81.00
233846	GAT PAINT WASHER WEEKLY PM	4/8/2019	4/9/2019 2:13:43 AM	1	\$81.00
233865	GAT PAINT WASHER WEEKLY PM	4/16/2019	4/15/2019 11:49:53 PM	0	\$81.00
233908	REPAIR OF EQUIPMENT Comments: weekly pm		4/23/2019 2:03:12 AM	43578	\$81.00
	performed pm				
233942	GAT PAINT WASHER WEEKLY PM	4/22/2019	4/22/2019	0	\$81.00
233962	GAT PAINT WASHER WEEKLY PM	4/29/2019	4/29/2019 8:42:42 PM	0	\$81.00
234196	GAT PAINT WASHER WEEKLY PM	5/6/2019	5/6/2019 11:02:56 PM	0	\$81.00
234197	GAT THREE STAGE PRE TREAT WA	5/7/2019	6/7/2019 2:52:30 PM	31	\$40.50
234198	GAT PAINT WASHER MONTHLY PM	5/29/2019	5/16/2019 11:11:56 PM	0	\$81.00
234237	GAT PAINT WASHER WEEKLY PM	5/13/2019	5/13/2019 9:00:19 PM	0	\$81.00
234318	GAT PAINT WASHER WEEKLY PM	5/20/2019	5/20/2019 11:06:26 PM	0	\$81.00
234434	GAT PAINT WASHER WEEKLY PM	5/27/2019	5/30/2019 1:59:49 PM	3	\$81.00
234618	GAT PAINT WASHER WEEKLY PM	6/6/2019	6/7/2019	1	\$81.00
234619	GAT PAINT WASHER MONTHLY PM	6/17/2019	7/17/2019 12:07:32 PM	30	\$81.00
234651	REPAIR OF EQUIPMENT Comments: washer will not start		6/7/2019 5:20:17 PM	43623	\$0.00
	2 fuses blown on input, fuseholder arced and fuse blown, replaced all of the above				
234703	GAT PAINT WASHER WEEKLY PM	6/14/2019	7/5/2019 12:07:14 PM	21	\$81.00
235030	GAT PAINT WASHER WEEKLY PM	7/12/2019	7/15/2019 10:10:08 AM	3	\$62.90
235062	REPAIR OF EQUIPMENT Comments: assist with washer pump-out		6/7/2019 10:07:30 AM	43623	\$47.18
235181	GAT PAINT WASHER WEEKLY PM	7/22/2019	7/22/2019 8:29:25 AM	0	\$81.00
235493	GAT PAINT WASHER WEEKLY PM	7/29/2019	8/16/2019 8:02:53 AM	18	\$81.00

Asset/Equipment Work Order History Brief

235494	GAT PAINT WASHER MONTHLY PM	8/5/2019	8/16/2019 2:43:03 PM	11	\$81.00
235656	GAT PAINT WASHER WEEKLY PM	8/19/2019	8/23/2019 9:29:09 AM	4	\$70.00
235795	GAT PAINT WASHER MONTHLY PM	9/16/2019	9/30/2019 8:00:29 AM	14	\$81.00
235816	GAT PAINT WASHER WEEKLY PM	8/30/2019	8/30/2019 9:42:25 AM	0	\$70.00
235819	GAT PAINT WASHER WEEKLY PM	9/6/2019	9/11/2019 9:57:00 AM	5	\$70.00
235822	GAT PAINT WASHER WEEKLY PM	9/18/2019	9/20/2019 9:59:56 AM	2	\$70.00
235851	GAT PAINT WASHER WEEKLY PM	9/27/2019	9/26/2019 8:05:41 AM	0	\$70.00
236145	GAT PAINT WASHER WEEKLY PM	10/3/2019	10/10/2019 9:30:26 AM	7	\$70.00
236146	GAT PAINT WASHER MONTHLY PM	10/30/2019	11/1/2019 1:20:04 PM	2	\$81.00
236193	GAT PAINT WASHER WEEKLY PM	10/17/2019	10/17/2019 8:59:59 AM	0	\$70.00
236241	GAT PAINT WASHER WEEKLY PM	10/24/2019	11/1/2019 7:05:28 AM	8	\$70.00
236274	GAT PAINT WASHER WEEKLY PM	10/31/2019	10/29/2019 1:23:10 PM	0	\$70.00
236514	GAT PAINT WASHER WEEKLY PM	11/5/2019	11/5/2019 10:05:54 AM	0	\$70.00
236515	GAT PAINT WASHER MONTHLY PM	11/28/2019	1/9/2020 3:01:44 PM	42	\$81.00
236554	GAT PAINT WASHER WEEKLY PM	11/12/2019	1/9/2020 2:43:46 PM	58	\$70.00
237192	GAT PAINT WASHER WEEKLY PM	1/16/2020	1/16/2020 2:43:08 PM	0	\$70.00
237480	GAT PAINT WASHER WEEKLY PM	1/30/2020	1/30/2020 4:50:36 PM	0	\$70.00
237481	GAT PAINT WASHER MONTHLY PM	2/10/2020	2/10/2020 9:38:09 AM	0	\$70.00
237521	GAT PAINT WASHER WEEKLY PM	2/13/2020	2/13/2020 9:43:32 AM	0	\$70.00
237596	GAT PAINT WASHER WEEKLY PM	2/27/2020	2/27/2020 9:58:55 AM	0	\$70.00
237908	GAT PAINT WASHER WEEKLY PM	3/12/2020	3/12/2020 3:58:28 PM	0	\$70.00
237909	GAT PAINT WASHER MONTHLY PM	3/11/2020	3/11/2020 3:56:32 PM	0	\$70.00
237995	GAT PAINT WASHER WEEKLY PM	3/26/2020	3/26/2020 4:54:41 PM	0	\$70.00

Asset/Equipment Work Order History Brief

238209	GAT PAINT WASHER WEEKLY PM	4/9/2020	4/9/2020 8:18:12 AM	0	\$70.00
238210	GAT PAINT WASHER MONTHLY PM	4/10/2020	4/10/2020 8:19:29 AM	0	\$70.00
238558	GAT PAINT WASHER WEEKLY PM	4/23/2020	4/23/2020 12:13:44 PM	0	\$70.00
238559	GAT PAINT WASHER MONTHLY PM	5/11/2020	5/11/2020 2:35:32 PM	0	\$70.00
238849	GAT THREE STAGE PRE TREAT WA	6/1/2020	8/31/2020 11:32:45 AM	91	\$40.50
	Comments: postponed until t&l tests washer fluid needs changing due to less weekly hours. 2-3 days				
238881	GAT PAINT WASHER WEEKLY PM	5/7/2020	5/14/2020 12:21:35 PM	7	\$70.00
238889	GAT PAINT WASHER WEEKLY PM	5/28/2020	5/28/2020 7:03:36 AM	0	\$70.00
239024	GAT PAINT WASHER WEEKLY PM	6/11/2020	6/15/2020 10:03:27 AM	4	\$70.00
239025	GAT PAINT WASHER MONTHLY PM	6/10/2020	6/15/2020 10:03:53 AM	5	\$70.00
239030	GAT PAINT WASHER WEEKLY PM	6/29/2020	6/30/2020 10:10:29 AM	1	\$70.00
239244	GAT PAINT WASHER WEEKLY PM	7/14/2020	7/14/2020 8:32:11 AM	0	\$70.00
239245	GAT PAINT WASHER MONTHLY PM	7/15/2020	7/15/2020 9:10:29 AM	0	\$70.00
239338	GAT PAINT WASHER WEEKLY PM	7/28/2020	7/31/2020 9:37:41 AM	3	\$70.00
239566	GAT PAINT WASHER WEEKLY PM	8/14/2020	8/18/2020 11:25:15 AM	4	\$70.00
239567	GAT PAINT WASHER MONTHLY PM	8/14/2020	8/18/2020 11:19:49 AM	4	\$70.00
239589	REPAIR OF EQUIPMENT		8/19/2020 10:33:53 AM	44062	\$40.50
	Comments: 1st stage washer is overflowing				
	closed interconnecting valve, drained excess water, clean up				
239942	GAT PAINT WASHER WEEKLY PM	9/1/2020	9/1/2020 8:42:36 AM	0	\$70.00
239943	GAT PAINT WASHER MONTHLY PM	9/17/2020	9/17/2020 6:57:04 AM	0	\$70.00
239989	GAT PAINT WASHER WEEKLY PM	9/15/2020	9/18/2020 7:31:40 AM	3	\$70.00
240213	GAT PAINT WASHER WEEKLY PM	10/2/2020	10/2/2020 9:19:03 AM	0	\$70.00
240214	GAT PAINT WASHER MONTHLY PM	10/19/2020	11/5/2020 10:00:05 AM	17	\$70.00
240253	GAT PAINT WASHER WEEKLY PM	10/16/2020	10/19/2020 10:17:36 AM	3	\$70.00
240471	GAT PAINT WASHER WEEKLY PM	11/2/2020	11/6/2020 8:02:29 AM	4	\$70.00

Asset/Equipment Work Order History Brief

240513	GAT PAINT WASHER WEEKLY PM	11/20/2020	12/1/2020 9:27:41 AM	11	\$70.00
240768	GAT PAINT WASHER WEEKLY PM	12/15/2020	12/15/2020 10:18:21 AM	0	\$70.00
240769	GAT PAINT WASHER MONTHLY PM	12/7/2020	12/7/2020 10:06:48 AM	0	\$70.00
241012	GAT PAINT WASHER WEEKLY PM	12/29/2020	2/9/2021 12:47:26 PM	42	\$70.00
241013	GAT PAINT WASHER MONTHLY PM	1/6/2021	2/9/2021 12:49:46 PM	34	\$70.00
241254	GAT PAINT WASHER WEEKLY PM	2/23/2021	2/23/2021 11:04:02 AM	0	\$70.00
241490	GAT PAINT WASHER WEEKLY PM	3/9/2021		0	\$0.00
241491	GAT PAINT WASHER MONTHLY PM	3/11/2021		0	\$0.00
Totals For: WASH 006		Total WOs: 466		Total Cost:	<u>\$44,522.75</u>
Report Totals:		Total Assets:	1		\$44,522.75

Selection SQL: Asset.ID Like "WASH 006**"