



Vehicle History Report™

2007 DODGE SPRINTER 2500

VIN: WD0BE745475173940
CARGO VAN
3.0L V6 F
DIESEL
REAR WHEEL DRIVE



No accidents or damage reported to CARFAX



At least 1 open recall



2 Previous owners



Types of owners: Commercial, Personal



Last owned in Ontario



18 Detailed records available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 12/9/22 at 3:21:51 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Ownership History

The number of owners is estimated

Owner 1

Owner 2

Year purchased

2007

2022

Type of owner

Commercial

Personal

Estimated length of ownership

15 yrs. 4 mo.

1 month

Owned in the following states/provinces

Ontario

Ontario

Estimated miles driven per year

Last reported odometer reading



Title History

CARFAX guarantees the information in this section

Owner 1

Owner 2

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon



Guaranteed
No Problem



Guaranteed
No Problem

Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits



Guaranteed
No Problem



Guaranteed
No Problem



GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not



Additional History

Not all accidents / issues are reported to CARFAX

	Owner 1	Owner 2
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires repair.	Recall Reported	No New Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired



Detailed History



Owner 1

Purchased: 2007

Commercial Vehicle

Date	Mileage	Source	Comments
06/12/2007		Ontario Ministry of Transportation Greater Toronto Area	Registration issued or renewed - First owner reported - Registered as commercial vehicle - Passed safety inspection - Vehicle color noted as White
06/12/2007		Ontario Ministry of Transportation Southwestern Ontario	Registration issued or renewed - Registered as commercial vehicle

02/29/2008

FCA US LLC

Manufacturer Safety recall issued

- NHTSA #07V-594
- Recall #H02 CRANKSHAFT POSITION SENSOR
- Status: Remedy available

Click here for a copy of the owner letter for this Recall or call 1- 800-853-1403 if you have any questions or need additional information on this recall.

⊖ [Learn more about this recall](#)

Description: THE CRANKSHAFT POSITION SENSOR MAY HAVE BEEN MANUFACTURED INCORRECTLY. THIS COULD CAUSE THE VEHICLES ENGINE TO STALL OR NOT START UNDER CERTAIN CONDITIONS

ENGINE STALLING COULD CAUSE A CRASH WITHOUT WARNING.

Remedy: THE CRANKSHAFT POSITION SENSOR MUST BE REPLACED ON ALL VEHICLES

07/01/2008

Ontario
Ministry of
Transportation
Southwestern Ontario

Registration issued or renewed

- Registered as commercial vehicle

02/26/2009

FCA US LLC

Manufacturer Emissions recall issued

- Recall #H44 REPROGRAM ECM
- Status: Remedy available

Click here for a copy of the owner letter for this Recall or call 1- 800-853-1403 if you have any questions or need additional information on this recall.

⊖ [Learn more about this recall](#)

Description: N/A

N/A

Remedy: THE ENGINE CONTROL MODULE (ECM) MUST BE REPROGRAMMED

07/01/2009

Ontario
Ministry of
Transportation
Southwestern Ontario

Registration issued or renewed

- Registered as commercial vehicle

07/01/2010

Ontario
Ministry of
Transportation
Southwestern Ontario

Registration issued or renewed

- Registered as commercial vehicle

07/01/2011	Ontario Ministry of Transportation Southwestern Ontario	Registration issued or renewed - Registered as commercial vehicle
07/01/2012	Ontario Ministry of Transportation Southwestern Ontario	Registration issued or renewed - Registered as commercial vehicle
07/01/2013	Ontario Ministry of Transportation Southwestern Ontario	Registration issued or renewed - Registered as commercial vehicle
07/01/2014	Ontario Ministry of Transportation Southwestern Ontario	Registration issued or renewed - Registered as commercial vehicle
07/01/2015	Ontario Ministry of Transportation Southwestern Ontario	Registration issued or renewed - Registered as commercial vehicle
08/21/2015	FCA US LLC	<p>Manufacturer Safety recall issued</p> <ul style="list-style-type: none"> - NHTSA #17V-478 - Recall #R49 PASSENGER AIRBAG MODULE - Status: Remedy available <p>Click here for a copy of the owner letter for this Recall or call 1- 800-853-1403 if you have any questions or need additional information on this recall.</p> <p>⊖ Learn more about this recall</p>

Description: THE PASSENGER AIRBAG INFLATOR HOUSING MAY RUPTURE, DUE TO EXCESSIVE INTERNAL PRESSURE, DURING NORMAL AIRBAG DEPLOYMENT EVENTS. THIS CONDITION IS MORE LIKELY TO OCCUR IF YOUR VEHICLE HAS BEEN EXPOSED TO HIGH LEVELS OF ABSOLUTE HUMIDITY FOR EXTENDED PERIODS OF TIME.

AN INFLATOR RUPTURE COULD RESULT IN METAL FRAGMENTS STRIKING AND POTENTIALLY SERIOUSLY INJURING THE VEHICLE OCCUPANT(S).

Remedy: THE PASSENGER AIRBAG INFLATOR MUST BE REPLACED.

04/06/2016

FCA US LLC

Manufacturer Safety recall issued

- NHTSA #16V-077
- Recall #S14 DRIVER AIRBAG MODULE
- Status: Remedy available

Click here for a copy of the owner letter for this Recall or call 1- 800-853-1403 if you have any questions or need additional information on this recall.

[⊖ Learn more about this recall](#)

Description: THE DRIVER AIRBAG INFLATOR MAY RUPTURE WHEN DEPLOYING DURING A CRASH. THE POTENTIAL FOR SUCH RUPTURES MAY OCCUR IN SOME OF THE SUBJECT AIRBAG INFLATORS AFTER SEVERAL YEARS OF EXPOSURE TO PERSISTENT CONDITIONS OF HIGH ABSOLUTE HUMIDITY.

IN THE EVENT OF A DRIVER AIRBAG INFLATOR RUPTURE, METAL FRAGMENTS COULD PASS THROUGH THE AIRBAG CUSHION MATERIAL, WHICH MAY RESULT IN ADDITIONAL INJURY OR DEATH TO VEHICLE OCCUPANTS.

Remedy: THE DRIVER AIRBAG MODULE MUST BE REPLACED ON ALL VEHICLES. CERTAIN 2007 AND 2008 MY VEHICLES WILL REQUIRE A STEERING WHEEL REPLACEMENT.

07/01/2016

Ontario
Ministry of
Transportation
Southwestern Ontario

Registration issued or renewed

- Registered as commercial vehicle

07/01/2017

Ontario
Ministry of
Transportation
Southwestern Ontario

Registration issued or renewed

- Registered as commercial vehicle

07/01/2018

Ontario
Ministry of
Transportation
Southwestern Ontario

Registration issued or renewed

- Registered as commercial vehicle



Owner 2

Purchased: 2022

Personal Vehicle

Date

Mileage

Source

Comments

10/19/2022

Ontario
Ministry of
Transportation

Requires Ontario safety standards inspection

- New owner reported
- Vehicle color noted as White

Have Questions? Please visit our Help Center at www.carfax.com.



Glossary

Commercial

Vehicle was registered for business purposes.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2022 CARFAX, Inc., part of S&P Global. All rights reserved.
12/9/22 3:21:51 PM (CST)