PHILIPS LIGHTING WORK ORDER - PREVENTIVE MAINTENANCE

Work Order: 233411 Description: GAT PAINT WASHER WEEKLY PM

Asset ID:	WASH 006			Model: 12097					Sch Date: 3/19/2019			
Asset:	t: GAT THREE STAGE PRE-TREAT WASHER			Serial No: 12097A					Add Date	: 3/20/2019	7:43:28	AM
Procedure:	GENERA	L AUTOMATIC TRANSF	ER WA	Location: PAINT	DEPT				Priority:	0		
Master WO ID:				Building:					Shift:			
Requested By:				Floor:		Room			Superviso	or:		
Telephone:		Ext:		Elec Line:					Status:	Open		
Request ID:				Asset ShutDn: 🗸	Plar	nt ShutDn	: 🗌		Skill:	ET		
Warranty:									Assigned	To:		
Labor:		Labar Dagarintian	Assigned To		Est Hrs	Rem	D	0	Daubla	Other	Data	
Craft Description		Labor Description		Cost ID		Hrs	Reg	Over	Double	Other	Date	
ELECTRONIC TECHNI B		BO RUTLEDGE	L 2	25	2.00	2.00			-		/ /	—
Task: 0	ID: WASH 006 OWPM Description: GENERAL AUTOMATIC TRANSFER COMPANY WASHER WEEKLY P											
Safety:	Text: 1 VISUALLY INSPECT ALL TANKS AND FLOOR AREA AROUND THE TANKS FOR ANY SIGN OF WATER											
	2	CHECK THE WA	ATER LEV	VEL IN ALL TANKS	TO INS	SURE THI	EY ARE	AT PF	ROPER			
	3			FOR ANY SIGNS INDICATING LEAK		IED CHE	MICAL	RESID	JE OR			
	4	SLUDGE ACC CAN RESULT	CUMULAT IN PUMF	SCREENS FROM E TION. REDUCTION P STARVATION AN S NECESSARY.	OF SC	CREEN O	PENIN	G OF 2	5% OR M	ORE		
	5			CONCENTRATIO		CORDAN	NCE W	TH SU	PPLIERS			
	6	PIPES. REPL THOROUGHL	ACE, AS Y INSPE	T THE ENTIRE SP REQUIRED, ANY I CT ALL RUBBER (CROSS FEED PIPE	MISSING CONNE	G NOZZL CTION H	ES OR OSES E	ELBO\ BETWE	VS. EN THE	PR		
	7	LUBE TURN RO	LLERS									
Completion In								Due (Count/Met	<u>ter</u>		
Date:		Supervisor:	Т	Γime On:		Current C	Count:					0
Shift:		Down Time:	Т	Time Off:		Current I	Meter:					0

3/21/2019 1:36:55 PM Page 1 of 1